

UNITED STATES
 DEPARTMENT OF THE INTERIOR
 BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED
 Budget Bureau No. 1004-0135
 Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS ^{AUG 24 3 12 PM '95}

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
 Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.
 NM-052

6. If Indian, Allottee or Tribe Name
 N/A

7. If Unit or CA, Agreement Designation
 N/A

8. Well Name and No.
 Mallon 34 Federal No. 1

9. API Well No.
 30-025-32605

10. Field, Pool, or Exploratory Area
 San Andres (96121)

11. County or Parish, State
 Lea County, New Mexico

SUBMIT IN TRIPLICATE

Type of Well
 Oil Well Gas Well Other SWD

Name of Operator
 Mallon Oil Company

Address and Telephone No.
 P.O. Box 3256, Carlsbad, NM 88220 (505) 885-4596

Location of Well (Footage, Sec., T., R., M., or Survey Description)
 660' FNL and 990' FWL (NW NW) Unit D
 Sec. 34, T19S-R34E

CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input checked="" type="checkbox"/> Conversion to Injection
	<input checked="" type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

July 24, 1995: Mallon Oil Company cement squeezed Grayburg (5094'-5102', 5132'-5138') with 157 sacks class C cement at 2000 psi, and Seven Rivers perforations (3956'-3962'). Cement squeeze with 100 sacks class C cement at 2000 psi. Drill out CIBP at 5950'.

Perforated San Andres 6180'-6186' 4 JSPF, 6218'-6260' 4 JSPF, 3000 gallons 15% HCL acid stimulation, 7 bpm, 3500 psi. Frac with 24,000 pounds 20/40 Ottawa sand at 11 bpm, 3800 psi. Run in hole with PVC lined 2-7/8" N80 tubing and neutral packer, set packer at 5882', 30 minute integrity test casing 300 psi. Convert well to salt water disposal well. NMOCD was notified 24 hours before integrity test was performed, no representative was present.

The San Andres formation salt water disposal has been approved by state commission order number SWD598.

I hereby certify that the foregoing is true and correct

Signed [Signature]

Title Production Superintendent

Date 8/25/95

(This space for Federal or State office use)

Approved by _____
 Conditions of approval, if any:

Title _____

ACCEPTED FOR RECORD

[Signature]

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

CARLSBAD, NEW MEXICO

