

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY RESLER AND SHELTON 302 Carper Bldg., Artesia, N.M.
(Address)

LEASE May A WELL NO. 2 UNIT G S 21 T 238 R 37E

DATE WORK PERFORMED October 12, 1958 POOL Langido Matrix

This is a Report of: (Check appropriate block)

Results of Test of Casing Shut-off

Beginning Drilling Operations Remedial Work

Plugging Other Completion

Detailed account of work done, nature and quantity of materials used and results obtained.

Perforated 3467-75 and from 3479-83 and fractured w/ 10,000 lbs sd. in 7,000 gallons water. Set packer @ 3460'. Perforated 3432-38 and from 3444-56'. Fractured w/ 20,000 lbs sd. in 12,000 gallons water. Removed packer and run tubing to 3420'. Put on production.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____		

(Company)

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name [Signature]
Title _____
Date _____

Name [Signature]
Position Partner
Company RESLER AND SHELTON