

APPROVED

Form 9-381a  
(Feb. 1961)

JUL 29 1960

Budget Bureau No. 42-R368.4  
Approval expires 12-31-60.

		1

SW  
E. W. ST  
DISTRICT

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office

Lease No. LC 068847

Unit RECEIVED

JUL 18 1960

U. S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Imp. dated 7-18-60  
O.K. for abandonment. J.L.G.

July 14, 1960

Federal-Marshall  
Well No. 1 is located 660 ft. from  N line and 660 ft. from  E line of sec. 21

NE/4 NE/4 Unit A Sec. 21 25-S 33-S NMPM  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Wildcat Lea New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3378 ft. NOTED

DETAILS OF WORK JUL 18 1960

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work) GORDON

June 20, 1960 T.D. - 5087'. Ran 30 sack cement plug from 5087' to 4955', 40 sack cement plug from 1900' to 1723', 20 sack cement plug from 310' to 222' and a 15' cement plug in top of surface casing. Remainder of hole was filled with low water loss mud. U. S. G. S. marker placed in top of surface casing and location restored to original level.


The 8-5/8" OD casing set at 275.50' and cemented with 125 sacks cement was left in the hole.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company George L. Buckles Company

Address P. O. Box 56

Monahans, Texas

By  (Robert M. Orr)

Title Chief Engineer