

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS
(Submit to appropriate District Office as per Commission Rule 1106)

Company Dalport Oil Corporation 930 Fidelity Union Life Bldg., Dallas, Texas
(Address)

Lease E. C. Winters "B" Well No. 4 Unit K S 7 T 25-S R 37-E

Date work performed 6-19-55 POOL Cooper - Jal

This is a Report of (Check appropriate block) ☐ Result of Test of Casing Shut-off

☐ Beginning Drilling Operations

☐ Remedial Work

☐ Plugging

☒ Other Fracture

Detailed account of work done, nature and quantity of materials used and results obtained.

Fractured with 10,000 gals control-frac and 15,000#s Sand from 3268 to 3358.

Production increased to 4 B.O.P.H.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl. Date _____

Tbng. Dia. _____ Tbng. Depth _____ Oil String Dia _____ Oil String Depth _____

Perf. Interval (s) _____

Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER

BEFORE

AFTER

Date of Test

Oil Production, bbls. per day

Gas Production, Mcf per day

Water Production, bbls. per day

Gas-Oil Ratio, cu. ft. per bbl.

Gas Well Potential, Mcf per day

Witnessed by _____

(Company)

Oil Conservation Commission

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name _____

Name W. F. T. Smith

Title _____

Position Vice-President

Date _____

Company Dalport Oil Corporation