

Form 9-331
Dec. 1973

Form Approved.
Budget Bureau No. 42-R1424

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well gas well other

2. NAME OF OPERATOR
Amoco Production Company

3. ADDRESS OF OPERATOR
P. O. Box 68, Hobbs, NM 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1840' FSL & 660' FEL, SEC. 15
AT TOP PROD. INTERVAL: (Unit I, NE/4 SE/4)
AT TOTAL DEPTH:

5. LEASE
NM-0321613

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME
South Mattix Unit Fed.

8. FARM OR LEASE NAME
South Mattix Unit Fed.

9. WELL NO.
37

10. FIELD OR WILDCAT NAME
Und.

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
15-24-37

12. COUNTY OR PARISH
Lea

13. STATE
NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3230.9 GR

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF	<input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	<input type="checkbox"/>
(other)	<input type="checkbox"/>	<input type="checkbox"/>

RECEIVED
SEP 4 1979

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Move in Service unit 7-20-79. Ran Correlation Log. Perforated 6091'-6098', 6131'-6140', 6230'-6235', 6253'-6257', 6271'-6278', 6292'-6297', with 2 JSPF. Packer set at 5809'. Tailpipe set at 6032'. Acidize with 4000 gal. 15% NE acid. Currently pump testing.

Subsurface Safety Valve: Manu. and Type _____

18. I hereby certify that the foregoing is true and correct

SIGNED Kay Cox TITLE Admin. Supervisor DATE 8-31-79

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD
SEP 4 1979
U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

0+4-USGS, H 1-Hou 1-Susp 1-BD 1-ARCO 1-Chevron 1-Tenneco 1-Conoco

FBI
LABORATORY

RECEIVED
SEP 11 1964
O.C.D. HOBBS, OFFICE