Case No
6216

Large Exhibits


R 23 E
T 20 S
T 20½ S
T 21 S
R 22 E
R 23 E
LEGEND
Location
Plugged and Abandoned Well
Wolfcamp Gas Well
Strawn Gas Well
Atoka Gas Well
Morrow Gas Well
Well Drilled to Morrow or Deeper
Wt. Gas Well
100' Structure Contours on Lower Cowden Marker
50' Isopach Contours of Justis to Upper Blinebry
Fault
Scale
YATES PETROLEUM CORP.
STINKING DRAW UNIT
EDDY COUNTY, NEW MEXICO
EXHIBIT No. 2



STRATIGRAPHIC CROSS SECTION AA'

EXHIBIT No. 3

BEFORE EXAMINER STOGNER
OIL CONSERVATION DIVISION
APPLICANT EXHIBIT NO. 3
CASE NO. 6216

U.S.G.S. PHOTOGRAPHICS



STRATIGRAPHIC CROSS SECTION AA'

EXHIBIT No. 3

BEFORE THE
Applicant
6216
6363