

JAVELINA UNIT P405 (405H, 406H, 407H, 408H) Facility ID [fVV2210349229 (Daily drilling inspection log)								
INSPECTION DATE	Liner integrity	Freeboard Height - Maintain at least 2ft	Fluid levels	Debris	Migratory birds / wildlife	Releases	Is fence maintained	NOTES
1/20/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
1/21/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
1/22/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
1/23/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
1/24/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
1/25/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
1/26/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
1/27/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
1/28/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
1/29/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
1/30/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
1/31/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/1/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/2/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/3/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/4/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/5/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/6/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/7/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/8/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/9/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/10/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/11/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/12/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/13/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/14/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/15/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/16/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/17/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/18/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/19/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/20/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/21/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/22/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/23/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/24/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/25/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/26/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/27/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/28/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
2/29/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
3/1/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
3/2/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
3/3/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
3/4/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
3/5/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
3/6/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
3/7/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
3/8/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
3/9/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
3/10/2024	Good	>3 ft	OK	No	No	None	Yes	No issues
3/11/2024	Good	>3 ft	OK	No	No	None	Yes	No issues

Released to Imaging: 5/23/2024 9:04:31 AM

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 346547

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 346547
	Action Type: [C-144] Temporary Pit Plan (C-144T)

CONDITIONS

Created By	Condition	Condition Date
joseph.kennedy	None	5/23/2024