

Javelina Unit 433 (433H, 434H, 435H) Facility ID fVV2214553037 (Daily drilling inspection log)								
INSPECTION DATE	Liner integrity	Freeboard Height - Maintain at least 2ft	Fluid levels	Debris	Migratory birds / wildlife	Releases	Is fence maintained	NOTES
3/16/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
3/17/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
3/18/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
3/19/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
3/20/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
3/21/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
3/22/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
3/23/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
3/24/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
3/25/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
3/26/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
3/27/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
3/28/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
3/29/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
3/30/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
3/31/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
4/1/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
4/2/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
4/3/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
4/4/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
4/5/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
4/6/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
4/7/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
4/8/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
4/9/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
4/10/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
4/11/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
4/12/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
4/13/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
4/14/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
4/15/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
4/16/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
4/17/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
4/18/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
4/19/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
4/20/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
4/21/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
4/22/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
4/23/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
4/24/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
4/25/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
4/26/2024	Yes	Yes	Yes	No	No	No	Yes	No issues
4/27/2024	Yes	Yes	Yes	No	No	No	Yes	No issues

Javelina Unit 433 (433H, 434H, 435H) Facility ID fVV2214553037 (Weekly Inspection log)								
INSPECTION DATE	Liner integrity	Freeboard Height - Maintain at least 2ft	Fluid levels	Debris	Migratory birds / wildlife	Releases	fence maintained	NOTES
4/3/2024	good	yes	<1"	no	no	no	yes	rain water, overlap inspection with drilling
4/10/2024	good	yes	<1"	no	no	no	yes	rain water, overlap inspection with drilling
4/17/2024	good	yes	<1"	no	no	no	yes	rain water, overlap inspection with drilling
4/24/2024	good	yes	<1"	no	no	no	yes	rain water, overlap inspection with drilling
4/29/2024	good	yes	<1"	no	no	no	yes	rain water, overlap inspection with drilling
5/1/2024	good	yes	<1"	no	no	no	yes	RP dewatered on 5/5/2024
5/8/2024	good	yes	<1"	no	no	no	yes	rain water, no issues
5/15/2024	good	yes	<1"	no	no	no	yes	rain water, no issues
5/22/2024	good	yes	<1"	no	no	no	yes	rain water, no issues
5/29/2024	good	yes	<1"	no	no	no	yes	rain water, no issues
6/5/2024	good	yes	<1"	no	no	no	yes	no issues to report
6/12/2024	good	yes	<1"	no	no	no	yes	no issues to report
6/21/2024	good	yes	<1"	no	no	no	yes	no issues to report
6/28/2024	good	yes	<1"	no	no	no	yes	no issues to report

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

COMMENTS

Action 360369

COMMENTS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 360369
	Action Type: [C-144] Temporary Pit Plan (C-144T)

COMMENTS

Created By	Comment	Comment Date
joseph.kennedy	Inspection Report Approved	7/2/2024

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 360369

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 360369
	Action Type: [C-144] Temporary Pit Plan (C-144T)

CONDITIONS

Created By	Condition	Condition Date
joseph.kennedy	None	7/2/2024