

Javelina Unit P429 (429H, 430H, 431H, 432H) Facility ID fVV2214455406 (Weekly Inspection log)								
INSPECTION DATE	Liner integrity	Freeboard Height - Maintain at least 2ft	Fluid levels	Debris	Migratory birds / wildlife	Releases	Is fence maintained	NOTES
5/1/2024	good	yes	<1'	no	no	no	yes	no issues to report
5/8/2024	good	yes	<1'	no	no	no	yes	no issues to report
5/15/2024	good	yes	<1'	no	no	no	yes	no issues to report
5/22/2024	good	yes	<1'	no	no	no	yes	no issues to report
5/29/2024	good	yes	<1'	no	no	no	yes	no issues to report
6/5/2024	good	yes	<1'	no	no	no	yes	no issues to report
6/12/2024	good	yes	<1'	no	no	no	yes	no issues to report
6/19/2024	good	yes	<1'	no	no	no	yes	no issues to report
6/26/2024	good	yes	<1'	no	no	no	yes	no issues to report
7/3/2024	good	yes	<1'	no	no	no	yes	no issues to report
7/10/2024	good	yes	<1'	no	no	no	yes	no issues to report
7/17/2024	good	yes	<1'	no	no	no	yes	no issues to report
7/24/2024	good	yes	<1'	no	no	no	yes	no issues to report
7/31/2024	good	yes	<1'	no	no	no	yes	no issues to report

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 383287

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 383287
	Action Type: [C-144] Temporary Pit Plan (C-144T)

CONDITIONS

Created By	Condition	Condition Date
joseph.kennedy	None	9/23/2024