

JAVELINA UNIT Pad 610 (507H, 508H, 610H, 611H, 612H) Facility ID - fJMB2221536628(Weekly inspection log)								
INSPECTION DATE	Liner integrity	Freeboard Height - Maintain at least 2ft	Fluid levels	Debris	Migratory birds / wildlife	Releases	Is fence maintained	NOTES
9/11/2024	GOOD	YES	<1"	x	NO	NO	YES	no issues to report
9/18/2024	GOOD	Yes	<1"	X	NO	NO	Yes	no issues to report
9/25/2024	GOOD	N/A - Mixing for Closure	N/A - Mixing for	X	NO	NO	Yes	no issues to report
10/2/2024	GOOD	N/A - Mixing for Closure	N/A - Mixing for	X	NO	NO	No - removed for closure	no issues to report
10/9/2024	GOOD	N/A - Mixing for Closure	N/A - Mixing for	X	NO	NO	No - removed for closure	no issues to report
10/16/2024	GOOD	N/A - Mixing for Closure	N/A - Mixing for	X	NO	NO	No - removed for closure	no issues to report
10/23/2024	GOOD	N/A - Mixing for Closure	N/A - Mixing for	X	NO	NO	No - removed for closure	no issues to report
10/30/2024	GOOD	N/A - Mixing for Closure	N/A - Mixing for	X	NO	NO	No - removed for closure	Pit closed

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 411232

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 411232
	Action Type: [C-144] Temporary Pit Plan (C-144T)

CONDITIONS

Created By	Condition	Condition Date
joseph.kennedy	Submit closure report for this pit	12/23/2024