

**Javelina Unit (Pad 433) (433H,
434H, 435H)
[fVV2214553037]**

**Weekly Inspection Report
Q3 2024**

[4323] CHEVRON USA INC

January 02, 2025

Javelina Unit 433 (433H, 434H, 435H) Facility ID fVV2214553037(Weekly Inspection log)								
INSPECTION DATE	Liner integrity	Freeboard Height - Maintain at least 2ft	Fluid levels	Debris	Migratory birds / wildlife	Releases	Is fence maintained	NOTES
7/3/2024	yes	yes	<1"	no	no	no	yes	no issures to report
7/10/2024	yes	yes	<1"	no	no	no	yes	no issures to report
7/17/2024	yes	yes	<1"	no	no	no	yes	no issures to report
7/24/2024	yes	yes	<1"	no	no	no	yes	no issures to report
7/31/2024	yes	yes	<1"	no	no	no	yes	no issures to report
8/7/2024	yes	yes	<1"	no	no	no	yes	no issures to report
8/14/2024	yes	yes	<1"	no	no	no	yes	no issures to report
8/21/2024	yes	yes	<1"	no	no	no	yes	no issures to report
8/28/2024	yes	yes	<1"	no	no	no	yes	no issures to report
9/4/2024	yes	yes	<1"	no	no	no	yes	no issures to report
9/11/2024	yes	yes	<1"	no	no	no	yes	no issures to report
9/18/2024	yes	yes	<1"	no	no	no	yes	no issures to report
9/25/2024	yes	yes	<1"	no	no	no	yes	no issures to report

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 416013

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 416013
	Action Type: [C-144] Temporary Pit Plan (C-144T)

CONDITIONS

Created By	Condition	Condition Date
jeffrey.harrison	None	1/2/2025