



March 19, 2025

New Mexico Oil Conservation Division

New Mexico Energy, Minerals, and Natural Resources Department
1220 South St. Francis Drive
Santa Fe, New Mexico 87505

Re: Closure Report

Former Bisti Landfarm
San Juan County, New Mexico
Western Refining Southwest LLC
NMOCD Permit Number: NM2-0010

To Whom it May Concern:

On behalf of Western Refining Southwest LLC (Western), Ensolum, LLC (Ensolum) is submitting this *Closure Report* to the New Mexico Oil Conservation Division (NMOCD) for the former Bisti Landfarm (Site), NMOCD Permit Number NM2-0010 (Figure 1). Closure activities at the Site were performed in accordance with the *Closure and Post-Closure Plan* (the "CPC Plan") prepared by Ensolum and dated February 17, 2023. Based on the treatment zone closure sampling performed in 2024 summarized in the *Notification of Cessation of Operations and Proposed Schedule* document dated September 9, 2024, Western ceased disking operations at the Landfarm and began closure activities. As required, Western retained Adamah to perform closure activities (performed in November and December of 2024) and included the removal of berms, fences, roads, and equipment from the Site. No buildings or other infrastructure were present at the Site. Additionally, reseeded was performed in December 2024 once closure activities were completed. As noted in the "Landfarm Closure Inspection List" attached as Appendix A, no soil staining was observed during the inspection, therefore sample collection was not necessary. Photographs taken during the closure inspection are included in Appendix B. Ensolum plans to conduct a Site visit in the spring of 2025 to assess revegetation and the need for additional seeding/mulching.

If you should have any questions or comments regarding this document, please contact the undersigned.

Sincerely,

Ensolum, LLC

Stuart Hyde
Senior Managing Geologist
(970) 903-1607
shyde@ensolum.com

Attachments:

Landfarm Closure Inspection List
Project Photographs

Ensolum, LLC | Environmental, Engineering & Hydrogeologic Consultants

848 East 2nd Ave | Durango, CO 81301 | ensolum.com


LANDFARM NAME	Bisti - NM 2-2010
DATE	1/6/2025

Landfarm Closure Inspection Checklist			
ITEM / AREA	Yes, No, NA	Cell Number	COMMENTS / ACTION TAKEN
Berms Removed?	Yes	Cell 1, Grade, API	Berms graded
Buildings, Fences, Roads, and Equipment Removed?	Yes	"	All fencing removed, roads graded
Residual Contamination/Staining Removed and Sampled?	No	"	No staining observed, no samples collected
Sampling Reports Submitted to NMOCD?	No	"	N/A

NA – Not Applicable

Comment section should be used to provide details of unsatisfactory findings.

Additional Inspection Remarks:

Inspector Signature: Eric CarrollName (Print): Eric CarrollManager Signature: Name (Print): Stuart Hyde

PROJECT PHOTOGRAPHS
Bisti Landfarm – Closure Inspection
San Juan County, New Mexico
Marathon Petroleum Company

Photograph 1

West Line Treatment Cell. Looking North

**Photograph 2**

East Line Treatment Cell. Looking West.



PROJECT PHOTOGRAPHS
Bisti Landfarm – Closure Inspection
San Juan County, New Mexico
Marathon Petroleum Company

Photograph 3

Pettigrew Treatment Cell. Looking Southwest to API Cell.

**Photograph 4**

Bisti Treatment Cell. Looking East.



PROJECT PHOTOGRAPHS
Bisti Landfarm – Closure Inspection
San Juan County, New Mexico
Marathon Petroleum Company

Photograph 5



Cell 1. Looking South.

**Photograph 6**

Entrance road. Looking Southwest.



PROJECT PHOTOGRAPHS
Bisti Landfarm – Closure Inspection
San Juan County, New Mexico
Marathon Petroleum Company

<p>Photograph 7</p> <p>Cell 1. Looking North to API Cell.</p>	 <p>Free version of GPS Camera 55</p> <p>06-Jan-25 12:24 Ad-hoc Tohatchi NM, 87325, United States © 06-Jan-25 12:24:12</p>
<p>Photograph 7</p> <p>Vegetation growing in Cell 1.</p>	 <p>Free version of GPS Camera 55</p> <p>06-Jan-25 12:29 Ad-hoc Tohatchi NM, 87325, United States © 06-Jan-25 12:23:39</p>

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 443907

CONDITIONS

Operator: Western Refining Southwest LLC 539 South Main Street Findlay, OH 45840	OGRID: 267595
	Action Number: 443907
	Action Type: [C-137] Non-Fee SWMF Submittal (SWMF NON-FEE SUBMITTAL)

CONDITIONS

Created By	Condition	Condition Date
lbarr	None	4/7/2025