

Javelina Unit P429 (429H, 430H, 431H, 432H) Facility ID fVV2214455406 (Weekly Inspection log)								
INSPECTION DATE	Liner integrity	Freeboard Height - Maintain at least 2ft	Fluid levels	Debris	Migratory birds / wildlife	Releases	Is fence maintained	NOTES
2/5/2025	good	yes	<1"	no	no	no	yes	no issure to report
2/12/2025	good	yes	<1"	no	no	no	yes	no issure to report
2/19/2025	good	yes	<1"	no	no	no	yes	no issure to report
2/26/2025	good	yes	<1"	no	no	no	yes	no issure to report
3/5/2025	good	yes	<1"	no	no	no	yes	no issure to report
3/12/2025	good	yes	<1"	no	no	no	yes	no issure to report
3/19/2025	good	yes	<1"	no	no	no	yes	no issure to report
3/26/2025	good	yes	<1"	no	no	no	yes	no issure to report
4/2/2025	good	yes	<1"	no	no	no	yes	no issure to report
4/9/2025	good	yes	<1"	no	no	no	yes	no issure to report
4/23/2025	good	yes	<1"	no	no	no	yes	no issure to report
4/30/2025	good	yes	<1"	no	no	no	yes	no issure to report

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 458942

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 458942
	Action Type: [C-144] Temporary Pit Plan (C-144T)

CONDITIONS

Created By	Condition	Condition Date
joel.stone	None	5/9/2025