

Moore LS #6B Small Landfarm

Hilcorp Energy Company

Letter of Commitment to Re-vegetate Small Landfarm as part of Closure

November 7, 2025



November 7, 2025

New Mexico Oil Conservation Division

1220 South St. Francis Drive
Santa Fe, New Mexico 87505

Re: Final Closure Report – Response to NMOCD

Moore LS #6B Small Landfarm
San Juan County, New Mexico
Hilcorp Energy Company

Mr. Kennedy:

In response to your letter dated November 4, 2025, Hilcorp Energy Company (Hilcorp) plans to re-vegetate the former small landfarm located at the Moore LS #6B well site located in Unit O, Section 25, Township 32 North, Range 12 West, San Juan County, New Mexico. Re-vegetation will be performed in accordance with the applicable section of Title 19, Chapter 15, Part 36 of the New Mexico Administrative Code (NMAC). The attached spreadsheet includes the information you have requested regarding landfarm operations required by 19.15.36.16.D NMAC. Additionally, all remediated soils from the small landfarm have been returned to the original site as backfill for the remedial excavation, also located on the Moore LS #6B well pad.

Seeding for re-vegetation of the former landfarm area will begin in the fall of 2025. In accordance with 19.15.36.18 NMAC, re-vegetation will be considered complete when vegetative cover is equal to “seventy percent of the native perennial vegetative cover (un-impacted by overgrazing, fire or other intrusion damaging to native vegetation) or scientifically documented ecological description consisting of at least three native plant species, including at least one grass, but not including noxious weeds” and coverage is maintained through two successive growing seasons. Once complete, Hilcorp will document activities at the Site and provide a closure request for the small landfarm to the New Mexico Oil Conservation Division.

Sincerely,

Ensolum, LLC

Stuart Hyde
Senior Managing Geologist
(970) 903-1607
shyde@ensolum.com

cc: Mitch Killough, Hilcorp Energy Company

Attachments:

Moore LS 6B Small Landfarm Soil Volume Tracking Form

Ensolum, LLC | Environmental, Engineering & Hydrogeologic Consultants
848 East 2nd Ave | Durango, CO 81301 | ensolum.com



Moore LS 6B Small Landfarm Soil Volume Tracking Form							
DATE	GENERATOR	HAULING COMPANY	ORIGIN	TOTAL VOLUME ACCEPTED	PASS PAINT FILTER TEST?	DISKED?	INITIALS
Waste Acceptance Instructions: Pass Paint Filter Test; Disk Within 72 Hours of Arrival; Maximum of 8-Inch Lifts; Maximum 1,000 cubic yards per 1 acre							
5/5/2025	Hilcorp	Ace Services	Moore LS #6B Excavation	320	Yes	No	CP
5/13/2025	Hilcorp	Ace Services	Moore LS #6B Excavation	200	Yes	No	CP
5/16/2025	Hilcorp	Ace Services	N/A	N/A	N/A	Yes	CP
5/27/2025	Hilcorp	Ace Services	Moore LS #6B Excavation	230	Yes	No	CP
5/28/2025	Hilcorp	Ace Services	Moore LS #6B Excavation	50	Yes	No	CP
5/30/2025	Hilcorp	Ace Services	N/A	N/A	N/A	Yes	CP
6/11/2025	Hilcorp	Ace Services	Moore LS #6B Excavation	50	Yes	No	CP
6/13/2025	Hilcorp	Ace Services	N/A	N/A	N/A	Yes	CP
6/27/2025	Hilcorp	Ace Services	N/A	N/A	N/A	Yes	CP
7/11/2025	Hilcorp	Ace Services	N/A	N/A	N/A	Yes	CP
7/25/2025	Hilcorp	Ace Services	N/A	N/A	N/A	Yes	CP

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 525798

CONDITIONS

Operator: HILCORP ENERGY COMPANY 1111 Travis Street Houston, TX 77002	OGRID: 372171
	Action Number: 525798
	Action Type: [C-137] Small Landfarm (C-137EZA)

CONDITIONS

Created By	Condition	Condition Date
joseph.kennedy	Record Retention	11/13/2025