

January 5, 2026

Electronic Delivery

Mr. Joseph Kennedy
New Mexico Oil Conservation Division
Environmental Bureau
1220 South St Francis Dr.
Santa Fe, New Mexico 87505

**RE : Lea Land LLC, Surface Waste Management Facility
OCD Permit No. NM1-35
Transmittal of January 2026 Facility Inspection Report
and January 2026 Vadose Zone Monitoring Report**

Dear Mr. Kennedy:

Transmitted herein are copies of the Vadose Zone monitoring report and Facility Inspection Report for monitoring and inspection events conducted at the Lea Land LLC Surface Waste Management Facility in Lea County, New Mexico on December 31, 2025.

No free liquid, methane, hydrogen sulfide, or carbon monoxide were detected in any of the monitoring wells during the vadose zone monitoring event. No issues were identified relative to inspection parameters for the landfill, leachate and stormwater controls at the surface waste management facility.

Thanks very much for your effort to review this document. Please contact me with your questions and comments.

Sincerely,

A handwritten signature in blue ink that reads 'Clay Kilmer'.

Clay Kilmer
Sr. Hydrogeologist

Attachment: Lea Land LLC December 31, 2025, Facility Inspection Report
Lea Land LLC December 31, 2025, Vadose Zone Monitoring Report

cc: Stephanie Grantham, President, Lea Land, LLC.
Joe Ontiveros, Site Manager, Lea Land LLC
I Keith Gordon, P.E., IKG, LLC

Clay Kilmer LLC
3312 June Street, Northeast
Albuquerque, NM 87111
(505) 235-4482
claykilmer@gmail.com

Vadose Zone Well Monitoring Log

Lea Land LLC
Surface Waste Management Facility
Lea County, New Mexico

Date: 12-31-25


Monitored by: G. ANTIVEROS

Weather Information

Date and Amount of Last Precipitation: 12/22 snow 1/2 inches

Current Temp: 10.01 SNOW 6 inc
58° 25°

Current Wind Speed: mph

Current Wind Direction:  E

Current Barometric Pressure: 29.86 in. Hg


Barometric Pressure Trend:

Gas Detection Equipment

Monitoring Equipment Used

Date and Time Last Calibrated:

Gas Alert Max
ed: 12-31-25




Vadose Zone Well Vapor Data

Vadose Zone Well Fluid Measurements

Lea Land LLC
Surface Waste Management Facility
OCD Permit No. NM1-35

Inspection Form

Date: 12-31-25
 Others: _____

Print Name: Genovino Contreras
 Signature: 

Inspection will be in accordance with NMOCD operational conditions.

Item	Satisfactory	Action Required
Entrance Sign	✓	
Berms and outside pond levees	✓	
Tank Labels	✓	
Sumps	✓	
Pond levels three-foot free board	✓	
Free oil on Pits-Ponds	N/A	
Pit and Pond condition	N/A	
Pit and Pond marker numbers	N/A	
Treatment Plant inspection	N/A	
Solid waste disposal area inspection	✓	
Blowing trash	✓	
Fences and Gates	✓	
Leak detection sumps - Landfill - Liquid present?		(Monthly analysis required if yes)
Leak detection sumps - Evaporation Ponds - Liquid present?	N/A	(Monthly analysis required if yes)
Leak detection sumps - Jet Out Pit - Liquid present?	N/A	(Monthly analysis required if yes)
Leak detection sumps - Stab. & Solid. - Liquid present?	N/A	(Monthly analysis required if yes)
Landfill Leachate Sump	✓	
Vadose Zone Monitoring	✓	
Pond Sludge Depth	✓	
*Comments & Repairs:	_____	

H₂S

READINGS ARE TO BE TAKEN 4 FT DOWNDOWN FROM EVAPORATION PONDS

Evaporation Pond (readings in ppm):
 POND

1	
2	
3	
4	
5	
6	
7	N/A
8	
9	
10	
11	
12	

*In the event that a reading of 10 ppm is registered at the Facility, IMPLEMENT THE CONTINGENCY PLAN!
 Personnel will evacuate the area and operator will monitor H₂S levels downwind of the Pond.

If H₂S levels reach 20 ppm, the Facility will be closed and notification will be given to the following:

Lea Land Office	575-887-4048	NMOCD Hobbs	575-393-6161
New Mexico State Police	575-392-5580	NMOCD Santa Fe	505-476-3440
Eddy County Sheriff	575-887-1888		
Lea County Sheriff	575-397-3611		

Receipt & Approval

Name: _____

Date: _____

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 540029

CONDITIONS

Operator: LEA LAND, LLC 1300 W Main St Oklahoma City, OK 73106	OGRID: 195376
	Action Number: 540029
	Action Type: [C-137] Non-Fee SWMF Submittal (SWMF NON-FEE SUBMITTAL)

CONDITIONS

Created By	Condition	Condition Date
joseph.kennedy	None	1/6/2026