

[illegible]

Cotton Draw Cobra 4 33 FED COM and 4 33 FED (Pad 601) (503H, 610H, 611H, 612H, 501H, 601H, 602H, 603H) [fJWH2500235244](Daily drilling inspection log)								
INSPECTION DATE	Liner integrity	Freeboard Height - Maintain at least 2ft	Fluid levels	Debris	Migratory birds / wildlife	Releases	Is fence maintained	NOTES
10/1/2025	Ok	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
10/2/2025	Ok	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
10/3/2025	Ok	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
10/4/2025	Ok	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
10/5/2025	Ok	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
10/6/2025	Ok	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
10/7/2025	Ok	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
10/8/2025	Ok	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
10/9/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
10/10/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
10/11/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
10/12/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
10/13/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
10/14/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
10/15/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
10/16/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
10/17/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
10/18/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
10/19/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
10/20/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
10/21/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
10/22/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
10/23/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
10/24/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
10/25/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
10/26/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
10/27/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
10/28/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
10/29/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
10/30/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
10/31/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
11/1/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
11/2/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
11/3/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
11/4/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
11/5/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
11/6/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
11/7/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
11/8/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
11/9/2025	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 541639

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 541639
	Action Type: [C-144] Temporary Pit Plan (C-144T)

CONDITIONS

Created By	Condition	Condition Date
joel.stone	None	1/9/2026