

State of New Mexico
 Energy Minerals and Natural Resources
 Department Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505
<https://www.emnrd.nm.gov/ocd/ocd-e-permitting/>

Recycling Facility and/or Recycling Containment

Type of Facility: Recycling Facility Recycling Containment*
Type of action: Permit Registration
 Modification Extension (01/02/2026-01/02/2027)
 Closure Other (explain) _____

*** At the time C-147 is submitted to the division for a Recycling Containment, a copy shall be provided to the surface owner.**

Be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.

1.

Operator: EOG Resources Inc. (For multiple operators attach page with information) OGRID #: 7377
 Address: 5509 Champions Dr. Midland, Texas 79706

Facility or well name (include API# if associated with a well): Galaxy Reuse Water Recycling Facility and Containment Pit

OCD Permit Number: 1RF-25-0 (For new facilities the permit number will be assigned by the district office)

U/L or Qtr/Qtr NE/NW Section 16 Township 24S Range 33E County: Lea

Surface Owner: Federal State Private Tribal Trust or Indian Allotment

2.

Recycling Facility:

Location of recycling facility (if applicable): Latitude 32.2214792 Longitude -103.5825816 NAD83

Proposed Use: Drilling* Completion* Production* Plugging *

**The re-use of produced water may NOT be used until fresh water zones are cased and cemented*

Other, requires permit for other uses. Describe use, process, testing, volume of produced water and ensure there will be no adverse impact on groundwater or surface water.

Fluid Storage

Above ground tanks Recycling containment Activity permitted under 19.15.17 NMAC explain type _____
 Activity permitted under 19.15.36 NMAC explain type: _____ Other explain _____
 For multiple or additional recycling containments, attach design and location information of each containment

Closure Report (required within 60 days of closure completion): Recycling Facility Closure Completion Date: _____

3.

Recycling Containment:

Annual Extension after initial 5 years (attach summary of monthly leak detection inspections for previous year) 01/02/2026-01/02/2027

Center of Recycling Containment (if applicable): Latitude 32.2214836 Longitude -103.5808435 NAD83

For multiple or additional recycling containments, attach design and location information of each containment

Lined Liner type: Thickness 60 mil LLDPE HDPE PVC Other _____

String-Reinforced

Liner Seams: Welded Factory Other _____ Volume: 1MM bbl Dimensions: L 600 x W 600 x D 16 (inside)

Recycling Containment Closure Completion Date: _____

4.

Bonding:

Covered under bonding pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC (These containments are limited to only the wells owned or operated by the owners of the containment.)

Bonding in accordance with 19.15.34.15(A)(1). Amount of bond \$_____ (work on these facilities cannot commence until bonding amounts are approved)

Attach closure cost estimate and documentation on how the closure cost was calculated.

5.

Fencing:

Four foot height, four strands of barbed wire evenly spaced between one and four feet

Alternate. Please specify. Please see the attached variance request detail on original approved permit dated 01/18/2018

6.

Signs:

12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers

Signed in compliance with 19.15.16.8 NMAC

7.

Variances:

Justifications and/or demonstrations that the proposed variance will afford reasonable protection against contamination of fresh water, human health, and the environment.

Check the below box only if a variance is requested:

Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. If a Variance is requested, include the variance information on a separate page and attach it to the C-147 as part of the application.

If a Variance is requested, it must be approved prior to implementation.

8.

Siting Criteria for Recycling Containment

Instructions: The applicant must provide attachments that demonstrate compliance for each siting criteria below as part of the application. Potential examples of the siting attachment source material are provided below under each criteria.

General siting**Ground water is less than 50 feet below the bottom of the Recycling Containment.**

NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells

Yes No
 NA

Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended.

- Written confirmation or verification from the municipality; written approval obtained from the municipality

Yes No
 NA

Within the area overlying a subsurface mine.

- Written confirmation or verification or map from the NM EMNRD-Mining and Minerals Division

Yes No

Within an unstable area.

- Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; topographic map

Yes No

Within a 100-year floodplain. FEMA map

Yes No

Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).

- Topographic map; visual inspection (certification) of the proposed site

Yes No

Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.

- Visual inspection (certification) of the proposed site; aerial photo; satellite image

Yes No

Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application.

- NM Office of the State Engineer - iWATERS database search; visual inspection (certification) of the proposed site

Yes No

Within 500 feet of a wetland.

- US Fish and Wildlife Wetland Identification map; topographic map; visual inspection (certification) of the proposed site

Yes No

9.

Recycling Facility and/or Containment Checklist:*Instructions: Each of the following items must be attached to the application. Indicate, by a check mark in the box, that the documents are attached.*

- Design Plan - based upon the appropriate requirements.
- Operating and Maintenance Plan - based upon the appropriate requirements.
- Closure Plan - based upon the appropriate requirements.
- Site Specific Groundwater Data -
- Siting Criteria Compliance Demonstrations -
- Certify that notice of the C-147 (only) has been sent to the surface owner(s)

10.

Operator Application Certification:

I hereby certify that the information and attachments submitted with this application are true, accurate and complete to the best of my knowledge and belief.

Name (Print): Morgan Hrcicirk Title: Sr. Regulatory AdministratorSignature: Morgan Hrcicirk Date: 01/07/2026e-mail address: morgan_hrcicirk@eogresources.com Telephone: (832) 627-5450

11.

OCD Representative Signature: Victoria Venegas Approval Date: 01/09/2026Title: Environmental Specialist OCD Permit Number: 1RF-25 OCD Conditions Additional OCD Conditions on Attachment



P.O. Box 2267, Midland, Texas 79702
Phone: (832) 627-5450

January 2, 2026

Ms. Victoria Venegas, Environmental Specialist
EMNRD- Oil Conservation Division
506 W. Texas Artesia, NM 88210

Re: EOG Galaxy Pit 1RF-25-0

Dear Ms. Venegas:

Thank you for allowing EOG to continue to promote water reuse in the State of New Mexico for our operations. EOG plans to continue active completion operations near this pit location well into 2027 and would like to formally request an extension to our currently approved permit.

Sincerely,

Morgan Hrcicirik

Morgan Hrcicirik
Sr. Regulatory Administrator



Forms Report

Forms Summary

Total Forms: 52

Form Date	Status	Form ID	Form Type	Application Name
01/08/2026	Completed	13416554	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416553	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416551	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416550	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416548	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416547	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416544	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416543	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416541	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416540	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416539	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416538	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416537	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416536	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416535	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416533	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416532	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416530	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416527	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416525	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416523	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416522	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416519	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416518	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416514	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416513	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416458	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416455	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416454	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416450	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416449	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416447	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416445	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416443	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416439	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416201	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416199	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13416197	Reuse Pit Inspection - NM	iEnvironmental
01/08/2026	Completed	13281360	Reuse Pit Inspection - NM	iEnvironmental
12/30/2025	Completed	13345925	Reuse Pit Inspection - NM	iEnvironmental
11/24/2025	Completed	12964576	Reuse Pit Inspection - NM	iEnvironmental
11/06/2025	Open	13416558	Reuse Pit Inspection - NM	iEnvironmental
09/01/2025	Completed	12801008	Reuse Pit Inspection - NM	iEnvironmental
07/07/2025	Completed	12747449	Reuse Pit Inspection - NM	iEnvironmental
07/05/2025	Open	13416556	Reuse Pit Inspection - NM	iEnvironmental
06/23/2025	Completed	12729230	Reuse Pit Inspection - NM	iEnvironmental
06/16/2025	Completed	12664163	Reuse Pit Inspection - NM	iEnvironmental
05/26/2025	Completed	12424841	Reuse Pit Inspection - NM	iEnvironmental
03/10/2025	Completed	12360619	Reuse Pit Inspection - NM	iEnvironmental



Form Date	Status	Form ID	Form Type	Application Name
02/17/2025	Completed	12282057	Reuse Pit Inspection - NM	iEnvironmental
01/20/2025	Completed	12211585	Reuse Pit Inspection - NM	iEnvironmental
12/30/2024	Completed	12176667	Reuse Pit Inspection - NM	iEnvironmental



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

13416554

Scheduled

10/30/2025

Completed

01/08/2026

Earliest Compliance

09/07/2025

Latest Compliance

09/13/2025

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Previous Form**

13416551

Comments**Last Modified By**

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

13416553

Scheduled

06/28/2025

Completed

01/08/2026

Earliest Compliance

01/11/2026

Latest Compliance

01/17/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Previous Form**

13416550

Comments**Last Modified By**

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

13416551

Scheduled

10/23/2025

Completed

01/08/2026

Earliest Compliance

01/11/2026

Latest Compliance

01/17/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Previous Form**

13416548

Comments**Last Modified By**

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

13416550

Scheduled

06/21/2025

Completed

01/08/2026

Earliest Compliance

01/11/2026

Latest Compliance

01/17/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Previous Form**

13416541

Comments**Last Modified By**

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID:
671

Schedule Name:
Weekly

Schedule Counter:
1

Schedule Period:
WEEK

Program Type:
Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

13416548

Scheduled

10/16/2025

Completed

01/08/2026

Earliest Compliance

01/11/2026

Latest Compliance

01/17/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Previous Form**

13416544

Comments**Last Modified By**

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

13416547

Scheduled

01/02/2026

Completed

01/08/2026

Earliest Compliance

01/11/2026

Latest Compliance

01/17/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Previous Form**

13416543

Comments**Last Modified By**

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID:
671

Schedule Name:
Weekly

Schedule Counter:
1

Schedule Period:
WEEK

Program Type:
Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
RH GALAXY REUSE PIT			074829000	
Form Description				Form ID
Reuse Pit Inspection - NM			13416544	
Scheduled	Completed	Earliest Compliance	Latest Compliance	
10/09/2025	01/08/2026	01/11/2026	01/17/2026	
Status	Assigned Group	Assigned Member	Previous Form	
Completed	NM - Water Reuse & Pipeline Jesse Terrazas Team		13416540	

Comments

Last Modified By	Created By
Jesse Terrazas	Jesse Terrazas
Last Modified Date	Created Date
01/08/2026	01/08/2026

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
RH GALAXY REUSE PIT			074829000	
Form Description				Form ID
Reuse Pit Inspection - NM			13416543	
Scheduled	Completed	Earliest Compliance	Latest Compliance	
12/26/2025	01/08/2026	01/11/2026	01/17/2026	
Status	Assigned Group	Assigned Member	Previous Form	
Completed	NM - Water Reuse & Pipeline Jesse Terrazas Team		13416539	

Comments

Last Modified By	Created By
Jesse Terrazas	Jesse Terrazas
Last Modified Date	Created Date
01/08/2026	01/08/2026

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

13416541

Scheduled

06/14/2025

Completed

01/08/2026

Earliest Compliance

01/11/2026

Latest Compliance

01/17/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Previous Form**

13416538

Comments**Last Modified By**

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

13416540

Scheduled

10/02/2025

Completed

01/08/2026

Earliest Compliance

01/11/2026

Latest Compliance

01/17/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Previous Form**

13416537

Comments**Last Modified By**

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

13416539

Scheduled

12/19/2025

Completed

01/08/2026

Earliest Compliance

01/11/2026

Latest Compliance

01/17/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Previous Form**

13416536

Comments**Last Modified By**

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

13416538

Scheduled

06/07/2025

Completed

01/08/2026

Earliest Compliance

01/11/2026

Latest Compliance

01/17/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Previous Form**

13416535

Comments**Last Modified By**

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

13416537

Scheduled

09/25/2025

Completed

01/08/2026

Earliest Compliance

01/11/2026

Latest Compliance

01/17/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Previous Form**

13416533

Comments**Last Modified By**

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
RH GALAXY REUSE PIT			074829000	
Form Description				Form ID
Reuse Pit Inspection - NM			13416536	
Scheduled	Completed	Earliest Compliance	Latest Compliance	
12/12/2025	01/08/2026	01/11/2026	01/17/2026	
Status	Assigned Group	Assigned Member	Previous Form	
Completed	NM - Water Reuse & Pipeline Jesse Terrazas Team		13416532	

Comments

Last Modified By	Created By
Jesse Terrazas	Jesse Terrazas
Last Modified Date	Created Date
01/08/2026	01/08/2026

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

13416535

Scheduled

05/31/2025

Completed

01/08/2026

Earliest Compliance

01/11/2026

Latest Compliance

01/17/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Previous Form**

13416525

Comments**Last Modified By**

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

13416533

Scheduled

09/18/2025

Completed

01/08/2026

Earliest Compliance

01/11/2026

Latest Compliance

01/17/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Previous Form**

13416530

Comments**Last Modified By**

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

13416532

Scheduled

12/05/2025

Completed

01/08/2026

Earliest Compliance

01/11/2026

Latest Compliance

01/17/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Previous Form**

13416527

Comments**Last Modified By**

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

13416530

Scheduled

09/11/2025

Completed

01/08/2026

Earliest Compliance

01/11/2026

Latest Compliance

01/17/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Previous Form**

13416523

Comments**Last Modified By**

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID:
671

Schedule Name:
Weekly

Schedule Counter:
1

Schedule Period:
WEEK

Program Type:
Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

13416527

Scheduled

11/28/2025

Completed

01/08/2026

Earliest Compliance

01/11/2026

Latest Compliance

01/17/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Previous Form**

13416522

Comments**Last Modified By**

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

13416525

Scheduled

05/24/2025

Completed

01/08/2026

Earliest Compliance

01/11/2026

Latest Compliance

01/17/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Previous Form**

13416519

Comments**Last Modified By**

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

13416523

Scheduled

09/04/2025

Completed

01/08/2026

Earliest Compliance

01/11/2026

Latest Compliance

01/17/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Previous Form**

13416518

Comments**Last Modified By**

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
RH GALAXY REUSE PIT			074829000	
Form Description				Form ID
Reuse Pit Inspection - NM			13416522	
Scheduled	Completed	Earliest Compliance	Latest Compliance	
1/21/2025	01/08/2026	01/11/2026	01/17/2026	
Status	Assigned Group	Assigned Member	Previous Form	
Completed	NM - Water Reuse & Pipeline Jesse Terrazas Team		13416514	

Comments

Last Modified By	Created By
Jesse Terrazas	Jesse Terrazas
Last Modified Date	Created Date
01/08/2026	01/08/2026

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

13416519

Scheduled

05/17/2025

Completed

01/08/2026

Earliest Compliance

01/11/2026

Latest Compliance

01/17/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Previous Form**

13416458

Comments**Last Modified By**

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

13416518

Scheduled

08/28/2025

Completed

01/08/2026

Earliest Compliance

01/11/2026

Latest Compliance

01/17/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Previous Form**

13416455

Comments**Last Modified By**

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID:
671

Schedule Name:
Weekly

Schedule Counter:
1

Schedule Period:
WEEK

Program Type:
Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
RH GALAXY REUSE PIT			074829000	
Form Description				Form ID
Reuse Pit Inspection - NM			13416514	
Scheduled	Completed	Earliest Compliance	Latest Compliance	
11/14/2025	01/08/2026	01/11/2026	01/17/2026	
Status	Assigned Group	Assigned Member	Previous Form	
Completed	NM - Water Reuse & Pipeline Jesse Terrazas Team		13416454	

Comments

Last Modified By	Created By
Jesse Terrazas	Jesse Terrazas
Last Modified Date	Created Date
01/08/2026	01/08/2026

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

13416513

Scheduled

01/01/2026

Completed

01/08/2026

Earliest Compliance

01/11/2026

Latest Compliance

01/17/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Previous Form**

13416450

Comments**Last Modified By**

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID:
671

Schedule Name:
Weekly

Schedule Counter:
1

Schedule Period:
WEEK

Program Type:
Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
RH GALAXY REUSE PIT			074829000	
Form Description				Form ID
Reuse Pit Inspection - NM			13416458	
Scheduled	Completed	Earliest Compliance	Latest Compliance	
05/10/2025	01/08/2026	01/11/2026	01/17/2026	
Status	Assigned Group	Assigned Member	Previous Form	
Completed	NM - Water Reuse & Pipeline Jesse Terrazas Team		13416449	

Comments

Last Modified By	Created By
Jesse Terrazas	Jesse Terrazas
Last Modified Date	Created Date
01/08/2026	01/08/2026

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

13416455

Scheduled

08/21/2025

Completed

01/08/2026

Earliest Compliance

01/11/2026

Latest Compliance

01/17/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Jesse Terrazas Team

Assigned Member**Previous Form**

13416447

Comments**Last Modified By**

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
RH GALAXY REUSE PIT			074829000	
Form Description				Form ID
Reuse Pit Inspection - NM			13416454	
Scheduled	Completed	Earliest Compliance	Latest Compliance	
11/07/2025	01/08/2026	01/11/2026	01/17/2026	
Status	Assigned Group	Assigned Member	Previous Form	
Completed	NM - Water Reuse & Pipeline Jesse Terrazas Team		13416445	

Comments

Last Modified By	Created By
Jesse Terrazas	Jesse Terrazas
Last Modified Date	Created Date
01/08/2026	01/08/2026

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
RH GALAXY REUSE PIT			074829000	
Form Description				Form ID
Reuse Pit Inspection - NM			13416450	
Scheduled	Completed	Earliest Compliance	Latest Compliance	
12/25/2025	01/08/2026	01/11/2026	01/17/2026	
Status	Assigned Group	Assigned Member	Previous Form	
Completed	NM - Water Reuse & Pipeline James Kelley Team			13416443

Comments

Last Modified By

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

13416449

Scheduled

05/03/2025

Completed

01/08/2026

Earliest Compliance

01/11/2026

Latest Compliance

01/17/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Joe Sanchez Team

Assigned Member**Previous Form**

13416197

Comments**Last Modified By**

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
RH GALAXY REUSE PIT			074829000	
Form Description				Form ID
Reuse Pit Inspection - NM			13416447	
Scheduled	Completed	Earliest Compliance	Latest Compliance	
08/14/2025	01/08/2026	01/11/2026	01/17/2026	
Status	Assigned Group	Assigned Member	Previous Form	
Completed	NM - Water Reuse & Pipeline Team	Cody Williams	13416199	

Comments

Last Modified By	Created By
Jesse Terrazas	Jesse Terrazas
Last Modified Date	Created Date
01/08/2026	01/08/2026

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
RH GALAXY REUSE PIT			074829000	
Form Description				Form ID
Reuse Pit Inspection - NM			13416445	
Scheduled	Completed	Earliest Compliance	Latest Compliance	
10/31/2025	01/08/2026	01/11/2026	01/17/2026	
Status	Assigned Group	Assigned Member	Previous Form	
Completed	NM - Water Reuse & Pipeline James Kelley Team		13416201	

Comments

Last Modified By

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
RH GALAXY REUSE PIT			074829000	
Form Description				Form ID
Reuse Pit Inspection - NM			13416443	
Scheduled	Completed	Earliest Compliance	Latest Compliance	
12/18/2025	01/08/2026	01/11/2026	01/17/2026	
Status	Assigned Group	Assigned Member	Previous Form	
Completed	NM - Water Reuse & Pipeline James Kelley Team			13416439
Comments				
Completed				

Last Modified By

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
RH GALAXY REUSE PIT			074829000	
Form Description				Form ID
Reuse Pit Inspection - NM			13416439	
Scheduled	Completed	Earliest Compliance	Latest Compliance	
12/11/2025	01/08/2026	01/11/2026	01/17/2026	
Status	Assigned Group	Assigned Member	Previous Form	
Completed	NM - Water Reuse & Pipeline James Kelley Team		13281360	

Comments

Last Modified By

Ashley Kungle

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

13416201

Scheduled

10/24/2025

Completed

01/08/2026

Earliest Compliance

01/11/2026

Latest Compliance

01/17/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline James Kelley Team

Assigned Member**Comments****Last Modified By**

Jesse Terrazas

Created By

Ashley Kungle

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
RH GALAXY REUSE PIT			074829000	
Form Description				Form ID
Reuse Pit Inspection - NM			13416199	
Scheduled	Completed	Earliest Compliance	Latest Compliance	
08/07/2025	01/08/2026	01/11/2026	01/17/2026	
Status	Assigned Group	Assigned Member		
Completed	NM - Water Reuse & Pipeline Team		Cody Williams	

Comments

Last Modified By	Created By
Jesse Terrazas	Ashley Kungle
Last Modified Date	Created Date
01/08/2026	01/08/2026

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

13416197

Scheduled

04/26/2025

Completed

01/08/2026

Earliest Compliance

01/11/2026

Latest Compliance

01/17/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Joe Sanchez Team

Assigned Member**Comments****Last Modified By**

Jesse Terrazas

Created By

Ashley Kungle

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
RH GALAXY REUSE PIT			074829000	
Form Description				Form ID
Reuse Pit Inspection - NM			13281360	
Scheduled	Completed	Earliest Compliance	Latest Compliance	
12/04/2025	01/08/2026	11/30/2025	12/06/2025	
Status	Assigned Group	Assigned Member	Previous Form	
Completed	NM - Water Reuse & Pipeline James Kelley Team		12964576	

Comments

Last Modified By	Created By
Jesse Terrazas	James Kelley
Last Modified Date	Created Date
01/08/2026	11/24/2025

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property	RH GALAXY REUSE PIT	Property ID	074829000
Form Description	Reuse Pit Inspection - NM	Form ID	13345925
Scheduled	Completed 12/29/2025	Earliest Compliance	Latest Compliance
Status	Completed	Assigned Group NM - Water Reuse & Pipeline Matt Dee Team	Assigned Member
Comments			

Last Modified By Matt Dee	Created By Jorge Gutierrez
Last Modified Date 12/30/2025	Created Date 12/15/2025

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter:	Schedule Period: Unscheduled	Program Type: EOG Voluntary
----------------------------	---------------------------------	--------------------------	--	---------------------------------------



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

12964576

Scheduled

11/24/2025

Completed

11/24/2025

Earliest Compliance

09/07/2025

Latest Compliance

09/13/2025

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline James Kelley Team

Assigned Member**Previous Form**

12801008

Comments

-Sched Dt Update--Sched Dt Update-

Last Modified By

James Kelley

Created By

Ricardo Villegas

Last Modified Date

11/24/2025

Created Date

09/01/2025

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:

No

Berm or Line issue:

Yes

Repair Request:

Galaxy West side of pit by step found patch came undone so water accumulated inside the liner but needs to be repaired again

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
RH GALAXY REUSE PIT			074829000	
Form Description				Form ID
Reuse Pit Inspection - NM			13416558	
Scheduled	Completed	Earliest Compliance		
11/06/2025			Latest Compliance	
Status	Assigned Group	Assigned Member	Previous Form	
Open	NM - Water Reuse & Pipeline Team	Jesse Terrazas	13416554	

Comments

Last Modified By

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property	RH GALAXY REUSE PIT	Property ID	074829000
Form Description	Reuse Pit Inspection - NM	Form ID	12801008
Scheduled	Completed 09/01/2025	Earliest Compliance	07/13/2025
Status	Completed	Assigned Group	NM - Water Reuse & Pipeline Ricardo Villegas Team
Assigned Member	Ricardo Villegas	Latest Compliance	07/19/2025
Comments		Previous Form	12747449

Last Modified By

Ricardo Villegas

Created By

Michael Jordan

Last Modified Date

09/01/2025

Created Date

07/07/2025

General

Visual inspection conducted: Yes	Bird Deterrent Issue: No	Berm or Line issue: No	Fence Issues: No
Is there a visible layer of oil on the surface of the recycling containment?: No	Is there at least 3 feet of freeboard at the containment?: Yes	Is leak detection system working properly?: Yes	Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
RH GALAXY REUSE PIT			074829000	
Form Description				Form ID
Reuse Pit Inspection - NM			12747449	
Scheduled	Completed	Earliest Compliance	Latest Compliance	
07/07/2025	07/07/2025	06/29/2025	07/05/2025	
Status	Assigned Group	Assigned Member	Previous Form	
Completed	NM - Water Reuse & Pipeline Team	Cody Williams	12729230	

Comments

Last Modified By	Created By
Michael Jordan	Cody Williams
Last Modified Date	Created Date
07/07/2025	06/23/2025

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

13416556

Scheduled

07/05/2025

Completed**Earliest Compliance****Latest Compliance**

06/29/2025

07/05/2025

Status

Open

Assigned Group**Assigned Member****Previous Form**

NM - Water Reuse & Pipeline Jesse Terrazas Team

13416553

Comments**Last Modified By**

Jesse Terrazas

Created By

Jesse Terrazas

Last Modified Date

01/08/2026

Created Date

01/08/2026

General

Visual inspection conducted:

Bird Deterrent Issue:

Berm or Line issue:

Fence Issues:

Is there a visible layer of oil on the surface of the recycling containment?:

Is there at least 3 feet of freeboard at the containment?:

Is leak detection system working properly?:

Attachments:

Schedule

Schedule ID:
671Schedule Name:
WeeklySchedule Counter:
1Schedule Period:
WEEKProgram Type:
Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
RH GALAXY REUSE PIT			074829000	
Form Description				Form ID
Reuse Pit Inspection - NM			12729230	
Scheduled	Completed	Earliest Compliance	Latest Compliance	
06/23/2025	06/23/2025	06/22/2025	06/28/2025	
Status	Assigned Group	Assigned Member	Previous Form	
Completed	NM - Water Reuse & Pipeline Team	Cody Williams	12664163	

Comments

Last Modified By	Created By
Cody Williams	Alfred Perez
Last Modified Date	Created Date
06/23/2025	06/16/2025

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

12664163

Scheduled

06/23/2025

Completed

06/16/2025

Earliest Compliance

06/01/2025

Latest Compliance

06/07/2025

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Joe Sanchez Team

Assigned Member**Previous Form**

12424841

Comments**Last Modified By**

Alfred Perez

Created By

Joe Sanchez

Last Modified Date

06/16/2025

Created Date

05/26/2025

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID: 671	Schedule Name: Weekly	Schedule Counter: 1	Schedule Period: WEEK	Program Type: Water Reuse
----------------------------	---------------------------------	-------------------------------	---------------------------------	-------------------------------------



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property

RH GALAXY REUSE PIT

Property ID

074829000

Form Description

Reuse Pit Inspection - NM

Form ID

12424841

Scheduled

05/26/2025

Completed

05/26/2025

Earliest Compliance

03/16/2025

Latest Compliance

03/22/2025

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Joe Sanchez Team

Assigned Member**Previous Form**

12360619

Comments**Last Modified By**

Joe Sanchez

Created By

Alfred Perez

Last Modified Date

05/26/2025

Created Date

03/10/2025

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID:
671

Schedule Name:
Weekly

Schedule Counter:
1

Schedule Period:
WEEK

Program Type:
Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
RH GALAXY REUSE PIT			074829000	
Form Description				Form ID
Reuse Pit Inspection - NM			12360619	
Scheduled	Completed	Earliest Compliance	Latest Compliance	
03/17/2025	03/10/2025	02/23/2025	03/01/2025	
Status	Assigned Group	Assigned Member	Previous Form	
Completed	NM - Water Reuse & Pipeline Team	Joe Sanchez	12282057	

Comments

Last Modified By	Created By
Ashley Kungle	Joe Sanchez
Last Modified Date	Created Date
01/08/2026	02/17/2025

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
RH GALAXY REUSE PIT			074829000	
Form Description				Form ID
Reuse Pit Inspection - NM			12282057	
Scheduled	Completed	Earliest Compliance	Latest Compliance	
02/17/2025	02/17/2025	01/26/2025	02/01/2025	
Status	Assigned Group	Assigned Member	Previous Form	
Completed	NM - Water Reuse & Pipeline Team	Joe Sanchez	12211585	

Comments

Last Modified By

Joe Sanchez

Created By

Michael Jordan

Last Modified Date

02/17/2025

Created Date

01/20/2025

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
RH GALAXY REUSE PIT			074829000	
Form Description				Form ID
Reuse Pit Inspection - NM			12211585	
Scheduled	Completed	Earliest Compliance	Latest Compliance	
01/20/2025	01/20/2025	01/05/2025	01/11/2025	
Status	Assigned Group	Assigned Member	Previous Form	
Completed	NM - Water Reuse & Pipeline Oscar Jimenez Team		12176667	

Comments

Last Modified By	Created By
Michael Jordan	Alfred Perez
Last Modified Date	Created Date
01/20/2025	12/30/2024

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 33876

Site Name: RH GALAXY REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
RH GALAXY REUSE PIT			074829000	
Form Description				Form ID
Reuse Pit Inspection - NM			12176667	
Scheduled	Completed	Earliest Compliance	Latest Compliance	
01/06/2025	12/30/2024	12/22/2024	12/28/2024	
Status	Assigned Group	Assigned Member	Previous Form	
Completed	NM - Water Reuse & Pipeline Joel Najar Team		12050306	

Comments

Last Modified By	Created By
Alfred Perez	Joel Najar
Last Modified Date	Created Date
12/30/2024	12/16/2024

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse

Venegas, Victoria, EMNRD

From: Venegas, Victoria, EMNRD
Sent: Friday, January 9, 2026 1:33 PM
To: morgan_hrncirik@eogresources.com
Subject: 1RF-25 - GALAXY REUSE WATER FACILITY AND CONTAINMENT FACILITY [fOY1801852871]
Attachments: C-147 1RF-25 - GALAXY REUSE WATER FACILITY AND CONTAINMENT [fOY1801852871]
01.09.2026.pdf

1RF-25 - GALAXY REUSE WATER FACILITY AND CONTAINMENT FACILITY [fOY1801852871]

Good afternoon Ms. Hrncirik

The NMOCD has reviewed the determination of registration/permit annual extension request for 1RF-25 - GALAXY REUSE WATER FACILITY AND CONTAINMENT FACILITY [fOY1801852871] received from [7377] EOG RESOURCES INC on 01/08/2026, Action ID **541442**. The registration/permit annual extension request is approved with the following conditions of approval:

- 1RF-25 - GALAXY REUSE WATER FACILITY AND CONTAINMENT FACILITY [fOY1801852871] is approved for one (1) year of operation from the date of the previous registration/permit expiration date of January 2, 2026. The new registration/permit expiration date is January 2, 2027.
- [7377] EOG RESOURCES INC will continue to operate, maintain, and close the 1RF-25 - GALAXY REUSE WATER FACILITY AND CONTAINMENT FACILITY [fOY1801852871] in compliance with 19.15.34 NMAC, to include but not limited to the performance of weekly inspections regardless of fluid levels in the containment; recording of detailed inspection reports; removal of debris, foreign objects and oil from the containment; and monthly reporting of recycling and reuse of produced water, drilling fluids, and liquid oil field waste via OCD Permitting.
- If less than 20% of the total fluid capacity is utilized every consecutive six months, operation of the facility is considered ceased and notification of cessation of operations should be sent electronically form through the OCD Permitting. An extension to extend the cessation of operations, not to exceed six months, may be submitted using a C-147 form via OCD Permitting.
- The recycling containment is bonded pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC. Water reuse and recycling from 1RF-25 - GALAXY REUSE WATER FACILITY AND CONTAINMENT FACILITY [fOY1801852871] is limited to wells owned or operated by [7377] EOG RESOURCES INC.
- A minimum of 3-feet freeboard must be maintained in the recycling containment at all times.
- [7377] EOG RESOURCES INC will comply with 19.15.29 NMAC Releases in the event of any release of produced water or produced water or other oil field wastes at 1RF-25 - GALAXY REUSE WATER FACILITY AND CONTAINMENT FACILITY [fOY1801852871]. [7377] EOG RESOURCES INC will comply with all other OCD rules.
- [7377] EOG RESOURCES INC must perform weekly inspections of the containment and leak detection system.
- If [7377] EOG RESOURCES INC wishes to extend the registration/permit past January 2, 2027, a registration/permit extension request must be submitted to OCD. Extension requests are reviewed on a case-by-case basis and evaluated on their merit. Extensions are considered for a maximum length of one year.
- Additional requests must be submitted to OCD Permitting on Form C-147 as an Extension request and should include a formal extension request letter, a summary of the prior registration/permit period inspection reports, and the copies of the detailed inspection records for the prior permit period. The extension request should be submitted no later than December 2, 2026.

Please let me know if you have any additional questions.

Best regards,

Victoria Venegas • Senior Environmental Scientist
EMNRD - Oil Conservation Division
506 W. Texas Ave. Artesia, NM 88210
575.909.0269 | Victoria.Venegas@emnrd.nm.gov

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 541442

CONDITIONS

Operator: EOG RESOURCES INC 5509 Champions Drive Midland, TX 79706	OGRID: 7377
	Action Number: 541442
	Action Type: [C-147] Water Recycle Long (C-147L)

CONDITIONS

Created By	Condition	Condition Date
vvenegas	• 1RF-25 - GALAXY REUSE WATER FACILITY AND CONTAINMENT FACILITY [fOY1801852871] is approved for one (1) year of operation from the date of the previous registration/permit expiration date of January 2, 2026. The new registration/permit expiration date is January 2, 2027. • If [7377] EOG RESOURCES INC wishes to extend the registration/permit past January 2, 2027, a registration/permit extension request must be submitted to OCD no later than December 2, 2026.	1/9/2026