

State of New Mexico
Energy Minerals and Natural Resources
Department Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505
<https://www.emnrd.nm.gov/ocd/ocd-e-permitting/>

Form C-147
Revised October 11, 2022

Recycling Facility and/or Recycling Containment

Type of Facility: ☐ Recycling Facility ☒ Recycling Containment*

Type of action: ☒ Permit ☐ Registration
☐ Modification ☒ Extension (07/07/2026-07/07/2027)
☐ Closure ☐ Other (explain) _____

*** At the time C-147 is submitted to the division for a Recycling Containment, a copy shall be provided to the surface owner.**

Be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.

1.

Operator: EOG Resources Inc. (For multiple operators attach page with information) OGRID #: _____
 Address: 5509 Champions Drive, Midland, TX 79706
 Facility or well name (include API# if associated with a well): JT Pit
 OCD Permit Number: 2RF-109 (For new facilities the permit number will be assigned by the district office)
 U/L or Qtr/Qtr D Section 16 Township 26S Range 30E County: Eddy
 Surface Owner: ☐ Federal ☒ State ☐ Private ☐ Tribal Trust or Indian Allotment

2.

☐ **Recycling Facility:**

Location of recycling facility (if applicable): Latitude 32.0464979 Longitude -103.8933291 NAD83

Proposed Use: ☐ Drilling* ☒ Completion* ☐ Production* ☐ Plugging *

***The re-use of produced water may NOT be used until fresh water zones are cased and cemented**

☐ Other, **requires permit for other uses. Describe use, process, testing, volume of produced water and ensure there will be no adverse impact on groundwater or surface water.**

☒ Fluid Storage

☐ Above ground tanks ☒ Recycling containment ☐ Activity permitted under 19.15.17 NMAC explain type _____

☐ Activity permitted under 19.15.36 NMAC explain type: _____ ☐ Other explain _____

☐ For multiple or additional recycling containments, attach design and location information of each containment

☐ **Closure Report (required within 60 days of closure completion):** ☐ Recycling Facility Closure Completion Date: _____

3.

☒ **Recycling Containment:**

Requesting Annual Extension 07/27/2026-07/07/2027

☒ Annual Extension after initial 5 years (attach summary of monthly leak detection inspections for previous year)

Center of Recycling Containment (if applicable): Latitude _____ Longitude _____ NAD83

☐ For multiple or additional recycling containments, attach design and location information of each containment

☒ Lined ☒ Liner type: Thickness 60 mil ☐ LLDPE ☒ HDPE ☐ PVC ☐ Other

☐ String-Reinforced

Liner Seams: ☒ Welded ☐ Factory ☐ Other _____ Volume: 473058 bbl Dimensions: L 650 x W 450 x D 17

☐ Recycling Containment Closure Completion Date: _____

4.

Bonding:

- ☒ Covered under bonding pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC (These containments are limited to only the wells owned or operated by the owners of the containment.)
- ☐ Bonding in accordance with 19.15.34.15(A)(1). Amount of bond \$ _____ (work on these facilities cannot commence until bonding amounts are approved)
- ☐ Attach closure cost estimate and documentation on how the closure cost was calculated.

5.

Fencing:

- ☐ Four foot height, four strands of barbed wire evenly spaced between one and four feet
- ☒ Alternate. Please specify 6 foot chain link fence

6.

Signs:

- ☒ 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers
- ☐ Signed in compliance with 19.15.16.8 NMAC

7.

Variances:

Justifications and/or demonstrations that the proposed variance will afford reasonable protection against contamination of fresh water, human health, and the environment.

Check the below box only if a variance is requested:

☒ Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. If a Variance is requested, include the variance information on a separate page and attach it to the C-147 as part of the application.

If a Variance is requested, it must be approved prior to implementation.

8.

Siting Criteria for Recycling Containment

Instructions: The applicant must provide attachments that demonstrate compliance for each siting criteria below as part of the application. Potential examples of the siting attachment source material are provided below under each criteria.

General siting**Ground water is less than 50 feet below the bottom of the Recycling Containment.**

NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells

☐ Yes ☒ No
☐ NA

Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended.

- Written confirmation or verification from the municipality; written approval obtained from the municipality

☐ Yes ☒ No
☐ NA

Within the area overlying a subsurface mine.

- Written confirmation or verification or map from the NM EMNRD-Mining and Minerals Division

☐ Yes ☒ No

Within an unstable area.

- Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; topographic map

☐ Yes ☒ No

Within a 100-year floodplain. FEMA map

☐ Yes ☒ No

Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).

- Topographic map; visual inspection (certification) of the proposed site

☐ Yes ☒ No

Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.

- Visual inspection (certification) of the proposed site; aerial photo; satellite image

☐ Yes ☒ No

Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application.

- NM Office of the State Engineer - iWATERS database search; visual inspection (certification) of the proposed site

☐ Yes ☒ No

Within 500 feet of a wetland.

- US Fish and Wildlife Wetland Identification map; topographic map; visual inspection (certification) of the proposed site

☐ Yes ☒ No

9.

Recycling Facility and/or Containment Checklist:

Instructions: Each of the following items must be attached to the application. Indicate, by a check mark in the box, that the documents are attached.

- ☒ Design Plan - based upon the appropriate requirements.
- ☒ Operating and Maintenance Plan - based upon the appropriate requirements.
- ☒ Closure Plan - based upon the appropriate requirements.
- ☒ Site Specific Groundwater Data -
- ☒ Siting Criteria Compliance Demonstrations –
- ☒ Certify that notice of the C-147 (only) has been sent to the surface owner(s)

10.

Operator Application Certification:

I hereby certify that the information and attachments submitted with this application are true, accurate and complete to the best of my knowledge and belief.

Name (Print): Morgan Hrnecirik Title: Sr. Regulatory Administrator
Signature: *Morgan Hrnecirik* Date: 7/7/2026
e-mail address: Morgan_Hrnecirik@eogresources.com Telephone: (832) 627-5450

11.

OCD Representative Signature: *Victoria Venegas* Approval Date: 07/09/2026
Title: Senior Environmental Scientist OCD Permit Number: 2RF-109
FMLB1722856120
☒ OCD Conditions
☒ Additional OCD Conditions on Attachment



P.O. Box 2267, Midland, Texas 79702
Phone: (832) 627-5450

July 8, 2026

Ms. Victoria Venegas, Environmental Specialist
EMNRD- Oil Conservation Division
506 W. Texas Artesia, NM 88210

Re: 2RF-109 JT PIT FACILITY ID [fMLB1722856120]

Dear Ms. Venegas:

Thank you for allowing EOG to continue to promote water reuse in the State of New Mexico for our operations. EOG Resources, Inc. would like to formally request an extension to our currently approved permit to July 27, 2027. EOG would like to clarify the correct dates of the enclosed inspection records. This relates to our inspection records database, which underwent a system update at the end of June 2025. This update inadvertently caused a conflict in how inspection records were timestamped and logged. While all inspections were physically conducted on their originally scheduled dates and in accordance with permit requirements, a technical error resulted in those records being reflected with 2026 completion dates when our team reentered the system to finalize documentation. This was an internal software issue that has since been identified and fully remediated and we are confident that required inspections were timely performed.

Sincerely,

Morgan Hrcirik

Morgan Hrcirik
Sr. Regulatory Administrator



Forms Report

Forms Summary

Total Forms: 55

Form Date	Status	Form ID	Form Type	Application Name
07/03/2026	Completed	14759059	Reuse Pit Inspection - NM	iEnvironmental
07/01/2026	Completed	14758694	Reuse Pit Inspection - NM	iEnvironmental
07/01/2026	Completed	14758693	Reuse Pit Inspection - NM	iEnvironmental
07/01/2026	Completed	14758692	Reuse Pit Inspection - NM	iEnvironmental
07/01/2026	Completed	14758691	Reuse Pit Inspection - NM	iEnvironmental
07/01/2026	Completed	14758690	Reuse Pit Inspection - NM	iEnvironmental
07/01/2026	Completed	14758689	Reuse Pit Inspection - NM	iEnvironmental
07/01/2026	Completed	14758688	Reuse Pit Inspection - NM	iEnvironmental
07/01/2026	Completed	14758582	Reuse Pit Inspection - NM	iEnvironmental
07/01/2026	Completed	14758499	Reuse Pit Inspection - NM	iEnvironmental
07/01/2026	Completed	14758498	Reuse Pit Inspection - NM	iEnvironmental
07/01/2026	Completed	14758497	Reuse Pit Inspection - NM	iEnvironmental
07/01/2026	Completed	14758496	Reuse Pit Inspection - NM	iEnvironmental
07/01/2026	Completed	14758495	Reuse Pit Inspection - NM	iEnvironmental
07/01/2026	Completed	14758494	Reuse Pit Inspection - NM	iEnvironmental
07/01/2026	Completed	14758493	Reuse Pit Inspection - NM	iEnvironmental
07/01/2026	Completed	14695771	Reuse Pit Inspection - NM	iEnvironmental
07/01/2026	Completed	13761526	Reuse Pit Inspection - NM	iEnvironmental
07/01/2026	Completed	13522788	Reuse Pit Inspection - NM	iEnvironmental
06/26/2026	Completed	14609131	Reuse Pit Inspection - NM	iEnvironmental
06/19/2026	Completed	14542285	Reuse Pit Inspection - NM	iEnvironmental
06/12/2026	Completed	14468328	Reuse Pit Inspection - NM	iEnvironmental
06/05/2026	Completed	14370821	Reuse Pit Inspection - NM	iEnvironmental
05/29/2026	Completed	14278775	Reuse Pit Inspection - NM	iEnvironmental
05/22/2026	Completed	14127206	Reuse Pit Inspection - NM	iEnvironmental
05/15/2026	Completed	14091733	Reuse Pit Inspection - NM	iEnvironmental
05/08/2026	Completed	14007065	Reuse Pit Inspection - NM	iEnvironmental
05/01/2026	Completed	13954531	Reuse Pit Inspection - NM	iEnvironmental
04/24/2026	Completed	13912883	Reuse Pit Inspection - NM	iEnvironmental
04/17/2026	Completed	13872701	Reuse Pit Inspection - NM	iEnvironmental
04/10/2026	Completed	13839616	Reuse Pit Inspection - NM	iEnvironmental
04/03/2026	Completed	13787735	Reuse Pit Inspection - NM	iEnvironmental
03/20/2026	Completed	13725882	Reuse Pit Inspection - NM	iEnvironmental
03/13/2026	Completed	13683241	Reuse Pit Inspection - NM	iEnvironmental
03/08/2026	Completed	13645689	Reuse Pit Inspection - NM	iEnvironmental
03/04/2026	Completed	13598988	Reuse Pit Inspection - NM	iEnvironmental
02/23/2026	Completed	13566892	Reuse Pit Inspection - NM	iEnvironmental
02/16/2026	Completed	13570101	Reuse Pit Inspection - NM	iEnvironmental
02/02/2026	Completed	13496818	Reuse Pit Inspection - NM	iEnvironmental
01/27/2026	Completed	13457843	Reuse Pit Inspection - NM	iEnvironmental
01/19/2026	Completed	13428853	Reuse Pit Inspection - NM	iEnvironmental
01/12/2026	Completed	13409037	Reuse Pit Inspection - NM	iEnvironmental
01/05/2026	Completed	13390800	Reuse Pit Inspection - NM	iEnvironmental
12/30/2025	Completed	13367905	Reuse Pit Inspection - NM	iEnvironmental
12/22/2025	Completed	13345917	Reuse Pit Inspection - NM	iEnvironmental
11/24/2025	Completed	13238143	Reuse Pit Inspection - NM	iEnvironmental
11/10/2025	Completed	13018247	Reuse Pit Inspection - NM	iEnvironmental
10/13/2025	Completed	13132514	Reuse Pit Inspection - NM	iEnvironmental
09/15/2025	Completed	12964605	Reuse Pit Inspection - NM	iEnvironmental



Form Date	Status	Form ID	Form Type	Application Name
09/01/2025	Completed	12925560	Reuse Pit Inspection - NM	iEnvironmental
08/18/2025	Completed	12883628	Reuse Pit Inspection - NM	iEnvironmental
08/04/2025	Completed	12865891	Reuse Pit Inspection - NM	iEnvironmental
07/29/2025	Completed	12753894	Reuse Pit Inspection - NM	iEnvironmental
06/16/2026	Completed	14542284	Reuse Pit Inspection Work Order	iEnvironmental
01/19/2026	Completed	13457844	Reuse Pit Inspection Work Order	iEnvironmental



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				14759059
Scheduled	Completed			
07/08/2026	07/03/2026			
Status	Assigned Group	Assigned Member	Associated Form	
Completed	NM - Water Reuse & Pipeline Team	Juan Elizondo	14695771	
Comments				

Last Modified By

James Kelley

Created By

Jesse Terrazas

General

Visual inspection
conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of
oil on the surface of the
recycling containment?:

No

Is there at least 3 feet of
freeboard at the
containment?:

Yes

Is leak detection system
working properly?:

Yes

Attachments:

Schedule

Schedule ID:

671

Schedule Name:

Weekly

Schedule Counter:

1

Schedule Period:

WEEK

Program Type:

Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property

JT REUSE PIT

Property ID

143051000

Form Description

Reuse Pit Inspection - NM

Form ID

14758694

Scheduled

12/15/2025

Completed

07/01/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Team

Assigned Member

Jesse Terrazas

Comments**Last Modified By**

Jesse Terrazas

Created By

Ashley Kungle

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:

Schedule

Schedule ID:

671

Schedule Name:

Weekly

Schedule Counter:**Schedule Period:**

Unscheduled

Program Type:

EOG Voluntary



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property			Property ID
JT REUSE PIT			143051000
Form Description			Form ID
Reuse Pit Inspection - NM			14758693
Scheduled	Completed		
12/08/2025	07/01/2026		
Status	Assigned Group	Assigned Member	
Completed	NM - Water Reuse & Pipeline Team	Jesse Terrazas	
Comments			

Last Modified By
Jesse Terrazas

Created By
Ashley Kungle

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly		Unscheduled	EOG Voluntary



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property			Property ID
JT REUSE PIT			143051000
Form Description			Form ID
Reuse Pit Inspection - NM			14758692
Scheduled	Completed		
11/17/2025	07/01/2026		
Status	Assigned Group	Assigned Member	
Completed	NM - Water Reuse & Pipeline Team	Jesse Terrazas	
Comments			

Last Modified By
Jesse Terrazas

Created By
Ashley Kungle

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly		Unscheduled	EOG Voluntary



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property			Property ID
JT REUSE PIT			143051000
Form Description			Form ID
Reuse Pit Inspection - NM			14758691
Scheduled	Completed		
11/03/2025	07/01/2026		
Status	Assigned Group	Assigned Member	
Completed	NM - Water Reuse & Pipeline Team	Jesse Terrazas	
Comments			

Last Modified By
Jesse Terrazas

Created By
Ashley Kungle

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly		Unscheduled	EOG Voluntary



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property			Property ID
JT REUSE PIT			143051000
Form Description			Form ID
Reuse Pit Inspection - NM			14758690
Scheduled	Completed		
10/27/2025	07/01/2026		
Status	Assigned Group	Assigned Member	
Completed	NM - Water Reuse & Pipeline Team	Jesse Terrazas	
Comments			

Last Modified By
Jesse Terrazas

Created By
Ashley Kungle

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly		Unscheduled	EOG Voluntary



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property			Property ID
JT REUSE PIT			143051000
Form Description			Form ID
Reuse Pit Inspection - NM			14758689
Scheduled	Completed		
10/20/2025	07/01/2026		
Status	Assigned Group	Assigned Member	
Completed	NM - Water Reuse & Pipeline Team	Jesse Terrazas	
Comments			

Last Modified By
Jesse Terrazas

Created By
Ashley Kungle

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly		Unscheduled	EOG Voluntary



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property			Property ID
JT REUSE PIT			143051000
Form Description			Form ID
Reuse Pit Inspection - NM			14758688
Scheduled	Completed		
10/06/2025	07/01/2026		
Status	Assigned Group	Assigned Member	
Completed	NM - Water Reuse & Pipeline Team	Jesse Terrazas	
Comments			

Last Modified By
Jesse Terrazas

Created By
Ashley Kungle

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly		Unscheduled	EOG Voluntary



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM**Property**

JT REUSE PIT

Property ID

143051000

Form Description

Reuse Pit Inspection - NM

Form ID

14758582

Scheduled

09/29/2025

Completed

07/01/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Team

Assigned Member

Jesse Terrazas

Comments**Last Modified By**

Jesse Terrazas

Created By

Ashley Kungle

General**Visual inspection conducted:**

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:**Schedule****Schedule ID:**

671

Schedule Name:

Weekly

Schedule Counter:**Schedule Period:**

Unscheduled

Program Type:

EOG Voluntary



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property			Property ID
JT REUSE PIT			143051000
Form Description			Form ID
Reuse Pit Inspection - NM			14758499
Scheduled	Completed		
09/22/2025	07/01/2026		
Status	Assigned Group	Assigned Member	
Completed	NM - Water Reuse & Pipeline Team	Jesse Terrazas	
Comments			

Last Modified By
Jesse Terrazas

Created By
Ashley Kungle

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly		Unscheduled	EOG Voluntary



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property	JT REUSE PIT		Property ID	143051000
Form Description	Reuse Pit Inspection - NM		Form ID	14758498
Scheduled	09/08/2025	Completed	07/01/2026	
Status	Completed	Assigned Group	NM - Water Reuse & Pipeline Team	Assigned Member
Comments	Jesse Terrazas			

Last Modified By
Jesse Terrazas

Created By
Ashley Kungle

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly		Unscheduled	EOG Voluntary



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property	JT REUSE PIT		Property ID	143051000
Form Description	Reuse Pit Inspection - NM		Form ID	14758497
Scheduled	08/25/2025	Completed	07/01/2026	
Status	Completed	Assigned Group	NM - Water Reuse & Pipeline Team	Assigned Member
Comments	Jesse Terrazas			

Last Modified By
Jesse Terrazas

Created By
Ashley Kungle

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly		Unscheduled	EOG Voluntary



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property			Property ID
JT REUSE PIT			143051000
Form Description			Form ID
Reuse Pit Inspection - NM			14758496
Scheduled	Completed		
08/11/2025	07/01/2026		
Status	Assigned Group	Assigned Member	
Completed	NM - Water Reuse & Pipeline Team	Jesse Terrazas	
Comments			

Last Modified By
Jesse Terrazas

Created By
Ashley Kungle

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly		Unscheduled	EOG Voluntary



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property			Property ID
JT REUSE PIT			143051000
Form Description			Form ID
Reuse Pit Inspection - NM			14758495
Scheduled	Completed		
07/21/2025	07/01/2026		
Status	Assigned Group	Assigned Member	
Completed	NM - Water Reuse & Pipeline Team	Jesse Terrazas	
Comments			

Last Modified By
Jesse Terrazas

Created By
Ashley Kungle

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly		Unscheduled	EOG Voluntary



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM**Property**

JT REUSE PIT

Property ID

143051000

Form Description

Reuse Pit Inspection - NM

Form ID

14758494

Scheduled

07/14/2025

Completed

07/01/2026

Status

Completed

Assigned Group

NM - Water Reuse & Pipeline Team

Assigned Member

Jesse Terrazas

Comments**Last Modified By**

Jesse Terrazas

Created By

Ashley Kungle

General**Visual inspection conducted:**

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:**Schedule****Schedule ID:**

671

Schedule Name:

Weekly

Schedule Counter:**Schedule Period:**

Unscheduled

Program Type:

EOG Voluntary



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property	JT REUSE PIT		Property ID	143051000
Form Description	Reuse Pit Inspection - NM		Form ID	14758493
Scheduled	07/07/2025	Completed	07/01/2026	
Status	Completed	Assigned Group	NM - Water Reuse & Pipeline Team	Assigned Member
Comments	Jesse Terrazas			

Last Modified By
Jesse Terrazas

Created By
Ashley Kungle

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly		Unscheduled	EOG Voluntary



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				14695771
Scheduled	Completed			
07/03/2026	07/01/2026			
Status	Assigned Group	Assigned Member	Associated Form	
Completed	NM - Water Reuse & Pipeline Team	Juan Elizondo	14609131	
Comments				

Last Modified By
Jesse Terrazas

Created By
Juan Elizondo

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				13761526
Scheduled	Completed			
03/27/2026	07/01/2026			
Status	Assigned Group	Assigned Member	Associated Form	
Completed	NM - Water Reuse & Pipeline Team	Carlos Trevino	13725882	
Comments				

Last Modified By
Jesse Terrazas

Created By
Jorge Gutierrez

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly		Unscheduled	EOG Voluntary



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				13522788
Scheduled	Completed			
02/09/2026	07/01/2026			
Status	Assigned Group	Assigned Member	Associated Form	
Completed	NM - Water Reuse & Pipeline Team	Jorge Gutierrez	13496818	
Comments				

Last Modified By
Jesse Terrazas

Created By
Ricardo Villegas

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly		Unscheduled	EOG Voluntary



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				14609131
Scheduled	Completed			
06/26/2026	06/26/2026			
Status	Assigned Group	Assigned Member	Associated Form	
Completed	NM - Water Reuse & Pipeline Team	Juan Elizondo	14542285	
Comments				

Last Modified By
Juan Elizondo

Created By
James Kelley

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				14542285
Scheduled	Completed			
06/19/2026	06/19/2026			
Status	Assigned Group	Assigned Member	Associated Form	
Completed	NM - Water Reuse & Pipeline Team	James Kelley	14468328	
Comments				

Last Modified By

James Kelley

Created By

Michael Lopez

General

Visual inspection
conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of
oil on the surface of the
recycling containment?:

No

Is there at least 3 feet of
freeboard at the
containment?:

Yes

Is leak detection system
working properly?:

Yes

Attachments:

Schedule

Schedule ID:

671

Schedule Name:

Weekly

Schedule Counter:

1

Schedule Period:

WEEK

Program Type:

Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				14468328
Scheduled	Completed			
06/12/2026	06/12/2026			
Status	Assigned Group	Assigned Member	Associated Form	
Completed	NM - Water Reuse & Pipeline Team	Michael Lopez	14370821	
Comments				

Last Modified By

Michael Lopez

Created By

James Kelley

General

Visual inspection conducted:	Bird Deterrent Issue:	Repair Request:	Berm or Line issue:
Yes	Yes	Sw corner bird deterrent battery needs to be replaced	No
Fence Issues:	Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:
No	No	Yes	Yes

Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property			Property ID
JT REUSE PIT			143051000
Form Description			Form ID
Reuse Pit Inspection - NM			14370821
Scheduled	Completed		
06/05/2026	06/05/2026		
Status	Assigned Group	Assigned Member	Associated Form
Completed	NM - Water Reuse & Pipeline Team	James Kelley	14278775
Comments			

Last Modified By

James Kelley

Created By

Jorge Gutierrez

General

Visual inspection
conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of
oil on the surface of the
recycling containment?:

No

Is there at least 3 feet of
freeboard at the
containment?:

Yes

Is leak detection system
working properly?:

Yes

Attachments:

Schedule

Schedule ID:

671

Schedule Name:

Weekly

Schedule Counter:

1

Schedule Period:

WEEK

Program Type:

Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				14278775
Scheduled	Completed			
05/29/2026	05/29/2026			
Status	Assigned Group	Assigned Member	Associated Form	
Completed	NM - Water Reuse & Pipeline Team	Jorge Gutierrez	14127206	
Comments				

Last Modified By
Jorge Gutierrez

Created By
James Kelley

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				14127206
Scheduled	Completed			
05/22/2026	05/22/2026			
Status	Assigned Group	Assigned Member	Associated Form	
Completed	NM - Water Reuse & Pipeline Team	James Kelley	14091733	

Comments

Last Modified By

James Kelley

Created By

Jorge Gutierrez

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				14091733
Scheduled	Completed			
05/16/2026	05/15/2026			
Status	Assigned Group	Assigned Member	Associated Form	
Completed	NM - Water Reuse & Pipeline Team	Jorge Gutierrez	14007065	
Comments				

Last Modified By
Jorge Gutierrez

Created By
Ashley Kungle

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				14007065
Scheduled	Completed			
05/08/2026	05/08/2026			
Status	Assigned Group	Assigned Member	Associated Form	
Completed	NM - Water Reuse & Pipeline Team	James Kelley	13954531	

Comments

Auto-Deferred by System due to missed inspection.

Last Modified By
James Kelley

Created By
Jorge Gutierrez

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				13954531
Scheduled	Completed			
05/01/2026	05/01/2026			
Status	Assigned Group	Assigned Member	Associated Form	
Completed	NM - Water Reuse & Pipeline Team	Jorge Gutierrez	13912883	
Comments				

Last Modified By
Jorge Gutierrez

Created By
James Kelley

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				13912883
Scheduled	Completed			
04/24/2026	04/24/2026			
Status	Assigned Group	Assigned Member	Associated Form	
Completed	NM - Water Reuse & Pipeline Team	James Kelley	13872701	
Comments				

Last Modified By
James Kelley

Created By
Carlos Trevino

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				13872701
Scheduled	Completed			
04/17/2026	04/17/2026			
Status	Assigned Group	Assigned Member	Associated Form	
Completed	NM - Water Reuse & Pipeline Team	Ricardo Villegas	13839616	
Comments				

Last Modified By
Carlos Trevino

Created By
Ricardo Villegas

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
JT REUSE PIT		143051000	
Form Description		Form ID	
Reuse Pit Inspection - NM		13839616	
Scheduled	Completed		
04/10/2026	04/10/2026		
Status	Assigned Group	Assigned Member	Associated Form
Completed	NM - Water Reuse & Pipeline Team	Ricardo Villegas	13787735
Comments			

Last Modified By

Ricardo Villegas

Created By

Jorge Gutierrez

General

Visual inspection
conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of
oil on the surface of the
recycling containment?:

No

Is there at least 3 feet of
freeboard at the
containment?:

Yes

Is leak detection system
working properly?:

Yes

Attachments:

Schedule

Schedule ID:

671

Schedule Name:

Weekly

Schedule Counter:

1

Schedule Period:

WEEK

Program Type:

Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				13787735
Scheduled	Completed			
04/04/2026	04/03/2026			
Status	Assigned Group	Assigned Member	Associated Form	
Completed	NM - Water Reuse & Pipeline Team	Carlos Trevino	13761526	
Comments				

Last Modified By

Jorge Gutierrez

Created By

Ashley Kungle

General

Visual inspection
conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of
oil on the surface of the
recycling containment?:

No

Is there at least 3 feet of
freeboard at the
containment?:

Yes

Is leak detection system
working properly?:

Yes

Attachments:

Schedule

Schedule ID:

671

Schedule Name:

Weekly

Schedule Counter:

1

Schedule Period:

WEEK

Program Type:

Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				13725882
Scheduled	Completed			
03/20/2026	03/20/2026			
Status	Assigned Group	Assigned Member	Associated Form	
Completed	NM - Water Reuse & Pipeline Team	Carlos Trevino	13683241	
Comments				

Last Modified By

Jorge Gutierrez

Created By

James Kelley

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:

Schedule

Schedule ID:

671

Schedule Name:

Weekly

Schedule Counter:

1

Schedule Period:

WEEK

Program Type:

Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				13683241
Scheduled	Completed			
03/15/2026	03/13/2026			
Status	Assigned Group	Assigned Member	Associated Form	
Completed	NM - Water Reuse & Pipeline Team	James Kelley	13645689	
Comments				

Last Modified By
James Kelley

Created By
Juan Elizondo

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				13645689
Scheduled	Completed			
03/11/2026	03/08/2026			
Status	Assigned Group	Assigned Member	Associated Form	
Completed	NM - Water Reuse & Pipeline Team	Juan Elizondo	13598988	
Comments				

Last Modified By
Juan Elizondo

Created By
Jorge Gutierrez

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				13598988
Scheduled	Completed			
03/02/2026	03/04/2026			
Status	Assigned Group	Assigned Member	Associated Form	
Completed	NM - Water Reuse & Pipeline Team	Jesse Terrazas	13566892	

Comments

Last Modified By

Jorge Gutierrez

Created By

Carlos Trevino

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				13566892
Scheduled	Completed			
02/23/2026	02/23/2026			
Status	Assigned Group	Assigned Member	Associated Form	
Completed	NM - Water Reuse & Pipeline Team	Carlos Trevino	13570101	
Comments				

Last Modified By
Carlos Trevino

Created By
Ricardo Villegas

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property		Property ID	
JT REUSE PIT		143051000	
Form Description		Form ID	
Reuse Pit Inspection - NM		13570101	
Scheduled	Completed		
02/21/2026	02/16/2026		
Status	Assigned Group	Assigned Member	Associated Form
Completed	NM - Water Reuse & Pipeline Team	Ricardo Villegas	13522788
Comments			

Last Modified By

Ricardo Villegas

Created By

Ashley Kungle

General

Visual inspection
conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of
oil on the surface of the
recycling containment?:

No

Is there at least 3 feet of
freeboard at the
containment?:

Yes

Is leak detection system
working properly?:

Yes

Attachments:

Schedule

Schedule ID:

671

Schedule Name:

Weekly

Schedule Counter:

1

Schedule Period:

WEEK

Program Type:

Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				13496818
Scheduled	Completed			
02/03/2026	02/02/2026			
Status	Assigned Group	Assigned Member	Associated Form	
Completed	NM - Water Reuse & Pipeline Team	Jorge Gutierrez	13457843	

Comments

Last Modified By

Ricardo Villegas

Created By

Jorge Gutierrez

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				13457843
Scheduled	Completed			
01/26/2026	01/27/2026			
Status	Assigned Group	Assigned Member	Associated Form	
Completed	NM - Water Reuse & Pipeline Team	Jorge Gutierrez	13428853	

Comments

Last Modified By

Jorge Gutierrez

Created By

Alan Ramirez

General

Visual inspection conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of oil on the surface of the recycling containment?:

No

Is there at least 3 feet of freeboard at the containment?:

Yes

Is leak detection system working properly?:

Yes

Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				13428853
Scheduled	Completed			
01/19/2026	01/19/2026			
Status	Assigned Group	Assigned Member	Associated Form	
Completed	NM - Water Reuse & Pipeline Team	Alan Ramirez	13409037	
Comments				

Last Modified By
Alan Ramirez

Created By
Carlos Trevino

General

Visual inspection conducted:	Bird Deterrent Issue:	Repair Request:	Berm or Line issue:
Yes	Yes	Bird Deterrents sound distorted.	No
Fence Issues:	Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:
No	No	Yes	Yes
Attachments:			

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				13409037
Scheduled	Completed			
01/12/2026	01/12/2026			
Status	Assigned Group	Assigned Member	Previous Form	
Completed	NM - Water Reuse & Pipeline Team	Carlos Trevino	13390800	
Comments				

Last Modified By
Carlos Trevino

Created By
Matt Dee

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				13390800
Scheduled	Completed			
01/05/2026	01/05/2026			
Status	Assigned Group	Assigned Member	Previous Form	
Completed	NM - Water Reuse & Pipeline Team	Matt Dee	13367905	
Comments				

Last Modified By
Matt Dee

Created By
Matt Dee

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly		Unscheduled	EOG Voluntary



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property			Property ID
JT REUSE PIT			143051000
Form Description			Form ID
Reuse Pit Inspection - NM			13367905
Scheduled	Completed		
12/29/2025	12/30/2025		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Matt Dee	13345917
Comments			

Last Modified By
Matt Dee

Created By
James Kelley

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly		Unscheduled	EOG Voluntary



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property			Property ID
JT REUSE PIT			143051000
Form Description			Form ID
Reuse Pit Inspection - NM			13345917
Scheduled	Completed		
12/22/2025	12/22/2025		
Status	Assigned Group	Assigned Member	
Completed	NM - Water Reuse & Pipeline Team	James Kelley	
Comments			

Last Modified By
James Kelley

Created By
Jorge Gutierrez

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly		Unscheduled	EOG Voluntary



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				13238143
Scheduled	Completed			
11/20/2025	11/24/2025			
Status	Assigned Group	Assigned Member	Previous Form	
Completed	NM - Water Reuse & Pipeline Team	Ricardo Villegas	13018247	
Comments				
-Sched Dt Update-				

Last Modified By
Ricardo Villegas

Created By
Ricardo Villegas

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				13018247
Scheduled	Completed			
10/23/2025	11/10/2025			
Status	Assigned Group	Assigned Member	Previous Form	
Completed	NM - Water Reuse & Pipeline Team	Ricardo Villegas	12964605	
Comments				
-Sched Dt Update-				

Last Modified By
Ricardo Villegas**Created By**
James Kelley**General**

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property	JT REUSE PIT		Property ID	143051000
Form Description	Reuse Pit Inspection - NM		Form ID	13132514
Scheduled	10/13/2025	Completed	10/13/2025	
Status	Completed	Assigned Group	NM - Water Reuse & Pipeline Team	Assigned Member
Comments	Inspection complete			

Last Modified By
Alex Madrid

Created By
Alex Madrid

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				12964605
Scheduled	Completed			
09/15/2025	09/15/2025			
Status	Assigned Group	Assigned Member	Previous Form	
Completed	NM - Water Reuse & Pipeline Team	Cody Williams	12925560	
Comments				

Last Modified By

James Kelley

Created By

James Kelley

General

Visual inspection
conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of
oil on the surface of the
recycling containment?:

No

Is there at least 3 feet of
freeboard at the
containment?:

Yes

Is leak detection system
working properly?:

Yes

Attachments:

Schedule

Schedule ID:

671

Schedule Name:

Weekly

Schedule Counter:

1

Schedule Period:

WEEK

Program Type:

Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				12925560
Scheduled	Completed			
09/01/2025	09/01/2025			
Status	Assigned Group	Assigned Member	Previous Form	
Completed	NM - Water Reuse & Pipeline Team	Cody Williams	12883628	
Comments				

Last Modified By
James Kelley

Created By
James Kelley

General

Visual inspection conducted:	Bird Deterrent Issue:	Berm or Line issue:	Fence Issues:
Yes	No	No	No
Is there a visible layer of oil on the surface of the recycling containment?:	Is there at least 3 feet of freeboard at the containment?:	Is leak detection system working properly?:	Attachments:
No	Yes	Yes	

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property			Property ID
JT REUSE PIT			143051000
Form Description			Form ID
Reuse Pit Inspection - NM			12883628
Scheduled	Completed		
08/18/2025	08/18/2025		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team		12865891
Comments			

Last Modified By
James Kelley

Created By
James Kelley

General

Visual inspection conducted:
Yes

Bird Deterrent Issue:
No

Berm or Line issue:
No

Fence Issues:
No

Is there a visible layer of oil on the surface of the recycling containment?:
No

Is there at least 3 feet of freeboard at the containment?:
Yes

Is leak detection system working properly?:
Yes

Attachments:

Schedule

Schedule ID:	Schedule Name:	Schedule Counter:	Schedule Period:	Program Type:
671	Weekly	1	WEEK	Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property			Property ID
JT REUSE PIT			143051000
Form Description			Form ID
Reuse Pit Inspection - NM			12865891
Scheduled	Completed		
08/04/2025	08/04/2025		
Status	Assigned Group	Assigned Member	Previous Form
Completed	NM - Water Reuse & Pipeline Team	Joel Najjar	12753894
Comments			

Last Modified By

James Kelley

Created By

Joel Najjar

General

Visual inspection
conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of
oil on the surface of the
recycling containment?:

No

Is there at least 3 feet of
freeboard at the
containment?:

Yes

Is leak detection system
working properly?:

Yes

Attachments:

Schedule

Schedule ID:

671

Schedule Name:

Weekly

Schedule Counter:

1

Schedule Period:

WEEK

Program Type:

Water Reuse



Site ID: 61994

Site Name: JT REUSE PIT

Reuse Pit Inspection - NM

Property				Property ID
JT REUSE PIT				143051000
Form Description				Form ID
Reuse Pit Inspection - NM				12753894
Scheduled	Completed			
07/28/2025	07/29/2025			
Status	Assigned Group	Assigned Member	Previous Form	
Completed	NM - Water Reuse & Pipeline Team	Joel Najjar	12747580	
Comments				

Last Modified By

Joel Najjar

Created By

Cody Williams

General

Visual inspection
conducted:

Yes

Bird Deterrent Issue:

No

Berm or Line issue:

No

Fence Issues:

No

Is there a visible layer of
oil on the surface of the
recycling containment?:

No

Is there at least 3 feet of
freeboard at the
containment?:

Yes

Is leak detection system
working properly?:

Yes

Attachments:

Schedule

Schedule ID:

671

Schedule Name:

Weekly

Schedule Counter:

1

Schedule Period:

WEEK

Program Type:

Water Reuse



Site ID: 61994
Site Name: JT REUSE PIT

Reuse Pit Inspection Work Order

Property		Property ID	
JT REUSE PIT		143051000	
Form Description		Form ID	
Reuse Pit Inspection Work Order		14542284	
Scheduled	Completed		
06/12/2026	06/16/2026		
Status	Assigned Group	Assigned Member	Associated Form
Completed	NM - Water Reuse & Pipeline Special Projects		14468328
Comments			Parent Form
			14468328

Last Modified By	Created By
Ryan Eldridge	Michael Lopez

Repair

Failed Audit:	Repair Request:	Repair Description:
Bird Deterrent Issue	Sw corner bird deterrent battery needs to be replaced	repaired deterrent



Site ID: 61994
Site Name: JT REUSE PIT

Reuse Pit Inspection Work Order

Property		Property ID	
JT REUSE PIT		143051000	
Form Description		Form ID	
Reuse Pit Inspection Work Order		13457844	
Scheduled	Completed		
01/19/2026	01/19/2026		
Status	Assigned Group	Assigned Member	Associated Form
Completed	NM - Water Reuse & Pipeline Special Projects	Alan Ramirez	13428853
Comments			Parent Form
This has been repaired			13428853

Last Modified By
James Kelley

Created By
Alan Ramirez

Repair

Failed Audit:	Repair Request:	Repair Description:
Bird Deterrent Issue	Bird Deterrents sound distorted.	This has been repaired

Venegas, Victoria, EMNRD

From: Venegas, Victoria, EMNRD
Sent: Thursday, July 9, 2026 10:16 AM
To: Morgan_HRNCIRIK@eogresources.com
Subject: 2RF-109 JT PIT [fMLB1722856120]
Attachments: C-147 2RF-109 JT PIT [fMLB1722856120] 07.09.2026.pdf

2RF-109 JT PIT [fMLB1722856120]

Good morning Ms. Hrncirik.

NMOCD has reviewed the registration/permit annual extension request for 2RF-109 JT PIT [fMLB1722856120], received from [7377] EOG RESOURCES INC on 06/22/2026, Application ID **598114**. The registration/permit extension request is approved with the following conditions of approval:

- 2RF-109 JT PIT [FMLB1722856120] is approved for one (1) year of operation from the date of the previous registration/permit expiration date of 07/27/2026. The new registration/permit expiration date is 07/27/2027.
- [7377] EOG RESOURCES INC will continue to operate, maintain, and close the 2RF-109 JT PIT [FMLB1722856120] in compliance with 19.15.34 NMAC, to include but not limited to the performance of weekly inspections regardless of fluid levels in the containment; recording of detailed inspection reports; removal of debris, foreign objects and oil from the containment; and monthly reporting of recycling and reuse of produced water, drilling fluids, and liquid oil field waste via from C-148, even if there is zero activity.
- [7377] EOG RESOURCES INC will maintain a liquid level in the containment that is at least equal to the weight of the liner plus 20%. [7377] EOG RESOURCES INC may maintain a higher liquid level if they choose.
- If less than 20% of the total fluid capacity is utilized every consecutive six months, operation of the facility is considered ceased and notification of cessation of operations should be sent electronically to OCD Permitting. A request to extend the cessation of operations, not to exceed six months, may be submitted using a C-147 long form through OCD Permitting.
- The recycling containment is bonded pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC. Water reused and recycled from 2RF-109 JT PIT [FMLB1722856120] is limited to wells owned or operated by [7377] EOG RESOURCES INC.
- A minimum of 3-feet freeboard must be maintained in the recycling containment at all times.
- [7377] EOG RESOURCES INC will comply with 19.15.29 NMAC Releases in the event of any release of produced water or produced water or other oil field wastes at 2RF-109 JT PIT [FMLB1722856120]. [7377] EOG RESOURCES INC will comply with all OCD rules.
- [7377] EOG RESOURCES INC must perform weekly inspections of the containment and leak detection system.
- If [7377] EOG RESOURCES INC wishes to extend the registration/permit past 7/27/2027, a registration/permit extension request must be submitted to OCD. Extension requests are reviewed on a case-by-case basis and evaluated on their merit. Extensions are considered for a maximum length of one year. Additional requests must be submitted to OCD through OCD Permitting on a Form C-147 as an Extension request and should include a formal extension request letter, a summary of the prior registration/permit period inspection reports, and the copies of the detailed inspection records for the prior permit period. The extension request should be submitted no later than 06/27/2027.

Please let me know if you have any additional questions.

Best regards,

Victoria Venegas • Senior Environmental Scientist
EMNRD - Oil Conservation Division
506 W. Texas Ave. Artesia, NM 88210
575.909.0269 | Victoria.Venegas@emnrd.nm.gov

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 598114

CONDITIONS

Operator: EOG RESOURCES INC 5509 Champions Drive Midland, TX 79706	OGRID: 7377
	Action Number: 598114
	Action Type: [C-147] Water Recycle Long (C-147L)

CONDITIONS

Created By	Condition	Condition Date
vvenegas	• 2RF-109 JT PIT [FMLB1722856120] is approved for one (1) year of operation from the date of the previous registration/permit expiration date of 07/27/2026. The new registration/permit expiration date is 07/27/2027. • If [7377] EOG RESOURCES INC wishes to extend the registration/permit past 7/27/2027, a registration/permit extension request must be submitted to OCD no later than 06/27/2027.	7/9/2026