

Daily Inspection Form
Sundance West

Date:

11/1/25

Print Name:

Daisy Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	☒					D ✓	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						D ✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						D ✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						D ✓	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						D ✓	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)						D ✓	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)						D ✓	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						D ✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)						D ✓	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)						D ✓	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)						D ✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)						D ✓	
Pond levels three-foot free board						D ✓	

Daily Inspection Form
Sundance West

Date:

11/21/25

Print Name:

Drew Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	☒					D ✓	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						D ✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						D ✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						D ✓	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						D ✓	
Vehicle Monitoring (H2S) (Vol. II - Sec.2- Pg.94)						D ✓	
Waste Screening and Forms (Vol. II - Sec.2- Pg.94)						D ✓	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						D ✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec.2- Pg.92)						D ✓	
Facility H2S Monitoring (Vol. II - Sec.3- Pg.127)						D ✓	
Evaporation Pond Tests-pH (Vol. II - Sec.3- Pg.130)-O2 (Vol. II - Sec.3- Pg.131)						D ✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)						D ✓	
Pond levels three-foot free board						D ✓	

Daily Inspection Form
Sundance West

Date:

11/2/25

Print Name:

Dustin Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
☒	☐	☐	☐	☐	Item		
					Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	D	
					Dust Control (Vol. II - Sec.4.3 - Pg.19)	D	
					Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)	D	
					Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)	D	
					Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)	D	
					Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)	D	
					Waste Screening and Forms (Vol. II - Sec 2- Pg.94)	D	
					Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)	D	
					Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)	D	
					Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)	D	
					Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)	D	
					Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)	D	
					Pond levels three-foot free board	D	

Daily Inspection Form
Sundance West

Date:

11/4/25

Print Name:

David Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
☒	☐	☐	☐	☐	Item		
					Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)	D ✓	
					Dust Control (Vol. II - Sec. 4.3 - Pg. 19)	D ✓	
					Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)	D ✓	
					Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)	D ✓	
					Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)	D ✓	
					Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)	D ✓	
					Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)	D ✓	
					Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)	D ✓	
					Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)	D ✓	
					Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)	D ✓	
					Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-O2 (Vol. II - Sec. 3 - Pg. 131)	D ✓	
					Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg. 223)	D ✓	
					Pond levels three-foot free board	D ✓	

Daily Inspection Form
Sundance West

Date:

11/5/25

Print Name:

Drew Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	☒					☒	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						☒	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						☒	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						☒	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						☒	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)						☒	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)						☒	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						☒	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)						☒	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)						☒	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)						☒	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)						☒	
Pond levels three-foot free board						☒	

Daily Inspection Form
Sundance West

Date:

11/6/25

Print Name:

Daisy Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	☒					D	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						D	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						D	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						D	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						D	
Vehicle Monitoring (H2S) (Vol. II - Sec.2- Pg.94)						D	
Waste Screening and Forms (Vol. II - Sec.2- Pg.94)						D	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						D	
Temporary Parking Inspection for Leaks (Vol. II - Sec.2- Pg.92)						D	
Facility H2S Monitoring (Vol. II - Sec.3- Pg.127)						D	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)						D	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)						D	
Pond levels three-foot free board						D	

Daily Inspection Form
Sundance West

Date:

11/7/25

Print Name:

Doris Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)						D	
Dust Control (Vol. II - Sec. 4.3 - Pg. 19)						D	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)						D	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)						D	
Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)						D	
Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)						D	
Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)						D	
Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)						D	
Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)						D	
Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)						D	
Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-O2 (Vol. II - Sec. 3 - Pg. 131)						D	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg. 223)						D	
Pond levels three-foot free board						D	

Daily Inspection Form
Sundance West

Date:

11/8/25

Print Name:

Doris Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	☒					D	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						D	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						D	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						D	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						D	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)						D	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)						D	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						D	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)						D	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)						D	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)						D	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)						D	
Pond levels three-foot free board						D	

Daily Inspection Form
Sundance West

Date:

11/9/25

Print Name:

Darius Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
Item							
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)					D	/	
Dust Control (Vol. II - Sec.4.3 - Pg.19)					D	/	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)					D	/	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)					D	/	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)					D	/	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)					D	/	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)					D	/	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)					D	/	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)					D	/	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)					D	/	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)					D	/	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)					D	/	
Pond levels three-foot free board					D	/	

Daily Inspection Form
Sundance West

Date:

11/10/25

Print Name:

Dawn Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)	☒					☒	
Dust Control (Vol. II - Sec. 4.3 - Pg. 19)						☒	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)						☒	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)						☒	
Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)						☒	
Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)						☒	
Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)						☒	
Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)						☒	
Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)						☒	
Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)						☒	
Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-O2 (Vol. II - Sec. 3 - Pg. 131)						☒	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2 - Pg. 223)						☒	
Pond levels three-foot free board						☒	

Daily Inspection Form
Sundance West

Date:

11/11/25

Print Name:

Dani Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	☒					☒	
Dust Control (Vol. II - Sec.4.3 - Pg.19)	☒					☒	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)	☒					☒	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)	☒					☒	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)	☒					☒	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)	☒					☒	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)	☒					☒	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)	☒					☒	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)	☒					☒	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)	☒					☒	
Evaporation Pond Tests-pH (Vol. II - Sec 3- Pg.130)-O2 (Vol. II - Sec 3- Pg.131)	☒					☒	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)	☒					☒	
Pond levels three-foot free board	☒					☒	

Daily Inspection Form
Sundance West

Date:

11/12/25

Print Name:

Dustin Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
Item							
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)					D	✓	
Dust Control (Vol. II - Sec.4.3 - Pg.19)					D	✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)					D	✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)					D	✓	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)					D	✓	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)					D	✓	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)					D	✓	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)					D	✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)					D	✓	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)					D	✓	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)					D	✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)					D	✓	
Pond levels three-foot free board					D	✓	

Daily Inspection Form
Sundance West

Date:

11/13/25

Print Name:

Dessi Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
Item							
Vehicle Screening (H2S) (Vol. II - Sec.4:2 - Pg.19)					D	✓	
Dust Control (Vol. II - Sec.4.3 - Pg.19)					D	✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)					D	✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)					D	✓	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)					D	✓	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)					D	✓	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)					D	✓	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)					D	✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)					D	✓	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)					D	✓	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)					D	✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)					D	✓	
Pond levels three-foot free board					D	✓	

Daily Inspection Form
Sundance West

Date:

11/14/25

Print Name:

David Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	D	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)						D	✓	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						D	✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						D	✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						D	✓	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						D	✓	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)						D	✓	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)						D	✓	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						D	✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)						D	✓	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)						D	✓	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)						D	✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)						D	✓	
Pond levels three-foot free board						D	✓	

Daily Inspection Form
Sundance West

Date:

11/15/25

Print Name:

Dawn Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)						☒	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						☒	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						☒	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						☒	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						☒	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)						☒	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)						☒	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						☒	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)						☒	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)						☒	
Evaporation Pond Tests-pH (Vol. II - Sec 3- Pg.130)-O2 (Vol. II - Sec 3- Pg.131)						☒	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)						☒	
Pond levels three-foot free board						☒	

Daily Inspection Form
Sundance West

Date:

11/16/25

Print Name:

Dawn Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	☒					D	
Dust Control (Vol. II - Sec.4.3 - Pg.19)	☒					D	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)	☒					D	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)	☒					D	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)	☒					D	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)	☒					D	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)	☒					D	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)	☒					D	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)	☒					D	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)	☒					D	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)	☒					D	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)	☒					D	
Pond levels three-foot free board	☒					D	

Daily Inspection Form
Sundance West

Date:

11/17/25

Print Name:

Dany Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
☒					Item		
					Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	D	
					Dust Control (Vol. II - Sec.4.3 - Pg.19)	D	
					Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)	D	
					Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)	D	
					Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)	D	
					Vehicle Monitoring (H2S) (Vol. II - Sec.2- Pg.94)	D	
					Waste Screening and Forms (Vol. II - Sec.2- Pg.94)	D	
					Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)	D	
					Temporary Parking Inspection for Leaks (Vol. II - Sec.2- Pg.92)	D	
					Facility H2S Monitoring (Vol. II - Sec.3- Pg.127)	D	
					Evaporation Pond Tests-pH (Vol. II- Sec.3- Pg.130)-O2 (Vol. II- Sec.3- Pg.131)	D	
					Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)	D	
					Pond levels three-foot free board	D	

Daily Inspection Form
Sundance West

Date:

11/18/25

Print Name:

Dawn Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)						D	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						D	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						D	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						D	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						D	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)						D	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)						D	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						D	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)						D	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)						D	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)						D	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)						D	
Pond levels three-foot free board						D	

Daily Inspection Form
Sundance West

Date:

11/19/25

Print Name:

Dustin Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
Item							
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)					D	✓	
Dust Control (Vol. II - Sec.4.3 - Pg.19)					D	✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)					D	✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)					D	✓	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)					D	✓	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)					D	✓	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)					D	✓	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)					D	✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)					D	✓	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)					D	✓	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)					D	✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)					D	✓	
Pond levels three-foot free board					D	✓	

Daily Inspection Form
Sundance West

Date:

11/20/25

Print Name:

Dale Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
☒					Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)	D	
					Dust Control (Vol. II - Sec. 4.3 - Pg. 19)	D	
					Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)	D	
					Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)	D	
					Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)	D	
					Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)	D	
					Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)	D	
					Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)	D	
					Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)	D	
					Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)	D	
					Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-O2 (Vol. II - Sec. 3 - Pg. 131)	D	
					Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg. 223)	D	
					Pond levels three-foot free board	D	

Daily Inspection Form
Sundance West

Date:

11/21/25

Print Name:

Drew Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
Item							
Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)					D	✓	
Dust Control (Vol. II - Sec. 4.3 - Pg. 19)					D	✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)					D	✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)					D	✓	
Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)					D	✓	
Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)					D	✓	
Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)					D	✓	
Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)					D	✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)					D	✓	
Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)					D	✓	
Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-O2 (Vol. II - Sec. 3 - Pg. 131)					D	✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg. 223)					D	✓	
Pond levels three-foot free board					D	✓	

Daily Inspection Form
Sundance West

Date:

11/22/25

Print Name:

Drew Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
Item							
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)					D	✓	
Dust Control (Vol. II - Sec.4.3 - Pg.19)					D	✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)					D	✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)					D	✓	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)					D	✓	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)					D	✓	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)					D	✓	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)					D	✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)					D	✓	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)					D	✓	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)					D	✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)					D	✓	
Pond levels three-foot free board					D	✓	

Daily Inspection Form
Sundance West

Date:

11/23/25

Print Name:

Doris Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	☒					D	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						D	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						D	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						D	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						D	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)						D	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)						D	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						D	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)						D	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)						D	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)						D	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)						D	
Pond levels three-foot free board						D	

Daily Inspection Form
Sundance West

Date:

11/24/25

Print Name:

Dawn Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	☒					D	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						D	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						D	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						D	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						D	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)						D	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)						D	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						D	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)						D	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)						D	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)						D	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)						D	
Pond levels three-foot free board						D	

Daily Inspection Form
Sundance West

Date:

11/25/25

Print Name:

Dewey Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
☒					Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	D ✓	
					Dust Control (Vol. II - Sec.4.3 - Pg.19)	D ✓	
					Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)	D ✓	
					Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)	D ✓	
					Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)	D ✓	
					Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)	D ✓	
					Waste Screening and Forms (Vol. II - Sec 2- Pg.94)	D ✓	
					Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)	D ✓	
					Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)	D ✓	
					Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)	D ✓	
					Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)	D ✓	
					Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)	D ✓	
					Pond levels three-foot free board	D ✓	

Daily Inspection Form
Sundance West

Date:

11/26/25

Print Name:

Dani Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
☒					Item		
					Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	<u>✓</u>	
					Dust Control (Vol. II - Sec.4.3 - Pg.19)	<u>✓</u>	
					Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)	<u>✓</u>	
					Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)	<u>✓</u>	
					Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)	<u>✓</u>	
					Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)	<u>✓</u>	
					Waste Screening and Forms (Vol. II - Sec 2- Pg.94)	<u>✓</u>	
					Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)	<u>✓</u>	
					Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)	<u>✓</u>	
					Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)	<u>✓</u>	
					Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)	<u>✓</u>	
					Evaporation Pond Oil Inspection (Vol. Section 6- Subsect 2.2- Pg.223)	<u>✓</u>	
					Pond levels three-foot free board	<u>✓</u>	

Daily Inspection Form
Sundance West

Date:

11/27/25

Print Name:

Dawn Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
☒					Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	D ✓	
					Dust Control (Vol. II - Sec.4.3 - Pg.19)	D ✓	
					Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)	D ✓	
					Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)	D ✓	
					Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)	D ✓	
					Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)	D ✓	
					Waste Screening and Forms (Vol. II - Sec 2- Pg.94)	D ✓	
					Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)	D ✓	
					Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)	D ✓	
					Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)	D ✓	
					Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)	D ✓	
					Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)	D ✓	
					Pond levels three-foot free board	D ✓	

Daily Inspection Form
Sundance West

Date:

11/28/25

Print Name:

Drew Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
Item							
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)					D	✓	
Dust Control (Vol. II - Sec.4.3 - Pg.19)					D	✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)					D	✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)					D	✓	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)					D	✓	
Vehicle Monitoring (H2S) (Vol. II - Sec.2 - Pg.94)					D	✓	
Waste Screening and Forms (Vol. II - Sec.2 - Pg.94)					D	✓	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)					D	✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec.2 - Pg.92)					D	✓	
Facility H2S Monitoring (Vol. II - Sec.3 - Pg.127)					D	✓	
Evaporation Pond Tests-pH (Vol. II - Sec.3 - Pg.130)-O2 (Vol. II - Sec.3 - Pg.131)					D	✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)					D	✓	
Pond levels three-foot free board					D	✓	

Daily Inspection Form
Sundance West

Date:

11/29/25

Print Name:

Dey Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	☒					D	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						D	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						D	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						D	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						D	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)						D	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)						D	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						D	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)						D	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)						D	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)						D	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)						D	
Pond levels three-foot free board							

**Daily Inspection Form
Sundance West**

Date:

11/30/25

Print Name:

Dani Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual	Item	Satisfactory	Action Required
☒					Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)	☒	
					Dust Control (Vol. II - Sec. 4.3 - Pg. 19)	☒	
					Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)	☒	
					Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)	☒	
					Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)	☒	
					Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)	☒	
					Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)	☒	
					Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)	☒	
					Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)	☒	
					Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)	☒	
					Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-O2 (Vol. II - Sec. 3 - Pg. 131)	☒	
					Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg. 223)	☒	
					Pond levels three-foot free board	☒	

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/1/25

Inspector(s):

Time: 11:50 amDouglas Romero**Weather:**Temperature 64 deg. F

Precipitation (last 24 hours) _____ inches

Skies FOUWind Speed 10 mphWind Direction NE (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.I.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/2/25

Inspector(s):

Time: 7:15 amDrusil Romero**Weather:**Temperature 48 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 8 mphWind Direction S (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/3/25Time: 9:50 am

Inspector(s):

Deysi Romero**Weather:**Temperature 72 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 9 mphWind Direction S (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

that a sample has been
 taken and referenced by

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/4/25

Inspector(s):

Time: 8:56amDeysi Romero**Weather:**Temperature 63 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 6 mphWind Direction SSW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

Water Sample has been
 taken and referenced by

Water Sample has been
 taken and referenced by

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/5/25

Inspector(s):

Time: 6:50 amDavis Romero**Weather:**Temperature 46 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 7 mphWind Direction WSW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/6/25

Inspector(s):

Time: 6:56amDaisy Romero**Weather:**Temperature 41 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 6 mphWind Direction WNW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/7/25

Inspector(s):

Time: 8:50amDeysi Romero**Weather:**Temperature 63 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 18 mphWind Direction NNE (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

that a Sample has been
 taken and referenced to

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/8/25

Inspector(s):

Time: 9:50 amDeusi Romero**Weather:**Temperature 75 deg. F

Precipitation (last 24 hours) _____ inches

Skies FAVWind Speed 16 mphWind Direction WNW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/9/25

Inspector(s):

Time: 7:50 amDavis, Romero**Weather:**Temperature 45 deg. F

Precipitation (last 24 hours) _____ inches

Skies FCUWind Speed 14 mphWind Direction N (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

not a Sample has been
 taken as referenced by

NOTES:

Page _____ of _____

Inspector(s):

Deusi Romero

Precipitation (last 24 hours) _____ inches

Wind Speed 6 mph

Wind Direction CALM (direction blowing from)

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/11/25

Inspector(s):

Time: 8:50amDouglas Romero**Weather:**Temperature 57 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 12 mphWind Direction SSW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/12/25

Inspector(s):

Time: 6:50amDouglas Romero**Weather:**Temperature 39 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 7 mphWind Direction WNW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/13/25

Inspector(s):

Time: 6:50 amDouglas Romero**Weather:**Temperature 41 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 6 mphWind Direction N (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

that a Sample has been
 collected as a reference only

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/14/25

Inspector(s):

Time: 8:50amDeysi Romero**Weather:**Temperature 70 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 6 mphWind Direction VAR (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/15/25

Inspector(s):

Time: 2:50 pmDouglas Romero**Weather:**Temperature 86 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 9 mphWind Direction WSW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/16/25

Inspector(s):

Time: 8:50amDouglas Romero**Weather:**Temperature 73 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 10 mphWind Direction WNW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

has a Sample has been
 collected for reference

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/17/25Time: 1:50 pm

Inspector(s):

Drus. Romero**Weather:**Temperature 75 deg. FSkies Fair / WindyWind Speed 22 mphWind Direction SW (direction blowing from)

Precipitation (last 24 hours) _____ inches

NOTES:

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/18/25

Inspector(s):

Time: 7:50 amDeusi Romero**Weather:**Temperature 57 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 5 mphWind Direction W (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

note: Sample has been collected and referenced by

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/19/25

Inspector(s):

Time: 8:50 amDaisy Romero**Weather:**Temperature 63 deg. F

Precipitation (last 24 hours) _____ inches

Skies CloudyWind Speed 0 mphWind Direction CALM (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/20/25

Inspector(s):

Time: 10:50amDeysi Ramiro**Weather:**Temperature 61 deg. F

Precipitation (last 24 hours) _____ inches

Skies cloudyWind Speed 6 mphWind Direction VAR (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/21/25

Inspector(s):

Time: 6:50 amDouglas Romero**Weather:**Temperature 41 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 8 mphWind Direction WSW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/22/25

Inspector(s):

Time: 11:50amDouglas Romero**Weather:**Temperature 61 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 5 mphWind Direction SSE (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/23/25

Inspector(s):

Time: 11:50 amDeusi Romero**Weather:**Temperature 68 deg. FSkies Mostly CloudyWind Speed 14 mphWind Direction S (direction blowing from)

Precipitation (last 24 hours) _____ inches

NOTES:

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/24/25

Inspector(s):

Time: 12:50 pmDouglas Romero**Weather:**Temperature 64 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 14 mphWind Direction WNW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/25/25

Inspector(s):

Time: 8:50amDeusi Romero**Weather:**Temperature 59 deg. F

Precipitation (last 24 hours) _____ inches

Skies FOVWind Speed 14 mphWind Direction WNW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page _____ of _____

Date: 11/26/25

Inspector(s):

Time: 6.50 am

Deusi Pomvū

Weather:

Temperature 41 deg. F

Precipitation (last 24 hours) 0.00 inches

Skies Cloudy

Wind Speed 10 mph

Wind Direction ENE (direction blowing from)

NOTES:

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.I.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/27/25

Inspector(s):

Time: 7:50amDeys. Romero**Weather:**Temperature 37 deg. F

Precipitation (last 24 hours) _____ inches

Skies FWVWind Speed 6 mphWind Direction NNE (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

not a sample has been
 collected

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/28/25

Inspector(s):

Time: 11:50 amDeysi Romero**Weather:**Temperature 57 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 17 mphWind Direction S (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.I.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/29/25

Inspector(s):

Time: 10:59amDavis Romero**Weather:**Temperature 70 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 18 mphWind Direction NW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

he. as while has been
 to the repair of.

at the time
 of the inspection.

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/30/25

Inspector(s):

Time: 11:50 amDaisy Romero**Weather:**Temperature 34 deg. F

Precipitation (last 24 hours) _____ inches

Skies cloudyWind Speed 8 mphWind Direction ENE (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM


Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

Office Pits

Date: 11/1/25

Before:
After:




9
Before:
After:

WEST


Before:
After:

10



Before:
After:


Before:
After:



7
Before:
After:

Before:
After:

8



Before:
After:

SOUTH

NORTH


Before:
After:



5
Before:
After:


Before:
After:

6



Before:
After:


Before:
After:



3
Before:
After:


Before:
After:

4



Before:
After:


Before:
After:



1
Before:
After:

Before:
After:

2



Before:
After:

EAST



Office Pits

Date: 11/2/25

Before:
After:

9

Before:
After:

Before:
After:

7

Before:
After:

Before:
After:

5

Before:
After:

Before:
After:

3

Before:
After:

Before:
After:

1

Before:
After:

WEST

Before:
After:

10

Before:
After:

8

Before:
After:

6

Before:
After:

4

Before:
After:

2

Before:
After:

NORTH





EAST



Office Pits






Date: 11/3/25

WEST


10Before:
After:Before:
After:Before:
After:9
Before:
After:Before:
After:7
Before:
After:Before:
After:8Before:
After:

NORTH

SOUTH

Before:
After:5
Before:
After:Before:
After:6Before:
After:Before:
After:3
Before:
After:Before:
After:4Before:
After:Before:
After:1
Before:
After:Before:
After:

EAST


2Before:
After:

Office Pits

Date: 11/4/25


WEST

10




Before:
After:

8




Before:
After:

6




Before:
After:

4



Before:
After:

2




Before:
After:

Before:
After:

EAST

1


Before:
After:



Before:
After:

3


Before:
After:



Before:
After:

5


Before:
After:



Before:
After:

7


Before:
After:



Before:
After:

9

Before:
After:



Before:
After:

SOUTH

NORTH




Office Pits

Date: 11/5/25

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:


EAST

1
Before:
After:




Before:
After:

3
Before:
After:



Before:
After:


5
Before:
After:



Before:
After:


SOUTH

7
Before:
After:



Before:
After:






9
Before:
After:




Before:
After:



Office Pits

Date: 11/6/25

WEST

Before:
After:Before:
After:Before:
After:Before:
After:Before:
After:8642Before:
After:Before:
After:Before:
After:Before:
After:Before:
After:

NORTH



EAST






Office Pits

Date: 11/7/25






WEST

10Before:
After:Before:
After:8Before:
After:Before:
After:

NORTH

6Before:
After:Before:
After:4Before:
After:Before:
After:2Before:
After:Before:
After:



EAST

1
Before:
After:Before:
After:3
Before:
After:Before:
After:5
Before:
After:Before:
After:7
Before:
After:Before:
After:9
Before:
After:Before:
After:




Office Pits

Date: 11/8/25




WEST

10Before:
After:Before:
After:8Before:
After:Before:
After:



NORTH

6Before:
After:Before:
After:4Before:
After:Before:
After:2Before:
After:Before:
After:

EAST

1
Before:
After:Before:
After:9
Before:
After:Before:
After:7
Before:
After:Before:
After:

SOUTH

5
Before:
After:Before:
After:3
Before:
After:Before:
After:

Office Pits

Date: 11/9/25

Before:
After:

6'0" →

0'0" →

9
Before:
After:

Before:
After:

0'0" →

0'0" →

7
Before:
After:

Before:
After:

1'5" →

1'2" →

5
Before:
After:

Before:
After:

1'4" →

1'3" →

3
Before:
After:

Before:
After:

1'2" →

1'0" →

1
Before:
After:

WEST

Before:
After:

10

← 0'0"

← 0'0"

Before:
After:

Before:
After:

8

← 0'0"

← 0'0"

Before:
After:

Before:
After:

6

← 1'3"

← 1'4"

Before:
After:

Before:
After:

4

← 1'2"

← 1'5"

Before:
After:

Before:
After:

2

← 1'3"

← 1'1"

Before:
After:

EAST




Office Pits

Date: 11/10/25

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:

EAST


1



Before:
After:

Before:
After:


9



Before:
After:

Before:
After:

7




Before:
After:

Before:
After:

SOUTH


5



Before:
After:

Before:
After:

3



Before:
After:



Before:
After:






Office Pits

Date: 11/11/25




WEST

10Before:
After:Before:
After:8Before:
After:Before:
After:



NORTH

6Before:
After:Before:
After:4Before:
After:Before:
After:2Before:
After:Before:
After:

EAST

1
Before:
After:Before:
After:9
Before:
After:Before:
After:7
Before:
After:Before:
After:

SOUTH


5
Before:
After:Before:
After:3
Before:
After:Before:
After:

Office Pits

Date: 11/12/25

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:

EAST


1



Before:
After:

Before:
After:


9



Before:
After:

Before:
After:

7




Before:
After:

Before:
After:

SOUTH


5



Before:
After:

Before:
After:

3



Before:
After:

Before:
After:




Office Pits

Date: 11/13/25

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:


EAST

1
Before:
After:




Before:
After:

3
Before:
After:



Before:
After:


5
Before:
After:



Before:
After:


SOUTH

7
Before:
After:



Before:
After:

9
Before:
After:





Before:
After:





Office Pits

Date: 11/14/25




WEST

10Before:
After:Before:
After:8Before:
After:Before:
After:


NORTH

6Before:
After:Before:
After:4Before:
After:Before:
After:2Before:
After:Before:
After:

EAST

1
Before:
After:Before:
After:3
Before:
After:Before:
After:5
Before:
After:Before:
After:

SOUTH


7
Before:
After:Before:
After:9
Before:
After:Before:
After:

Office Pits

Date: 11/15/25

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:

EAST


1



Before:
After:

Before:
After:


7



Before:
After:

Before:
After:


9



Before:
After:

Before:
After:


5



Before:
After:

Before:
After:

3



Before:
After:

Before:
After:




Office Pits

Date: 11/15/25

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:

EAST

1




Before:
After:




Before:
After:



Office Pits







Date: 11/16/25

WEST

10Before:
After:Before:
After:8

SOUTH


NORTH

Before:
After:6Before:
After:4Before:
After:2




EAST



Office Pits







Date: 11/17/25

WEST

10Before:
After:8Before:
After:

SOUTH

NORTH

Before:
After:6Before:
After:Before:
After:4Before:
After:Before:
After:2Before:
After:



EAST






Office Pits

Date: 11/18/25





WEST

10Before:
After:Before:
After:8Before:
After:Before:
After:

NORTH

6Before:
After:Before:
After:4Before:
After:Before:
After:2Before:
After:Before:
After:



EAST

1
Before:
After:Before:
After:3
Before:
After:Before:
After:5
Before:
After:Before:
After:7
Before:
After:Before:
After:9
Before:
After:Before:
After:




Office Pits

Date: 11/19/25





WEST

10Before:
After:Before:
After:8Before:
After:Before:
After:


NORTH

6Before:
After:Before:
After:4Before:
After:Before:
After:2Before:
After:Before:
After:

EAST

1
Before:
After:Before:
After:3
Before:
After:Before:
After:5
Before:
After:Before:
After:7
Before:
After:Before:
After:

SOUTH

9
Before:
After:Before:
After:

Office Pits

Date: 11/20/25

		WEST			
SOUTH	Before: After:	<u>9</u> Before: After:		<u>10</u> Before: After:	Before: After:
	Before: After:	<u>7</u> Before: After:	Before: After:	<u>8</u> Before: After:	Before: After:
	Before: After:	<u>5</u> Before: After:	Before: After:	<u>6</u> Before: After:	Before: After:
	Before: After:	<u>3</u> Before: After:	Before: After:	<u>4</u> Before: After:	Before: After:
	Before: After:	<u>1</u> Before: After:	Before: After:	<u>2</u> Before: After:	Before: After:
		EAST			




Office Pits

Date: 11/21/25

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:

EAST

1



Before:
After:



Before:
After:






Office Pits

Date: 11/22/25



WEST

10Before:
After:Before:
After:8Before:
After:Before:
After:



NORTH

6Before:
After:Before:
After:4Before:
After:Before:
After:2Before:
After:Before:
After:

EAST

9Before:
After:Before:
After:7Before:
After:Before:
After:

SOUTH


5Before:
After:Before:
After:3Before:
After:Before:
After:1Before:
After:Before:
After:

Office Pits

Date: 11/23/25

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:

EAST

1




Before:
After:




Before:
After:



Office Pits







Date: 11/24/25

WEST

10Before:
After:Before:
After:8Before:
After:

SOUTH

NORTH

Before:
After:6Before:
After:Before:
After:4Before:
After:Before:
After:2Before:
After:



EAST






Office Pits

Date: 11/25/25



WEST

10Before:
After:Before:
After:8Before:
After:Before:
After:



NORTH

6Before:
After:Before:
After:4Before:
After:Before:
After:2Before:
After:Before:
After:

EAST

9Before:
After:Before:
After:7Before:
After:Before:
After:










SOUTH

5Before:
After:Before:
After:3Before:
After:Before:
After:1Before:
After:Before:
After:

Office Pits

Date: 11/26/25

WEST

10Before:
After:Before:
After:9Before:
After:Before:
After:8Before:
After:Before:
After:7Before:
After:Before:
After:6Before:
After:Before:
After:5Before:
After:Before:
After:4Before:
After:Before:
After:3Before:
After:Before:
After:2Before:
After:Before:
After:1Before:
After:Before:
After:

EAST




Office Pits

Date: 11/27/25

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:


EAST

1
Before:
After:



Before:
After:

3
Before:
After:



Before:
After:

5
Before:
After:




Before:
After:

7
Before:
After:



Before:
After:

9
Before:
After:





Before:
After:






Office Pits

Date: 11/28/25



WEST

10Before:
After:Before:
After:8Before:
After:Before:
After:




NORTH

6Before:
After:Before:
After:4Before:
After:Before:
After:2Before:
After:Before:
After:

EAST

9Before:
After:Before:
After:7Before:
After:Before:
After:

SOUTH


5Before:
After:Before:
After:3Before:
After:Before:
After:1Before:
After:Before:
After:

Office Pits

Date: 11/29/25

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:


EAST

1
Before:
After:




Before:
After:

3
Before:
After:



Before:
After:

5
Before:
After:




Before:
After:

7
Before:
After:



Before:
After:

9
Before:
After:



Before:
After:




Office Pits

Date: 11/30/25

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:

EAST

1
Before:
After:




Before:
After:

7
Before:
After:




Before:
After:

9
Before:
After:




Before:
After:

5
Before:
After:



Before:
After:

3
Before:
After:



Before:
After:



**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590

1001 6th Street P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS****DATE:**

11/1/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'2"		
MW-36	3.0	42'	22'1"		
MW-37	3.0	39'3"	18'1"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'2"		
MW-51	3.0	65'5"	48'1"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	54'2"		
MW-73	2.0	28'	14'1"		VZ-4
MW-74	3.0	33'	22'8"		
VZ-1	2.0	27'	4'9"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	14'1"		MW-73
VZ-5	2.0	32'6"	17'1"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'1"		
MH-69	2.0	28'1"	0'1"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Box 1737

Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/2/05

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16' 5"	0' 1"		
MW-36	3.0	42'	22' 2"		
MW-37	3.0	39' 3"	18' 3"		
MW-40	3.0	29' 7"	15' 2"		
MW-41	3.0	77'	57' 3"		
MW-51	3.0	65' 5"	48' 2"		
MW-69	3.0	50' 4"	0' 1"		
MW-71	6.0	61' 9"	54' 1"		
MW-73	2.0	28'	13' 9"		VZ-4
MW-74	3.0	33'	23' 1"		
VZ-1	2.0	27'	4' 8"		PGI-8
VZ-2	2.0	38' 8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	13' 9"		MW-73
VZ-5	2.0	32' 6"	17' 1"		
VZ-6	2.0	26' 3"	0' 0"		
VZ-7	2.0	49' 8"	22' 1"		
MH-69	2.0	28' 1"	0' 2"		



SUNDANCE SERVICES WEST, INC.

Main Office: 575-394-2511

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Plant Office: 575-394-3212

Fax: 575-394-2590

Box 1737

Eunice, New Mexico 88231

1001 5th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/3/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'2"		
MW-36	3.0	42'	22'1"		
MW-37	3.0	39'3"	18'2"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'2"		
MW-51	3.0	65'5"	48'1"		
MW-69	3.0	50'4"	0'2"		
MW-71	6.0	61'9"	54'2"		
MW-73	2.0	28'	14'1"		VZ-4
MW-74	3.0	33'	23'4"		
VZ-1	2.0	27'	4'9"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	14'1"		MW-73
VZ-5	2.0	32'6"	17'1"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'1"		
MH-69	2.0	28'1"	0'1"		

SUNDANCE SERVICES WEST, INC.
ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Box 1737

Eunice, New Mexico 88231

1001 6th Street

P.O.

www.sundanceservices.com
www.sundanceservices.net
PARABO DISPOSAL FACILITY
www.sundanceservices.org
MONITOR WELLS

DATE:

11/4/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'3"		
MW-37	3.0	39'3"	18'1"		
MW-40	3.0	29'7"	15'2"		
MW-41	3.0	77'	57'3"		
MW-51	3.0	65'5"	48'2"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	54'3"		
MW-73	2.0	28'	13'8"		VZ-4
MW-74	3.0	33'	23'6"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	13'8"		MW-73
VZ-5	2.0	32'6"	17'1"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'1"		
MH-69	2.0	28'1"	0'1"		

SUNDANCE SERVICES WEST, INC.

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS**

DATE:

11/5/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'2"		
MW-36	3.0	42'	22'3"		
MW-37	3.0	39'3"	17'2"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'3"		
MW-51	3.0	65'5"	48'6"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	54'3"		
MW-73	2.0	28'	13'8"		VZ-4
MW-74	3.0	33'	23'7"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	13'8"		MW-73
VZ-5	2.0	32'6"	17'1"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'3"		
MH-69	2.0	28'1"	0'2"		



SUNDANCE SERVICES WEST, INC.

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Box 1737

Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org

MONITOR WELLS

DATE:

11/6/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'4"		
MW-37	3.0	39'3"	17'7"		
MW-40	3.0	29'7"	15'2"		
MW-41	3.0	77'	57'4"		
MW-51	3.0	65'5"	48'7"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	54'2"		
MW-73	2.0	28'	14'1"		VZ-4
MW-74	3.0	33'	24'1"		
VZ-1	2.0	27'	5'2"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	14'1"		MW-73
VZ-5	2.0	32'6"	17'1"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'1"		
MH-69	2.0	28'1"	0'1"		

SUNDANCE SERVICES WEST, INC.

Main Office: 575-394-2511

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Plant Office: 575-394-3212 Fax: 575-394-2590

Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS**

DATE:

11/7/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'2"		
MW-36	3.0	42'	22'3"		
MW-37	3.0	39'3"	17'2"		
MW-40	3.0	29'7"	15'3"		
MW-41	3.0	77'	57'2"		
MW-51	3.0	65'5"	48'8"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	54'2"		
MW-73	2.0	28'	13'8"		VZ-4
MW-74	3.0	33'	24'3"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	13'8"		MW-73
VZ-5	2.0	32'6"	17'2"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'1"		
MH-69	2.0	28'1"	0'2"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231
 PARABO DISPOSAL FACILITY
www.sundanceservices.com www.sundanceservices.net www.sundanceservices.org

1001 6th Street

P.O.

MONITOR WELLS

DATE:

11/8/05

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	6' 1"		
MW-36	3.0	42'	22'3"		
MW-37	3.0	39'3"	17'1"		
MW-40	3.0	29'7"	15'2"		
MW-41	3.0	77'	57'2"		
MW-51	3.0	65'5"	48'6"		
MW-69	3.0	50'4"	0' 1"		
MW-71	6.0	61'9"	54'1"		
MW-73	2.0	28'	13'2"		VZ-4
MW-74	3.0	33'	24'5"		
VZ-1	2.0	27'	5'0"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	13'2"		MW-73
VZ-5	2.0	32'6"	17'1"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'3"		
MH-69	2.0	28'1"	0' 1"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS**

DATE:

11/9/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'2"		
MW-36	3.0	42'	22'4"		
MW-37	3.0	39'3"	17'3"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'1"		
MW-51	3.0	65'5"	48'3"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	54'2"		
MW-73	2.0	28'	13'1"		VZ-4
MW-74	3.0	33'	24'7"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	13'1"		MW-73
VZ-5	2.0	32'6"	17'1"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'2"		
MH-69	2.0	28'1"	0'1"		

SUNDANCE SERVICES WEST, INC.
ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Box 1737

Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS**

DATE:

11/10/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16' 5"	0' 1"		
MW-36	3.0	42'	22' 3"		
MW-37	3.0	39' 3"	17' 1"		
MW-40	3.0	29' 7"	15' 2"		
MW-41	3.0	77'	57' 2"		
MW-51	3.0	65' 5"	48' 2"		
MW-69	3.0	50' 4"	0' 2"		
MW-71	6.0	61' 9"	54' 2"		
MW-73	2.0	28'	13' 4"		VZ-4
MW-74	3.0	33'	24' 8"		
VZ-1	2.0	27'	5' 1"		PGI-8
VZ-2	2.0	38' 8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	13' 4"		MW-73
VZ-5	2.0	32' 6"	16' 9"		
VZ-6	2.0	26' 3"	0' 0"		
VZ-7	2.0	49' 8"	22' 1"		
MH-69	2.0	28' 1"	0' 1"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/11/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'7"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'2"		
MW-36	3.0	42'	22'1"		
MW-37	3.0	39'3"	17'2"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'3"		
MW-51	3.0	65'5"	48'1"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	54'1"		
MW-73	2.0	28'	13'6"		VZ-4
MW-74	3.0	33'	25'1"		
VZ-1	2.0	27'	5'0"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	13'6"		MW-73
VZ-5	2.0	32'6"	16'9"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'2"		
MH-69	2.0	28'1"	0'0"		

SUNDANCE SERVICES WEST, INC.
ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Box 1737

Eunice, New Mexico 88231

1001 6th Street

P.O.

www.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**PARABO DISPOSAL FACILITY****MONITOR WELLS**

DATE:

11/12/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16' 5"	0' 1"		
MW-36	3.0	42'	22' 2"		
MW-37	3.0	39' 3"	17' 1"		
MW-40	3.0	29' 7"	15' 2"		
MW-41	3.0	77'	57' 2"		
MW-51	3.0	65' 5"	48' 2"		
MW-69	3.0	50' 4"	0' 2"		
MW-71	6.0	61' 9"	54' 1"		
MW-73	2.0	28'	13' 7"		VZ-4
MW-74	3.0	33'	25' 3'		
VZ-1	2.0	27'	5' 1"		PGI-8
VZ-2	2.0	38' 8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	13' 7"		MW-73
VZ-5	2.0	32' 6"	16' 8"		
VZ-6	2.0	26' 3"	0' 0"		
VZ-7	2.0	49' 8"	22' 1"		
MH-69	2.0	28' 1"	0' 1"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Box 1737

Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/13/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'2"		
MW-36	3.0	42'	22'1"		
MW-37	3.0	39'3"	17'2"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'2"		
MW-51	3.0	65'5"	48'1"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	54'2"		
MW-73	2.0	28'	13'8"		VZ-4
MW-74	3.0	33'	25'8"		
VZ-1	2.0	27'	5'2"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'6"		
VZ-4	2.0	28'	13'8"		MW-73
VZ-5	2.0	32'6"	16'9"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'2"		
MH-69	2.0	28'1"	0'2"		

SUNDANCE SERVICES WEST, INC.
ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Box 1737

Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS**

DATE:

11/14/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'3"		
MW-37	3.0	39'3"	17'1"		
MW-40	3.0	29'7"	15'2"		
MW-41	3.0	77'	57'1"		
MW-51	3.0	65'5"	48'2"		
MW-69	3.0	50'4"	0'2"		
MW-71	6.0	61'9"	54'1"		
MW-73	2.0	28'	13'9"		VZ-4
MW-74	3.0	33'	26'1"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'6"		
VZ-3	2.0	28'	0'6"		
VZ-4	2.0	28'	13'9"		MW-73
VZ-5	2.0	32'6"	16'9"		
VZ-6	2.0	26'3"	0'0'		
VZ-7	2.0	49'8"	22'1"		
MH-69	2.0	28'1"	0'1"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Box 1737

Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/15/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0' 2"		
MW-36	3.0	42'	22' 1"		
MW-37	3.0	39'3"	17' 2"		
MW-40	3.0	29'7"	15' 1"		
MW-41	3.0	77'	57' 2"		
MW-51	3.0	65'5"	48' 2"		
MW-69	3.0	50'4"	0' 1"		
MW-71	6.0	61'9"	54' 1"		
MW-73	2.0	28'	13' 8"		VZ-4
MW-74	3.0	33'	26' 4"		
VZ-1	2.0	27'	5' 2"		PGI-8
VZ-2	2.0	38'8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	13' 8"		MW-73
VZ-5	2.0	32'6"	16' 7"		
VZ-6	2.0	26'3"	0' 6"		
VZ-7	2.0	49'8"	22' 3"		
MH-69	2.0	28'1"	0' 2"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231
 PARABO DISPOSAL FACILITY
www.sundanceservices.com www.sundanceservices.net www.sundanceservices.org

1001 6th Street

P.O.

MONITOR WELLS

DATE:

11/16/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16' 5"	0' 1"		
MW-36	3.0	42'	22' 3"		
MW-37	3.0	39' 3"	17' 1"		
MW-40	3.0	29' 7"	15' 2"		
MW-41	3.0	77'	57' 3"		
MW-51	3.0	65' 5"	49' 1"		
MW-69	3.0	50' 4"	0' 1"		
MW-71	6.0	61' 9"	54' 2"		
MW-73	2.0	28'	13' 9"		VZ-4
MW-74	3.0	33'	26' 5"		
VZ-1	2.0	27'	5' 1"		PGI-8
VZ-2	2.0	38' 8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	13' 9"		MW-73
VZ-5	2.0	32' 6"	16' 8"		
VZ-6	2.0	26' 3"	0' 0"		
VZ-7	2.0	49' 8"	22' 1"		
MH-69	2.0	28' 1"	0' 1"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590

Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/17/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16' 5"	0' 2"		
MW-36	3.0	42'	22' 4"		
MW-37	3.0	39' 3"	17' 2"		
MW-40	3.0	29' 7"	15' 1"		
MW-41	3.0	77'	57' 2"		
MW-51	3.0	65' 5"	49' 2"		
MW-69	3.0	50' 4"	0' 2"		
MW-71	6.0	61' 9"	54' 1"		
MW-73	2.0	28'	14' 1"		VZ-4
MW-74	3.0	33'	26' 6"		
VZ-1	2.0	27'	5' 2"		PGI-8
VZ-2	2.0	38' 8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	14' 1"		MW-73
VZ-5	2.0	32' 6"	16' 9"		
VZ-6	2.0	26' 3"	0' 0"		
VZ-7	2.0	49' 8"	22' 1"		
MH-69	2.0	28' 1"	0' 2"		

SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS**

DATE:

11/18/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'3"		
MW-37	3.0	39'3"	17'2"		
MW-40	3.0	29'7"	15'2"		
MW-41	3.0	77'	57'2"		
MW-51	3.0	65'5"	47'3"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	54'2"		
MW-73	2.0	28'	14'2"		VZ-4
MW-74	3.0	33'	26'7"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	14'2"		MW-73
VZ-5	2.0	32'6"	16'9"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'2"		
MH-69	2.0	28'1"	0'1"		

SUNDANCE SERVICES WEST, INC.
ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Box 1737

Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS**

DATE:

11/19/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0' 1"		
MW-36	3.0	42'	22' 4"		
MW-37	3.0	39'3"	17' 1"		
MW-40	3.0	29'7"	15' 1"		
MW-41	3.0	77'	57' 2"		
MW-51	3.0	65'5"	49' 1"		
MW-69	3.0	50'4"	0' 1"		
MW-71	6.0	61'9"	54' 1"		
MW-73	2.0	28'	14' 3"		VZ-4
MW-74	3.0	33'	26' 8"		
VZ-1	2.0	27'	5' 2"		PGI-8
VZ-2	2.0	38'8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	14' 3"		MW-73
VZ-5	2.0	32'6"	16' 9"		
VZ-6	2.0	26'3"	0' 0"		
VZ-7	2.0	49'8"	22' 1"		
MH-69	2.0	28'1"	0' 2"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Box 1737

Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/20/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'2"		
MW-36	3.0	42'	22'3"		
MW-37	3.0	39'3"	17'2"		
MW-40	3.0	29'7"	15'2"		
MW-41	3.0	77'	57'3"		
MW-51	3.0	65'5"	49'2"		
MW-69	3.0	50'4"	0'2"		
MW-71	6.0	61'9"	54'2"		
MW-73	2.0	28'	14'2"		VZ-4
MW-74	3.0	33'	26'9"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	14'2"		MW-73
VZ-5	2.0	32'6"	16'9"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'1"		
MH-69	2.0	28'1"	0'1"		



SUNDANCE SERVICES WEST, INC.

Main Office: 575-394-2511

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Plant Office: 575-394-3212

Fax: 575-394-2590

Box 1737

Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/21/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0' 1"		
MW-36	3.0	42'	22' 2"		
MW-37	3.0	39'3"	17' 1"		
MW-40	3.0	29'7"	15' 2"		
MW-41	3.0	77'	57' 3"		
MW-51	3.0	65'5"	49' 1"		
MW-69	3.0	50'4"	0' 1"		
MW-71	6.0	61'9"	54' 1"		
MW-73	2.0	28'	14' 1"		VZ-4
MW-74	3.0	33'	27' 1"		
VZ-1	2.0	27'	5' 1"		PGI-8
VZ-2	2.0	38'8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	14' 1"		MW-73
VZ-5	2.0	32'6"	16' 9"		
VZ-6	2.0	26'3"	0' 0"		
VZ-7	2.0	49'8"	22' 1"		
MH-69	2.0	28'1"	0' 1"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS**

DATE:

11/22/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'1"		
MW-37	3.0	39'3"	17'2"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'4"		
MW-51	3.0	65'5"	49'1"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	54'2"		
MW-73	2.0	28'	14'3"		VZ-4
MW-74	3.0	33'	27'3"		
VZ-1	2.0	27'	5'2"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	14'3"		MW-73
VZ-5	2.0	32'6"	16'8"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'1"		
MH-69	2.0	28'1"	0'2"		

SUNDANCE SERVICES WEST, INC.

Main Office: 575-394-2511

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Plant Office: 575-394-3212

Fax: 575-394-2590

Box 1737

Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS**

DATE:

11/23/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16' 5"	0' 1"		
MW-36	3.0	42'	22' 2"		
MW-37	3.0	39' 3"	17' 1"		
MW-40	3.0	29' 7"	15' 2"		
MW-41	3.0	77'	57' 3"		
MW-51	3.0	65' 5"	49' 2"		
MW-69	3.0	50' 4"	0' 2"		
MW-71	6.0	61' 9"	54' 1"		
MW-73	2.0	28'	14' 1"		VZ-4
MW-74	3.0	33'	27' 4"		
VZ-1	2.0	27'	5' 2"		PGI-8
VZ-2	2.0	38' 8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	14' 1"		MW-73
VZ-5	2.0	32' 6"	16' 9"		
VZ-6	2.0	26' 3"	0' 0"		
VZ-7	2.0	49' 8"	22' 1"		
MH-69	2.0	28' 1"	0' 1"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/24/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16' 5"	0' 1"		
MW-36	3.0	42'	22' 3"		
MW-37	3.0	39' 3"	17' 1"		
MW-40	3.0	29' 7"	15' 1"		
MW-41	3.0	77'	57' 2"		
MW-51	3.0	65' 5"	49' 2"		
MW-69	3.0	50' 4"	0' 1"		
MW-71	6.0	61' 9"	54' 2"		
MW-73	2.0	28'	14' 2"		VZ-4
MW-74	3.0	33'	27' 6"		
VZ-1	2.0	27'	5' 1"		PGI-8
VZ-2	2.0	38' 8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	14' 2"		MW-73
VZ-5	2.0	32' 6"	16' 8"		
VZ-6	2.0	26' 3"	0' 0"		
VZ-7	2.0	49' 8"	22' 1"		
MH-69	2.0	28' 1"	6' 2"		



SUNDANCE SERVICES WEST, INC.

Main Office: 575-394-2511

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Plant Office: 575-394-3212

Fax: 575-394-2590

Box 1737

Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/25/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16' 5"	0' 2"		
MW-36	3.0	42'	22' 4"		
MW-37	3.0	39' 3"	17' 2"		
MW-40	3.0	29' 7"	15' 2"		
MW-41	3.0	77'	57' 1"		
MW-51	3.0	65' 5"	49' 3"		
MW-69	3.0	50' 4"	0' 2"		
MW-71	6.0	61' 9"	54' 1"		
MW-73	2.0	28'	14' 1"		VZ-4
MW-74	3.0	33'	27' 5"		
VZ-1	2.0	27'	5' 1"		PGI-8
VZ-2	2.0	38' 8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	14' 1"		MW-73
VZ-5	2.0	32' 6"	16' 9"		
VZ-6	2.0	26' 3"	0' 0"		
VZ-7	2.0	49' 8"	22' 2"		
MH-69	2.0	28' 1"	0' 1"		

SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS**

DATE:

11/26/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'3"		
MW-37	3.0	39'3"	17'1"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'2"		
MW-51	3.0	65'5"	49'2"		GI 7
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	54'2"		
MW-73	2.0	28'	14'2"		VZ-4
MW-74	3.0	33'	27'6"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	14'2"		MW-73
VZ-5	2.0	32'6"	16'9"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'3"		
MH-69	2.0	28'1"	0'2"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/27/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'2"		
MW-36	3.0	42'	22'3"		
MW-37	3.0	39'3"	17'2"		
MW-40	3.0	29'7"	15'2"		
MW-41	3.0	77'	57'7"		
MW-51	3.0	65'5"	44'3"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	54'1"		
MW-73	2.0	28'	14'3"		VZ-4
MW-74	3.0	33'	27'8"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	14'3"		MW-73
VZ-5	2.0	32'6"	16'9"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'1"		
MH-69	2.0	28'1"	0'1"		

SUNDANCE SERVICES WEST, INC.

 ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590

Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

www.sundanceservices.com

PARABO DISPOSAL FACILITY

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/28/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'3"		
MW-37	3.0	39'3"	17'1"		
MW-40	3.0	29'7"	15'1"		MW-5
MW-41	3.0	77'	57'1"		
MW-51	3.0	65'5"	49'2"		
MW-69	3.0	50'4"	0'2"		
MW-71	6.0	61'9"	54'1"		
MW-73	2.0	28'	14'1"		VZ-4
MW-74	3.0	33'	27'9"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	14'1"		MW-73
VZ-5	2.0	32'6"	16'8"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'7"		
MH-69	2.0	28'1"	0'2"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590

Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/29/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'3"		
MW-37	3.0	39'3"	17'1"		
MW-40	3.0	29'7"	15'2"		
MW-41	3.0	77'	57'2"		
MW-51	3.0	65'5"	49'1"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	54'2"		
MW-73	2.0	28'	14'1"		VZ-4
MW-74	3.0	33'	28'1"		
VZ-1	2.0	27'	5'2"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	14'1"		MW-73
VZ-5	2.0	32'6"	16'9"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'1"		
MH-69	2.0	28'1"	0'1"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Box 1737

Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/30/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'2"		
MW-37	3.0	39'3"	17'1"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'1"		
MW-51	3.0	65'5"	49'2"		
MW-69	3.0	50'4"	0'2"		
MW-71	6.0	61'9"	54'1"		
MW-73	2.0	28'	14'2"		VZ-4
MW-74	3.0	33'	28'3"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	14'2"		MW-73
VZ-5	2.0	32'6"	16'8"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'1"		
MH-69	2.0	28'1"	0'2"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 575-394-
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

utilas

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: S/S-394
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 11/2/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
1001 6th Street P.O. Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com www.sundanceservices.net www.sundanceservices.org

MONITOR WELLS

DATE: 11/3/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
1001 6th Street P.O. Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com www.sundanceservices.net www.sundanceservices.org

MONITOR WELLS

DATE: 11/4/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 373-3941
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/5/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11 16 25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 373-3941
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/7/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 11/8/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511
1001 6th Street

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/9/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11 110 125

[illegible]



ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 373-3941
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

DATE:

11/11/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 373-3941
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: _____

11 112 125

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511
1001 6th Street

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 373-394
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 11/13/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES	ROLL-OFF TRUCKS	DUMP TRUCKS	VACUUM TRUCKS
1	1	1	1
2	2	2	2
3	3	3	3
4	4	4	4
5	5	5	5
6	6	6	6
7	7	7	7
8	8	8	8
9	9	9	9
10	10	10	10
11	11	11	11
12	12	12	12
13	13	13	13
14	14	14	14
15	15	15	15
16	16	16	16
17	17	17	17
18	18	18	18
19	19	19	19
20	20	20	20
21	21	21	21
22	22	22	22
23	23	23	23
24	24	24	24
25	25	25	25
26	26	26	26
27	27	27	27
28	28	28	28
29	29	29	29
30	30	30	30
31	31	31	31
32	32	32	32
33	33	33	33
34	34	34	34
35	35	35	35
36	36	36	36
37	37	37	37
38	38	38	38
39	39	39	39
40	40	40	40
41	41	41	41
42	42	42	42
43	43	43	43
44	44	44	44
45	45	45	45
46	46	46	46
47	47	47	47
48	48	48	48
49	49	49	49
50	50	50	50
51	51	51	51
52	52	52	52
53	53	53	53
54	54	54	54
55	55	55	55
56	56	56	56
57	57	57	57
58	58	58	58
59	59	59	59
60	60	60	60
61	61	61	61
62	62	62	62
63	63	63	63
64	64	64	64
65	65	65	65
66	66	66	66
67	67	67	67
68	68	68	68
69	69	69	69
70	70	70	70
71	71	71	71
72	72	72	72
73	73	73	73
74	74	74	74
75	75	75	75
76	76	76	76
77	77	77	77
78	78	78	78
79	79	79	79
80	80	80	80
81	81	81	81
82	82	82	82
83	83	83	83
84	84	84	84
85	85	85	85
86	86	86	86
87	87	87	87
88	88	88	88
89	89	89	89
90	90	90	90
91	91	91	91
92	92	92	92
93	93	93	93
94	94	94	94
95	95	95	95
96	96	96	96
97	97	97	97
98	98	98	98
99	99	99	99
100	100	100	100

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 373-3341
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/14/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 373-394
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/15/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 373-3941
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11 | 16 | 25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 573-394-
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/17/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11 | 18 | 25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DIST. USAM FACILITY:
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/19/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 373-3941
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11	20	25
----	----	----

[illegible]



ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 373-394
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

DATE: 11/21/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511
1001 6th Street

Plant Office: 575-394-3212
Box 1737 Eunice, N.

Fax: 575-394-2590
Mexico 88231

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/22/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 373-394
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 11/23/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES	ROLL-OFF TRUCKS	DUMP TRUCKS	VACUUM TRUCKS
1	1	1	1
2	2	2	2
3	3	3	3
4	4	4	4
5	5	5	5
6	6	6	6
7	7	7	7
8	8	8	8
9	9	9	9
10	10	10	10
11	11	11	11
12	12	12	12
13	13	13	13
14	14	14	14
15	15	15	15
16	16	16	16
17	17	17	17
18	18	18	18
19	19	19	19
20	20	20	20
21	21	21	21
22	22	22	22
23	23	23	23
24	24	24	24
25	25	25	25
26	26	26	26
27	27	27	27
28	28	28	28
29	29	29	29
30	30	30	30
31	31	31	31
32	32	32	32
33	33	33	33
34	34	34	34
35	35	35	35
36	36	36	36
37	37	37	37
38	38	38	38
39	39	39	39
40	40	40	40
41	41	41	41
42	42	42	42
43	43	43	43
44	44	44	44
45	45	45	45
46	46	46	46
47	47	47	47
48	48	48	48
49	49	49	49
50	50	50	50
51	51	51	51
52	52	52	52
53	53	53	53
54	54	54	54
55	55	55	55
56	56	56	56
57	57	57	57
58	58	58	58
59	59	59	59
60	60	60	60
61	61	61	61
62	62	62	62
63	63	63	63
64	64	64	64
65	65	65	65
66	66	66	66
67	67	67	67
68	68	68	68
69	69	69	69
70	70	70	70
71	71	71	71
72	72	72	72
73	73	73	73
74	74	74	74
75	75	75	75
76	76	76	76
77	77	77	77
78	78	78	78
79	79	79	79
80	80	80	80
81	81	81	81
82	82	82	82
83	83	83	83
84	84	84	84
85	85	85	85
86	86	86	86
87	87	87	87
88	88	88	88
89	89	89	89
90	90	90	90
91	91	91	91
92	92	92	92
93	93	93	93
94	94	94	94
95	95	95	95
96	96	96	96
97	97	97	97
98	98	98	98
99	99	99	99
100	100	100	100

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 373-394
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/24/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 373-394
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/25/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511
1001 6th Street

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 373-3940
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11 126 125

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
1001 6th Street P.O. Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com www.sundanceservices.net www.sundanceservices.org

MONITOR WELLS

DATE:

11 | 27 | 25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 373-3941
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 11/28/25

[illegible]



ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Fax: 575-394-2590

Eunice, New Mexico 88231

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

DATE: 11/29/25

[illegible]



ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Fax: 575-394-2590
Mexico 88231

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

DATE:

11	30	25
----	----	----

[illegible]

SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE: 11/1/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'7"		
WS-2	Poly	14'7"	1'1"		
WS-3	Poly	14'7"	0'3"		
WS-4	Poly	14'7"	2'8"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'9"		

SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590 1001 6th Street P.O.
 Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY
www.sundanceservices.com www.sundanceservices.net www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE: 11/2/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2' 8"		
WS-2	Poly	14'7"	1' 3"		
WS-3	Poly	14'7"	0' 4"		
WS-4	Poly	14'7"	2' 3"		
WS-5	Poly	23'6"	14' 1"		
WS-6	Poly	8'0"	0' 8"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY
www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

11/3/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'7"		
WS-2	Poly	14'7"	1'4"		
WS-3	Poly	14'7"	0'3"		
WS-4	Poly	14'7"	2'1"		
WS-5	Poly	23'6"	14'0"		
WS-6	Poly	8'0"	0'9"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

11/4/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2' 8'		
WS-2	Poly	14'7"	1' 3'		
WS-3	Poly	14'7"	0' 2'		
WS-4	Poly	14'7"	2' 3'		
WS-5	Poly	23'6"	14' 1'		
WS-6	Poly	8'0"	0' 8"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

11/5/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1'4"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'5"		
WS-5	Poly	23'6"	14'1"		
WS-6	Poly	8'0"	0'9"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

11/6/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'7"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'4"		
WS-5	Poly	23'6"	14'2"		
WS-6	Poly	8'0"	0'8"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

11/7/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1'2"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	2'3"		
WS-5	Poly	23'6"	14'7"		
WS-6	Poly	8'0"	0'7"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

11/8/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'3'		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'1"		
WS-5	Poly	23'6"	13'8"		
WS-6	Poly	8'0"	0'9"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

11/9/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'7"		
WS-2	Poly	14'7"	1'4"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'3"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'8"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

11/10/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	2'5"		
WS-5	Poly	23'6"	14'1"		
WS-6	Poly	8'0"	0'9"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE: 11/11/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'4"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'8"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

11/12/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'2"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'5"		
WS-5	Poly	23'6"	13'8"		
WS-6	Poly	8'0"	0'9"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE: 11/13/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	2'6"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'7"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

11/14/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'4"		
WS-5	Poly	23'6"	13'8"		
WS-6	Poly	8'0"	0'6"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

11/15/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'7"		
WS-2	Poly	14'7"	1'4"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	2'3"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'7"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

11/16/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1'3'		
WS-3	Poly	14'7"	0'1'		
WS-4	Poly	14'7"	2'7'		
WS-5	Poly	23'6"	14' 7"		
WS-6	Poly	8'0"	0'8'		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE: 11/17/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'2"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	2'3"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'9"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
Box 1737 Eunice, New Mexico 88231

1001 6th Street P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

11/18/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'1"		
WS-5	Poly	23'6"	14'1"		
WS-6	Poly	8'0"	0'8"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

11/19/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'2"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	2'3"		
WS-5	Poly	23'6"	14'3"		
WS-6	Poly	8'0"	0'9"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY
www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

11/20/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'7"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'1"		
WS-5	Poly	23'6"	14'1"		
WS-6	Poly	8'0"	0'8"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

11/21/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'2"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'2"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'7"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

11/22/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'7"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	2'1"		
WS-5	Poly	23'6"	13'7"		
WS-6	Poly	8'0"	0'8"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

11/23/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1'4"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'3"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'8"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

11/24/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	2'4"		
WS-5	Poly	23'6"	13'8"		
WS-6	Poly	8'0"	0'7"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE: 11/25/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'7"		
WS-2	Poly	14'7"	1'2"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'5"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'6"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

11/26/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	2'6"		
WS-5	Poly	23'6"	13'8"		
WS-6	Poly	8'0"	0'7"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE: 11/27/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1'4"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'7"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'8"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

11/28/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	2'6"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'7"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org

MONITOR WELLS WASH OUT

DATE: 11/29/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'7"		
WS-2	Poly	14'7"	1'4"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'5"		
WS-5	Poly	23'6"	13'8"		
WS-6	Poly	8'0"	0'9"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

11/30/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'6"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'8"		

Daily Inspection Form
Sundance West

Date:

12/11/25

Others:

Print Name:

Douglas Romero

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
☒					Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)	D ✓	
					Dust Control (Vol. II - Sec. 4.3 - Pg. 19)	D ✓	
					Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)	D ✓	
					Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)	D ✓	
					Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)	D ✓	
					Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)	D ✓	
					Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)	D ✓	
					Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)	D ✓	
					Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)	D ✓	
					Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)	D ✓	
					Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-O2 (Vol. II - Sec. 3 - Pg. 131)	D ✓	
					Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg. 223)	D ✓	
					Pond levels three-foot free board	D ✓	

Daily Inspection Form
Sundance West

Date:

12/2/25

Print Name:

Daisy Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily ☒	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)						☒	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						☒	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						☒	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						☒	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						☒	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)						☒	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)						☒	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						☒	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)						☒	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)						☒	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)						☒	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)						☒	
Pond levels three-foot free board						☒	

Daily Inspection Form
Sundance West

Date:

12/3/25

Print Name:

Drew Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)	☒					D	
Dust Control (Vol. II - Sec. 4.3 - Pg. 19)						D	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)						D	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)						D	
Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)						D	
Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)						D	
Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)						D	
Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)						D	
Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)						D	
Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)						D	
Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-O2 (Vol. II - Sec. 3 - Pg. 131)						D	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg. 223)						D	
Pond levels three-foot free board						D	

Daily Inspection Form
Sundance West

Date:

12/4/25

Print Name:

Dennis Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
☒					Item		
					Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)	☒	
					Dust Control (Vol. II - Sec. 4.3 - Pg. 19)	☒	
					Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)	☒	
					Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)	☒	
					Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)	☒	
					Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)	☒	
					Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)	☒	
					Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)	☒	
					Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)	☒	
					Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)	☒	
					Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-O2 (Vol. II - Sec. 3 - Pg. 131)	☒	
					Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2 - Pg. 223)	☒	
					Pond levels three-foot free board	☒	

Daily Inspection Form
Sundance West

Date:

12/5/25

Others:

Print Name:

Dawn Romero

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
Item							
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)					D	☒	
Dust Control (Vol. II - Sec.4.3 - Pg.19)					D	☒	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)					D	☒	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)					D	☒	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)					D	☒	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)					D	☒	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)					D	☒	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)					D	☒	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)					D	☒	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)					D	☒	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)					D	☒	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)					D	☒	
Pond levels three-foot free board					D	☒	

Daily Inspection Form
Sundance West

Date:

12/6/25

Print Name:

Darius Roman

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
Item							
Vehicle Screening (H2S) (Vol. II - Sec 4.2 - Pg.19)					D	/	
Dust Control (Vol. II - Sec.4.3 - Pg.19)					D	/	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)					D	/	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)					D	/	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)					D	/	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)					D	/	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)					D	/	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)					D	/	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)					D	/	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)					D	/	
Evaporation Pond Tests-pH (Vol. II - Sec 3- Pg.130)-O2 (Vol. II - Sec 3- Pg.131)					D	/	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)					D	/	
Pond levels three-foot free board					D	/	

Daily Inspection Form
Sundance West

Date:

12/7/25

Print Name:

Dave Rando

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	☒					D	
Dust Control (Vol. II - Sec.4.3 - Pg.19)	☒					D	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)	☒					D	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)	☒					D	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)	☒					D	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)	☒					D	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)	☒					D	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)	☒					D	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)	☒					D	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)	☒					D	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)	☒					D	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)	☒					D	
Pond levels three-foot free board	☒					D	

Daily Inspection Form
Sundance West

Date:

12/8/25

Print Name:

Dawn Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	☒					D ✓	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						D ✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						D ✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						D ✓	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						D ✓	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)						D ✓	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)						D ✓	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						D ✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)						D ✓	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)						D ✓	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)						D ✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)						D ✓	
Pond levels three-foot free board						D ✓	

Daily Inspection Form
Sundance West

Date:

12/9/25

Print Name:

Dessi Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)						D	✓	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						D	✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						D	✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						D	✓	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						D	✓	
Vehicle Monitoring (H2S) (Vol. II - Sec.2- Pg.94)						D	✓	
Waste Screening and Forms (Vol. II - Sec.2- Pg.94)						D	✓	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						D	✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec.2- Pg.92)						D	✓	
Facility H2S Monitoring (Vol. II - Sec.3- Pg.127)						D	✓	
Evaporation Pond Tests-pH (Vol. II- Sec.3- Pg.130)-O2 (Vol. II- Sec.3- Pg.131)						D	✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)						D	✓	
Pond levels three-foot free board						D	✓	

Daily Inspection Form
Sundance West

Date:

12/10/25

Print Name:

Daisy Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)						<u>/</u>	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						<u>/</u>	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						<u>/</u>	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						<u>/</u>	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						<u>/</u>	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)						<u>/</u>	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)						<u>/</u>	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						<u>/</u>	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)						<u>/</u>	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)						<u>/</u>	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)						<u>/</u>	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)						<u>/</u>	
Pond levels three-foot free board						<u>/</u>	

Daily Inspection Form
Sundance West

Date:

12/11/25

Print Name:

Drew Ramon

Others:

Signature:

TYPE OF INSPECTION

Item	☒ Daily	☐ Weekly	☐ Monthly	☐ Quarterly	☐ Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)						D ✓	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						D ✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						D ✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						D ✓	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						D ✓	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)						D ✓	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)						D ✓	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						D ✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)						D ✓	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)						D ✓	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)						D ✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)						D ✓	
Pond levels three-foot free board							

Daily Inspection Form
Sundance West

Date:

12/12/25

Others:

Print Name:

Dustin Romero

Signature:

TYPE OF INSPECTION

Item	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	☒				D ✓	
Dust Control (Vol. II - Sec.4.3 - Pg.19)					D ✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)					D ✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)					D ✓	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)					D ✓	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)					D ✓	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)					D ✓	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)					D ✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)					D ✓	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)					D ✓	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)					D ✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)					D ✓	
Pond levels three-foot free board					D ✓	

Daily Inspection Form
Sundance West

Date:

12/13/25

Print Name:

Davi Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)	☒					D ✓	
Dust Control (Vol. II - Sec. 4.3 - Pg. 19)						D ✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)						D ✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)						D ✓	
Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)						D ✓	
Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)						D ✓	
Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)						D ✓	
Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)						D ✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)						D ✓	
Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)						D ✓	
Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-O2 (Vol. II - Sec. 3 - Pg. 131)						D ✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg. 223)						D ✓	
Pond levels three-foot free board						D ✓	

Daily Inspection Form
Sundance West

Date:

12/14/25

Print Name:

Darius Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	☒					☒	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						☒	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						☒	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						☒	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						☒	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)						☒	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)						☒	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						☒	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)						☒	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)						☒	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)						☒	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)						☒	
Pond levels three-foot free board						☒	

Daily Inspection Form
Sundance West

Date:

12/15/25

Print Name:

Dustin Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)						☒	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						☒	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						☒	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						☒	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						☒	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)						☒	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)						☒	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						☒	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)						☒	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)						☒	
Evaporation Pond Tests-pH (Vol. II - Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)						☒	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)						☒	
Pond levels three-foot free board						☒	

Daily Inspection Form
Sundance West

Date:

12/16/25

Print Name:

Deyi Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)						☒	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						☒	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						☒	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						☒	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						☒	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)						☒	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)						☒	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						☒	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)						☒	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)						☒	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)						☒	
Evaporation Pond Oil Inspection (Vol. Section 6- Subsect 2.2- Pg.223)						☒	
Pond levels three-foot free board						☒	

Daily Inspection Form
Sundance West

Date:

12/17/25

Print Name:

Dennis Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	☒					☒	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						☒	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						☒	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						☒	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						☒	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)						☒	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)						☒	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						☒	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)						☒	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)						☒	
Evaporation Pond Tests-pH (Vol. II - Sec 3- Pg.130)-O2 (Vol. II - Sec 3- Pg.131)						☒	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)						☒	
Pond levels three-foot free board						☒	

Daily Inspection Form Sundance West

Date:

12/18/25

Print Name:

Devin Lomew

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)	☒					D ✓	
Dust Control (Vol. II - Sec. 4.3 - Pg. 19)						D ✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)						D ✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)						D ✓	
Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)						D ✓	
Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)						D ✓	
Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)						D ✓	
Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)						D ✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)						D ✓	
Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)						D ✓	
Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-O2 (Vol. II - Sec. 3 - Pg. 131)						D ✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg. 223)						D ✓	
Pond levels three-foot free board						D ✓	

Daily Inspection Form
Sundance West

Date:

12/19/25

Print Name:

Dawn Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily ☒	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)						☒	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						☒	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						☒	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						☒	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						☒	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)						☒	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)						☒	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						☒	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)						☒	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)						☒	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)						☒	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)						☒	
Pond levels three-foot free board						☒	

Daily Inspection Form Sundance West

Date:

12/20/25

Print Name:

Dana Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	☒					☒	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						☒	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						☒	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						☒	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						☒	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)						☒	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)						☒	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						☒	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)						☒	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)						☒	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)						☒	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)						☒	
Pond levels three-foot free board						☒	

Daily Inspection Form
Sundance West

Date:

12/21/25

Print Name:

Deysi Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	☒					☒	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						☒	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						☒	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						☒	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						☒	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)						☒	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)						☒	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						☒	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)						☒	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)						☒	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)						☒	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)						☒	
Pond levels three-foot free board						☒	

Daily Inspection Form Sundance West

Date:

12/22/25

Print Name:

Drew Bonner

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
Item							
Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)					D	✓	
Dust Control (Vol. II - Sec. 4.3 - Pg. 19)					D	✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)					D	✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)					D	✓	
Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)					D	✓	
Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)					D	✓	
Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)					D	✓	
Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)					D	✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)					D	✓	
Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)					D	✓	
Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-O2 (Vol. II - Sec. 3 - Pg. 131)					D	✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg. 223)					D	✓	
Pond levels three-foot free board					D	✓	

Daily Inspection Form Sundance West

Print Name:

Signature:

Drew Remer

Date:

12/23/25

Others:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	☒					☒	
Dust Control (Vol. II - Sec.4.3 - Pg.19)	☒					☒	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)	☒					☒	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)	☒					☒	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)	☒					☒	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)	☒					☒	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)	☒					☒	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)	☒					☒	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)	☒					☒	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)	☒					☒	
Evaporation Pond Tests-pH (Vol. II - Sec 3- Pg.130)-O2 (Vol. II - Sec 3- Pg.131)	☒					☒	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)	☒					☒	
Pond levels three-foot free board	☒					☒	

一、政治
 二、經濟
 三、文化
 四、教育
 五、社會
 六、宗教
 七、藝術
 八、科學
 九、法律
 十、軍事
 十一、外交
 十二、內政
 十三、財政
 十四、交通
 十五、衛生
 十六、農業
 十七、工業
 十八、商業
 十九、金融
 二十、稅收
 二十一、保險
 二十二、銀行
 二十三、證券
 二十四、期貨
 二十五、期權
 二十六、債券
 二十七、股票
 二十八、基金
 二十九、信託
 三十、遺產
 三十一、贈與
 三十二、遺囑
 三十三、繼承
 三十四、婚姻
 三十五、離婚
 三十六、協議
 三十七、調解
 三十八、仲裁
 三十九、訴訟
 四十、執行
 四十一、和解
 四十二、調停
 四十三、斡旋
 四十四、調處
 四十五、調和
 四十六、調劑
 四十七、調製
 四十八、調配
 四十九、調度
 五十、調節
 五十一、調整
 五十二、調整
 五十三、調治
 五十四、調治
 五十五、調治
 五十六、調治
 五十七、調治
 五十八、調治
 五十九、調治
 六十、調治
 六十一、調治
 六十二、調治
 六十三、調治
 六十四、調治
 六十五、調治
 六十六、調治
 六十七、調治
 六十八、調治
 六十九、調治
 七十、調治
 七十一、調治
 七十二、調治
 七十三、調治
 七十四、調治
 七十五、調治
 七十六、調治
 七十七、調治
 七十八、調治
 七十九、調治
 八十、調治
 八十一、調治
 八十二、調治
 八十三、調治
 八十四、調治
 八十五、調治
 八十六、調治
 八十七、調治
 八十八、調治
 八十九、調治
 九十、調治
 九十一、調治
 九十二、調治
 九十三、調治
 九十四、調治
 九十五、調治
 九十六、調治
 九十七、調治
 九十八、調治
 九十九、調治
 一百、調治

Print Name: _____

Signature:

TYPE OF INSPECTION			
Daily	Weekly	Monthly	Quarterly Annual
Item			
Vehcle Screening (H2S) (Vol. II - Sec.4 ² 2 - Pg.19)			
Dust Control (Vol. II - Sec.4.3 - Pg.19)			
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)			
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)			
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)			
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)			
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)			
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)			
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)			
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)			
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)			
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)			
Pond levels three-foot free board			

Pond levels three-foot free board

Daily Inspection Form
Sundance West

Date:

12/25/25

Print Name:

Drew Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
☒					Item		
					Vehicle Screening (H2S) (Vol. II - Sec.4.2 -Pg.19)	☒	
					Dust Control (Vol. II - Sec.4.3 - Pg.19)	☒	
					Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)	☒	
					Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)	☒	
					Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)	☒	
					Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)	☒	
					Waste Screening and Forms (Vol. II - Sec 2- Pg.94)	☒	
					Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)	☒	
					Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)	☒	
					Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)	☒	
					Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)	☒	
					Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)	☒	
					Pond levels three-foot free board	☒	

Daily Inspection Form
Sundance West

Date:

12/26/25

Print Name:

Dustin Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)						D	
Dust Control (Vol. II - Sec. 4.3 - Pg. 19)						D	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)						D	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)						D	
Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)						D	
Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)						D	
Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)						D	
Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)						D	
Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)						D	
Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)						D	
Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-O2 (Vol. II - Sec. 3 - Pg. 131)						D	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg. 223)						D	
Pond levels three-foot free board						D	

Daily Inspection Form
Sundance West

Date:

12/27/25

Print Name:

Deyi Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	☒					✓	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						✓	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						✓	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)						✓	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)						✓	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)						✓	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)						✓	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)						✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)						✓	
Pond levels three-foot free board						✓	

Daily Inspection Form
Sundance West

Date:

12/28/25

Print Name:

Dustin Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec 4.2 - Pg.19)	☒					☒	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						☒	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						☒	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						☒	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						☒	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)						☒	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)						☒	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						☒	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)						☒	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)						☒	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)						☒	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)						☒	
Pond levels three-foot free board						☒	

Daily Inspection Form
Sundance West

Date: 12/28/25

Print Name: Deys Romero

Others: _____

Signature: _____

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	☒					☒	
Dust Control (Vol. II - Sec.4.3 - Pg.19)	☒					☒	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)	☒					☒	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)	☒					☒	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)	☒					☒	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)	☒					☒	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)	☒					☒	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)	☒					☒	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)	☒					☒	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)	☒					☒	
Evaporation Pond Tests-pH (Vol. II - Sec 3- Pg.130)-O2 (Vol. II - Sec 3- Pg.131)	☒					☒	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)	☒					☒	
Pond levels three-foot free board	☒					☒	

Daily Inspection Form
Sundance West

Date:

12/29/25

Print Name:

Deyi Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)						D	✓	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						D	✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						D	✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						D	✓	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						D	✓	
Vehicle Monitoring (H2S) (Vol. II - Sec.2- Pg.94)						D	✓	
Waste Screening and Forms (Vol. II - Sec.2- Pg.94)						D	✓	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						D	✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec.2- Pg.92)						D	✓	
Facility H2S Monitoring (Vol. II - Sec.3- Pg.127)						D	✓	
Evaporation Pond Tests-pH (Vol. II- Sec.3- Pg.130)-O2 (Vol. II- Sec.3- Pg.131)						D	✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)						D	✓	
Pond levels three-foot free board						D	✓	

Daily Inspection Form
Sundance West

Daily
Scale
Foot

Date:

12-130-125

Print Name:

Doris Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)						✓	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						✓	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						✓	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)						✓	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)						✓	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)						✓	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)						✓	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)						✓	
Evaporation Pond Oil Inspection (Vol. Section 6- Subsect 2.2- Pg.223)						✓	
Pond levels three-foot free board							

Journal of Management Education

Print Name: _____

Signature:

Deusi Ramro

TYPE OF INSPECTION					
Daily	Weekly	Monthly	Quarterly	Annual	
Item					
☒					Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)
					Dust Control (Vol. II - Sec.4.3 - Pg.19)
					Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)
					Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)
					Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)
					Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)
					Waste Screening and Forms (Vol. II - Sec 2- Pg.94)
					Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)
					Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)
					Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)
					Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)
					Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)
					Pond levels three-foot free board

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/1/25

Inspector(s):

Time: 6:30 amDrew Pomeroy**Weather:**Temperature 21 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 7 mphWind Direction NNE (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/2/25

Inspector(s):

Time: 6:50amDouglas Romero**Weather:**Temperature 28 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 9 mphWind Direction SW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/3/25Time: 9:50 am

Inspector(s):

Days Romero**Weather:**Temperature 50 deg. FSkies Partly CloudyWind Speed 12 mphWind Direction NNE (direction blowing from)

Precipitation (last 24 hours) _____ inches

NOTES:

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/4/25

Inspector(s):

Time: 7:50amDeusi Romero**Weather:**Temperature 36 deg. F

Precipitation (last 24 hours) _____ inches

Skies cloudyWind Speed 10 mphWind Direction N (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/5/25

Inspector(s):

Time: 6:50amDarius Romero**Weather:**Temperature 28 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 6 mphWind Direction WSW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/6/25

Inspector(s):

Time: 10:50 amDaisy Romero**Weather:**Temperature 59 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 18 mphWind Direction WSW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/7/25

Inspector(s):

Time: 8:50 amDeusi Romero**Weather:**Temperature 48 deg. FSkies FairWind Speed 10 mphWind Direction NNW (direction blowing from)

Precipitation (last 24 hours) _____ inches

NOTES:

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/8/25

Inspector(s):

Time: 9:50 amDeusi Romero**Weather:**Temperature 57 deg. F

Precipitation (last 24 hours) _____ inches

Skies FWVWind Speed 15 mphWind Direction SSW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/9/25

Inspector(s):

Time: 6:50 amDeysi Romero**Weather:**Temperature 28 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 9 mphWind Direction W (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/10/25
Time: 8:50am

Inspector(s): Deysi Romero

Weather:

Temperature 55 deg. F

Precipitation (last 24 hours) _____ inches

Skies fair

Wind Speed 18 mph

Wind Direction NNW (direction blowing from)

NOTES:

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/11/25

Inspector(s):

Time: 11:50 amDyusi Romero**Weather:**Temperature 72 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 14 mphWind Direction WSW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/17/25

Inspector(s):

Time: 7:50amDeysi Romero**Weather:**Temperature 54 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 13 mphWind Direction N (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/13/25

Inspector(s):

Time: 10:50amDeusi Romero**Weather:**Temperature 68 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 12 mphWind Direction WSW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/14/25

Inspector(s):

Time: 6:50 amDeusi Romero**Weather:**Temperature 32 deg. F

Precipitation (last 24 hours) _____ inches

Skies CloudyWind Speed 10 mphWind Direction NNE (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/15/25

Inspector(s):

Time: 8:50amDeusi Romero**Weather:**Temperature 37 deg. F

Precipitation (last 24 hours) _____ inches

Skies cloudyWind Speed 10 mphWind Direction SSW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/16/25

Inspector(s):

Time: 8:50amDeusi Romero**Weather:**Temperature 48 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 8 mphWind Direction SSW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/17/25

Inspector(s):

Time: 7:50 amDarius Romero**Weather:**Temperature 43 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 10 mphWind Direction N (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/18/25

Inspector(s):

Time: 12:50pmDouglas Romero**Weather:**Temperature 61 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 12 mphWind Direction ENE (direction blowing from)

Page ____ of ____

NOTES:

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/19/25Time: 2:50 pm

Inspector(s):

Deusi Romero**Weather:**Temperature 75 deg. FSkies FairWind Speed 19 mphWind Direction SSW (direction blowing from)

Precipitation (last 24 hours) _____ inches

NOTES:

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/20/25Time: 4:50 pm

Inspector(s):

Doug Romero**Weather:**Temperature 70 deg. FSkies FairWind Speed 9 mphWind Direction WNW (direction blowing from)

Precipitation (last 24 hours) _____ inches

NOTES:

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/21/25

Inspector(s):

Time: 3:50 pmDeysi Romero**Weather:**Temperature 63 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 6 mphWind Direction S (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/22/25Time: 7:50 am

Inspector(s):

Devin Romero**Weather:**Temperature 45 deg. F

Precipitation (last 24 hours) _____ inches

Skies FewWind Speed 3 mphWind Direction SW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.I.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/23/25

Inspector(s):

Time: 8 50 amDouglas Romero**Weather:**Temperature 59 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 6 mphWind Direction SW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/24/25Time: 12:50pm

Inspector(s):

Deysi Romero**Weather:**Temperature 75 deg. FSkies FairWind Speed 16 mphWind Direction SSW (direction blowing from)

Precipitation (last 24 hours) _____ inches

NOTES:

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/25/25

Inspector(s):

Time: 2:50 pmDeysi Romero**Weather:**Temperature 81 deg. F

Precipitation (last 24 hours) _____ inches

Skies FCWWind Speed 15 mphWind Direction SW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

C:\Users\jcm\BoltAppData\Local\Microsoft\Windows\NetCache\Content.Outlook\ACBMOJ\VS\Sundance West II.1-Alt II.1.D-EvapPondLeakInspect

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/26/25

Inspector(s):

Time: 1:50 PMDawn Romero**Weather:**Temperature 77 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 14 mphWind Direction SW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/27/25

Inspector(s):

Time: 9:50 pmDeusi Romero**Weather:**Temperature 68 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 8 mphWind Direction S (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/28/25

Inspector(s):

Time: 6:50amDeysi Romero**Weather:**Temperature 55 deg. F

Precipitation (last 24 hours) _____ inches

Skies ClearWind Speed 7 mphWind Direction SSW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/29/25

Inspector(s):

Time: 7:50 amDawn Romero**Weather:**Temperature 34 deg. F

Precipitation (last 24 hours) _____ inches

Skies Mostly CloudyWind Speed 7 mphWind Direction N (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/30/25

Inspector(s):

Time: 9:50amDeusi Romero**Weather:**Temperature 41 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 10 mphWind Direction SSW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 12/31/25

Inspector(s):

Time: 7:50amDouglas Romero**Weather:**Temperature 30 deg. F

Precipitation (last 24 hours) _____ inches

Skies FairWind Speed 8 mphWind Direction N (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		


NOTES:

Office Pits

Date: 12/1/25

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:

EAST

1



Before:
After:



Before:
After:






Office Pits

Date: 12/2/25





WEST

10Before:
After:Before:
After:8Before:
After:Before:
After:

NORTH

6Before:
After:Before:
After:4Before:
After:Before:
After:2Before:
After:Before:
After:

EAST


1
Before:
After:Before:
After:9
Before:
After:Before:
After:7
Before:
After:Before:
After:5
Before:
After:Before:
After:3
Before:
After:Before:
After:

Office Pits

Date: 12/13/25

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:


EAST

1
Before:
After:




Before:
After:

3
Before:
After:




Before:
After:

5
Before:
After:




Before:
After:

7
Before:
After:



Before:
After:


9
Before:
After:






Before:
After:



Office Pits






Date: 12/4/25

WEST


Before:
After:

SOUTH


NORTH

Before:
After:Before:
After:




EAST

Before:
After:

Office Pits







Date: 12/5/25

WEST

10Before:
After:Before:
After:8Before:
After:

SOUTH

NORTH






Before:
After:6Before:
After:Before:
After:4Before:
After:Before:
After:2Before:
After:

EAST



Office Pits


Date: 12/6/25



WEST

10


Before:
After:



Before:
After:

8

Before:
After:




Before:
After:

NORTH

6


Before:
After:



Before:
After:

4


Before:
After:



Before:
After:

2

Before:
After:








Before:
After:

EAST








Office Pits

Date: 12/7/25



WEST








NORTH



EAST






Office Pits

Date: 12/18/25

WEST

Before:
After:Before:
After:8

NORTH

6Before:
After:Before:
After:42Before:
After:Before:
After:

EAST




Office Pits

Date: 12/9/25

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:

EAST


9



Before:
After:

Before:
After:

7




Before:
After:

Before:
After:

SOUTH


5



Before:
After:

Before:
After:


3



Before:
After:

Before:
After:

1



Before:
After:

Before:
After:




Office Pits

Date: 12/10/25

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:


2



Before:
After:


Before:
After:

EAST



9
Before:
After:


Before:
After:



7
Before:
After:


Before:
After:

SOUTH




5
Before:
After:

Before:
After:



3
Before:
After:

Before:
After:








1
Before:
After:

Before:
After:

Office Pits


Date: 12 / 11 / 25



WEST


10

Before: After:



8


Before: After:



NORTH


6

Before: After:




4

Before: After:



2

Before: After:




EAST



Office Pits


Date: 12/12/25

Before:
After:




9
Before:
After:

Before:
After:




7
Before:
After:

Before:
After:




5
Before:
After:

Before:
After:



3
Before:
After:

Before:
After:




1
Before:
After:

WEST

10


Before:
After:



Before:
After:

8


Before:
After:



Before:
After:

6

Before:
After:




Before:
After:

NORTH

4


Before:
After:



Before:
After:

2

Before:
After:



Before:
After:

EAST




Office Pits

Date: 12/13/25

WEST


10



Before:
After:

Before:
After:


9



Before:
After:

Before:
After:


8



Before:
After:

Before:
After:

7




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


5



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:


3



Before:
After:

Before:
After:


2



Before:
After:

Before:
After:

1



Before:
After:

Before:
After:

EAST




Office Pits

Date: 12/14/25

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:

EAST


1



Before:
After:

Before:
After:


9



Before:
After:

Before:
After:

7



Before:
After:

Before:
After:


5



Before:
After:

Before:
After:

3



Before:
After:

Before:
After:




Office Pits

Date: 12/15/25

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:

EAST


9



Before:
After:

Before:
After:

7




Before:
After:

Before:
After:

SOUTH


5



Before:
After:

Before:
After:


3



Before:
After:

Before:
After:

1



Before:
After:

Before:
After:




Office Pits

Date: 12/16/25

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:

EAST


1



Before:
After:

Before:
After:


9



Before:
After:

Before:
After:


7



Before:
After:

Before:
After:


5



Before:
After:

Before:
After:

3



Before:
After:

Before:
After:




Office Pits

Date: 12/17/25

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:

EAST


9



Before:
After:

Before:
After:

7




Before:
After:

Before:
After:

SOUTH


5



Before:
After:

Before:
After:


3



Before:
After:

Before:
After:

1



Before:
After:

Before:
After:




Office Pits

Date: 12/18/25

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:

EAST


1



Before:
After:

Before:
After:

3



Before:
After:

Before:
After:


5



Before:
After:

Before:
After:


7



Before:
After:

Before:
After:

9



Before:
After:

Before:
After:

SOUTH




Office Pits

Date: 12/19/25

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:


EAST

1
Before:
After:




Before:
After:

9
Before:
After:




Before:
After:

7
Before:
After:




Before:
After:

5
Before:
After:



Before:
After:

3
Before:
After:



Before:
After:




Office Pits

Date: 12/20/25

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:

EAST


1



Before:
After:


Before:
After:

Before:
After:



9
Before:
After:


Before:
After:



7
Before:
After:


SOUTH

Before:
After:



5
Before:
After:

Before:
After:



3
Before:
After:




Office Pits

Date: 12/21/25

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:


EAST

1
Before:
After:




Before:
After:

3
Before:
After:




Before:
After:

5
Before:
After:




Before:
After:

7
Before:
After:



Before:
After:

9
Before:
After:



Before:
After:




Office Pits

Date: 12/22/25

WEST


10




Before:
After:

Before:
After:

Before:
After:




9
Before:
After:



7
Before:
After:

Before:
After:




8

Before:
After:


Before:
After:

SOUTH



5
Before:
After:

Before:
After:




6

Before:
After:


Before:
After:

NORTH



3
Before:
After:

Before:
After:



4


Before:
After:

Before:
After:



1
Before:
After:

Before:
After:



2

Before:
After:

Before:
After:

EAST




Office Pits

Date: 12/23/25

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:

EAST


1



Before:
After:

Before:
After:


3



Before:
After:

Before:
After:


5



Before:
After:

Before:
After:


7



Before:
After:

Before:
After:

9




Before:
After:

Before:
After:

SOUTH





Office Pits

Date: 12/24/25


WEST

10

Before:
After:




Before:
After:



8

SOUTH



NORTH



Before:
After:


6

Before:
After:

4

Before:
After:

EAST


2

Office Pits

Date: 12/25/25

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:


EAST

1
Before:
After:




Before:
After:

9
Before:
After:



Before:
After:


7
Before:
After:



Before:
After:


SOUTH

5
Before:
After:



Before:
After:

3
Before:
After:



Before:
After:




Office Pits

Date: 12/26/25

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2



Before:
After:


Before:
After:

EAST



9


Before:
After:



Before:
After:

7

Before:
After:




Before:
After:

SOUTH

5


Before:
After:



Before:
After:

3


Before:
After:



Before:
After:


1

Before:
After:



Before:
After:



Office Pits

Date: 12/27/25


WEST

10

Before:
After:




Before:
After:



8

SOUTH



NORTH




Before:
After:

6

Before:
After:

4


Before:
After:

2

EAST





Office Pits

Date: 12/28/25


WEST

10

Before:
After:




Before:
After:



8

SOUTH



NORTH




Before:
After:

6

Before:
After:

4


Before:
After:

2




EAST



Office Pits





Date: 12/29/25

WEST


10Before:
After:Before:
After:8

SOUTH

NORTH

Before:
After:6Before:
After:4Before:
After:


EAST

2

Office Pits

Date: 12/30/25


Before:
After:



9
Before:
After:


WEST

10



Before:
After:


Before:
After:



7
Before:
After:

Before:
After:

8




Before:
After:

SOUTH

NORTH


Before:
After:



5
Before:
After:


Before:
After:

6



Before:
After:


Before:
After:



3
Before:
After:


Before:
After:

4



Before:
After:


Before:
After:



1
Before:
After:

Before:
After:

2








Before:
After:



EAST






Office Pits

Date: 12/31/25

WEST

Before:
After:8

NORTH

Before:
After:6Before:
After:4Before:
After:2

EAST





SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

12/1/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'2"		
MW-36	3.0	42'	22'1"		
MW-37	3.0	39'3"	17'1"		
MW-40	3.0	29'7"	15'2"		
MW-41	3.0	77'	57'3"		
MW-51	3.0	65'5"	49'3"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	54'2"		
MW-73	2.0	28'	14'3"		VZ-4
MW-74	3.0	33'	28'6"	23'1"	
VZ-1	2.0	27'	5'2"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	14'3"		MW-73
VZ-5	2.0	32'6"	16'8"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'1"		
MH-69	2.0	28'1"	0'1"		



SUNDANCE SERVICES WEST, INC.

Main Office: 575-394-2511

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Plant Office: 575-394-3212

Fax: 575-394-2590

Box 1737

Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

12/21/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'3"		
MW-37	3.0	39'3"	17'1"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'3"		
MW-51	3.0	65'5"	49'1"		
MW-69	3.0	50'4"	0'2"		
MW-71	6.0	61'9"	54'2"		
MW-73	2.0	28'	14'4"		VZ-4
MW-74	3.0	33'	23'4"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	14'4"		MW-73
VZ-5	2.0	32'6"	16'8"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'1"		
MH-69	2.0	28'1"	0'1"		



SUNDANCE SERVICES WEST, INC.

Main Office: 575-394-2511

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Plant Office: 575-394-3212

Fax: 575-394-2590

Box 1737

Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org

MONITOR WELLS

DATE:

12/3/05

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16' 5"	0' 2"		
MW-36	3.0	42'	22' 2"		
MW-37	3.0	39' 3"	17' 2"		
MW-40	3.0	29' 7"	15' 2"		
MW-41	3.0	77'	57' 2"		
MW-51	3.0	65' 5"	49' 2"		
MW-69	3.0	50' 4"	0' 1"		
MW-71	6.0	61' 9"	54' 2"		
MW-73	2.0	28'	14' 2"		VZ-4
MW-74	3.0	33'	23' 5"		
VZ-1	2.0	27'	5' 0"		PGI-8
VZ-2	2.0	38' 8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	14' 2"		MW-73
VZ-5	2.0	32' 6"	16' 8"		
VZ-6	2.0	26' 3"	0' 0"		
VZ-7	2.0	49' 8"	22' 1"		
MH-69	2.0	28' 1"	0' 2"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS**

DATE:

12/4/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0' 1"		
MW-36	3.0	42'	22'3"		
MW-37	3.0	39'3"	17' 1"		
MW-40	3.0	29'7"	15' 1"		
MW-41	3.0	77'	57' 1"		
MW-51	3.0	65'5"	44' 1"		
MW-69	3.0	50'4"	0' 2"		
MW-71	6.0	61'9"	54' 2"		
MW-73	2.0	28'	14' 1"		VZ-4
MW-74	3.0	33'	23'4"		
VZ-1	2.0	27'	5' 1"		PGI-8
VZ-2	2.0	38'8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	14' 3"		MW-73
VZ-5	2.0	32'6"	16' 9"		
VZ-6	2.0	26'3"	0' 0"		
VZ-7	2.0	49'8"	22' 1"		
MH-69	2.0	28'1"	0' 1"		



SUNDANCE SERVICES WEST, INC.

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Box 1737

Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

12/5/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'2"		
MW-36	3.0	42'	22'4"		
MW-37	3.0	39'3"	17'2"		
MW-40	3.0	29'7"	15'2"		
MW-41	3.0	77'	57'2"		
MW-51	3.0	65'5"	49'2"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	54'1"		
MW-73	2.0	28'	14'3"		VZ-4
MW-74	3.0	33'	23'6"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	14'3"		MW-73
VZ-5	2.0	32'6"	16'8"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'1"		
MH-69	2.0	28'1"	0'2"		

SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231
PARABO DISPOSAL FACILITY
www.sundanceservices.com www.sundanceservices.net www.sundanceservices.org

1001 6th Street

P.O.

MONITOR WELLS

DATE:

12/6/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0' 1"		
MW-36	3.0	42'	22' 3"		
MW-37	3.0	39'3"	17' 1"		
MW-40	3.0	29'7"	15' 1"		
MW-41	3.0	77'	57' 1"		
MW-51	3.0	65'5"	49' 2"		
MW-69	3.0	50'4"	0' 2"		
MW-71	6.0	61'9"	54' 1"		
MW-73	2.0	28'	14' 2"		VZ-4
MW-74	3.0	33'	23' 7"		
VZ-1	2.0	27'	5' 1"		PGI-8
VZ-2	2.0	38'8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	14' 2"		MW-73
VZ-5	2.0	32'6"	16' 8"		
VZ-6	2.0	26'3"	0' 0"		
VZ-7	2.0	49'8"	22' 1"		
MH-69	2.0	28'1"	0' 1"		

SUNDANCE SERVICES WEST, INC.
ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS**

DATE:

12/7/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0' 2"		
MW-36	3.0	42'	22' 4"		
MW-37	3.0	39'3"	17' 2"		
MW-40	3.0	29'7"	15' 2"		
MW-41	3.0	77'	57' 2"		
MW-51	3.0	65'5"	49' 3"		
MW-69	3.0	50'4"	0' 1"		
MW-71	6.0	61'9"	54' 2"		
MW-73	2.0	28'	14' 2"		VZ-4
MW-74	3.0	33'	23' 8"		
VZ-1	2.0	27'	5' 1"		PGI-8
VZ-2	2.0	38'8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	14' 2"		MW-73
VZ-5	2.0	32'6"	16' 9"		
VZ-6	2.0	26'3"	0' 0"		
VZ-7	2.0	49'8"	22' 1"		
MH-69	2.0	28'1"	0' 1"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590

Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net


www.sundanceservices.org

MONITOR WELLS

DATE:

12/18/23

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0' 1"		
MW-36	3.0	42'	22' 3"		
MW-37	3.0	39'3"	17' 1"		
MW-40	3.0	29'7"	15' 1"		
MW-41	3.0	77'	57' 1"		
MW-51	3.0	65'5"	49' 2"		
MW-69	3.0	50'4"	0' 1"		
MW-71	6.0	61'9"	54' 2"		
MW-73	2.0	28'	14' 1"		VZ-4
MW-74	3.0	33'	24' 1"		
VZ-1	2.0	27'	5' 2"		PGI-8
VZ-2	2.0	38'8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	14' 1"		MW-73
VZ-5	2.0	32'6"	16' 8"		
VZ-6	2.0	26'3"	0' 0"		
VZ-7	2.0	49'8"	22' 1"		
MH-69	2.0	28'1"	0' 2"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

12/9/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'0"		
MW-36	3.0	42'	22'4"		
MW-37	3.0	39'3"	17'2"		
MW-40	3.0	29'7"	15'2"		
MW-41	3.0	77'	57'2"		
MW-51	3.0	65'5"	44'2"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	54'2"		
MW-73	2.0	28'	14'2"		VZ-4
MW-74	3.0	33'	24'4"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	14'2"		MW-73
VZ-5	2.0	32'6"	16'7"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'1"		
MH-69	2.0	28'1"	0'1"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
Box 1737 Eunice, New Mexico 88231

1001 6th Street P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

12/10/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'0"		
MW-36	3.0	42'	22'5"		
MW-37	3.0	39'3"	17'1"		
MW-40	3.0	29'7"	15'2"		
MW-41	3.0	77'	57'7"		
MW-51	3.0	65'5"	49'1"		
MW-69	3.0	50'4"	0'2"		
MW-71	6.0	61'9"	54'1"		
MW-73	2.0	28'	14'1"		VZ-4
MW-74	3.0	33'	24'5"		
VZ-1	2.0	27'	5'2"		PGI-8
VZ-2	2.0	38'8"	6'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	14'1"		MW-73
VZ-5	2.0	32'6"	16'7"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'1"		
MH-69	2.0	28'1"	0'2"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
Box 1737 Eunice, New Mexico 88231

1001 6th Street P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

12/11/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'0"		
MW-36	3.0	42'	22'5"		
MW-37	3.0	39'3"	17'2"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'2"		
MW-51	3.0	65'5"	49'2"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	54'2"		
MW-73	2.0	28'	14'3"		VZ-4
MW-74	3.0	33'	24'6"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	14'3"		MW-73
VZ-5	2.0	32'6"	16'8"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'1"		
MH-69	2.0	28'1"	0'1"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com
www.sundanceservices.net
www.sundanceservices.org

MONITOR WELLS

DATE:

12/12/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'0"		
MW-36	3.0	42'	22'6"		
MW-37	3.0	39'3"	17'7"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'3"		
MW-51	3.0	65'5"	49'3"		
MW-69	3.0	50'4"	0'2"		
MW-71	6.0	61'9"	54'3"		
MW-73	2.0	28'	14'2"		VZ-4
MW-74	3.0	33'	24'7"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	64'2"		MW-73
VZ-5	2.0	32'6"	16'9"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'3"		
MH-69	2.0	28'1"	0'0"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231

1001 6th Street P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

12/13/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'0"		
MW-36	3.0	42'	22'6"		
MW-37	3.0	39'3"	17'2"		
MW-40	3.0	29'7"	15'2"		
MW-41	3.0	77'	57'1"		
MW-51	3.0	65'5"	49'1"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	54'2"		
MW-73	2.0	28'	14'1"		VZ-4
MW-74	3.0	33'	24'8"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	14'1"		MW-73
VZ-5	2.0	32'6"	16'8"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'1"		
MH-69	2.0	28'1"	0'1"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590

Box 1737 Eunice, New Mexico 88231

1001 6th Street P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

12/14/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'0"		
MW-36	3.0	42'	22'1"		
MW-37	3.0	39'3"	17'1"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'2"		
MW-51	3.0	65'5"	49'2"		
MW-69	3.0	50'4"	0'2"		
MW-71	6.0	61'9"	54'1"		
MW-73	2.0	28'	13'9"		VZ-4
MW-74	3.0	33'	24'9"		
VZ-1	2.0	27'	5'2"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	13'9"		MW-73
VZ-5	2.0	32'6"	16'9"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'7"		
MH-69	2.0	28'1"	0'1"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
Box 1737 Eunice, New Mexico 88231

1001 6th Street P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

12/15/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'0"		
MW-36	3.0	42'	22'1"		
MW-37	3.0	39'3"	17'3"		
MW-40	3.0	29'7"	15'2"		
MW-41	3.0	77'	57'1"		
MW-51	3.0	65'5"	49'2"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	54'2"		
MW-73	2.0	28'	14'1"		VZ-4
MW-74	3.0	33'	25'2"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	14'1"		MW-73
VZ-5	2.0	32'6"	16'8"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'1"		
MH-69	2.0	28'1"	0'2"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590

1001 6th Street P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net


www.sundanceservice

MONITOR WELLS

DATE:

12/16/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'0"		
MW-36	3.0	42'	22'3"		
MW-37	3.0	39'3"	17'2"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'1"		
MW-51	3.0	65'5"	49'1"		
MW-69	3.0	50'4"	0'2"		
MW-71	6.0	61'9"	54'1"		
MW-73	2.0	28'	14'2"		VZ-4
MW-74	3.0	33'	25'1"		
VZ-1	2.0	27'	5'0"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	14'2"		MW-73
VZ-5	2.0	32'6"	16'8"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'1"		
MH-69	2.0	28'1"	0'1"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590 1001 6th Street P.O.
 Box 1737 Eunice, New Mexico 88231
PARABO DISPOSAL FACILITY
www.sundanceservices.com www.sundanceservices.net www.sundanceservices.org

MONITOR WELLS

DATE:

12/17/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16' 5"	0' 0"		
MW-36	3.0	42'	22' 4"		
MW-37	3.0	39' 3"	17' 1"		
MW-40	3.0	29' 7"	15' 2"		
MW-41	3.0	77'	57' 1"		
MW-51	3.0	65' 5"	49' 2"		
MW-69	3.0	50' 4"	0' 1"		
MW-71	6.0	61' 9"	54' 2"		
MW-73	2.0	28'	14' 1"		VZ-4
MW-74	3.0	33'	25' 3"		
VZ-1	2.0	27'	5' 0"		PGI-8
VZ-2	2.0	38' 8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	14' 1"		MW-73
VZ-5	2.0	32' 6"	16' 9"		
VZ-6	2.0	26' 3"	0' 0"		
VZ-7	2.0	49' 8"	22' 1"		
MH-69	2.0	28' 1"	0' 2"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590 1001 6th Street P.O.
 Box 1737 Eunice, New Mexico 88231
 PARABO DISPOSAL FACILITY
www.sundanceservices.com www.sundanceservices.net www.sundanceservices.org

MONITOR WELLS

DATE:

12/18/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'0"		
MW-36	3.0	42'	22'3"		
MW-37	3.0	39'3"	17'1"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'2"		
MW-51	3.0	65'5"	44'2"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	54'1"		
MW-73	2.0	28'	14'2"		VZ-4
MW-74	3.0	33'	25'6"		
VZ-1	2.0	27'	5'2"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	14'2"		MW-73
VZ-5	2.0	32'6"	16'8"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'3"		
MH-69	2.0	28'1"	0'1"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
Box 1737 Eunice, New Mexico 88231

1001 6th Street P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com www.sundanceservices.net www.sundanceservices.org

MONITOR WELLS

DATE:

12/19/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'0"		
MW-36	3.0	42'	22'11"		
MW-37	3.0	39'3"	17'2"		
MW-40	3.0	29'7"	15'2"		
MW-41	3.0	77'	57'11"		
MW-51	3.0	65'5"	49'3"		
MW-69	3.0	50'4"	0'2"		
MW-71	6.0	61'9"	54'2"		
MW-73	2.0	28'	14'11"		VZ-4
MW-74	3.0	33'	25'7"		
VZ-1	2.0	27'	5'7"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	14'11"		MW-73
VZ-5	2.0	32'6"	16'8"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'11"		
MH-69	2.0	28'1"	0'1"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590 1001 6th Street P.O.
 Box 1737 Eunice, New Mexico 88231
 PARABO DISPOSAL FACILITY
www.sundanceservices.com www.sundanceservices.net www.sundanceservices.org

MONITOR WELLS

DATE:

12/20/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16' 5"	0' 1"		
MW-36	3.0	42'	22' 2"		
MW-37	3.0	39' 3"	17' 1"		
MW-40	3.0	29' 7"	15' 1"		
MW-41	3.0	77'	57' 2"		
MW-51	3.0	65' 5"	49' 2"		
MW-69	3.0	50' 4"	0' 1"		
MW-71	6.0	61' 9"	54' 1"		
MW-73	2.0	28'	14' 2"		VZ-4
MW-74	3.0	33'	25' 9"		
VZ-1	2.0	27'	5' 2"		PGI-8
VZ-2	2.0	38' 8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	14' 2"		MW-73
VZ-5	2.0	32' 6"	16' 8"		
VZ-6	2.0	26' 3"	0' 0"		
VZ-7	2.0	49' 8"	22' 1"		
MH-69	2.0	28' 1"	0' 2"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
Box 1737 Eunice, New Mexico 88231

1001 6th Street P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

12/21/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16' 5"	0' 2"		
MW-36	3.0	42'	22' 4"		
MW-37	3.0	39' 3"	17' 4"		
MW-40	3.0	29' 7"	15' 1"		
MW-41	3.0	77'	57' 8"		
MW-51	3.0	65' 5"	49' 3"		
MW-69	3.0	50' 4"	0' 1"		
MW-71	6.0	61' 9"	54' 2"		
MW-73	2.0	28'	14' 3"		VZ-4
MW-74	3.0	33'	26' 1"		
VZ-1	2.0	27'	5' 1"		PGI-8
VZ-2	2.0	38' 8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	14' 3"		MW-73
VZ-5	2.0	32' 6"	16' 9"		
VZ-6	2.0	26' 3"	0' 0"		
VZ-7	2.0	49' 8"	22' 1"		
MH-69	2.0	28' 1"	0' 1"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590

1001 6th Street P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

12/22/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0' 1"		
MW-36	3.0	42'	22' 3"		
MW-37	3.0	39'3"	17' 1"		
MW-40	3.0	29'7"	15' 2"		
MW-41	3.0	77'	57' 6"		
MW-51	3.0	65'5"	50' 1"		
MW-69	3.0	50'4"	0' 1"		
MW-71	6.0	61'9"	54' 3"		
MW-73	2.0	28'	14' 1"		VZ-4
MW-74	3.0	33'	26' 3"		
VZ-1	2.0	27'	5' 2"		PGI-8
VZ-2	2.0	38'8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	14' 1"		MW-73
VZ-5	2.0	32'6"	16' 9"		
VZ-6	2.0	26'3"	0' 0"		
VZ-7	2.0	49'8"	22' 2"		
MH-69	2.0	28'1"	0' 0"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
Box 1737 Eunice, New Mexico 88231

1001 6th Street P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

12/23/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'4"		
MW-37	3.0	39'3"	17'2"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	53'5"		
MW-51	3.0	65'5"	50'1"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	54'2"		
MW-73	2.0	28'	14'0"		VZ-4
MW-74	3.0	33'	26'3"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	14'0"		MW-73
VZ-5	2.0	32'6"	16'8"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'1"		
MH-69	2.0	28'1"	0'1"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590

Box 1737 Eunice, New Mexico 88231

1001 6th Street P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

12/24/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0' 1"		
MW-36	3.0	42'	22' 3"		
MW-37	3.0	39'3"	17' 1"		
MW-40	3.0	29'7"	15' 1"		
MW-41	3.0	77'	57' 6"		
MW-51	3.0	65'5"	50' 2"		
MW-69	3.0	50'4"	0' 2"		
MW-71	6.0	61'9"	54' 1"		
MW-73	2.0	28'	14' 3"		VZ-4
MW-74	3.0	33'	26' 6"		
VZ-1	2.0	27'	5' 0"		PGI-8
VZ-2	2.0	38'8"	0' 0"		
VZ-3	2.0	28'	6' 0"		
VZ-4	2.0	28'	14' 3"		MW-73
VZ-5	2.0	32'6"	16' 9"		
VZ-6	2.0	26'3"	0' 0"		
VZ-7	2.0	49'8"	22' 2"		
MH-69	2.0	28'1"	0' 0"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS**

DATE:

12/25/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	6' 1"		
MW-36	3.0	42'	22' 4"		
MW-37	3.0	39'3"	17' 2"		
MW-40	3.0	29'7"	15' 1"		
MW-41	3.0	77'	57' 7"		
MW-51	3.0	65'5"	50' 2"		
MW-69	3.0	50'4"	6' 1"		
MW-71	6.0	61'9"	54' 2"		
MW-73	2.0	28'	14' 2"		VZ-4
MW-74	3.0	33'	26' 8"		
VZ-1	2.0	27'	5' 1"		PGI-8
VZ-2	2.0	38'8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	14' 2"		MW-73
VZ-5	2.0	32'6"	16' 8"		
VZ-6	2.0	26'3"	0' 0"		
VZ-7	2.0	49'8"	22' 2"		
MH-69	2.0	28'1"	0' 0"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS****DATE:**

12/26/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0' 2"		
MW-36	3.0	42'	22' 3"		
MW-37	3.0	39'3"	17' 1"		
MW-40	3.0	29'7"	15' 2"		
MW-41	3.0	77'	57' 6"		
MW-51	3.0	65'5"	50' 1"		
MW-69	3.0	50'4"	0' 2"		
MW-71	6.0	61'9"	54' 1"		
MW-73	2.0	28'	14' 2"		VZ-4
MW-74	3.0	33'	26' 9"		
VZ-1	2.0	27'	5' 2"		PGI-8
VZ-2	2.0	38'8"	0' 6"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	14' 2"		MW-73
VZ-5	2.0	32'6"	16' 9"		
VZ-6	2.0	26'3"	0' 0"		
VZ-7	2.0	49'8"	22' 3"		
MH-69	2.0	28'1"	0' 1"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590

1001 6th Street P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS**

DATE:

12/27/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16' 5"	0' 1"		
MW-36	3.0	42'	22' 1"		
MW-37	3.0	39' 3"	17' 2"		
MW-40	3.0	29' 7"	15' 1"		
MW-41	3.0	77'	57' 5"		
MW-51	3.0	65' 5"	50' 2"		
MW-69	3.0	50' 4"	0' 1"		
MW-71	6.0	61' 9"	54' 2"		
MW-73	2.0	28'	14' 1"		VZ-4
MW-74	3.0	33'	27' 2"		
VZ-1	2.0	27'	5' 0"		PGI-8
VZ-2	2.0	38' 8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	14' 1"		MW-73
VZ-5	2.0	32' 6"	16' 9"		
VZ-6	2.0	26' 3"	0' 0"		
VZ-7	2.0	49' 8"	22' 1"		
MH-69	2.0	28' 1"	0' 1"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590 1001 6th Street P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS**

DATE:

12/28/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	6'2"		
MW-36	3.0	42'	22'2"		
MW-37	3.0	39'3"	17'1"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'6"		
MW-51	3.0	65'5"	50'1"		
MW-69	3.0	50'4"	0'2"		
MW-71	6.0	61'9"	54'1"		
MW-73	2.0	28'	14'3"		VZ-4
MW-74	3.0	33'	27'6"		
VZ-1	2.0	27'	4'9"		PGI-8
VZ-2	2.0	38'8"	0'0'		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	14'3'		MW-73
VZ-5	2.0	32'6"	16'9"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'1"		
MH-69	2.0	28'1"	0'1"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS**

DATE:

12/29/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16' 5"	0' 1"		
MW-36	3.0	42'	22' 1"		
MW-37	3.0	39' 3"	17' 0"		
MW-40	3.0	29' 7"	15' 2"		
MW-41	3.0	77'	57' 7"		
MW-51	3.0	65' 5"	50' 1"		
MW-69	3.0	50' 4"	0' 1"		
MW-71	6.0	61' 9"	54' 2"		
MW-73	2.0	28'	14' 1"		VZ-4
MW-74	3.0	33'	27' 9"		
VZ-1	2.0	27'	4' 9"		PGI-8
VZ-2	2.0	38' 8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	14' 1"		MW-73
VZ-5	2.0	32' 6"	16' 8"		
VZ-6	2.0	26' 3"	0' 0"		
VZ-7	2.0	49' 8"	27' 1"		
MH-69	2.0	28' 1"	0' 0"		

**SUNDANCE SERVICES WEST, INC.****ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS**

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARADO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS**

DATE:

12/30/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	6'1"		
MW-36	3.0	42'	22'3"		
MW-37	3.0	39'3"	17'1"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'2"		
MW-51	3.0	65'5"	50'1"		
MW-69	3.0	50'4"	0'2"		
MW-71	6.0	61'9"	54'1"		
MW-73	2.0	28'	14'3"		VZ-4
MW-74	3.0	33'	27'9"		
VZ-1	2.0	27'	4'8"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	14'3"		MW-73
VZ-5	2.0	32'6"	16'8"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	22'1"		
MH-69	2.0	28'1"	0'1"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231

1001 6th Street P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org

MONITOR WELLS

DATE:

12/31/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16' 5"	0' 1"		
MW-36	3.0	42'	22' 2"		
MW-37	3.0	39' 3"	17' 1"		
MW-40	3.0	29' 7"	15' 3"		
MW-41	3.0	77'	57' 2"		
MW-51	3.0	65' 5"	50' 2"		
MW-69	3.0	50' 4"	0' 1"		
MW-71	6.0	61' 9"	54' 2"		
MW-73	2.0	28'	14' 1"		VZ-4
MW-74	3.0	33'	28' 4"	23' 1"	
VZ-1	2.0	27'	4' 9"		PGI-8
VZ-2	2.0	38' 8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	14' 1"		MW-73
VZ-5	2.0	32' 6"	16' 9"		
VZ-6	2.0	26' 3"	0' 0"		
VZ-7	2.0	49' 8"	22' 2"		
MH-69	2.0	28' 1"	0' 1"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511
1001 6th Street

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 373-3941
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 12/1/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 575-394-
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

12/2/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 573-394
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

12/3/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES	ROLL-OFF TRUCKS	DUMP TRUCKS	VACUUM TRUCKS
1	1	1	1
2	2	2	2
3	3	3	3
4	4	4	4
5	5	5	5
6	6	6	6
7	7	7	7
8	8	8	8
9	9	9	9
10	10	10	10
11	11	11	11
12	12	12	12
13	13	13	13
14	14	14	14
15	15	15	15
16	16	16	16
17	17	17	17
18	18	18	18
19	19	19	19
20	20	20	20
21	21	21	21
22	22	22	22
23	23	23	23
24	24	24	24
25	25	25	25
26	26	26	26
27	27	27	27
28	28	28	28
29	29	29	29
30	30	30	30
31	31	31	31
32	32	32	32
33	33	33	33
34	34	34	34
35	35	35	35
36	36	36	36
37	37	37	37
38	38	38	38
39	39	39	39
40	40	40	40
41	41	41	41
42	42	42	42
43	43	43	43
44	44	44	44
45	45	45	45
46	46	46	46
47	47	47	47
48	48	48	48
49	49	49	49
50	50	50	50
51	51	51	51
52	52	52	52
53	53	53	53
54	54	54	54
55	55	55	55
56	56	56	56
57	57	57	57
58	58	58	58
59	59	59	59
60	60	60	60
61	61	61	61
62	62	62	62
63	63	63	63
64	64	64	64
65	65	65	65
66	66	66	66
67	67	67	67
68	68	68	68
69	69	69	69
70	70	70	70
71	71	71	71
72	72	72	72
73	73	73	73
74	74	74	74
75	75	75	75
76	76	76	76
77	77	77	77
78	78	78	78
79	79	79	79
80	80	80	80
81	81	81	81
82	82	82	82
83	83	83	83
84	84	84	84
85	85	85	85
86	86	86	86
87	87	87	87
88	88	88	88
89	89	89	89
90	90	90	90
91	91	91	91
92	92	92	92
93	93	93	93
94	94	94	94
95	95	95	95
96	96	96	96
97	97	97	97
98	98	98	98
99	99	99	99
100	100	100	100

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

12 14 25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 573-394
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 12/5/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 12/6/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 573-554
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

12/7/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 373-394
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

12/8/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

12/19/23

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 373-3941
1001 6th Street

P.O. Box 1737

Eupice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundancerservices.org

MONITOR WELLS

DATE:

12 | 10 | 25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 373-394
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 12/11/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212.

Fax: 575-394-2590

Office: 575-594-
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

12/12/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 12/13/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 373-3941
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

12 14 25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 373-3941
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88331

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.gundance.org/icas.asp

MONITOR WELLS

DATE: 17 / 15 / 25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

17/16/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 575-394
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

12 / 16 / 25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 575-394-
1001 6th Street

Plant Office
P.O. Box 1737

5-394-3212 Fax: 575-394-
Euplice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundancerevivals.org

MONITOR WELLS

DATE:

12/17/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88331

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 6/18/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 12/19/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

12/20/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 373-3941
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 10/21/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

12/22/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 12/23/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 12/24/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: _____

12/25/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 12/26/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 12/27/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: _____

12 | 28 | 25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 373-3941
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE. 12/29/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 373-394
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceeservices.org

MONITOR WELLS

DATE: 12/30/25

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 12/31/25

[illegible]

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE: 12/11/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'7"		
WS-2	Poly	14'7"	1'4"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	2'6"		
WS-5	Poly	23'6"	13'8"		
WS-6	Poly	8'0"	0'9"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

12/2/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'5"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'7"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

12/3/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'7"		
WS-2	Poly	14'7"	1'4"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	2'6"		
WS-5	Poly	23'6"	13'8"		
WS-6	Poly	8'0"	0'9"		

**SUNDANCE SERVICES WEST, INC.****ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS**

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

12/4/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'5"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'8"		

SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

12/5/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1'4"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	2'6"		
WS-5	Poly	23'6"	13'8"		
WS-6	Poly	8'0"	0'9"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARADO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

12/6/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'7"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'8"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

12/7/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1'5"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	2'8"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'9"		

SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

12/8/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'6"		
WS-5	Poly	23'6"	13'8"		
WS-6	Poly	8'0"	0'9"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231

1001 6th Street P.O.

PARABO DISPOSAL FACILITY
www.sundanceservices.com www.sundanceservices.net www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

12/9/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1'4"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'7"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	6'8"		

SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

12/10/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'7"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	2'9"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'9"		

SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

12/11/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'6"		
WS-5	Poly	23'6"	13'8"		
WS-6	Poly	8'0"	0'7"		

**SUNDANCE SERVICES WEST, INC.****ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS**

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE: 12/12/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'7"		
WS-2	Poly	14'7"	1'4"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	2'6"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'8"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590

1001 6th Street P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

12/13/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'7"		
WS-5	Poly	23'6"	13'8"		
WS-6	Poly	8'0"	0'9"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590

Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE: 12/14/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1'4"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	2'8"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'8"		

SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE: 12/15/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'6"		
WS-5	Poly	23'6"	13'7"		
WS-6	Poly	8'0"	0'7"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590

Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

12/16/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1'2"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	2'3"		
WS-5	Poly	23'6"	13'8"		
WS-6	Poly	8'0"	0'8"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231

1001 6th Street P.O.**PARABO DISPOSAL FACILITY**www.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

12/17/2025

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'3"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'7"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

12/18/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	21'9"		
WS-2	Poly	14'7"	1'2"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'4"		
WS-5	Poly	23'6"	13'8"		
WS-6	Poly	8'0"	0'9"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

12/19/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'3"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'8"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

12/20/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'7"		
WS-2	Poly	14'7"	1'2"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'4"		
WS-5	Poly	23'6"	13'8"		
WS-6	Poly	8'0"	0'9"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

12/21/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	2'3"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'8"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590

Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

12/22/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'4"		
WS-5	Poly	23'6"	13'8"		
WS-6	Poly	8'0"	0'7"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

12/23/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'4"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	2'3"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'8"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
Box 1737 Eunice, New Mexico 88231

1001 6th Street P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

12/24/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'7"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'4"		
WS-5	Poly	23'6"	13'8"		
WS-6	Poly	8'0"	0'7"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

12/25/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	2'3"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'8"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2580

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

12/26/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'2"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	2'3"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'6"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE: 12/27/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'4"		
WS-5	Poly	23'6"	14'1"		
WS-6	Poly	8'0"	0'8"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

12/28/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'4"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	2'3"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'9"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

www.sundanceservices.com
www.sundanceservices.net

PARABO DISPOSAL FACILITY

www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE: 12/29/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'7"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'7"		
WS-4	Poly	14'7"	2'1"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'8"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231

1001 6th Street P.O.**PARABO DISPOSAL FACILITY**www.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE: 12/30/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'4"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	2'3"		
WS-5	Poly	23'6"	13'8"		
WS-6	Poly	8'0"	0'9"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITYwww.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

12/31/25

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'7"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'4"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'8"		

Daily Inspection Form
Sundance West

Date:

11/1/26

Print Name:

Daisy Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)	☒					D	☒	
Dust Control (Vol. II - Sec. 4.3 - Pg. 19)						D	☒	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)						D	☒	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)						D	☒	
Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)						D	☒	
Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)						D	☒	
Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)						D	☒	
Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)						D	☒	
Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)						D	☒	
Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)						D	☒	
Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-O2 (Vol. II - Sec. 3 - Pg. 131)						D	☒	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg. 223)						D	☒	
Pond levels three-foot free board						D	☒	

Daily Inspection Form
Sundance West

Date:

11/2/26

Print Name:

Daisy Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)						D	✓	
Dust Control (Vol. II - Sec. 4.3 - Pg. 19)						D	✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)						D	✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)						D	✓	
Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)						D	✓	
Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)						D	✓	
Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)						D	✓	
Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)						D	✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)						D	✓	
Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)						D	✓	
Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-O2 (Vol. II - Sec. 3 - Pg. 131)						D	✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg. 223)						D	✓	
Pond levels three-foot free board						D	✓	

Daily Inspection Form
Sundance West

Date:

11/3/26

Print Name:

Deysi Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
☒					Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)	D ✓	
					Dust Control (Vol. II - Sec. 4.3 - Pg. 19)	D ✓	
					Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)	D ✓	
					Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)	D ✓	
					Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)	D ✓	
					Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)	D ✓	
					Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)	D ✓	
					Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)	D ✓	
					Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)	D ✓	
					Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)	D ✓	
					Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-O2 (Vol. II - Sec. 3 - Pg. 131)	D ✓	
					Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2 - Pg. 223)	D ✓	
					Pond levels three-foot free board	D ✓	

Daily Inspection Form
Sundance West

Date:

11/4/26

Print Name:

Doris Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
☒	☐	☐	☐	☐	Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	D ✓	
☐	☐	☐	☐	☐	Dust Control (Vol. II - Sec.4.3 - Pg.19)	D ✓	
☐	☐	☐	☐	☐	Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)	D ✓	
☐	☐	☐	☐	☐	Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)	D ✓	
☐	☐	☐	☐	☐	Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)	D ✓	
☐	☐	☐	☐	☐	Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)	D ✓	
☐	☐	☐	☐	☐	Waste Screening and Forms (Vol. II - Sec 2- Pg.94)	D ✓	
☐	☐	☐	☐	☐	Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)	D ✓	
☐	☐	☐	☐	☐	Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)	D ✓	
☐	☐	☐	☐	☐	Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)	D ✓	
☐	☐	☐	☐	☐	Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)	D ✓	
☐	☐	☐	☐	☐	Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)	D ✓	
☐	☐	☐	☐	☐	Pond levels three-foot free board	D ✓	
☐	☐	☐	☐	☐			
☐	☐	☐	☐	☐			

Daily Inspection Form
Sundance West

Date:

11/5/26

Print Name:

Deyan Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)	☒					D	☒	
Dust Control (Vol. II - Sec. 4.3 - Pg. 19)						D	☒	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)						D	☒	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)						D	☒	
Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)						D	☒	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg. 94)						D	☒	
Waste Screening and Forms (Vol. II - Sec 2- Pg. 94)						D	☒	
Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)						D	☒	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg. 92)						D	☒	
Facility H2S Monitoring (Vol. II - Sec 3- Pg. 127)						D	☒	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg. 130)-O2 (Vol. II- Sec 3- Pg. 131)						D	☒	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg. 223)						D	☒	
Pond levels three-foot free board						D	☒	

Daily Inspection Form
Sundance West

Date:

11/6/26

Print Name:

Signature:

Debra Romero

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
☒					Item		
					Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)	D ✓	
					Dust Control (Vol. II - Sec. 4.3 - Pg. 19)	D ✓	
					Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)	D ✓	
					Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)	D ✓	
					Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)	D ✓	
					Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)	D ✓	
					Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)	D ✓	
					Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)	D ✓	
					Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)	D ✓	
					Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)	D ✓	
					Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-O2 (Vol. II - Sec. 3 - Pg. 131)	D ✓	
					Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg. 223)	D ✓	
					Pond levels three-foot free board	D ✓	

Daily Inspection Form
Sundance West

Date:

1/7/28

Print Name:

Dustin Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
☒					Item		
					Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	☒	
					Dust Control (Vol. II - Sec.4.3 - Pg.19)	☒	
					Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)	☒	
					Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)	☒	
					Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)	☒	
					Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)	☒	
					Waste Screening and Forms (Vol. II - Sec 2- Pg.94)	☒	
					Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)	☒	
					Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)	☒	
					Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)	☒	
					Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)	☒	
					Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)	☒	
					Pond levels three-foot free board	☒	

[illegible]

1/8/26

Devi Korneo

Signature:

[illegible]

Daily Inspection Form
Sundance West

Date:

1/9/26

Date

Print Name:

Daryl Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
Item							
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)					D	✓	
Dust Control (Vol. II - Sec.4.3 - Pg.19)					D	✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)					D	✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)					D	✓	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)					D	✓	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)					D	✓	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)					D	✓	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)					D	✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)					D	✓	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)					D	✓	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)					D	✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)					D	✓	
Pond levels three-foot free board					D	✓	

Daily Inspection Form
Sundance West

To Insp. with
Sundance WA

Date:

1/10/26

Print Name:

Dennis Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
Item							
Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)					D	✓	
Dust Control (Vol. II - Sec. 4.3 - Pg. 19)					D	✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)					D	✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)					D	✓	
Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)					D	✓	
Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)					D	✓	
Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)					D	✓	
Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)					D	✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)					D	✓	
Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)					D	✓	
Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-02 (Vol. II - Sec. 3 - Pg. 131)					D	✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2 - Pg. 223)					D	✓	
Pond levels three-foot free board					D	✓	

Daily Inspection Form
Sundance West

By:
Date:

Date:

11/1/26

Print Name:

Devin Pomeroy

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)	☒					D	✓	
Dust Control (Vol. II - Sec. 4.3 - Pg. 19)						D	✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)						D	✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)						D	✓	
Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)						D	✓	
Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)						D	✓	
Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)						D	✓	
Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)						D	✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)						D	✓	
Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)						D	✓	
Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-O2 (Vol. II - Sec. 3 - Pg. 131)						D	✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2 - Pg. 223)						D	✓	
Pond levels three-foot free board						D	✓	

Daily Inspection Form
Sundance WestCity Inspector
Sundance West

Date:

11/2/26

Print Name:

Deyi Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	☒					D ✓	
Dust Control (Vol. II - Sec.4.3 - Pg.19)	☒					D ✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)	☒					D ✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)	☒					D ✓	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)	☒					D ✓	
Vehicle Monitoring (H2S) (Vol. II - Sec.2- Pg.94)	☒					D ✓	
Waste Screening and Forms (Vol. II - Sec.2- Pg.94)	☒					D ✓	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)	☒					D ✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec.2- Pg.92)	☒					D ✓	
Facility H2S Monitoring (Vol. II - Sec.3- Pg.127)	☒					D ✓	
Evaporation Pond Tests-pH (Vol. II- Sec.3- Pg.130)-O2 (Vol. II- Sec.3- Pg.131)	☒					D ✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)	☒					D ✓	
Pond levels three-foot free board	☒					D ✓	

Daily Inspection Form
Sundance West

Date:

11/13/26

Print Name:

Dustin Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)						D ✓	
Dust Control (Vol. II - Sec. 4.3 - Pg. 19)						D ✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)						D ✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)						D ✓	
Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)						D ✓	
Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)						D ✓	
Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)						D ✓	
Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)						D ✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)						D ✓	
Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)						D ✓	
Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-O2 (Vol. II - Sec. 3 - Pg. 131)						D ✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg. 223)						D ✓	
Pond levels three-foot free board						D ✓	

Daily Inspection Form
Sundance WestDate: 11/14/26
Print Name: Densi Romero
Signature: _____

Date:

Others: _____

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)						✓	
Dust Control (Vol. II - Sec. 4.3 - Pg. 19)						✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)						✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)						✓	
Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)						✓	
Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)						✓	
Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)						✓	
Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)						✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)						✓	
Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)						✓	
Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-O2 (Vol. II - Sec. 3 - Pg. 131)						✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2 - Pg. 223)						✓	
Pond levels three-foot free board						✓	

Daily Inspection Form
Sundance West

Date:

11/5/26

Print Name:

Daisy Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
☒					Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)	☒	D
					Dust Control (Vol. II - Sec. 4.3 - Pg. 19)	☒	D
					Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)	☒	D
					Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)	☒	D
					Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)	☒	D
					Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)	☒	D
					Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)	☒	D
					Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)	☒	D
					Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)	☒	D
					Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)	☒	D
					Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-O2 (Vol. II - Sec. 3 - Pg. 131)	☒	D
					Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg. 223)	☒	D
					Pond levels three-foot free board	☒	D

Daily Inspection Form
Sundance West

Date:

11/6/26

Print Name:

Deysi Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
☒					Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)	✓	
☒					Dust Control (Vol. II - Sec. 4.3 - Pg. 19)	✓	
☒					Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)	✓	
☒					Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)	✓	
☒					Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)	✓	
☒					Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)	✓	
☒					Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)	✓	
☒					Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)	✓	
☒					Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)	✓	
☒					Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)	✓	
☒					Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-O2 (Vol. II - Sec. 3 - Pg. 131)	✓	
☒					Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2 - Pg. 223)	✓	
☒					Pond levels three-foot free board	✓	

Daily Inspection Form
Sundance West

Date:

11/17/26

Print Name:

Dawn Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)	☒					D	
Dust Control (Vol. II - Sec. 4.3 - Pg. 19)	☒					D	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)	☒					D	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)	☒					D	
Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)	☒					D	
Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)	☒					D	
Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)	☒					D	
Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)	☒					D	
Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)	☒					D	
Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)	☒					D	
Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-O2 (Vol. II - Sec. 3 - Pg. 131)	☒					D	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg. 223)	☒					D	
Pond levels three-foot free board							

Daily Inspection Form
Sundance West

Date:

11/18/26

Print Name:

Deyan Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)	☒					D	☒	
Dust Control (Vol. II - Sec. 4.3 - Pg. 19)						D	☒	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)						D	☒	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)						D	☒	
Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)						D	☒	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg. 94)						D	☒	
Waste Screening and Forms (Vol. II - Sec 2- Pg. 94)						D	☒	
Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)						D	☒	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg. 92)						D	☒	
Facility H2S Monitoring (Vol. II - Sec 3- Pg. 127)						D	☒	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg. 130)-O2 (Vol. II- Sec 3- Pg. 131)						D	☒	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg. 223)						D	☒	
Pond levels three-foot free board						D	☒	

Daily Inspection Form
Sundance West

Date:

11/19/26

Print Name:

Deyni Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	☒					D	☒	
Dust Control (Vol. II - Sec.4.3 - Pg.19)	☒					D	☒	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)	☒					D	☒	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)	☒					D	☒	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)	☒					D	☒	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)	☒					D	☒	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)	☒					D	☒	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)	☒					D	☒	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)	☒					D	☒	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)	☒					D	☒	
Evaporation Pond Tests-pH (Vol. II - Sec 3- Pg.130)-O2 (Vol. II - Sec 3- Pg.131)	☒					D	☒	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)	☒					D	☒	
Pond levels three-foot free board	☒					D	☒	

Daily Inspection Form
Sundance West

Date:

1/26/26

Print Name:

Deysi Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
Item							
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)					D	✓	
Dust Control (Vol. II - Sec.4.3 - Pg.19)					D	✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)					D	✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)					D	✓	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)					D	✓	
Vehicle Monitoring (H2S) (Vol. II - Sec.2 - Pg.94)					D	✓	
Waste Screening and Forms (Vol. II - Sec.2 - Pg.94)					D	✓	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)					D	✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec.2 - Pg.92)					D	✓	
Facility H2S Monitoring (Vol. II - Sec.3 - Pg.127)					D	✓	
Evaporation Pond Tests-pH (Vol. II - Sec.3 - Pg.130)-O2 (Vol. II - Sec.3 - Pg.131)					D	✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2 - Pg.223)					D	✓	
Pond levels three-foot free board					D	✓	

Daily Inspection Form
Sundance West

Date:

9/21/26

Print Name:

Dewey Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
☒	☐	☐	☐	☐	D	☒	
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)					D	☒	
Dust Control (Vol. II - Sec.4.3 - Pg.19)					D	☒	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)					D	☒	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)					D	☒	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)					D	☒	
Vehicle Monitoring (H2S) (Vol. II - Sec.2 - Pg.94)					D	☒	
Waste Screening and Forms (Vol. II - Sec.2 - Pg.94)					D	☒	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)					D	☒	
Temporary Parking Inspection for Leaks (Vol. II - Sec.2 - Pg.92)					D	☒	
Facility H2S Monitoring (Vol. II - Sec.3 - Pg.127)					D	☒	
Evaporation Pond Tests-pH (Vol. II - Sec.3 - Pg.130)-O2 (Vol. II - Sec.3 - Pg.131)					D	☒	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2 - Pg.223)					D	☒	
Pond levels three-foot free board					D	☒	

Daily Inspection Form
Sundance WestDaily Inc. 11/22/26
Sund: Deysi Romero

Date:

Print Name:

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
Item							
Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)					D	✓	
Dust Control (Vol. II - Sec. 4.3 - Pg. 19)					D	✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)					D	✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5.5 - Pg. 27)					D	✓	
Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)					D	✓	
Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)					D	✓	
Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)					D	✓	
Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)					D	✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)					D	✓	
Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)					D	✓	
Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-O2 (Vol. II - Sec. 3 - Pg. 131)					D	✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg. 223)					D	✓	
Pond levels three-foot free board					D	✓	

Daily Inspection Form
Sundance West

Date:

1/23/26

Print Name:

Devi Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
Item							
Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)					D	✓	
Dust Control (Vol. II - Sec. 4.3 - Pg. 19)					D	✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)					D	✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)					D	✓	
Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)					D	✓	
Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)					D	✓	
Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)					D	✓	
Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)					D	✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)					D	✓	
Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)					D	✓	
Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-O2 (Vol. II - Sec. 3 - Pg. 131)					D	✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2 - Pg. 223)					D	✓	
Pond levels three-foot free board					D	✓	

Daily Inspection Form
Sundance West

Date:

11/24/26

Print Name:

Deysi Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
☒					D	☒	
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)					D	☒	
Dust Control (Vol. II - Sec.4.3 - Pg.19)					D	☒	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)					D	☒	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)					D	☒	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)					D	☒	
Vehicle Monitoring (H2S) (Vol. II - Sec.2 - Pg.94)					D	☒	
Waste Screening and Forms (Vol. II - Sec.2 - Pg.94)					D	☒	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)					D	☒	
Temporary Parking Inspection for Leaks (Vol. II - Sec.2 - Pg.92)					D	☒	
Facility H2S Monitoring (Vol. II - Sec.3 - Pg.127)					D	☒	
Evaporation Pond Tests-pH (Vol. II - Sec.3-Pg.130)-O2 (Vol. II- Sec.3- Pg.131)					D	☒	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)					D	☒	
Pond levels three-foot free board					D	☒	

Signature:

Deus, Rex

Others:

11/5/26

TYPE OF INSPECTION				
Daily	Weekly	Monthly	Quarterly	Annual
Item				
Vehicle Screening (H2S) (Vol. II - Sec.4:2 - Pg.19)				
Dust Control (Vol. II - Sec.4:3 - Pg.19)				
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5:4 - Pg.24)				
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)				
Daily Cover Required (Vol. II - Sec.5:4 - Pg.27)				
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)				
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)				
Mechanical Evaporation System (Vol. II - Sec.7:3:3 - Pg.44)				
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)				
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)				
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)				
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)				
Pond levels three-foot free board				

Daily Inspection Form
Sundance West

Date:

11/26/26

Print Name:

Deyan Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
Item							
Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)					D	✓	
Dust Control (Vol. II - Sec. 4.3 - Pg. 19)					D	✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)					D	✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)					D	✓	
Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)					D	✓	
Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)					D	✓	
Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)					D	✓	
Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)					D	✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)					D	✓	
Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)					D	✓	
Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-O2 (Vol. II - Sec. 3 - Pg. 131)					D	✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2 - Pg. 223)					D	✓	
Pond levels three-foot free board					D	✓	

Daily Inspection Form
Sundance WestDaily In.
Sund.Date
Page

Date:

11/27/26

Print Name:

Deysi Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual	Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4:2 - Pg.19)						D ✓	
Dust Control (Vol. II - Sec.4:3 - Pg.19)						D ✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5:4 - Pg.24)						D ✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						D ✓	
Daily Cover Required (Vol. II - Sec.5:4 - Pg.27)						D ✓	
Vehicle Monitoring (H2S) (Vol. II - Sec.2- Pg.94)						D ✓	
Waste Screening and Forms (Vol. II - Sec.2- Pg.94)						D ✓	
Mechanical Evaporation System (Vol. II - Sec.7:3.3 - Pg.44)						D ✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec.2- Pg.92)						D ✓	
Facility H2S Monitoring (Vol. II - Sec.3- Pg.127)						D ✓	
Evaporation Pond Tests-pH (Vol. II- Sec.3- Pg.130)-O2 (Vol. II- Sec.3- Pg.131)						D ✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)						D ✓	
Pond levels three-foot free board						D ✓	

Daily Inspection Form
Sundance West

Date:

11/28/26

Print Name:

Deysi Romero

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
☒					Item		
					Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	☒	
					Dust Control (Vol. II - Sec.4.3 - Pg.19)	☒	
					Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)	☒	
					Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)	☒	
					Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)	☒	
					Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)	☒	
					Waste Screening and Forms (Vol. II - Sec 2- Pg.94)	☒	
					Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)	☒	
					Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)	☒	
					Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)	☒	
					Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)	☒	
					Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)	☒	
					Pond levels three-foot free board	☒	

Daily Inspection Form
Sundance West

Date:

11/29/26

Print Name:

Dennis Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)						D	✓	
Dust Control (Vol. II - Sec.4.3 - Pg.19)						D	✓	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)						D	✓	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)						D	✓	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)						D	✓	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)						D	✓	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)						D	✓	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)						D	✓	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)						D	✓	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)						D	✓	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-O2 (Vol. II- Sec 3- Pg.131)						D	✓	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)						D	✓	
Pond levels three-foot free board						D	✓	

Daily Inspection Form
Sundance West

Date:

11/30/26

Print Name:

Deysi Romero

Others:

Signature:

TYPE OF INSPECTION

Item	Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
Vehicle Screening (H2S) (Vol. II - Sec.4.2 - Pg.19)	☒					D	☒	
Dust Control (Vol. II - Sec.4.3 - Pg.19)	☒					D	☒	
Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec.5.4 - Pg.24)	☒					D	☒	
Landfill Waste Lifts (2-3-FT) (Vol. II - Sec.5 - Pg.27)	☒					D	☒	
Daily Cover Required (Vol. II - Sec.5.4 - Pg.27)	☒					D	☒	
Vehicle Monitoring (H2S) (Vol. II - Sec 2- Pg.94)	☒					D	☒	
Waste Screening and Forms (Vol. II - Sec 2- Pg.94)	☒					D	☒	
Mechanical Evaporation System (Vol. II - Sec.7.3.3 - Pg.44)	☒					D	☒	
Temporary Parking Inspection for Leaks (Vol. II - Sec 2- Pg.92)	☒					D	☒	
Facility H2S Monitoring (Vol. II - Sec 3- Pg.127)	☒					D	☒	
Evaporation Pond Tests-pH (Vol. II- Sec 3- Pg.130)-02 (Vol. II- Sec 3- Pg.131)	☒					D	☒	
Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2- Pg.223)	☒					D	☒	
Pond levels three-foot free board								

Daily Inspection Form
Sundance West

Sundance West
Sundance West

Date:

11/31/26

Print Name:

Drew R. Rando

Others:

Signature:

TYPE OF INSPECTION

Daily	Weekly	Monthly	Quarterly	Annual		Satisfactory	Action Required
☒					Vehicle Screening (H2S) (Vol. II - Sec. 4.2 - Pg. 19)	☒	
					Dust Control (Vol. II - Sec. 4.3 - Pg. 19)	☒	
					Landfill Unloading Area (50-100-FT Wide) (Vol. II - Sec. 5.4 - Pg. 24)	☒	
					Landfill Waste Lifts (2-3-FT) (Vol. II - Sec. 5 - Pg. 27)	☒	
					Daily Cover Required (Vol. II - Sec. 5.4 - Pg. 27)	☒	
					Vehicle Monitoring (H2S) (Vol. II - Sec. 2 - Pg. 94)	☒	
					Waste Screening and Forms (Vol. II - Sec. 2 - Pg. 94)	☒	
					Mechanical Evaporation System (Vol. II - Sec. 7.3.3 - Pg. 44)	☒	
					Temporary Parking Inspection for Leaks (Vol. II - Sec. 2 - Pg. 92)	☒	
					Facility H2S Monitoring (Vol. II - Sec. 3 - Pg. 127)	☒	
					Evaporation Pond Tests-pH (Vol. II - Sec. 3 - Pg. 130)-O2 (Vol. II - Sec. 3 - Pg. 131)	☒	
					Evaporation Pond Oil Inspection (Vol. Section 6-Subsect 2.2 - Pg. 223)	☒	
					Pond levels three-foot free board	☒	

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/1/26

Inspector(s):

Time: 6:50 amDeys Romero**Weather:**Temperature 50 deg. FPrecipitation (last 24 hours) 0 inchesSkies FairWind Speed 9 mphWind Direction W (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
<u>✓</u>	<u>✓</u>	<u>✓</u>	<u>✓</u>	<u>✓</u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u>✓</u>	<u>✓</u>
Pond A-2	60-FT	<u>✓</u>	<u>✓</u>
Pond A-3	60-FT	<u>✓</u>	
Pond A-4	60-FT	<u>✓</u>	<u>✓</u>
Pond A-5	60-FT	<u>✓</u>	<u>✓</u>
Pond B-1	60-FT	<u>✓</u>	<u>✓</u>
Pond B-2	60-FT	<u>✓</u>	
Pond B-3	60-FT	<u>✓</u>	<u>✓</u>
Pond B-4	60-FT	<u>✓</u>	<u>✓</u>
Pond B-5	60-FT	<u>✓</u>	<u>✓</u>

NOTES:

C:\Users\cam\BosAppData\Local\Microsoft\Windows\WinCache\Content\Outlook\ACSMQJV\SWest-II.1-AH II.1.D-EvapPondLeakInspect

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 1/2/26

Inspector(s):

Time: 10:50 amDeysi Romero**Weather:**Temperature 66 deg. FPrecipitation (last 24 hours) 0 inchesSkies Fair / WindyWind Speed 25 mphWind Direction WNW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/3/26

Inspector(s):

Time: 7:50 amDeysi Romero**Weather:**Temperature 46 deg. FPrecipitation (last 24 hours) 0. inchesSkies FAIRWind Speed 10 mphWind Direction NNW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/4/26

Inspector(s):

Time: 8:50 amDouglas Romero**Weather:**Temperature 52 deg. FPrecipitation (last 24 hours) 0 inchesSkies ForWind Speed 12 mphWind Direction S (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 1/5/26

Inspector(s):

Time: 9:50amDrew Romero**Weather:**Temperature 63 deg. FSkies Fair / WindyWind Speed 21 mphWind Direction W (direction blowing from)Precipitation (last 24 hours) 0 inches**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/6/26

Inspector(s):

Time: 10:50amDeysi Romero**Weather:**Temperature 61 deg. FPrecipitation (last 24 hours) 0 inchesSkies FairWind Speed 9 mphWind Direction NW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/7/26

Inspector(s):

Time: 8:50 amDeane Romero**Weather:**Temperature 54 deg. FPrecipitation (last 24 hours) 0 inchesSkies FairWind Speed 7 mphWind Direction SSW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/8/26

Inspector(s):

Time: 9:50 amDeyi Romero**Weather:**Temperature 54 deg. FPrecipitation (last 24 hours) 0 inchesSkies Fair / WindyWind Speed 23 mphWind Direction SW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 1/9/26

Inspector(s):

Time: 7:50 amDeusi Romero**Weather:**Temperature 43 deg. FPrecipitation (last 24 hours) 0 inchesSkies FairWind Speed 17 mphWind Direction SW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/10/26

Inspector(s):

Time: 7:50amDeysi Romero**Weather:**Temperature 27 deg. FPrecipitation (last 24 hours) 0 inchesSkies FairWind Speed 9 mphWind Direction NW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 1/11/26

Inspector(s):

Time: 11:50 amDeusi Romero**Weather:**Temperature 52 deg. FPrecipitation (last 24 hours) 0 inchesSkies FAWWind Speed 6 mphWind Direction ENE (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/2/26

Inspector(s):

Time: 6:50 amDawn Romero**Weather:**Temperature 23 deg. FPrecipitation (last 24 hours) 0 inchesSkies ClearWind Speed 8 mphWind Direction WNW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/13/26

Inspector(s):

Time: 7:50 amDrew Romero**Weather:**Temperature 30 deg. FPrecipitation (last 24 hours) 0 inchesSkies FairWind Speed 3 mphWind Direction W (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/14/26

Inspector(s):

Time: 10:50 amDeysi Romero**Weather:**Temperature 57 deg. FPrecipitation (last 24 hours) 0 inchesSkies Few WindyWind Speed 22 mphWind Direction NNE (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Pond B-3 Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/15/26

Inspector(s):

Time: 11:50 amDeusi Romero**Weather:**Temperature 64 deg. FPrecipitation (last 24 hours) 0 inchesSkies FairWind Speed 13 mphWind Direction SW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/6/25

Inspector(s):

Time: 1:50 pmDeysi Romero**Weather:**Temperature 50 deg. FPrecipitation (last 24 hours) 0 inchesSkies FairWind Speed 0 mphWind Direction NNE (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/7/20

Inspector(s):

Time: 11:50 amDeusi Romero**Weather:**Temperature 37 deg. FPrecipitation (last 24 hours) 0 inchesSkies FairWind Speed 18 mphWind Direction ENE (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/18/26

Inspector(s):

Time: 11:50 amDaryl Romero**Weather:**Temperature 59 deg. FPrecipitation (last 24 hours) 0 inchesSkies FAVWind Speed 10 mphWind Direction WSW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>

NOTES:

Page ____ of ____

Inspector(s):

Deysi Romero

Temperature 41 deg. F

Precipitation (last 24 hours) 0 inches

Skies Fair

Wind Speed 20 mph

Wind Direction NE (direction blowing from)

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

Location	Item			
	Erosion	Vegetation . Established	Vectors	Sample

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT		
Pond A-2	60-FT		
Pond A-3	60-FT		
Pond A-4	60-FT		
Pond A-5	60-FT		
Pond B-1	60-FT		
Pond B-2	60-FT		
Pond B-3	60-FT		
Pond B-4	60-FT		
Pond B-5	60-FT		

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 1/20/26

Inspector(s):

Time: 6:50 amDrew Romero**Weather:**Temperature 19 deg. FPrecipitation (last 24 hours) 0 inchesSkies FairWind Speed 0 mphWind Direction CALM (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 1/21/26

Inspector(s):

Time: 12:50 pmDeusi Romero**Weather:**Temperature 52 deg. FPrecipitation (last 24 hours) 0 inchesSkies FairWind Speed 5 mphWind Direction N (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
<u>Pond B-1</u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
<u>Pond A-1</u>	<u>60-FT</u>	<u> </u>	<u> </u>
<u>Pond A-2</u>	<u>60-FT</u>	<u> </u>	<u> </u>
<u>Pond A-3</u>	<u>60-FT</u>	<u> </u>	<u> </u>
<u>Pond A-4</u>	<u>60-FT</u>	<u> </u>	<u> </u>
<u>Pond A-5</u>	<u>60-FT</u>	<u> </u>	<u> </u>
<u>Pond B-1</u>	<u>60-FT</u>	<u> </u>	<u> </u>
<u>Pond B-2</u>	<u>60-FT</u>	<u> </u>	<u> </u>
<u>Pond B-3</u>	<u>60-FT</u>	<u> </u>	<u> </u>
<u>Pond B-4</u>	<u>60-FT</u>	<u> </u>	<u> </u>
<u>Pond B-5</u>	<u>60-FT</u>	<u> </u>	<u> </u>

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 1/22/26

Inspector(s):

Time: 9:50 amDeysi Romero**Weather:**Temperature 45 deg. FPrecipitation (last 24 hours) 0 inchesSkies CloudyWind Speed 7 mphWind Direction S (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>

NOTES:

ATTACHMENT II.I.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 1/23/26

Inspector(s):

Time: 6:50 amDeus Romero**Weather:**Temperature 36 deg. FPrecipitation (last 24 hours) 0 inchesSkies CloudyWind Speed 12 mphWind Direction NINE (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 1/24/26

Inspector(s):

Time: 6:50 amDaisy Romero**Weather:**Temperature 14 deg. FPrecipitation (last 24 hours) 0 inchesSkies Freezing RainWind Speed 14 mphWind Direction NE (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 1/25/26

Inspector(s):

Time: 7:50amDasi Romero**Weather:**Temperature 14 deg. FPrecipitation (last 24 hours) 0 inchesSkies SnowWind Speed 8 mphWind Direction NNW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 1/26/26

Inspector(s):

Time: 11:50amDeusi Romero**Weather:**Temperature 25 deg. FPrecipitation (last 24 hours) 0 inchesSkies FairWind Speed 8 mphWind Direction WSW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/27/26
Time: 10:50am

Inspector(s):
Deusi Romero

Weather:

Temperature 41 deg. F

Precipitation (last 24 hours) 0 inches

Skies Fair

Wind Speed 7 mph

Wind Direction WSW (direction blowing from)

NOTES:

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 11/28/26

Inspector(s):

Time: 8:50 amDaniel Romero**Weather:**Temperature 36 deg. FPrecipitation (last 24 hours) 0 inchesSkies FairWind Speed 5 mphWind Direction WSW (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 1/29/26

Inspector(s):

Time: 9:50amAusi Romero**Weather:**Temperature 52 deg. FPrecipitation (last 24 hours) 0 inchesSkies FairWind Speed 15 mphWind Direction N (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 1/30/26

Inspector(s):

Time: 7:50 amAustin Romero**Weather:**Temperature 32 deg. FPrecipitation (last 24 hours) 0 inchesSkies FairWind Speed 7 mphWind Direction N (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>

NOTES:

ATTACHMENT II.1.D
Evaporation Pond Integrity/Leak Detection Inspection Checklist
Sundance West

Page ____ of ____

Date: 1/31/26
Time: 10:50 am

Inspector(s):Deysi Romero**Weather:**Temperature 39 deg. FPrecipitation (last 24 hours) 0 inchesSkies FairWind Speed 11 mphWind Direction W (direction blowing from)**NOTES:**

"X" indicates that a Deficiency has been noted. "P" indicates that a Photograph has been taken. "S" indicates that a Sample has been collected. Complete descriptions of Deficiencies, Photographs, and Samples are provided on attached pages. Items are referenced by Location.

EVAPORATION POND CONTAINMENT CONDITION

Location	Item			
	Erosion	Vegetation Established	Vectors	Sample
	<u> </u>	<u> </u>	<u> </u>	<u> </u>

EVAPORATION POND LEAK DETECTION SYSTEM

Riser #	Total Length	Deficiency	
		Depth of H ₂ O	Structural Defect
Pond A-1	60-FT	<u> </u>	<u> </u>
Pond A-2	60-FT	<u> </u>	<u> </u>
Pond A-3	60-FT	<u> </u>	<u> </u>
Pond A-4	60-FT	<u> </u>	<u> </u>
Pond A-5	60-FT	<u> </u>	<u> </u>
Pond B-1	60-FT	<u> </u>	<u> </u>
Pond B-2	60-FT	<u> </u>	<u> </u>
Pond B-3	60-FT	<u> </u>	<u> </u>
Pond B-4	60-FT	<u> </u>	<u> </u>
Pond B-5	60-FT	<u> </u>	<u> </u>


NOTES:

Office Pits

Date: 11/1/26

WEST


10



Before:
After:

Before:
After:


8



Before:
After:

Before:
After:


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2



Before:
After:

Before:
After:

EAST




Office Pits

Date: 11/2/26

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2



Before:
After:

Before:
After:

EAST



Office Pits

Date: 11/3/26


Before: After:		<u>9</u> Before: After:	WEST Before: After:	<u>10</u>		Before: After:
Before: After:		<u>7</u> Before: After:	Before: After:	<u>8</u>		Before: After:
Before: After:		<u>5</u> Before: After:	Before: After:	<u>6</u>		Before: After:
Before: After:		<u>3</u> Before: After:	Before: After:	<u>4</u>		Before: After:
Before: After:		<u>1</u> Before: After:	EAST Before: After:	<u>2</u>		Before: After:

Office Pits

Date: 11/4/26

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:


2




Before:
After:

Before:
After:


EAST




9
Before:
After:




7
Before:
After:



5
Before:
After:



3
Before:
After:





1
Before:
After:




Office Pits

Date: 11/5/26

WEST

10Before:
After:Before:
After:8Before:
After:Before:
After:

NORTH

6Before:
After:Before:
After:4Before:
After:Before:
After:2Before:
After:Before:
After:

EAST




Office Pits

Date: 11/6/26

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2



Before:
After:

Before:
After:



EAST






Office Pits

Date: 1/7/26

WEST

10Before:
After:Before:
After:8Before:
After:Before:
After:

NORTH


6Before:
After:Before:
After:4Before:
After:Before:
After:2Before:
After:Before:
After:

EAST



Office Pits

Date: 1/8/26




Office Pits

Date: 11/9/26

WEST


10



Before:
After:

Before:
After:


8



Before:
After:

Before:
After:


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2



Before:
After:

Before:
After:

EAST




Office Pits

Date: 11/10/26

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2



Before:
After:

Before:
After:



EAST






Office Pits

Date: 11/11/26

WEST

10Before:
After:Before:
After:8Before:
After:Before:
After:

NORTH

6Before:
After:Before:
After:4Before:
After:Before:
After:2Before:
After:Before:
After:

EAST




Office Pits

Date: 11/12/26

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2



Before:
After:

Before:
After:

EAST




Office Pits

Date: 1/13/26

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2



Before:
After:

Before:
After:

EAST




Office Pits

Date: 1/14/26

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2



Before:
After:

Before:
After:

EAST




Office Pits

Date: 11/15/26

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2



Before:
After:

Before:
After:

EAST




Office Pits

Date: 1/16/26

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:

EAST




9




Before:
After:

7




Before:
After:

5




Before:
After:

3



Before:
After:

1




Before:
After:

Office Pits

Date: 11/17/26

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:

EAST

9



Before:
After:

Before:
After:


7



Before:
After:

Before:
After:


5



Before:
After:

Before:
After:


3



Before:
After:

Before:
After:

1













Before:
After:

Before:
After:



Office Pits

Date: 1/18/26

Before: After:	1 	9 Before: After:	WEST Before: After:	10		Before: After:
Before: After:		7 Before: After:	Before: After:	8		Before: After:
Before: After:		5 Before: After:	Before: After:	6		Before: After:
Before: After:		3 Before: After:	Before: After:	4		Before: After:
Before: After:		1 Before: After:	EAST Before: After:	2		Before: After:




Office Pits

Date: 1/19/26

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:


2



Before:
After:


Before:
After:

EAST




9
Before:
After:

Before:
After:




7
Before:
After:

Before:
After:




5
Before:
After:

Before:
After:



3
Before:
After:

Before:
After:



1
Before:
After:


Before:
After:

Office Pits

Date: 11/20/26

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2



Before:
After:

Before:
After:

EAST




Office Pits

Date: 11/21/26

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:


2



Before:
After:


Before:
After:

EAST



9
Before:
After:

Before:
After:




7
Before:
After:

Before:
After:




5
Before:
After:

Before:
After:



3
Before:
After:

Before:
After:



1
Before:
After:


Before:
After:

Office Pits

Date: 1/22/26

WEST


10



Before:
After:

Before:
After:


8



Before:
After:

Before:
After:


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2



Before:
After:

Before:
After:

EAST




Office Pits

Date: 1/23/26

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:


2




Before:
After:

Before:
After:


EAST




9
Before:
After:




7
Before:
After:



5
Before:
After:



3
Before:
After:




1
Before:
After:

Office Pits

Date: 11/24/26

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2



Before:
After:

Before:
After:

EAST




Office Pits

Date: 11/25/26

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:


EAST

9



Before:
After:

7




Before:
After:

5




Before:
After:

3



Before:
After:

1



Before:
After:




Office Pits

Date: 1/26/26

WEST


10



Before:
After:

Before:
After:


8



Before:
After:

Before:
After:


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2



Before:
After:

Before:
After:

EAST




Office Pits

Date: 11/27/26

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2



Before:
After:

Before:
After:

EAST




Office Pits

Date: 11/28/26

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2



Before:
After:

Before:
After:



EAST






Office Pits

Date: 11/29/26

WEST

10Before:
After:Before:
After:8Before:
After:Before:
After:

NORTH

6Before:
After:Before:
After:4Before:
After:Before:
After:2Before:
After:Before:
After:

EAST




Office Pits

Date: 11/30/26

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2




Before:
After:

Before:
After:


EAST

1
Before:
After:




Before:
After:

3
Before:
After:



Before:
After:

5
Before:
After:




Before:
After:

7
Before:
After:



Before:
After:

9
Before:
After:



Before:
After:




Office Pits

Date: 1/31/26

WEST


10



Before:
After:

Before:
After:

8




Before:
After:

Before:
After:

NORTH


6



Before:
After:

Before:
After:


4



Before:
After:

Before:
After:

2



Before:
After:

Before:
After:

EAST





SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590 1001 6th Street P.O.
 Box 1737 Eunice, New Mexico 88231
 PARABO DISPOSAL FACILITY
www.sundanceservices.com www.sundanceservices.net www.sundanceservices.org

MONITOR WELLS

DATE:

11/1/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'6"		
MW-37	3.0	39'3"	17'6"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'3"		
MW-51	3.0	65'5"	53'1"		
MW-69	3.0	50'4"	0'2"		
MW-71	6.0	61'9"	51'7"		
MW-73	2.0	28'	13'9"		VZ-4
MW-74	3.0	33'	24'3"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	6'0"		
VZ-3	2.0	28'	6'0"		
VZ-4	2.0	28'	13'9"		MW-73
VZ-5	2.0	32'6"	17'3"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	21'2"		
MH-69	2.0	28'1"	6'0"		

**SUNDANCE SERVICES WEST, INC.**


ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590 1001 6th Street P.O.
 Box 1737 Eunice, New Mexico 88231
PARABO DISPOSAL FACILITY
www.sundanceservices.com www.sundanceservices.net www.sundanceservices.org

MONITOR WELLS

DATE:

11/2/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'7"		
MW-37	3.0	39'3"	17'8"		
MW-40	3.0	29'7"	15'2"		
MW-41	3.0	77'	57'2"		
MW-51	3.0	65'5"	53'1"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	51'8"		
MW-73	2.0	28'	13'7"		VZ-4
MW-74	3.0	33'	24'6"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	13'7"		MW-73
VZ-5	2.0	32'6"	17'2"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	21'2"		
MH-69	2.0	28'1"	0'0"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590 1001 6th Street P.O.
 Box 1737 Eunice, New Mexico 88231
PARABO DISPOSAL FACILITY
www.sundanceservices.com www.sundanceservices.net www.sundanceservices.org

MONITOR WELLS

DATE:

1/3/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'7"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'2"		
MW-36	3.0	42'	22'6"		
MW-37	3.0	39'3"	17'9"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'1"		
MW-51	3.0	65'5"	53'2"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	51'8"		
MW-73	2.0	28'	13'9"		VZ-4
MW-74	3.0	33'	24'7"		
VZ-1	2.0	27'	5'2"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	13'9"		MW-73
VZ-5	2.0	32'6"	17'1"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	21'2"		
MH-69	2.0	28'1"	0'0"		



SUNDANCE SERVICES WEST, INC.


ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590 1001 6th Street P.O.
 Box 1737 Eunice, New Mexico 88231
 PARABO DISPOSAL FACILITY
www.sundanceservices.com www.sundanceservices.net www.sundanceservices.org

MONITOR WELLS

DATE:

11/4/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'7"		
MW-37	3.0	39'3"	17'6"		
MW-40	3.0	29'7"	15'2"		
MW-41	3.0	77'	57'2"		
MW-51	3.0	65'5"	53'1"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	51'9"		
MW-73	2.0	28'	13'8"		VZ-4
MW-74	3.0	33'	24'9"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	6'0"		
VZ-3	2.0	28'	6'0"		
VZ-4	2.0	28'	13'8"		MW-73
VZ-5	2.0	32'6"	17'1"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	21'1"		
MH-69	2.0	28'1"	0'0"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590

1001 6th Street P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/5/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'6"		
MW-37	3.0	39'3"	17'1"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'1"		
MW-51	3.0	65'5"	53'2"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	51'8"		
MW-73	2.0	28'	13'6"		VZ-4
MW-74	3.0	33'	25'3"		
VZ-1	2.0	27'	5'0"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	13'6"		MW-73
VZ-5	2.0	32'6"	17'1"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	21'2"		
MH-69	2.0	28'1"	0'1"		

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

F-111

SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

1/6/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'5"		
MW-37	3.0	39'3"	17'2"		
MW-40	3.0	29'7"	15'2"		
MW-41	3.0	77'	57'1"		
MW-51	3.0	65'5"	53'2"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	51'9"		
MW-73	2.0	28'	13'6"		VZ-4
MW-74	3.0	33'	25'6"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0'		
VZ-3	2.0	28'	0'0'		
VZ-4	2.0	28'	13'6"		MW-73
VZ-5	2.0	32'6"	17'1"		
VZ-6	2.0	26'3"	0'0'		
VZ-7	2.0	49'8"	21'1"		
MH-69	2.0	28'1"	0'0"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231

1001 6th Street P.O.**PARABO DISPOSAL FACILITY**


www.sundanceservices.com www.sundanceservices.net www.sundanceservices.org

MONITOR WELLS

DATE:

1/7/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0' 1"		
MW-36	3.0	42'	22' 6"		
MW-37	3.0	39'3"	17' 3"		
MW-40	3.0	29'7"	15' 1"		
MW-41	3.0	77'	57' 2"		
MW-51	3.0	65'5"	53' 1"		
MW-69	3.0	50'4"	0' 1"		
MW-71	6.0	61'9"	51' 8"		
MW-73	2.0	28'	13' 8"		VZ-4
MW-74	3.0	33'	25' 8"		
VZ-1	2.0	27'	4' 9"		PGI-8
VZ-2	2.0	38'8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	13' 8"		MW-73
VZ-5	2.0	32'6"	17' 2"		
VZ-6	2.0	26'3"	0' 0"		
VZ-7	2.0	49'8"	21' 1"		
MH-69	2.0	28'1"	0' 0"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590

1001 6th Street P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net


www.sundanceservices.org

MONITOR WELLS

DATE:

1/8/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'7"		
MW-37	3.0	39'3"	17'4"		
MW-40	3.0	29'7"	15'2"		
MW-41	3.0	77'	57'1"		
MW-51	3.0	65'5"	53'2"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	51'8"		
MW-73	2.0	28'	13'9"		VZ-4
MW-74	3.0	33'	25'9"		
VZ-1	2.0	27'	4'8"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	13'9"		MW-73
VZ-5	2.0	32'6"	17'2"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	21'1"		
MH-69	2.0	28'1"	0'1"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590 1001 6th Street P.O.
 Box 1737 Eunice, New Mexico 88231
 PARABO DISPOSAL FACILITY
www.sundanceservices.com www.sundanceservices.net www.sundanceservices.org

MONITOR WELLS

DATE:

11/09/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'2"		
MW-36	3.0	42'	22'8"		
MW-37	3.0	39'3"	17'3"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'2"		
MW-51	3.0	65'5"	53'2"		
MW-69	3.0	50'4"	0'2"		
MW-71	6.0	61'9"	51'9"		
MW-73	2.0	28'	13'8"		VZ-4
MW-74	3.0	33'	26'1"		
VZ-1	2.0	27'	4'9"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	13'8"		MW-73
VZ-5	2.0	32'6"	17'2"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	21'1"		
MH-69	2.0	28'1"	0'1"		



SUNDANCE SERVICES WEST, INC.


ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590 1001 6th Street P.O.
 Box 1737 Eunice, New Mexico 88231
PARABO DISPOSAL FACILITY
www.sundanceservices.com www.sundanceservices.net www.sundanceservices.org

MONITOR WELLS

DATE:

1/10/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'7"		
MW-37	3.0	39'3"	17'2"		
MW-40	3.0	29'7"	15'2"		
MW-41	3.0	77'	57'1"		
MW-51	3.0	65'5"	53'1"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	51'8"		
MW-73	2.0	28'	13'6"		VZ-4
MW-74	3.0	33'	26'4"		
VZ-1	2.0	27'	4'9"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	13'6"		MW-73
VZ-5	2.0	32'6"	17'1"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	21'2"		
MH-69	2.0	28'1"	0'1"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590

1001 6th Street P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/1/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'2"		
MW-36	3.0	42'	22'8"		
MW-37	3.0	39'3"	17'1"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'2"		
MW-51	3.0	65'5"	53'1"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	51'7"		
MW-73	2.0	28'	13'8"		VZ-4
MW-74	3.0	33'	26'6"		
VZ-1	2.0	27'	4'8"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	13'8"		MW-73
VZ-5	2.0	32'6"	17'1"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	21'2"		
MH-69	2.0	28'1"	0'2"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231

1001 6th Street P.O.**PARABO DISPOSAL FACILITY**

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

1/12/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'9"		
MW-37	3.0	39'3"	17'2"		
MW-40	3.0	29'7"	15'2"		
MW-41	3.0	77'	57'1"		
MW-51	3.0	65'5"	53'1"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	51'8"		
MW-73	2.0	28'	13'6"		VZ-4
MW-74	3.0	33'	26'8"		
VZ-1	2.0	27'	4'9"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	13'6"		MW-73
VZ-5	2.0	32'6"	17'2"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	21'1"		
MH-69	2.0	28'1"	0'1"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590

Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

1/13/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'7"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'2"		
MW-36	3.0	42'	22'7"		
MW-37	3.0	39'3"	17'2"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'2"		
MW-51	3.0	65'5"	53'2"		
MW-69	3.0	50'4"	0'2"		
MW-71	6.0	61'9"	51'7"		
MW-73	2.0	28'	13'4"		VZ-4
MW-74	3.0	33'	26'9"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	13'4"		MW-73
VZ-5	2.0	32'6"	17'7"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	21'1"		
MH-69	2.0	28'1"	0'2"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590

1001 6th Street P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS**DATE:**

11/14/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16' 5"	0' 1"		
MW-36	3.0	42'	22' 8"		
MW-37	3.0	39' 3"	17' 1"		
MW-40	3.0	29' 7"	15' 2"		
MW-41	3.0	77'	57' 1"		
MW-51	3.0	65' 5"	53' 1"		
MW-69	3.0	50' 4"	0' 1"		
MW-71	6.0	61' 9"	51' 7"		
MW-73	2.0	28'	13' 1"		VZ-4
MW-74	3.0	33'	27' 1"		
VZ-1	2.0	27'	5' 1"		PGI-8
VZ-2	2.0	38' 8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	13' 1"		MW-73
VZ-5	2.0	32' 6"	17' 1"		
VZ-6	2.0	26' 3"	0' 0"		
VZ-7	2.0	49' 8"	21' 1"		
MH-69	2.0	28' 1"	0' 1"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/15/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'9"		
MW-37	3.0	39'3"	17'1"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'2"		
MW-51	3.0	65'5"	53'1"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	51'8"		
MW-73	2.0	28'	12'9"		VZ-4
MW-74	3.0	33'	27'4"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	12'9"		MW-73
VZ-5	2.0	32'6"	17'1"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	21'2"		
MH-69	2.0	28'1"	0'2"		



SUNDANCE SERVICES WEST, INC.

Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590 1001 6th Street P.O.
 Box 1737 Eunice, New Mexico 88231
PARABO DISPOSAL FACILITY
www.sundanceservices.com www.sundanceservices.net www.sundanceservices.org

MONITOR WELLS

DATE:

11/16/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'8"		
MW-37	3.0	39'3"	17'2"		
MW-40	3.0	29'7"	15'2"		
MW-41	3.0	77'	57'1"		
MW-51	3.0	65'5"	53'1"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	51'7"		
MW-73	2.0	28'	12'9"		VZ-4
MW-74	3.0	33'	27'6"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	12'9"		MW-73
VZ-5	2.0	32'6"	17'1"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	21'2"		
MH-69	2.0	28'1"	0'1"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

1/17/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'7"		
MW-37	3.0	39'3"	17'1"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'1"		
MW-51	3.0	65'5"	53'2"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	51'8"		
MW-73	2.0	28'	13'1"		VZ-4
MW-74	3.0	33'	28'1"	23'1"	
VZ-1	2.0	27'	5'0"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	13'1"		MW-73
VZ-5	2.0	32'6"	17'1"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	21'1"		
MH-69	2.0	28'1"	0'1"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231
PARABO DISPOSAL FACILITY
www.sundanceservices.com www.sundanceservices.net www.sundanceservices.org

1001 6th Street P.O.**MONITOR WELLS**

DATE:

1/18/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'8"		
MW-37	3.0	39'3"	17'2"		
MW-40	3.0	29'7"	15'3"		
MW-41	3.0	77'	57'1"		
MW-51	3.0	65'5"	53'2"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	51'6"		
MW-73	2.0	28'	13'2"		VZ-4
MW-74	3.0	33'	23'3"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	13'2"		MW-73
VZ-5	2.0	32'6"	17'1"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	21'2"		
MH-69	2.0	28'1"	0'2"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231
PARABO DISPOSAL FACILITY
www.sundanceservices.com www.sundanceservices.net www.sundanceservices.org

1001 6th Street P.O.**MONITOR WELLS**

DATE:

1/19/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0' 1"		
MW-36	3.0	42'	22' 9"		
MW-37	3.0	39'3"	17' 1"		
MW-40	3.0	29'7"	15' 3"		
MW-41	3.0	77'	57' 1"		
MW-51	3.0	65'5"	53' 1"		
MW-69	3.0	50'4"	0' 1"		
MW-71	6.0	61'9"	51' 3"		
MW-73	2.0	28'	13' 1"		VZ-4
MW-74	3.0	33'	23' 4"		
VZ-1	2.0	27'	5' 1"		PGI-8
VZ-2	2.0	38'8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	13' 1"		MW-73
VZ-5	2.0	32'6"	17' 2"		
VZ-6	2.0	26'3"	0' 0"		
VZ-7	2.0	49'8"	21' 2"		
MH-69	2.0	28'1"	0' 1"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231
PARABO DISPOSAL FACILITY
 www.sundanceservices.com www.sundanceservices.net www.sundanceservices.org

1001 6th Street P.O.**MONITOR WELLS**

DATE:

11/20/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'7"		
MW-37	3.0	39'3"	17'1"		
MW-40	3.0	29'7"	15'4"		
MW-41	3.0	77'	57'2"		
MW-51	3.0	65'5"	53'1"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	51'2"		
MW-73	2.0	28'	12'9"		VZ-4
MW-74	3.0	33'	23'6"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	12'9"		MW-73
VZ-5	2.0	32'6"	17'1"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	21'1"		
MH-69	2.0	28'1"	0'1"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590

1001 6th Street P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/21/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'1"		
MW-37	3.0	39'3"	17'2"		
MW-40	3.0	29'7"	15'3"		
MW-41	3.0	77'	51'1"		
MW-51	3.0	65'5"	53'2"		
MW-69	3.0	50'4"	0'2"		
MW-71	6.0	61'9"	51'1"		
MW-73	2.0	28'	13'1"		VZ-4
MW-74	3.0	33'	23'8"		
VZ-1	2.0	27'	5'0"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	13'1"		MW-73
VZ-5	2.0	32'6"	17'2"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	21'1"		
MH-69	2.0	28'1"	0'1"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/22/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'2"		
MW-37	3.0	39'3"	17'1"		
MW-40	3.0	29'7"	15'2"		
MW-41	3.0	77'	57'2"		
MW-51	3.0	65'5"	53'1"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	51'2"		
MW-73	2.0	28'	13'2"		VZ-4
MW-74	3.0	33'	23'9"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0'		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	13'2"		MW-73
VZ-5	2.0	32'6"	17'1"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	21'1"		
MH-69	2.0	28'1"	0'14"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590

Box 1737 Eunice, New Mexico 88231

1001 6th Street P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/23/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	6'1"		
MW-36	3.0	42'	22'3"		
MW-37	3.0	39'3"	17'1"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'1"		
MW-51	3.0	65'5"	53'2"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	51'3"		
MW-73	2.0	28'	13'1"		VZ-4
MW-74	3.0	33'	23'8"		
VZ-1	2.0	27'	5'2"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	13'1"		MW-73
VZ-5	2.0	32'6"	17'1"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	21'1"		
MH-69	2.0	28'1"	0'1"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231
 PARABO DISPOSAL FACILITY
www.sundanceservices.com www.sundanceservices.net www.sundanceservices.org

1001 6th Street P.O.

MONITOR WELLS

DATE:

1/24/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'4"		
MW-37	3.0	39'3"	17'2"		
MW-40	3.0	29'7"	15'4"		
MW-41	3.0	77'	57'2"		
MW-51	3.0	65'5"	53'1"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	51'2"		
MW-73	2.0	28'	13'0"		VZ-4
MW-74	3.0	33'	23'9"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	13'0"		MW-73
VZ-5	2.0	32'6"	17'2"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	21'2"		
MH-69	2.0	28'1"	0'1"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Box 1737

Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/25/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'3"		
MW-37	3.0	39'3"	17'1"		
MW-40	3.0	29'7"	15'3"		
MW-41	3.0	77'	57'1"		
MW-51	3.0	65'5"	53'2"		
MW-69	3.0	50'4"	0'2"		
MW-71	6.0	61'9"	51'3"		
MW-73	2.0	28'	12'9"		VZ-4
MW-74	3.0	33'	24'1"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	12'9"		MW-73
VZ-5	2.0	32'6"	17'1"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	21'1"		
MH-69	2.0	28'1"	0'2"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
 Box 1737 Eunice, New Mexico 88231
PARABO DISPOSAL FACILITY
www.sundanceservices.com www.sundanceservices.net www.sundanceservices.org

1001 6th Street P.O.

MONITOR WELLS

DATE:

1/26/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'4"		
MW-37	3.0	39'3"	17'2"		
MW-40	3.0	29'7"	15'2"		
MW-41	3.0	77'	57'2"		
MW-51	3.0	65'5"	53'1"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	51'2"		
MW-73	2.0	28'	12'8"		VZ-4
MW-74	3.0	33'	24'3"		
VZ-1	2.0	27'	5'2"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	12'8"		MW-73
VZ-5	2.0	32'6"	17'1"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	21'1"		
MH-69	2.0	28'1"	0'1"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590

Box 1737 Eunice, New Mexico 88231

1001 6th Street P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/27/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'2"		
MW-36	3.0	42'	22'5"		
MW-37	3.0	39'3"	17'1"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'2"		
MW-51	3.0	65'5"	53'1"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	51'3"		
MW-73	2.0	28'	12'7"		VZ-4
MW-74	3.0	33'	24'4"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	12'7"		MW-73
VZ-5	2.0	32'6"	17'2"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	21'2"		
MH-69	2.0	28'1"	0'2"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590

Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/28/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'4"		
MW-37	3.0	39'3"	17'2"		
MW-40	3.0	29'7"	15'1"		
MW-41	3.0	77'	57'2"		
MW-51	3.0	65'5"	53'1"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	51'4"		
MW-73	2.0	28'	12'6"		VZ-4
MW-74	3.0	33'	24'6"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	12'6"		MW-73
VZ-5	2.0	32'6"	17'1"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	21'1"		
MH-69	2.0	28'1"	0'0"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
 Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590

Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

11/29/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'5"		
MW-37	3.0	39'3"	17'1"		
MW-40	3.0	29'7"	15'3"		
MW-41	3.0	77'	57'7"		
MW-51	3.0	65'5"	53'1"		
MW-69	3.0	50'4"	0'1"		
MW-71	6.0	61'9"	51'3"		
MW-73	2.0	28'	12'7"		VZ-4
MW-74	3.0	33'	24'7"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0'		
VZ-3	2.0	28'	0'0'		
VZ-4	2.0	28'	12'7"		MW-73
VZ-5	2.0	32'6"	17'2"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	21'1"		
MH-69	2.0	28'1"	0'1"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS
Main Office: 575-394-2511 Plant Office: 575-394-3212 Fax: 575-394-2590
Box 1737 Eunice, New Mexico 88231

1001 6th Street P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com www.sundanceservices.net www.sundanceservices.org

MONITOR WELLS

DATE:

11/30/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4'8"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0'1"		
MW-36	3.0	42'	22'6"		
MW-37	3.0	39'3"	17'2"		
MW-40	3.0	29'7"	15'4"		
MW-41	3.0	77'	57'2"		
MW-51	3.0	65'5"	53'2"		
MW-69	3.0	50'4"	0'2"		
MW-71	6.0	61'9"	51'2"		
MW-73	2.0	28'	12'8"		VZ-4
MW-74	3.0	33'	24'9"		
VZ-1	2.0	27'	5'1"		PGI-8
VZ-2	2.0	38'8"	0'0"		
VZ-3	2.0	28'	0'0"		
VZ-4	2.0	28'	12'8"		MW-73
VZ-5	2.0	32'6"	17'1"		
VZ-6	2.0	26'3"	0'0"		
VZ-7	2.0	49'8"	21'2"		
MH-69	2.0	28'1"	0'2"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS**DATE:**

11/31/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
MW-7	3.0	27'	4' 9"		PGI-7
MW-13	3.0	COVER UP	COVER UP	COVER UP	COVER UP
MW-35	3.0	16'5"	0' 2"		
MW-36	3.0	42'	22' 7"		
MW-37	3.0	39'3"	17' 1"		
MW-40	3.0	29'7"	15' 3"		
MW-41	3.0	77'	57' 1"		
MW-51	3.0	65'5"	53' 1"		
MW-69	3.0	50'4"	0' 1"		
MW-71	6.0	61'9"	51' 2"		
MW-73	2.0	28'	12' 9"		VZ-4
MW-74	3.0	33'	25' 1"		
VZ-1	2.0	27'	5' 2"		PGI-8
VZ-2	2.0	38'8"	0' 0"		
VZ-3	2.0	28'	0' 0"		
VZ-4	2.0	28'	12' 9"		MW-73
VZ-5	2.0	32'6"	17' 1"		
VZ-6	2.0	26'3"	0' 0"		
VZ-7	2.0	49'8"	21' 1"		
MH-69	2.0	28'1"	0' 1"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundancservices.org

MONITOR WELLS

DATE:

1 | 1 | 26

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundance-services.net

www.sundanceservices.org

MONITOR WELLS

DATE:

112126

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. BOX 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundance.org

MONITOR WELLS

DATE:

113126

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

1 | 4 | 26

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. BOX 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 11/5/26

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

16126

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. BOX 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundancoservices.org

MONITOR WELLS

DATE: 117/26

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 1/8/26

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

119/26

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 1/10/26

[illegible]



ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundancservices.org

DATE:

111126

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 1/12/20

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

1113126

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 373-3941
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

114126

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

115 126

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

116120

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 1/17/26

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

111826

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

1	19	26
---	----	----

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 11/20/26

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 1/21/26

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

1122120

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Office: 373-3941
1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundancoservices.org

MONITOR WELLS

DATE: 1/23/26

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 1/24/26

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 11/25/26

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. BOX 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

1126/26

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundancerecords.com

MONITOR WELLS

DATE:

1/27/26

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: 11/28/26

[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE:

$$1 \overline{) 29} \overline{) 28}$$
[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O. Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com


DISPOSAL FACILITY
www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS

DATE: _____

$$1 \mid 30 \mid 26$$
[illegible]



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE: 11/1/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'1"		
WS-3	Poly	14'7"	0'6"		
WS-4	Poly	14'7"	3'2"		
WS-5	Poly	23'6"	13'8"		
WS-6	Poly	8'0"	0'9"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

11/2/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'7"		
WS-2	Poly	14'7"	1'2"		
WS-3	Poly	14'7"	0'0"		
WS-4	Poly	14'7"	3'1"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'8"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

11/3/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'0"		
WS-4	Poly	14'7"	3'2"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'9"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net


www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

11/4/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2' 9"		
WS-2	Poly	14'7"	1' 2"		
WS-3	Poly	14'7"	0' 1"		
WS-4	Poly	14'7"	3' 1"		
WS-5	Poly	23'6"	13' 8"		
WS-6	Poly	8'0"	0' 8"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

11/5/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	3' 1"		
WS-2	Poly	14'7"	1' 3"		
WS-3	Poly	14'7"	0' 1"		
WS-4	Poly	14'7"	3' 2"		
WS-5	Poly	23'6"	13' 9"		
WS-6	Poly	8'0"	0' 9"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737 Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net


www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

11/6/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1'2"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	3'1"		
WS-5	Poly	23'6"	14'1"		
WS-6	Poly	8'0"	0'9"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

11/7/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'9"		
WS-5	Poly	23'6"	14'1"		
WS-6	Poly	8'0"	0'8"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Box 1737

Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

1/8/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1'2"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	2'8"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'7"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY


www.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

11/9/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	2'9"		
WS-5	Poly	23'6"	14'1"		
WS-6	Poly	8'0"	0'8"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net


www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

1/10/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1'2"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	3'1"		
WS-5	Poly	23'6"	14'1"		
WS-6	Poly	8'0"	0'9"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Box 1737 Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

1/11/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	3'1"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'8"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

11/12/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1'2"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	3'0"		
WS-5	Poly	23'6"	13'8"		
WS-6	Poly	8'0"	0'9"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Box 1737

Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

11/13/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	3'1"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'8"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net


www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

1/14/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1'2"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	3'2"		
WS-5	Poly	23'6"	14'1"		
WS-6	Poly	8'0"	0'9"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Box 1737

Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

1/15/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1.2"		
WS-3	Poly	14'7"	0.1"		
WS-4	Poly	14'7"	3.1"		
WS-5	Poly	23'6"	14.2"		
WS-6	Poly	8'0"	0.8"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231


PARABO DISPOSAL FACILITY

www.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

11/6/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8'		
WS-2	Poly	14'7"	1'1'		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	3'1'		
WS-5	Poly	23'6"	14'2"		
WS-6	Poly	8'0"	0'8"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net


www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

11/7/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1'2"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	3'1"		
WS-5	Poly	23'6"	14'1"		
WS-6	Poly	8'0"	0'9"		

**SUNDANCE SERVICES WEST, INC.**

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231


PARABO DISPOSAL FACILITY

www.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org**MONITOR WELLS WASH OUT**

DATE:

1/18/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	3'2"		
WS-5	Poly	23'6"	14'1"		
WS-6	Poly	8'0"	0'8"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Box 1737

Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com


www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE: 1/19/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	3'1"		
WS-5	Poly	23'6"	13'8"		
WS-6	Poly	8'0"	0'9"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net


www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

11/20/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2' 8'		
WS-2	Poly	14'7"	1' 2"		
WS-3	Poly	14'7"	0' 1'		
WS-4	Poly	14'7"	3' 2"		
WS-5	Poly	23'6"	13' 9"		
WS-6	Poly	8'0"	0' 8"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

11/21/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'2"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	3'1"		
WS-5	Poly	23'6"	13'8"		
WS-6	Poly	8'0"	0'9"		

SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY


www.sundanceservices.comwww.sundanceservices.netwww.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

11/22/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1'3"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	3'1"		
WS-5	Poly	23'6"	14'1"		
WS-6	Poly	8'0"	0'8"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

Box 1737

Eunice, New Mexico 88231

1001 6th Street

P.O.

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net


www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

11/23/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'2"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	3'2"		
WS-5	Poly	23'6"	14'1"		
WS-6	Poly	8'0"	0'9"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net


www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

1/24/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'7"		
WS-2	Poly	14'7"	1'8"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	3'2"		
WS-5	Poly	23'6"	14'2"		
WS-6	Poly	8'0"	0'9"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Elmwood, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net


www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

11/25/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'8"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	3'1"		
WS-5	Poly	23'6"	14'1"		
WS-6	Poly	8'0"	0'8"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net


www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

11/26/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'7"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	3'2"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'9"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net


www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

11/27/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1'7"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	3'1"		
WS-5	Poly	23'6"	13'8"		
WS-6	Poly	8'0"	0'8"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net


www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

11/28/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'8"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	3'1"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'8"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net


www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

11/29/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1'7"		
WS-3	Poly	14'7"	0'2"		
WS-4	Poly	14'7"	3'2"		
WS-5	Poly	23'6"	13'8"		
WS-6	Poly	8'0"	0'8"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net


www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

11/30/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'8"		
WS-2	Poly	14'7"	1'6"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	3'7"		
WS-5	Poly	23'6"	14'1"		
WS-6	Poly	8'0"	0'9"		



SUNDANCE SERVICES WEST, INC.

ROLL-OFF BOXES ROLL-OFF TRUCKS DUMP TRUCKS VACUUM TRUCKS

Main Office: 575-394-2511

Plant Office: 575-394-3212

Fax: 575-394-2590

1001 6th Street

P.O.

Box 1737

Eunice, New Mexico 88231

PARABO DISPOSAL FACILITY

www.sundanceservices.com

www.sundanceservices.net

www.sundanceservices.org

MONITOR WELLS WASH OUT

DATE:

11/31/26

WELL #	WELL DIAMETER	PRE-PURGING	BEFORE PURGING	AFTER PURGING	COMMENTS
WS-1	Poly	14'7"	2'9"		
WS-2	Poly	14'7"	1'7"		
WS-3	Poly	14'7"	0'1"		
WS-4	Poly	14'7"	3'2"		
WS-5	Poly	23'6"	13'9"		
WS-6	Poly	8'0"	0'8"		

MONITOR WELLS

WELL #

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 625310

CONDITIONS

Operator: Sundance Services West, Inc. PO Box 1737 Eunice, NM 88231	OGRID: 371811
	Action Number: 625310
	Action Type: [C-137] Non-Fee SWMF Submittal (SWMF NON-FEE SUBMITTAL)

CONDITIONS

Created By	Condition	Condition Date
joseph.kennedy	None	9/17/2026