

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party	CAMERON OIL & GAS INC.	OGRID	181109
Contact Name	MIKE PILCHER	Contact Telephone	575-263-3028
Contact email	MPILCHER@CAMERONOIL.NET	Incident # (assigned by OCD)	
Contact mailing address	PO BOX 1089, EUNICE, NM 88231		

Location of Release Source

Latitude N 32.894072 Longitude W-103.298036
(NAD 83 in decimal degrees to 5 decimal places)

Site Name	STATE Q #003	Site Type	WELL
Date Release Discovered	10/16/20	API# (if applicable)	30-025-21792

Unit Letter	Section	Township	Range	County
E	30	16S	37E	LEA COUNTY, NM

Surface Owner: ☒ State ☐ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input checked="" type="checkbox"/> Crude Oil	Volume Released (bbls) UNKNOWN (HISTORICAL RELEASE)	Volume Recovered (bbls) NONE
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) UNKNOWN (HISTORICAL RELEASE)	Volume Recovered (bbls) NONE
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

A ROUTINE INSPECTION REVEALED EXTENSIVE STAINING FROM AN APPARENT RELEASE OF HYDROCARBONS AND PRODUCED WATER, AS WELL AS ADDED SOIL AT THE WELLHEAD. THE INSPECTION ID # IS IEZB2029045721.

Page 2

Incident ID	
District RP	
Facility ID	
Application ID	

<p>Was this a major release as defined by 19.15.29.7(A) NMAC?</p> <p><input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p>	<p>If YES, for what reason(s) does the responsible party consider this a major release?</p>
<p>If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?</p>	

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input type="checkbox"/> The source of the release has been stopped. <input type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.						
If all the actions described above have <u>not</u> been undertaken, explain why: 						
<p>Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.</p> <p>I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.</p>						
<table style="width: 100%;"> <tr> <td style="width: 50%;">Printed Name: <u>MIKE PILCHER</u></td> <td style="width: 50%;">Title: <u>Superintendent</u></td> </tr> <tr> <td>Signature: <u><i>Mike Pilcher</i></u></td> <td>Date: <u>11/30/20</u></td> </tr> <tr> <td>email: <u>MPILCHER@CAMERONOIL.NET</u></td> <td>Telephone: <u>575-263-3028</u></td> </tr> </table>	Printed Name: <u>MIKE PILCHER</u>	Title: <u>Superintendent</u>	Signature: <u><i>Mike Pilcher</i></u>	Date: <u>11/30/20</u>	email: <u>MPILCHER@CAMERONOIL.NET</u>	Telephone: <u>575-263-3028</u>
Printed Name: <u>MIKE PILCHER</u>	Title: <u>Superintendent</u>					
Signature: <u><i>Mike Pilcher</i></u>	Date: <u>11/30/20</u>					
email: <u>MPILCHER@CAMERONOIL.NET</u>	Telephone: <u>575-263-3028</u>					
<u>OCD Only</u> Received by: _____ Date: _____						

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

CONDITIONS

Action 11362

Operator:	SAFETY & ENVIRONMENTAL Solutio	PO Box 1613	OGRID:	329088	Action Number:	11362	Action Type:	C-141
	703 E Clinton	Hobbs, NM88240						

OCD Reviewer	Condition
rmarcus	None