

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011.

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR ☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production **Contact** Leonard Aguilar Production Assistant Foreman

Address 6488 Seven Rivers Hwy Artesia, NM 88220 **Telephone No.** 575.513.1930

Facility Name Chimayo 16 State 3 **Facility Type** SWD


Surface Owner State **Mineral Owner State** **API No.** 30-015-38105

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	16	25S	29E	1610	FNL	1455	FWL	EDDY

Latitude: Longitude:

NATURE OF RELEASE

Type of Release Spill	Produced Water	Volume of Release	7 BBL Produced Water	Volume Recovered	7 BBL Produced Water ?
Source of Release	Sump Tank	Date and Hour of Occurrence	11/18/15 at 3:00 PM	Date and Hour of Discovery	11/18/15 at 3:00 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	OCD Jim Amos BLM Mike Bratcher		
By Whom?	Leonard Aguilar	Date and Hour	OCD 11/19/15 at 11:52 am BLM 11/19/15 at 11:55 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		
If a Watercourse was Impacted, Describe Fully.* N/A			RECEIVED		
Describe Cause of Problem and Remedial Action Taken.* Sump tank overfilled bad check valve, bad check valve allowed produced water from the charge pump to flow back into the sump tank. Isolated the tank by closing valves upstream and downstream of sump tank.					
Describe Area Affected and Cleanup Action Taken.* 7 BBL of Produced water released on a 30 x 50 area all on pad, 7 BBL of Produced water recovered. Vacuum truck was already on location. An environmental agency will be called out for remediation.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: Jeanette Barron		OIL CONSERVATION DIVISION			
Printed Name: Jeanette Barron		Approved by Environmental Specialist: 			
Title: Field Admin Support		Approval Date: 11/23/15		Expiration Date: N/A	
E-mail Address: Jeanette.barron@dvn.com		Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>			
Date: 11/20/15 Phone: 575.748.1813		SUBMIT REMEDIATION PROPOSAL NO			

* Attach Additional Sheets If Necessary

LATER THAN: 12/23/15

2RP-3412

Patterson, Heather, EMNRD

From: Barron, Jeanette <Jeanette.Barron@dvn.com>
Sent: Friday, November 20, 2015 1:14 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Cc: Fulks, Brett; Aguilar, Leonard; Garcia, Ruben
Subject: C-141 Chimayo 16 state 3
Attachments: C-141 Chimayo 16 state 3 11.18.15.doc; Chimayo 16 state 3 11.18.15.jpg; Chimayo 16 state 3.pdf

Please see attached, should you have any questions please contact Production Assistant Foreman or EHS representative Brett Fulks.

Have a great Thanksgiving!

Thanks,

Jeanette Barron

Field Admin Support-Production

Devon Energy Corporation

P.O. Box 250

Artesia, NM 88211

575 748 1813 Direct

jeanette.barron@dvn.com


devon

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

Action 11739

OCD Reviewer	Condition
rmarcus	None