

## Closure Report

| Site Description   |                              |
|--------------------|------------------------------|
| Site Name:         | Boo 9-2H                     |
| Company:           | Oxy, Permian                 |
| Legal Description: | U/L H, Section 9, T23S, R26E |
| County:            | Eddy County, NM              |
| GPS Coordinates:   | N 32.32146 W -104.29029      |

| Release Data       |                |
|--------------------|----------------|
| Date of Release:   | 8/5/2020       |
| Type of Release:   | Produced water |
| Source of Release: | Corrosion      |
| Volume of Release: | 15 bbls        |
| Volume Recovered:  | 0 bbls         |

| Remediation Specifications |  |
|----------------------------|--|
| Remediation Parameters:    | The release was in a lined facility. The liner was covered by gravel and exposed in a few places to check for liner integrity. The liner integrity was intact. |
| Remediation Activities:    | Liner integrity was checked  |

|                       |     |  |
|-----------------------|-----|--|
| Plan Sent to OCD:     | N/A |  |
| OCD Approval of Plan: | N/A |  |
| Plan Sent to BLM:     | N/A |  |
| BLM Approval of Plan: | N/A |  |

| Supporting Documentation |                               |
|--------------------------|-------------------------------|
| Initial C-141            | signed and included           |
| C-141, page 6            | signed and included           |
| Site Diagram             | Google earth map of leak area |
| Pictures                 | Liner integrity photos        |
| Lab Summary/Analysis     | N/A                           |


| Request for Closure   |           |
|---|-----------|
| Based on the completion of the remediation plan as agreed upon, BBC International requests closure approval from NMOCD. |           |
| Cliff Brunson, President of BBC International Inc.  | 11/2/2020 |



# Oxy, Boo 9-2H

Leak Date: 8-5-2020  
Eddy County, NM  
API: 30-015-41831

Legend  
Leak Area























Form C-141

State of New Mexico  
Oil Conservation Division

Page 6

|                |               |
|----------------|---------------|
| Incident ID    | NRM2023460796 |
| District RP    |               |
| Facility ID    |               |
| Application ID |               |

## Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

**Closure Report Attachment Checklist:** Each of the following items must be included in the closure report.

- ☒ A scaled site and sampling diagram as described in 19.15.29.11 NMAC
- ☒ Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- ☒ Laboratory analyses of final sampling (Note: appropriate OCD District office must be notified 2 days prior to final sampling)
- ☒ Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Wade Dittrich Title: Environmental Coordinator


Signature:  Date: 10-22-20

email: wade\_dittrich@oxy.com Telephone: (575) 390-2828

### OCD Only

Received by: Cristina Eads Date: 11/06/2020

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by:  Date: 01/29/2021

Printed Name: Cristina Eads Title: Environmental Specialist



**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS  
  
Action 11102

CONDITIONS OF APPROVAL

|              |             |               |                      |        |       |                |       |              |           |
|--------------|-------------|---------------|----------------------|--------|-------|----------------|-------|--------------|-----------|
| Operator:    | OXY USA INC | P.O. Box 4294 | Houston, TX772104294 | OGRID: | 16696 | Action Number: | 11102 | Action Type: | C-141     |
| OCD Reviewer |             |               |                      |        |       |                |       |              | Condition |
| ceads        |             |               |                      |        |       |                |       |              | None      |