

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nAPP2105050187
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party Harvest Midstream Company	OGRID 373888
Contact Name Kijun Hong	Contact Telephone 505-632-4475
Contact email khong@harvestmidstream.com	Incident # (assigned by OCD) nAPP2105050187
Contact mailing address 1755 Arroyo Dr., Bloomfield, NM 87413	

Location of Release Source

Latitude 36.954092 Longitude -108.085317
(NAD 83 in decimal degrees to 5 decimal places)

Site Name Horton Compressor Station	Site Type Compressor Station
Date Release Discovered 2/19/2021- 10:50 am	API# (if applicable) Facility # fCS00000000189

Unit Letter	Section	Township	Range	County
K	27	32N	12W	San Juan

Surface Owner: ☐ State ☐ Federal ☐ Tribal ☒ Private (Name): Lesher, James D and Karen C

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

☐ Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
☒ Produced Water	Volume Released (bbls) approx. 30	Volume Recovered (bbls) 30
	Is the concentration of total dissolved solids (TDS) in the produced water >10,000 mg/l?	☐ Yes ☒ No
☒ Condensate	Volume Released (bbls) approx. 55	Volume Recovered (bbls) 55
☐ Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
☐ Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

A tank valve failed due to freezing. Internal corrosion also played a role. The leak has been repaired.


State of New Mexico
Oil Conservation Division

Page 2

Incident ID	nAPP2105050187
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? ☒ Yes ☐ No	If YES, for what reason(s) does the responsible party consider this a major release? NMAC 19.15.29.7(A1): an unauthorized release of liquids exceeding 25 bbls
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Notice provided via electronic mail by Kijun Hong to Cory Smith and Jim Griswold of NMOCD on Feb. 19, 2021 1:34 PM	

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

☒ The source of the release has been stopped.	
☒ The impacted area has been secured to protect human health and the environment.	
☒ Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.	
☒ All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why:	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Kijun Hong</u>	Title: <u>Environmental Specialist</u>
Signature: 	Date: <u>3/4/2021</u>
email: <u>khong@harvestmidstream.com</u>	Telephone: <u>505-632-4475</u>
<u>OCD Only</u>	
Received by: _____	Date: _____

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 19722

CONDITIONS OF APPROVAL

Operator:				OGRID:	Action Number:	Action Type:
	HARVEST FOUR CORNERS, LLC	1111 Travis Street	Houston, TX77002	373888	19722	C-141

OCD Reviewer	Condition
marcus	When submitting future reports regarding this release, please submit the calculations used or specific justification for the volumes reported on the initial C-141.