District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

)

Incident ID	NAPP2113333790
District RP	
Facility ID	
Application ID	

# **Release Notification**

#### **Responsible Party**

Responsible Party: ETC Texas Pipeline, Ltd.	OGRID: 371183		
Contact Name: Carolyn Blackaller	Contact Telephone: (432) 203-8920		
Contact email: <u>Carolyn.blackaller@energytransfer.com</u> Incident # (assigned by OCD)			
Contact mailing address: 600 N. Marienfeld St., Suite 700, Midland, TX 79701			

#### **Location of Release Source**

Latitude 32.3990406

*Longitude <u>-103.2109201</u>* (NAD 83 in decimal degrees to 5 decimal places)

Site Name: Trunk M Pipeline	Site Type: Pipeline
Date Release Discovered: 4/30/2021	API# (if applicable)

Unit Letter	Section	Township	Range	County
A	S13	T22S	R36E	Lea

Surface Owner: X State Federal Tribal Private (Name:\_\_\_\_\_

### Nature and Volume of Release

Mater	ial(s) Released (Select all that apply and attach calculations or specific	justification for the volumes provided below)	
Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)	
Produced Water	Volume Released (bbls)	Volume Recovered (bbls)	
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No	
Condensate	Volume Released (bbls)	Volume Recovered (bbls)	
X Natural Gas	Volume Released (Mcf): 400.6 mcf	Volume Recovered (Mcf): 0 mcf	
X Other (describe) Pipeline liquids	Volume/Weight Released (provide units): 6.4 bbls	Volume/Weight Recovered (provide units): 1.5 bbls	
	release was attributed to corrosion of the pipeline segmen out the line back into service after repairs. The line was b	nt. An additional 239.4 mcf field gas was released when slown-down through a truck.	

Page 2

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the responsible party consider this a major release?
Yes X No	
If YES, was immediate no	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?
1	

## **Initial Response**

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

 $\mathbf{X}$  The source of the release has been stopped.

The impacted area has been secured to protect human health and the environment.

X Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

X All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Carolyn Blackaller	Title: Sr. Environmental Specialist
Signature: Carol. Scono Com	Date: <u>5/13/2021</u>
email: <u>Carolyn.blackaller@energvtransfer.com</u>	Telephone: (432) 203-8920
OCD Only	
Received by: Ramona Marcus	Date:5/17/2021

.

NAPP2113333790

**Blowdown Calculation** 

PIPELINE

 Flow Area=
 2.180556 ft^2

 Pip Vol=
 144821.6 ft^3

 Dens Diff=
 -0.15693 lb/ft^3

 MassCont=
 -22726.7 lbs

MSCF= -400.624

Spill Calcs	
Length (ft)	15.000
Width (ft)	20.000
Depth (in)	2.000
% Oil in Liquid	10.000
Porosity Factor	0.550
Vol. of Impacted Soil (ft <sup>3</sup> )	1.852
Oil in Soil (bbls)	0.490
H2O in Soil (bbls)	4.408

NAPP2113333790

# **Purge Time Calculation**

Diameter (in inches)	20	RECOMMENDED PURGE TIME	91
Length (in miles)	12.579	ACTUAL PURGE TIME (in min)	20
Pipeline Pressure (psia)	53	VOLUME OF PURGE GAS (Mcf)	<u>239</u>
Blowdown Size (valve)	4		
K (Blowoff Coefficient)	13.50		

CONDITIONS

Action 28056

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170 <u>District IV</u> 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

## State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

#### CONDITIONS OF APPROVAL

Operator:			OGRID:	Action Number:	Action Type:
ETC T	EXAS PIPELINE, LTD.	8111 Westchester Drive	371183	28056	C-141
Suite 600	Dallas, TX75225				
OCD Reviewer			Condition		
rmarcus			None		