District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505

Latitude __32.309272

State of New Mexico **Energy Minerals and Natural** Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NAPP2113430119
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party	Enterprise Field Services LLC	OGRID	241602	
Contact Name	Robert Dunaway	Contact Telephone	575-628-6802	
Contact email	rhdunaway@eprod.com	Incident # (assigned by OCD) nAPP2113331984		
Contact mailing address	PO Box 4324, Houston, TX 77210			
Location of Palagea Source				

Location of Release Source

(NAD 83 in decimal degrees to 5 decimal places)

Longitude

-104.035949

Site Name Line 1003				Site Type	Gathering Pipeline	
Date Release Discovered May 7, 2021		API# (if applicable)				
Unit Letter	Section	Township	Range	Coun	ty	
A	13	23S	28E	Edd	у	
Surface Owner: State Federal Tribal Private (Name: Mosiac Potash Carlsbad Inc. Nature and Volume of Release						
Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)						
Crude Oil		Volume Released (bbls)		=======================================	Volume Recovered (bbls)	
Produced	Water	Volume Released (bbls)			Volume Recovered (bbls)	
		Is the concentration of dissolved chloride in the produced water >10,000 mg/l?		de in the	☐ Yes ☐ No	
Condensar	te	Volume Released (bbls)			Volume Recovered (bbls)	
Natural G	as	Volume Released (Mcf) 74.33			Volume Recovered (Mcf) - 0	
Other (des	scribe)	Volume/Weight Released (provide units)		s)	Volume/Weight Recovered (provide units)	
Cause of Rele	ease					
		ering pipeline, caus	se is to be determined.			

Form C-141 Page 2

State of New Mexico Oil Conservation Division

Incident ID	NAPP2113430119
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? ☐ Yes ☒ No If YES, was immediate no		whom? When and by what means (phone, email, etc)?	
	Initial l	Response	
The responsible	party must undertake the following actions immedia	tely unless they could create a safety hazard that would result in injury	
☐ The source of the rele	ease has been stopped. s been secured to protect human health as	ad the environment.	
	<u>-</u>	dikes, absorbent pads, or other containment devices.	
All free liquids and re	ecoverable materials have been removed a	and managed appropriately.	
Per 19 15 29 8 B (4) NM	AC the responsible party may commence	remediation immediately after discovery of a release. If remediation	
has begun, please attach a	a narrative of actions to date. If remedia	l efforts have been successfully completed or if the release occurred please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.			
Printed Name: Robert	Bunaway	Title: Senior Environmental Engineer	
Signature: 1/h	uns	Date: 5/2/	
email: <u>rhdunaway@epro</u>	d.com_	Telephone: _575-628-6802	
OCD Only			
Received by: Ramona	Marcus	Date: <u>5/26/2021</u>	

	NIA DD	9 112120110
Horisevieltoji OCD: 5/26/2021 9:.	35:12 AM Pa	2 113430119 ge 3 of 4
Diameter of hole (inches)	0.025	
Line Pressure at Leak	650	Hourly Bas
Volume of Gas Leaked	0.42	0.42
Calculations:		
Volume of Gas Leaked (MSCF) = Diameter		
**Reference: Pipeline Rules of Thumb Han	dbook, 3rd Edition, Mc.	Allister. Page
Footage of Pipe blowndown	2800	
Initial line pressure	650	
Diameter of Pipe (inches)	8	
Volume of Gas Blown Down	51.20640	MSCF
Calculations:		
Volume of Gas Blown Down (MSCF) = Volu		
(1000 scf/mscf)*Standard Pressure (14.7psi)		
Volume at pipeline conditions (scf) = Diamo		
**Reference: Gas Pipeline Hydraulics, Men	ison (200 <u>5)</u> Pages 132-1	34. Assumin
Released to Imaging: 5/26/2021	2:28:48 PM	
Total Gas Loss	51.62	MSCF

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 29559

CONDITIONS

Operator:	OGRID:
Enterprise Field Services, LLC	241602
PO Box 4324	Action Number:
Houston, TX 77210	29559
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
rmarcus	None	5/26/2021