District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NAPP2109850746
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party Chevron U.S.A., Inc.					OGRID 4323			
Contact Name Jessica Zemen					Contact Te	elephone 432-53	80-9187	
Contact email jessicazemen@chevron.com					Incident # (assigned by OCD)			
Contact mailing address 6301 Deauville Blvd. Midland, TX 79706					1			
			Location	ı of R	delease So	ource		
Latitude 32.15954 Longitude -103.65771 (NAD 83 in decimal degrees to 5 decimal places)								
Site Name: C	Cotton Draw	3 Compressor Sta	ation		Site Type:	Oil		
Date Release	Discovered	4/1/2021			API# (if app	licable): N/A		
Unit Letter	Section	Township	Range		Coun	ıty		
Н	03	25S	32E	Lea				
Cmr.do Oil						justification for the	volumes provided below)	
Crude Oil		Volume Release				Volume Reco		
Produced	Water	Volume Release				Volume Recovered (bbls)		
		Is the concentra produced water	tion of dissolved >10.000 mg/l?	chloride	e in the	Yes No		
Condensa	ite	Volume Release				Volume Reco	vered (bbls)	
Natural G	ras	Volume Release	ed (Mcf): 479			Volume Recovered (Mcf): 0		
Other (describe) Volume/Weight Released (provide units)	Volume/Weig	tht Recovered (provide units)		
Cause of Rele	ease	•				•		
The compress shutdown res			e fuel skid havinş	g an ele	ctrostatic disc	charge from a L	SHH alarm. This	

Th			0
Pao	0	n	t '
Pag	C 4	v	<i>-</i>

Incident ID	NAPP2109850746
District RP	
Facility ID	
Application ID	

Was this a major	If YES, for what reason(s) does the responsible party consider this a major release?
release as defined by 19.15.29.7(A) NMAC?	N/A
, ,	
☐ Yes ⊠ No	
If YES, was immediate no	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?
11 120, 1140 111111001410 11	successive and a color of manners and construction of the successive and the successive a
	Initial Response
TI II	-
The responsible j	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury
The source of the rele	ease has been stopped.
	is been secured to protect human health and the environment.
	ave been contained via the use of berms or dikes, absorbent pads, or other containment devices.
	ecoverable materials have been removed and managed appropriately.
<u> </u>	d above have not been undertaken, explain why:
if all the actions described	1 above have <u>not</u> been undertaken, explain why.
Released material was no	t a liquid therefore the fourth option does not apply.
has begun, please attach	AC the responsible party may commence remediation immediately after discovery of a release. If remediation a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred at area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
	rmation given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and
regulations all operators are public health or the environr failed to adequately investig addition, OCD acceptance o	required to report and/or file certain release notifications and perform corrective actions for releases which may endanger ment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have at and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In f a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws
and/or regulations.	
Printed Name:Jess	ica Zemen Title: Lead Environmental Specialist, Field Support
Jes	iva X Zemen Date:4/8/2021
Signature:/	Date:4/8/2021
email:jessicazen	nen@chevron.com Telephone:432-530-9187
OCD Only	
Received by Pama	na Marcus Date: 4/30/2021
Received byRaillo	na marcus Date;

Page 3 of 5

Incident ID	NAPP2109850746
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report. N/A due to release report is a flare event.						
☐ A scaled site and sampling diagram as described in 19.15.29.11 NMAC						
Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)						
☐ Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)						
☐ Description of remediation activities						
hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, numan health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete. Printed Name:						
Signature: Date:4/8/2021						
email:jessicazemen@chevron.com Telephone:432-530-9187						
OCD Only						
Received by: Ramona Marcus Date: 4/30/2021						
Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.						
Closure Approved by: Date: 06/17/2021						
Printed Name: Cristina Eads Title: Environmental Specialist						

Received by OCD: 4/8/2021 5:16:33 PM Form C-141 State of New Mexico Page 4 Oil Conservation Division

	Page 4 oj
Incident ID	NAPP2109850746
District RP	
Facility ID	
A1! (! ID)	

3. Time of	3. Time of Event					1. Vented	2. Calculating Valumetric	c Rolowo Rato (far PRU Roloaros Incapab		3. Garenur Tolumetric (scf/hr ur scf/event)	Rologro Reto	
Date of discovery	Time of Directory or School	Date of start of event	Time of Start of Event : -	Date of and of avent Schools	Time of est, or actual end of event or Schedule	Dereties of	Tont or Fi	lr Tulumo Motorod, Ertimetod ar Othoru Kanun?	Daily Production (barrole —	Sita-spacific GOR Availabla?	Site-specfic 60R (ref qur barrel nil	Talus 🔻	Unitr 🔻
4/1/2021	2:30:00	4/1/2021	2:30:00	4/1/2021	3:00:00	0.50	Flare					479	mscf/event

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 23549

CONDITIONS

Operator:	OGRID:
CHEVRON U S A INC	4323
6301 Deauville Blvd	Action Number:
Midland, TX 79706	23549
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

C	Created By	Condition	Condition Date		
С	ceads	None	6/17/2021		