



Certificate of Analysis

Number: 5030-21060198-002A

Midland Laboratory

2200 East I-20

Midland, TX 79706

Phone 432-689-7252

JIMMY POOLE
SALT CREEK MIDSTREAM
1369 I-20
PECOS, TX 79772

June 11, 2021

Station Name: NAILED IT A CDP
Station Number: 2.10.9
Method: GPA-2261
Cylinder No: 5030-03952
Analyzed: 06/09/2021 09:20:07 by MGN

Sampled By: C PAUL
Sample Of: Gas Spot
Sample Date: 06/04/2021 15:30
Sample Conditions: 113 psig, @ 66 °F
PO/Ref. No: WO 20.07000.W3197

Analytical Data

Components	Mol. %	Wt. %	GPM at 14.65 psia		
Nitrogen	0.586	0.746		GPM TOTAL C2+	6.224
Carbon Dioxide	0.207	0.414		GPM TOTAL C3+	3.256
Methane	77.896	56.784		GPM TOTAL iC5+	1.053
Ethane	11.118	15.191	2.968		
Propane	4.867	9.752	1.339		
Iso-butane	0.880	2.324	0.287		
n-Butane	1.833	4.841	0.577		
Iso-pentane	0.551	1.806	0.201		
n-Pentane	0.617	2.023	0.223		
Hexanes Plus	1.445	6.119	0.629		
	100.000	100.000	6.224		

Calculated Physical Properties	Total	C6+
Relative Density Real Gas	0.7627	3.2176
Calculated Molecular Weight	22.01	93.19
Compressibility Factor	0.9960	
GPA 2172 Calculation:		
Calculated Gross BTU per ft³ @ 14.65 psia & 60°F		
Real Gas Dry BTU	1316	5113
Water Sat. Gas Base BTU	1294	5024

Report generated by: Marco Barrientos

Quality Assurance: The above analyses are performed in accordance with ASTM, UOP, GPA guidelines for quality assurance, unless otherwise stated.

Flaring Summary

(Column Names) » date

Data table:
flare_report_data (2)
Colors:
All values

battery	Sum(TOTAL FLARE (HP + LP))	
	6/12/2021	
Nailed It A Tank Battery		216.90
Grand total		216.90

battery

Sum(TOTAL FLARE (HP + LP))

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 32623

QUESTIONS

Operator: TAP ROCK OPERATING, LLC 523 Park Point Drive Golden, CO 80401	OGRID: 372043 Action Number: 32623 Action Type: [C-129] Venting and/or Flaring (C-129)
--	---

QUESTIONS**Determination of Reporting Requirements**

Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.

Was or is this venting or flaring caused by an emergency or malfunction	No
Did or will this venting or flaring last eight hours or more cumulatively within any 24-hour period from a single event	No
Is this considered a submission for a notification of a major venting or flaring	Yes, minor venting or flaring of natural gas.
The operator shall file a form C-141 instead of a form C-129 for a release that includes liquid during venting or flaring that is or may be a major or minor release under 19.13.29.7 NMAC	
Was there or will there be at least 50 MCF of natural gas vented or flared during this event	Yes
Did this venting or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No

Unregistered Facility Site

Please provide the facility details, if the venting or flaring occurred or is occurring at a facility that does not have an Facility ID (##) yet.

Facility or Site Name	Nailed It CTB
Facility Type	Tank Battery - (TB)

Equipment Involved

Primary Equipment Involved	Not answered.
Additional details for Equipment Involved. Please specify	Not answered.

Representative Compositional Analysis of Vented or Flared Natural Gas

Please provide the mole percent for the percentage questions in this group.

Methane (CH4) percentage	78
Nitrogen (N2) percentage, if greater than one percent	1
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	0
Oxygen (O2) percentage, if greater than one percent	0
If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.	
Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Date(s) and Time(s)

Date venting or flaring was discovered or commenced	06/11/2021
Time venting or flaring was discovered or commenced	06:00 AM
Is the venting or flaring event complete	Yes
Date venting or flaring was terminated	06/11/2021
Time venting or flaring was terminated	06:00 PM
Total duration of venting or flaring in hours, if venting or flaring has terminated	12
Longest duration of cumulative hours within any 24-hour period during this event	4

Measured or Estimated Volume of Vented or Flared Natural Gas

Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Cause: High Line Pressure Other (Specify) Natural Gas Flared Spilled: 217 Mcf Recovered: 0 Mcf Lost: 217 Mcf]
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity

Was or is this venting or flaring a result of downstream activity	Not answered.
Date notified of downstream activity requiring this venting or flaring	Not answered.
Time notified of downstream activity requiring this venting or flaring	Not answered.

Steps and Actions to Prevent Waste

--

For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	False
Please explain reason for why this event was beyond your operator's control	Not answered.
Steps taken to limit the duration and magnitude of venting or flaring	Since the discovery of data, the well has been either choked back/or shut in to meet regulations. Tap Rock is working on getting equipment/alternative methods to dispose of the gas in the future to allow for 100% gas capture.
Corrective actions taken to eliminate the cause and reoccurrence of venting or flaring	Tap Rock is working on getting equipment/alternative methods to dispose of the gas in the future to allow for 100% gas capture.

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 32623

CONDITIONS

Operator: TAP ROCK OPERATING, LLC 523 Park Point Drive Golden, CO 80401	OGRID: 372043
	Action Number: 32623
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
system	If the information provided in this report requires an amendment, submit a [C-129] Request to Amend Venting and/or Flaring Incident, utilizing your incident number from this event.	6/17/2021