www.permianls.com 575.397.3713 2609 W Marland Hobbs NM 88240



6778G	NCW1471393	Coriander AOC 1-12 St 2 Alloc
Sample Point Code	Sample Point Name	Sample Point Location

Laborato	ry Services	2021043954	0754		J Mcpherson - Spot
Source L	aboratory	Lab File No	Container Ider	ntity	Sampler
USA		USA	USA		New Mexico
District		Area Name	Field Name		Facility Name
Jul 24, 202	1 09:30	Jul 24, 2021 09:30		Jul 27, 2021 07:31	Jul 27, 2021
Date Sar	npled	Date Effective		Date Received	Date Reported
82.00		Luis	135	@ 84	
Ambient Temp (°F)	Flow Rate (Mcf)	Analyst	Press PSI (Source C	@ Temp °F Conditions	
Cimarex	Energy				NG
Oper	ator	_			Lab Source Description

Component	Normalized Mol %	Un-Normalized Mol %	GPM
H2S (H2S)	0.0000	0	
Nitrogen (N2)	2.9010	2.9013	
CO2 (CO2)	10.7970	10.79719	
Methane (C1)	69.7130	69.71241	
Ethane (C2)	8.9140	8.91363	2.3830
Propane (C3)	4.5080	4.50782	1.2420
I-Butane (IC4)	0.5110	0.51078	0.1670
N-Butane (NC4)	1.2190	1.21856	0.3840
I-Pentane (IC5)	0.3260	0.32649	0.1190
N-Pentane (NC5)	0.3360	0.33634	0.1220
Hexanes Plus (C6+)	0.7750	0.7755	0.3360
TOTAL	100.0000	100.0000	4.7530

Method(s): Gas C6+ - GPA 2261, Extended Gas - GPA 2286, Calculations - GPA 2172

	Analyze	r Information	
Device Type:	Gas Chromatograph	Device Make:	Shimadzu
Device Model:	GC-2014	Last Cal Date:	Jul 25, 2021

0.000	5.555			
14.696 PSI @ 60.	00 °F	14.73 PS	SI @ 60.00 °F	
Dry	Saturated	Dry	Saturated	
1,101.8	1,083.9	1,104.3	1,086.4	
Calcu	ulated Total S	Sample Proper	ties	
GPA2	145-16 *Calculate	d at Contract Conditi	ions	
Relative Density	Real	Relative	Density Ideal	
0.8183		().8156	
Molecular Weight				
23.6216	5			
C6+ Group Properties				
	Assumed C	Composition		
C6 - 60.000%	C7 - 30	.000%	C8 - 10.000%	
	Field	H2S		
	4 F	PPM		
PROTREND STATUS:		DATA S	SOURCE:	

Gross Heating Values (Real, BTU/ft3)

DATA SOURCE:

Passed By Validator on Jul 27, 2021 Imported

PASSED BY VALIDATOR REASON:

Close enough to be considered reasonable.

VALIDATOR:

Dustin Armstrong

VALIDATOR COMMENTS:

OK

CORIANDER 1-12 STATE COM CDP FLARE			_	Digital (gas)	_	15513	_	_	
		5/2021	7/24/2021	7/23/2021	7/22/2021	7/21/2021	7/20/2021	7/19/2021	7/18/2021
Static	(PSI)	127	123	132	128	130	99	123	115
Differential	(In H2O	0	0	0	0	0	0	0	0
Gas Flowed	(MCF)	0.0	0.0	6.0	9.0	22.0	34.0	1.0	86.0

2 Hours

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III 1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 39399

QUESTIONS

Operator:	OGRID:
CIMAREX ENERGY CO.	215099
600 N. Marienfeld Street	Action Number:
Midland, TX 79701	39399
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

QUESTIONS

Determination of Reporting Requirements		
Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide addional guidance.		
Was or is this venting or flaring caused by an emergency or malfunction	Yes	
Did or will this venting or flaring last eight hours or more cumulatively within any 24-hour period from a single event	No	
Is this considered a submission for a notification of a major venting or flaring	Yes, minor venting or flaring of natural gas.	
The operator shall file a form C-141 instead of a form C-129 for a release that includes liquid during vi	nting or flaring that is or may be a major or minor release under	
Was there or will there be at least 50 MCF of natural gas vented or flared during this event	Yes	
Did this venting or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No	

Unregistered Facility Site		
Please provide the facility details, if the venting or flaring occurred or is occuring at a facility that does not have an Facility ID (f#) yet.		
Facility or Site Name	CORIANDER 1-12 STATE COM CDP FLARE	
Facility Type	Flare Stack - (FS)	

Equipment Involved	
Primary Equipment Involved	Not answered.
Additional details for Equipment Involved. Please specify	Not answered.

Representative Compositional Analysis of Vented or Flared Natural Gas		
Please provide the mole percent for the percentage questions in this group.		
Methane (CH4) percentage	70	
Nitrogen (N2) percentage, if greater than one percent	3	
Hydrogen Sulfide (H2S) PPM, rounded up	0	
Carbon Dioxide (C02) percentage, if greater than one percent	11	
Oxygen (02) percentage, if greater than one percent	0	
If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.		
Methane (CH4) percentage quality requirement	Not answered.	
Nitrogen (N2) percentage quality requirement	Not answered.	
Hydrogen Sufide (H2S) PPM quality requirement	Not answered.	
Carbon Dioxide (C02) percentage quality requirement	Not answered.	
Oxygen (02) percentage quality requirement	Not answered.	

Date(s) and Time(s)		
Date venting or flaring was discovered or commenced	07/18/2021	
Time venting or flaring was discovered or commenced	01:00 AM	
Is the venting or flaring event complete	Yes	
Date venting or flaring was terminated	07/23/2021	
Time venting or flaring was terminated	01:00 AM	
Total duration of venting or flaring in hours, if venting or flaring has terminated	2	
Longest duration of cumulative hours within any 24-hour period during this event	2	

Measured or Estimated Volume of Vented or Flared Natural Gas		
Natural Gas Vented (Mcf) Details	Not answered.	
Natural Gas Flared (Mcf) Details	Cause: High Line Pressure Gas Compressor Station Natural Gas Flared Spilled: 152 Mcf Recovered: 0 Mcf Lost: 152 Mcf]	
Other Released Details	Not answered.	
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.	
Is this a gas only submission (i.e. only Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.	

Venting or Flaring Resulting from Downstream Activity	
Was or is this venting or flaring a result of downstream activity	Yes
Date notified of downstream activity requiring this venting or flaring	Not answered.
Time notified of downstream activity requiring this venting or flaring	Not answered.

Steps and Actions to Prevent Waste

For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True
Please explain reason for why this event was beyond your operator's control	High line pressure was caused by third party gas gatherer.
Steps taken to limit the duration and magnitude of venting or flaring	Wells were shut in and minor subsequent flaring was caused by well unloading and power outage.
Corrective actions taken to eliminate the cause and reoccurrence of venting or flaring	Cimarex will continue to monitor third party gas gathering system and will shit in wells to prevent
	flaring if necessary.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 39399

CONDITIONS

Operator:	OGRID:
CIMAREX ENERGY CO.	215099
600 N. Marienfeld Street	Action Number:
Midland, TX 79701	39399
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
system	If the information provided in this report requires an amendment, submit a [C-129] Request to Amend Venting and/or Flaring Incident, utilizing your incident number from this event.	8/2/2021