



Athens, TX (903) 677-0700 . Beeville, TX (361) 354-5200 . Midland, TX (432) 704-5351

GAS ANALYSIS REPORT

LAB REPORT NUMBER: WT-1027 - 06042020

PHYSICAL CONSTANTS PER GPA 2145-16

CUSTOMER:	BTA OIL PRODUCERS LLC	DATE ANALYZED:	6/17/2020
STATION:	80938151	DATE ON:	6/4/2020
PRODUCER:	BTA OIL PRODUCERS	DATE OFF:	
LEASE:	HARROUN #4 C-M	SAMPLED BY	Landon Johnson
EFFECTIVE DATE:	6/1/2020		

<u>COMPONENT:</u>	<u>MOLE %</u>	<u>GPM</u>	<u>WT. %</u>
H2S	0.000		0.000
OXYGEN	0.065		0.093
NITROGEN	18.042		22.667
CARBON DIOXIDE	0.900		1.776
METHANE	66.700		47.988
ETHANE	7.413	1.977	9.997
PROPANE	3.847	1.057	7.608
I-BUTANE	0.478	0.156	1.246
N-BUTANE	0.940	0.296	2.450
I-PENTANE	0.316	0.115	1.023
N-PENTANE	0.293	0.106	0.948
HEXANE PLUS	<u>1.006</u>	<u>0.435</u>	<u>4.204</u>
TOTAL	100.000	4.141	100.000

(ALL VALUES CALCULATED @ 14.65 PSIA + 60 DEG. F)

REAL GRAVITY	0.7717	BTU WET BASIS	1005.93
MOL WT.	22.298	BTU DRY BASIS	1023.47
H2S PPM:	0.000	CO2 %:	

SAMPLE TYPE	SPOT	SAMPLE PRESS:	66
CYLINDER NO	WT-1027	SAMPLE TEMP:	93
NOTES		COUNTY/STATE:	EDDY, NM

7/8/2020

Harroun Ranch East Flare 7/29/2021



Gas Meter Report

Harroun Ranch East Flare Gas - Harroun Ranch East HP Flare Meter 1

Date: 8/9/2021

Time: 3:39 PM

Selected Time Frame: Last 5 Years

Gas Meter Readings				
Date	Diff	Static	MCF	Line
--- Gas Meter: Harroun Ranch East HP Flare Meter 1				
08/01/2021	0.00	0	0	0
07/31/2021	0.00	0	0	0
07/30/2021	0.00	0	0	0
07/29/2021	0.00	0	123	0
07/28/2021	0.00	0	0	0
07/27/2021	0.00	0	0	0

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 41197

QUESTIONS

Operator: BTA OIL PRODUCERS, LLC 104 S Pecos Midland, TX 79701	OGRID: 260297
	Action Number: 41197
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS

Determination of Reporting Requirements	
<i>Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.</i>	
Was or is this venting or flaring caused by an emergency or malfunction	No
Did or will this venting or flaring last eight hours or more cumulatively within any 24-hour period from a single event	Yes
Is this considered a submission for a notification of a major venting or flaring	Yes, minor venting or flaring of natural gas.
The operator shall file a form C-141 instead of a form C-129 for a release that includes liquid during venting or flaring that is or may be a major or minor release under 19-1-29, NMAC.	
Was there or will there be at least 50 MCF of natural gas vented or flared during this event	Yes
Did this venting or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No

Unregistered Facility Site	
<i>Please provide the facility details, if the venting or flaring occurred or is occurring at a facility that does not have an Facility ID (F#) yet.</i>	
Facility or Site Name	Harroun Ranch East CTB
Facility Type	Flare Stack - (FS)

Equipment Involved	
Primary Equipment Involved	Separator
Additional details for Equipment Involved. Please specify	Not answered.

Representative Compositional Analysis of Vented or Flared Natural Gas	
<i>Please provide the mole percent for the percentage questions in this group.</i>	
Methane (CH4) percentage	67
Nitrogen (N2) percentage, if greater than one percent	18
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	0
Oxygen (O2) percentage, if greater than one percent	0
If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.	
Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Date(s) and Time(s)	
Date venting or flaring was discovered or commenced	07/29/2021
Time venting or flaring was discovered or commenced	12:00 AM
Is the venting or flaring event complete	Yes
Date venting or flaring was terminated	07/29/2021
Time venting or flaring was terminated	11:59 PM
Total duration of venting or flaring in hours, if venting or flaring has terminated	24
Longest duration of cumulative hours within any 24-hour period during this event	24

Measured or Estimated Volume of Vented or Flared Natural Gas	
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Cause: High Line Pressure Separator Natural Gas Flared Spilled: 123 Mcf Recovered: 0 Mcf Lost: 123 Mcf]
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.
Is this a gas only submission (i.e. only Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity	
Was or is this venting or flaring a result of downstream activity	Yes
Date notified of downstream activity requiring this venting or flaring	Not answered.
Time notified of downstream activity requiring this venting or flaring	Not answered.

Steps and Actions to Prevent Waste	
---	--

For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True
Please explain reason for why this event was beyond your operator's control	High Line Pressure
Steps taken to limit the duration and magnitude of venting or flaring	Battery Redesign
Corrective actions taken to eliminate the cause and reoccurrence of venting or flaring	Battery Redesign

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS
 Action 41197

CONDITIONS

Operator: BTA OIL PRODUCERS, LLC 104 S Pecos Midland, TX 79701	OGRID: 260297
	Action Number: 41197
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
system	If the information provided in this report requires an amendment, submit a [C-129] Request to Amend Venting and/or Flaring Incident, utilizing your incident number from this event.	8/11/2021