District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	nAPP2133326844
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party Hilcorp Energy Company				OGRID 372171			
Contact Name Mitch Killough			Contact Telephone 713-757-5247				
Contact email mkillough@hilcorp.com			Incident # nAPP2133326844				
Contact mail 77002	ing address	1111 Travis Stree	et, Houston, Texas	S			
			Location	of R	elease So	ource	
Latitude 36.	955822		(NAD 83 in dec			.107.7127533 nal places)	
Site Name S	on Ivon 22	9 Hait 222			Cita Tuma	Notural Cas Dra	duction Facility
							duction Facility
Date Release Discovered 11/16/2021 @ 12:30pm MT			API# 30-04	15-27972			
Unit Letter	Section	Township	Range		Coun	ty	
G	30	32N	08W	San J	n Juan		
Surface Owner	r: ☐ State	Federal Tr	ihal □ Private ()	Name:)
Surface 5 wife	i. 🗀 state			_			,
			Nature and				
Crude Oil		Volume Release		calculati	ions or specific	Volume Reco	volumes provided below) vered (bbls)
☐ Produced	Water	Volume Release				Volume Recovered (bbls) 53	
	,, a.c.i		ion of dissolved c	hlorida	in the	Yes No	
		produced water		moriae	in the		0
Condensate Volume Released (bbls)				Volume Recovered (bbls)			
☐ Natural G	las	Volume Release	d (Mcf)			Volume Recovered (Mcf)	
Other (describe) Volume/Weight Released (provide units)		e units)		Volume/Weight Recovered (provide units)			
the San Juan	21 at approx 32-8 Unit 2	33 (API: 30-045-2	7972) in San Juan	County	y, NM. Base	ed on assessmen	d a 184-bbl release of produced water at ts conducted by Hilcorp personnel, the ly upon discovery, the storage tank was
Ī							

Received by OCD: 11/29/2021 10:30:08 AM Form C-141 State of New Mexico Page 2 Oil Conservation Division

State of New Mexico	<u></u>	
State of New Mexico	Incident ID	nAPP213

	Page 2 of .
Incident ID	nAPP2133326844
District RP	
Facility ID	
Application ID	

Was this a major	If YES, for what reason(s) does the responsib	le party consider this a major release?				
release as defined by 19.15.29.7(A) NMAC?	The spill amount exceeded 25 bbls.					
	r					
∑ Yes □ No						
If VES was immediate no	otice given to the OCD? By whom? To whom	? When and by what means (phone, email, etc)?				
	the BLM (FFO) and NMOCD via 24-hour email					
	Initial Response					
The responsible p	party must undertake the following actions immediately un	less they could create a safety hazard that would result in injury				
☐ The source of the rele	ease has been stopped.					
l <u></u>	ease has been stopped. as been secured to protect human health and the	anvironment				
<u> </u>	•					
		s, absorbent pads, or other containment devices.				
	ecoverable materials have been removed and m					
If all the actions described	d above have <u>not</u> been undertaken, explain why	:				
		d) and did not migrate horizontally outside of this surface area				
or the pad. However, 131 secondary containment ar		and migrated vertically into the underlying soils beneath the				
secondary contaminent ar	.cu.					
Par 10 15 20 8 R (4) NM	MAC the responsible party may commence remo	ediation immediately after discovery of a release. If remediation				
		orts have been successfully completed or if the release occurred				
within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.						
		of my knowledge and understand that pursuant to OCD rules and				
		ions and perform corrective actions for releases which may endanger does not relieve the operator of liability should their operations have				
failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In						
addition, OCD acceptance of and/or regulations.	at a C-141 report does not relieve the operator of resp	consibility for compliance with any other federal, state, or local laws				
_	Killough	Title:Environmental Specialist				
Timed Pame Witten I	Kinough	rideEnvironmental Specialist				
	11 14					
Signature:	which holy	Date: 11/29/2021				
email: mkillough@hi	ilcorp.com	713-757-5247				
OCD Only						
Received by: Ramona N	Marcus D	ate:				
1.000110d by						

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 63893

CONDITIONS

Operator:	OGRID:
HILCORP ENERGY COMPANY	372171
1111 Travis Street	Action Number:
Houston, TX 77002	63893
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
rmarcus	When submitting future reports regarding this release, please submit the calculations used or specific justification for the volumes reported on the initial C-141	11/29/2021