

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Incident ID	NAPP2114536249
District RP	
Facility ID	
Application ID	

REVIEWED

By Nelson Velez at 3:00 pm, Feb 22, 2022

Release Notification

Responsible Party

Responsible Party Enduring Resources LLC	OGRID 372286
Contact Name Jim Mars	Contact Telephone (505)947-2460
Contact email jmars@enduringresources.com	Incident # (assigned by OCD) NAPP2114536249
Contact mailing address 200 Energy Court	Farmington, NM 87401

Location of Release Source

Latitude **36.21508** Longitude **-107.62494**
(NAD 83 in decimal degrees to 5 decimal places)

Site Name Chaco 2308 24H #153H	Site Type Well site
Date Release Discovered 5/24/2021	API# (if applicable) 30-045-35550

Unit Letter	Section	Township	Range	County
H	24	23 N	8 W	San Juan

Surface Owner: State Federal Tribal Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

Enduring Resources would like to close this incident out as it was incorrectly reported for the Chaco 2308 24H 153H and should have been reported on the Chaco 2308 24I 155H, which is an adjacent well pad just south. A new incident report and C-141 will be submitted for the correct location information..


Incident ID	NAPP2114536249
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release?
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input type="checkbox"/> The source of the release has been stopped. <input type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.
If all the actions described above have <u>not</u> been undertaken, explain why:
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.
Printed Name: <u>Heather Huntington</u> Title: <u>Permitting Technician</u> Signature: <u>Heather Huntington</u> Date: <u>5/27/2021</u> email: <u>hhuntington@enduringresources.com</u> Telephone: <u>(505) 636-9751</u>
OCD Only Received by: <u>Ramona Marcus</u> Date: <u>5/28/2021</u>



SWNE

SENE

SENW

NWSE

NESE

NESW

SESE

L4

SESW

CHACO 2308 24H #153H

CHACO 153 PAD
CHACO 154 PAD

CHACO 155 PAD
CHACO 156 PAD

CHACO 2308 24I #155H
CHACO 2308 24I #156H

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720
District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720
District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS
 Action 29811

CONDITIONS

Operator: ENDURING RESOURCES, LLC 6300 S Syracuse Way, Suite 525 Centennial, CO 80111	OGRID: 372286
	Action Number: 29811
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
nvelez	Well site was inadvertently mis-identified. Appropriate action was taken; therefore, closing this incident.	2/22/2022