



February 2, 2022

Vertex Project #: 21E-00580-009

Spill Closure Report: Billiken 6 CTB 1
Unit D, Section 06, Township 26 South, Range 35 East
County: Lea
API: N/A
Tracking Number: nAPP2134155628

Prepared For: Devon Energy Production Company
6488 Seven Rivers Highway
Artesia, New Mexico 88210

New Mexico Oil Conservation Division – District 1 – Hobbs

1625 North French Drive
Hobbs, New Mexico 88240

Devon Energy Production Company (Devon) retained Vertex Resource Services Inc. (Vertex) to conduct a spill assessment and liner inspection for a produced water release that occurred at Billiken 6 CTB 1 (hereafter referred to as “Billiken CTB”). Devon provided immediate notification of the spill to New Mexico Oil Conservation Division (NMOCD) District 1 and the Bureau of Land Management (BLM), who own the property, on December 4, 2021, via phone call and email. The initial C-141 Release Notification was received by NMOCD on December 22, 2021 (Attachment 1). The NMOCD tracking number assigned to this incident is nAPP2134155628.

This letter provides a description of the liner inspection and demonstrates that closure criteria established in 19.15.29.12 *New Mexico Administrative Code* (NMAC; New Mexico Oil Conservation Division, 2022) have been met and all applicable regulations are being followed. This document is intended to serve as a final report to obtain approval from NMOCD for closure of this release.

Incident Description

On December 3, 2021, a release occurred at Devon’s Billiken CTB site when a leak developed in a flowline. The incident resulted in the release of approximately 236.28 barrels (bbl) of produced water into lined containment. A hydrovac arrived on-site to recover free fluids; approximately 236.28 bbls of produced water were recovered and removed for disposal off-site. The spill was fully contained within the bermed, lined containment on the facility pad. No produced water was released into undisturbed areas or waterways.

Site Characterization

The release at Billiken CTB occurred on federally-owned land, N 32.076535, W 103.411171, approximately 12.5 miles west of Jal, New Mexico. The legal description for the site is Unit D, Section 06, Township 26 South, Range 35 East, Lea County, New Mexico. This location is within the Permian Basin in southeast New Mexico and has historically been used for oil and gas exploration and production, and rangeland. An aerial map of the site is included in Attachment 2.

vertex.ca

3101 Boyd Drive, Carlsbad, New Mexico 88220, USA | P 575.725.5001

Billiken CTB is typical of oil and gas exploration and production sites in the western portion of the Permian Basin and is currently used for oil and gas production and storage. The following sections specifically describe the area in which the Billiken CTB facility is located.

The surrounding landscape is associated with sandy plains typical of elevations of 3,000 to 3,900 feet above sea level. The climate is semi-arid, with average annual precipitation ranging between 10 and 12 inches. Historically, the plant community was dominated by grasses, which stabilized the potentially erosive sandy soils; however, more recent conditions, resulting from fire suppression and extensive grazing, show increased woody plant abundance. The dominant grass species are black grama, dropseeds and bluestems, with scattered shinnery oak and sand sage. Litter and, to a lesser extent, bare ground are a significant proportion of ground cover while grasses compose the remainder (United States Department of Agriculture, Natural Resources Conservation Service, 2022). Limited to no vegetation is allowed to grow on the compacted facility pad.

The *Geological Map of New Mexico* indicates the surface geology at Billiken CTB is comprised of Qep – eolian and piedmont deposits that include eolian sands interlaid with piedmont-slope deposits (New Mexico Bureau of Geology and Mineral Resources, 2022). The Natural Resources Conservation Service *Web Soil Survey* characterizes the soil at the site as Pyote and Maljamar fine sands, characterized by deep, fine sandy and loamy fine sandy soil. It tends to be well-drained with very low to negligible runoff and low available moisture levels in the soil profile (United States Department of Agriculture, Natural Resources Conservation Service, 2022). There is low potential for karst geology to be present near Billiken CTB, though some erosional karst is possible (United States Department of the Interior, Bureau of Land Management, 2018).

There is no surface water located at Billiken CTB. The nearest significant watercourse, as defined in Subsection P of 19.15.17.7 NMAC, is an intermittent stream located approximately 1.19 miles east of the site. An emergent wetland is located approximately 0.64 miles west of the site. An intermittent lake is located approximately 14 miles south-southeast of the release site (United States Fish and Wildlife Service, 2022). At Billiken CTB, there are no continuously flowing watercourses, lakebeds, sinkholes, playa lakes, or other critical water or community features nearby as outlined in Paragraph (4) of Subsection C of 19.15.29.12 NMAC.

The nearest well to Billiken CTB is a United States Geological Survey-identified well located approximately 2.4 miles south of the site, with no groundwater data. New Mexico Office of the State Engineer-identified wells are located approximately 2.57 miles north and 3.57 miles west of the site with recorded depths to groundwater of 300 and 230 feet below ground surface, respectively (bgs; New Mexico Office of the State Engineer, New Mexico Water Rights Reporting System, 2022). Documentation pertaining to site characterization and depth to groundwater determination is included in Attachment 3.

Closure Criteria Determination

Using site characterization information, a closure criteria determination worksheet (Attachment 3) was completed to determine if the release was subject to any of the special case scenarios outlined in Paragraph (4) of Subsection C of 19.15.29.12 NMAC.

Based on data included in the closure criteria determination worksheet, the release at Billiken CTB is not subject to the requirements of Paragraph (4) of Subsection C of 19.15.29.12 NMAC. The nearest depth to groundwater reference is

vertex.ca

Devon Energy Production Company
Billiken 6 CTB 1

2022 Spill Assessment and Closure
February 2022

more than 0.5 miles from the site; therefore, the closure criteria for the incident assume the most stringent conditions (depth to groundwater <50 feet bgs) and are determined to be associated with the following constituent concentration limits.

Table 1. Closure Criteria for Soils Impacted by a Release		
Minimum depth below any point within the horizontal boundary of the release to ground water less than 10,000 mg/L TDS ¹	Constituent	Limit
< 50 feet	Chloride	600 mg/kg
	TPH ² (GRO + DRO + MRO)	100 mg/kg
	BTEX ³	50 mg/kg
	Benzene	10 mg/kg

¹Total Dissolved Solids (TDS)

²Total petroleum hydrocarbons (TPH) = gasoline range organics (GRO) + diesel range organics (DRO) + motor oil range organics (MRO)

³Benzene, toluene, ethylbenzene and xylenes (BTEX)

Liner Inspection

On January 13, 2022, Vertex provided 48-hour notification of the liner inspection to NMOCD and the BLM, as required by Subparagraph (a) of Paragraph (5) of Subsection A 19.15.29.11 NMAC (Attachment 4). On January 21, 2022, Vertex was on-site to conduct an inspection of the lined containment and verify that the liner was intact and had the ability to contain the release. The Daily Field Report and associated photographs of the liner inspection are included in Attachment 5. The inspection confirmed the liner remained intact and had the ability to contain the release. This was further evidenced by the amount of fluid released (~236.28 bbl) and recovered (~236.28 bbl).

Closure Request

Vertex recommends no additional remediation action to address the release at Billiken CTB. The secondary containment liner was intact and contained the release. There are no anticipated risks to human, ecological or hydrological receptors associated with the release site.

Vertex requests that this incident (nAPP2134155628) be closed as all closure requirements set forth in Subsection E of 19.15.29.12 NMAC have been met. Devon certifies that all information in this report and the attachments is correct, and that they have complied with all applicable closure requirements and conditions specified in Division rules and directives to meet NMOCD requirements to obtain closure on the December 3, 2021, release at Billiken CTB. A complete C-141 form is presented in Attachment 6.

Should you have any questions or concerns, please do not hesitate to contact the undersigned at 832.588.0674 or dhanton@vertex.ca

vertex.ca

3101 Boyd Drive, Carlsbad, New Mexico 88220, USA | P 575.725.5001

Devon Energy Production Company
Billiken 6 CTB 1

2022 Spill Assessment and Closure
February 2022



Lakin Pullman, B.Sc.
ENVIRONMENTAL TECHNICIAN, REPORT

February 2, 2022

Date

Dhugal Hanton, B.Sc., P.Ag, P.Biol., SR/WA.
VICE PRESIDENT- USA, REPORT REVIEW

February 2, 2022

Date

Attachments

- Attachment 1. NMOCD C-141 Initial Notification
- Attachment 2. Aerial Site Map
- Attachment 3. Closure Criteria for Soils Impacted by a Release Research Determination Documentation
- Attachment 4. 48-hr Notification of Confirmatory Sampling to Regulatory Agencies
- Attachment 5. Daily Field Report with Photographs
- Attachment 6. Complete C-141 Form

vertex.ca

3101 Boyd Drive, Carlsbad, New Mexico 88220, USA | P 575.725.5001

Devon Energy Production Company
Billiken 6 CTB 1

2022 Spill Assessment and Closure
February 2022

References

- New Mexico Bureau of Geology and Mineral Resources. (2022). *Interactive Geologic Map*. Retrieved from <http://geoinfo.nmt.edu>.
- New Mexico Office of the State Engineer, New Mexico Water Rights Reporting System. (2022). *Water Column/Average Depth to Water Report*. Retrieved from <http://nmwrrs.ose.state.nm.us/nmwrrs/waterColumn.html>.
- New Mexico Oil Conservation Division. (2022). *New Mexico Administrative Code – Natural Resources and Wildlife Oil and Gas Releases*. Santa Fe, New Mexico.
- United States Department of Agriculture, Natural Resources Conservation Service. (2022). *Web Soil Survey*. Retrieved from <https://websoilsurvey.nrcs.usda.gov/app/WebSoilSurvey.aspx>.
- United States Department of the Interior, Bureau of Land Management. (2018). *CFO Karst Public*. https://www.nm.blm.gov/shapeFiles/cfo/carlsbad_spatial_data.html
- United States Fish and Wildlife Service. (2022). *National Wetlands Inventory*. Retrieved from <https://www.fws.gov/wetlands/data/Mapper.html>.

Devon Energy Production Company
Billiken 6 CTB 1

2022 Spill Assessment and Closure
February 2022

Limitations

This report has been prepared for the sole benefit of Devon Energy Production Company (Devon). This document may not be used by any other person or entity, with the exception of the New Mexico Oil Conservation Division and Bureau of Land Management, without the express written consent of Vertex Resource Services Inc. (Vertex) and Devon. Any use of this report by a third party, or any reliance on decisions made based on it, or damages suffered as a result of the use of this report are the sole responsibility of the user.

The information and conclusions contained in this report are based upon work undertaken by trained professional and technical staff in accordance with generally accepted scientific practices current at the time the work was performed. The conclusions and recommendations presented represent the best judgement of Vertex based on the data collected during the assessment. Due to the nature of the assessment and the data available, Vertex cannot warrant against undiscovered environmental liabilities. Conclusions and recommendations presented in this report should not be considered legal advice.

ATTACHMENT 1

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nAPP2134155628
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party Devon Energy Production Company	OGRID 6137
Contact Name Dale Woodall	Contact Telephone
Contact email Dale.Woodall@dvn.com	Incident # (assigned by OCD)
Contact mailing address 6488 Seven Rivers Hwy Artesia, NM 88210	

Location of Release Source

Latitude 32.076535 Longitude -103.411171
(NAD 83 in decimal degrees to 5 decimal places)

Site Name Billiken 6 CTB 1	Site Type Oil
Date Release Discovered 12/03/2021	API# (if applicable)

Unit Letter	Section	Township	Range	County
D	6	23S	35E	Lea

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 236.28 BBLS	Volume Recovered (bbls) 236.28 BBLS
	Is the concentration of total dissolved solids (TDS) in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release Leak developed in flowline. Fluid remained in lined containment.

Incident ID	nAPP2134155628
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? The spill is over 25 BBLS.
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Notice given by Dale Woodall to OCD.	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why: 	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: Kendra DeHoyos	Title: EHS Associate
Signature: <u>Kendra DeHoyos</u>	Date: <u>12/22/2021</u>
email: Kendra.Ruiz@dvn.com	Telephone: 575-748-0167
<u>OCD Only</u>	
Received by: <u>Ramona Marcus</u>	Date: <u>12/27/2021</u>

NAPP2134155628

Spills In Lined Containment	
Measurements Of Standing Fluid	
Length(Ft)	100
Width(Ft)	53
Depth(in.)	4
Total Capacity without tank displacements (bbls)	314.66
No. of 500 bbl Tanks In Standing Fluid	7
No. of Other Tanks In Standing Fluid	1
OD Of Other Tanks In Standing Fluid(feet)	
Total Volume of standing fluid accounting for tank displacement.	236.28

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 68440

CONDITIONS


Operator: DEVON ENERGY PRODUCTION COMPANY, LP 333 West Sheridan Ave. Oklahoma City, OK 73102	OGRID: 6137
	Action Number: 68440
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
rmarcus	None	12/27/2021

ATTACHMENT 2



 Containment (~7,161 sq. ft.)



0 25 50 100 ft.
NAD 1983 UTM Zone 13N
Date: Jan 24/22

Map Center:
Lat: 32.076583,
Long: -103.411132



Aerial Site Map
Billiken 6 CTB 1

FIGURE:
1



Geospatial data presented in this figure may be derived from external sources and Vertex does not assume any liability for inaccuracies. This figure is intended for reference use only and is not certified for legal, survey, or engineering purposes.

Note: Feature locations from aerial imagery, ESRI, 2021.

VERSATILITY. EXPERTISE.

ATTACHMENT 3

Closure Criteria Worksheet			
Site Name: Billiken 6 CTB 1			
Spill Coordinates:		X: 32.076535	Y: -103.411171
Site Specific Conditions		Value	Unit
1	Depth to Groundwater	<50	feet
2	Within 300 feet of any continuously flowing watercourse or any other significant watercourse	12,664	feet
3	Within 200 feet of any lakebed, sinkhole or playa lake (measured from the ordinary high-water mark)	74,079	feet
4	Within 300 feet from an occupied residence, school, hospital, institution or church	46,941	feet
5	i) Within 500 feet of a spring or a private, domestic fresh water well used by less than five households for domestic or stock watering purposes, or	13,556	feet
	ii) Within 1000 feet of any fresh water well or spring	13,556	feet
6	Within incorporated municipal boundaries or within a defined municipal fresh water field covered under a municipal ordinance adopted pursuant to Section 3-27-3 NMSA 1978 as amended, unless the municipality specifically approves	No	(Y/N)
7	Within 300 feet of a wetland	3,374	feet
8	Within the area overlying a subsurface mine	No	(Y/N)
9	Within an unstable area (Karst Map)	Low	Critical High Medium Low
10	Within a 100-year Floodplain	N/A	year
11	Soil Type	Fine Sand, Fine Sandy Loam, Sandy Clay Loam	
12	Ecological Classification	Loamy Sand	
13	Geology	Qep	
NMAC 19.15.29.12 E (Table 1) Closure Criteria		<50'	<50' 51-100' >100'

USGS Well Distance

2.40 miles

Legend

- 323010103244001
- 📌 Billiken 6 CTB 1 - liner inspection

Billiken 6 CTB 1 - liner inspection

323010103244001

Google Earth




1 mi

NMOSE Well Distance

2.57 Miles (13,556 Feet)

Legend

1





New Mexico Office of the State Engineer

Point of Diversion Summary

		(quarters are 1=NW 2=NE 3=SW 4=SE)						(NAD83 UTM in meters)	
		(quarters are smallest to largest)						X	Y
Well Tag	POD Number	Q64	Q16	Q4	Sec	Tw	Rng		
	C 02299	4	2	4	24	25S	34E	649517	3554125
<hr/>									
Driller License: 122		Driller Company: UNKNOWN							
Driller Name: UNKNOWN									
Drill Start Date:		Drill Finish Date:				12/31/1949			
Log File Date:		PCW Rev Date:				Source:			
Pump Type:		Pipe Discharge Size:				Estimated Yield: 3 GPM			
Casing Size: 8.00		Depth Well:				Depth Water: 300 feet			

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

1/27/22 6:55 AM

POINT OF DIVERSION SUMMARY



New Mexico Office of the State Engineer

Water Right Summary



WR File Number: C 02299 **Subbasin:** CUB **Cross Reference:** -
Primary Purpose: PLS NON 72-12-1 LIVESTOCK WATERING
Primary Status: DCL DECLARATION
Total Acres: 0 **Subfile:** - **Header:** -
Total Diversion: 3 **Cause/Case:** -
Owner: INTREPID POTASH NEW MEXICO LLC
Contact: KATIE KELLER

Documents on File

Trn #	Doc	File/Act	Status			Transaction Desc.	From/		Acres	Diversion	Consumptive
			1	2			To				
get images	673682	UWL 2020-05-15	UWL	ACC		C 02299	T		0	0	
get images	652933	COWNF 2019-06-11	CHG	PRC		C 02299	T		0	0	
get images	648796	COWNF 2019-03-20	CHG	PRC		C 02299	T		0	0	
get images	198392	DCL 1993-02-02	DCL	PRC		C-02299	T		0	3	

Current Points of Diversion

POD Number	Well Tag	Source	Q				(NAD83 UTM in meters)			Other Location Desc
			64	Q16	Q4	Sec Tw	X	Y		
C 02299			4	2	4	24 25S 34E	649517	3554125		

Priority Summary

Priority	Status	Acres	Diversion	Pod Number
12/31/1949	DCL	0	3	C 02299

Place of Use

Q Q		Acres	Diversion	CU	Use	Priority	Status	Other Location Desc
256	64 Q16 Q4							
		0	3		PLS	12/31/1949	DCL	NO PLACE OF USE GIVEN

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.


1/27/22 6:55 AM

WATER RIGHT
SUMMARY

NMOSE Well Distance

3.57 miles

Legend



Google Earth

1 mi



New Mexico Office of the State Engineer

Point of Diversion Summary

(quarters are 1=NW 2=NE 3=SW 4=SE)

(quarters are smallest to largest)

(NAD83 UTM in meters)

Well Tag	POD Number	Q64 Q16 Q4 Sec Tws Rng	X	Y
	CP 01305 POD1	1 4 31 25S 37E	655628	3551065

x

Driller License: 1706 **Driller Company:** ELITE DRILLERS CORPORATION

Driller Name: WALLACE, BRYCE J.

Drill Start Date: 05/04/2017	Drill Finish Date: 05/06/2017	Plug Date:
Log File Date: 07/07/2017	PCW Rev Date:	Source: Artesian
Pump Type:	Pipe Discharge Size:	Estimated Yield: 60 GPM
Casing Size: 6.00	Depth Well: 420 feet	Depth Water: 230 feet

x

Water Bearing Stratifications:	Top	Bottom	Description
	280	320	Sandstone/Gravel/Conglomerate
	330	400	Sandstone/Gravel/Conglomerate
	400	420	Shale/Mudstone/Siltstone

x

Casing Perforations:	Top	Bottom
	320	420

x

Meter Number: 19203	Meter Make: TURBINES
Meter Serial Number: 7678015	Meter Multiplier: 1.0000
Number of Dials: 9	Meter Type: Diversion
Unit of Measure: Barrels 42 gal.	Return Flow Percent:
Usage Multiplier:	Reading Frequency: Monthly

x

Meter Readings (in Acre-Feet)

Read Date	Year	Mtr Reading	Flag	Rdr Comment	Mtr Amount Online
03/31/2021	2021	141799	A	RPT Initial reading submitted	0
05/31/2021	2021	1470544	A	ad	171.266
10/31/2021	2021	1610094	A	ad	17.987

x

**YTD Meter Amounts:	Year	Amount
	2021	189.253

x

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

1/27/22 6:55 AM

POINT OF DIVERSION SUMMARY



New Mexico Office of the State Engineer

Water Right Summary


[get image list](#)

WR File Number: CP 01305 **Subbasin:** CP **Cross Reference:** -
Primary Purpose: COM COMMERCIAL
Primary Status: PMT PERMIT
Total Acres: 0 **Subfile:** - **Header:** -
Total Diversion: 100 **Cause/Case:** -
Owner: FULFER OIL & CATTLE COMPANY
Contact: GREGG FULFER
Owner: ATKINS ENGR ASSOC INC
Contact: RICHARD CIBAK

Documents on File


[get images](#)

Trn #	Doc	File/Act	Status		Transaction Desc.	From/	Acres	Diversion	Consumptive
			1	2		To			
604490	APPRO	2016-01-21	PMT	MTR	CP 01305	T	0	100	100

Current Points of Diversion

(NAD83 UTM in meters)

POD Number	Well Tag	Source	Q	64Q16Q4Sec	Tw	Rng	X	Y	Other Location Desc
CP 01305 POD1		Artesian	1	4	31	25S 37E	655628	3551065	

Priority Summary

Priority	Status	Acres	Diversion	Pod Number	
03/27/2014	PMT	0	100	CP 01305 POD1	Artesian

Place of Use

Q	Q	256	64	Q16	Q4Sec	Tw	Rng	Acres	Diversion	CU	Use	Priority	Status	Other Location Desc
								0	100	100	COM	03/27/2014	PMT	NO PLACE OF USE GIVEN


Source

Acres	Diversion	CU	Use	Priority	Source Description
0	100	100	COM	03/27/2014	GW

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

1/27/22 6:55 AM

 WATER RIGHT
SUMMARY



Nearest Continuously Flowing Watercourse



January 20, 2022


Wetlands

- Estuarine and Marine Deepwater
- Estuarine and Marine Wetland


- Freshwater Emergent Wetland
- Freshwater Forested/Shrub Wetland
- Freshwater Pond

- Lake
- Other
- Riverine

This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.



Lake 14 Miles (74,079 Feet)



January 20, 2022

Wetlands

- Estuarine and Marine Deepwater
- Estuarine and Marine Wetland

- Freshwater Emergent Wetland
- Freshwater Forested/Shrub Wetland
- Freshwater Pond

- Lake
- Other
- Riverine

This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.

Nearest Residence

8.89 Miles (46,941 Feet)

Legend

 1

Billiken 6 CTB 1

Resident


3

Google Earth

TEXAS



7 km



Emergent Wetland 0.64 Miles (3,374 Feet)



January 20, 2022

Wetlands


- Estuarine and Marine Deepwater
- Estuarine and Marine Wetland

- Freshwater Emergent Wetland
- Freshwater Forested/Shrub Wetland
- Freshwater Pond



- Lake
- Other
- Riverine

This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.

Active Mines in New Mexico




1/20/2022, 10:48:08 AM



U.S. Bureau of Land Management - New Mexico State Office, Sources:
Esri, USGS, NOAA, Sources: Esri, Garmin, USGS, NPS

EMNRD MMD GIS Coordinator

Document Path: G:\Projects\US PROJECTS\Devon Energy Corporation\21E-00580\009 - Billiken 6 CTB 1\Figure x Karst Potential Map Billiken 6 CTB 1 (21E-00580).mxd



Karst Potential

- Critical
- High
- Medium
- Low

Site Location

Site Buffer (1,000 ft.)

Overview Map

0 0.25 0.5 1 mi



Detail Map

0 150 300 600 ft.



Map Center:
Lat/Long: 32.077000, -103.411171

NAD 1983 UTM Zone 13N
Date: Jan 20/22



Karst Potential Map
Billiken 6 CTB 1

FIGURE:

X



Geospatial data presented in this figure may be derived from external sources and Vertex does not assume any liability for inaccuracies. This figure is intended for reference use only and is not certified for legal, survey, or engineering purposes.

Note: Inset Map, ESRI 2021; Overview Map: ESRI World Topographic

VERSATILITY. EXPERTISE.

National Flood Hazard Layer FIRMMette



103°24'59"W 32°4'51"N



Legend

SEE FIS REPORT FOR DETAILED LEGEND AND INDEX MAP FOR FIRM PANEL LAYOUT

SPECIAL FLOOD HAZARD AREAS		Without Base Flood Elevation (BFE) Zone A, V, A99
		With BFE or Depth Zone AE, AO, AH, VE, AR
		Regulatory Floodway
OTHER AREAS OF FLOOD HAZARD		0.2% Annual Chance Flood Hazard, Areas of 1% annual chance flood with average depth less than one foot or with drainage areas of less than one square mile Zone X
		Future Conditions 1% Annual Chance Flood Hazard Zone X
		Area with Reduced Flood Risk due to Levee. See Notes. Zone X
		Area with Flood Risk due to Levee Zone D
		NO SCREEN Area of Minimal Flood Hazard Zone X
OTHER AREAS		Effective LOMRs
		Area of Undetermined Flood Hazard Zone D
GENERAL STRUCTURES		Channel, Culvert, or Storm Sewer
		Levee, Dike, or Floodwall
OTHER FEATURES		20.2 Cross Sections with 1% Annual Chance Water Surface Elevation
		17.5 Cross Sections with 1% Annual Chance Water Surface Elevation
		Coastal Transect
		Base Flood Elevation Line (BFE)
		Limit of Study
		Jurisdiction Boundary
		Coastal Transect Baseline
		Profile Baseline
MAP PANELS		Digital Data Available
		No Digital Data Available
		Unmapped



The pin displayed on the map is an approximate point selected by the user and does not represent an authoritative property location.

This map complies with FEMA's standards for the use of digital flood maps if it is not void as described below. The basemap shown complies with FEMA's basemap accuracy standards

The flood hazard information is derived directly from the authoritative NFHL web services provided by FEMA. This map was exported on 1/20/2022 at 12:55 PM and does not reflect changes or amendments subsequent to this date and time. The NFHL and effective information may change or become superseded by new data over time.

This map image is void if the one or more of the following map elements do not appear: basemap imagery, flood zone labels, legend, scale bar, map creation date, community identifiers, FIRM panel number, and FIRM effective date. Map images for unmapped and unmodernized areas cannot be used for regulatory purposes.



United States
Department of
Agriculture

NRCS

Natural
Resources
Conservation
Service

A product of the National
Cooperative Soil Survey,
a joint effort of the United
States Department of
Agriculture and other
Federal agencies, State
agencies including the
Agricultural Experiment
Stations, and local
participants

Custom Soil Resource Report for **Lea County, New Mexico**



January 20, 2022

Preface

Soil surveys contain information that affects land use planning in survey areas. They highlight soil limitations that affect various land uses and provide information about the properties of the soils in the survey areas. Soil surveys are designed for many different users, including farmers, ranchers, foresters, agronomists, urban planners, community officials, engineers, developers, builders, and home buyers. Also, conservationists, teachers, students, and specialists in recreation, waste disposal, and pollution control can use the surveys to help them understand, protect, or enhance the environment.

Various land use regulations of Federal, State, and local governments may impose special restrictions on land use or land treatment. Soil surveys identify soil properties that are used in making various land use or land treatment decisions. The information is intended to help the land users identify and reduce the effects of soil limitations on various land uses. The landowner or user is responsible for identifying and complying with existing laws and regulations.

Although soil survey information can be used for general farm, local, and wider area planning, onsite investigation is needed to supplement this information in some cases. Examples include soil quality assessments (<http://www.nrcs.usda.gov/wps/portal/nrcs/main/soils/health/>) and certain conservation and engineering applications. For more detailed information, contact your local USDA Service Center (<https://offices.sc.egov.usda.gov/locator/app?agency=nrcs>) or your NRCS State Soil Scientist (http://www.nrcs.usda.gov/wps/portal/nrcs/detail/soils/contactus/?cid=nrcs142p2_053951).

Great differences in soil properties can occur within short distances. Some soils are seasonally wet or subject to flooding. Some are too unstable to be used as a foundation for buildings or roads. Clayey or wet soils are poorly suited to use as septic tank absorption fields. A high water table makes a soil poorly suited to basements or underground installations.

The National Cooperative Soil Survey is a joint effort of the United States Department of Agriculture and other Federal agencies, State agencies including the Agricultural Experiment Stations, and local agencies. The Natural Resources Conservation Service (NRCS) has leadership for the Federal part of the National Cooperative Soil Survey.

Information about soils is updated periodically. Updated information is available through the NRCS Web Soil Survey, the site for official soil survey information.

The U.S. Department of Agriculture (USDA) prohibits discrimination in all its programs and activities on the basis of race, color, national origin, age, disability, and where applicable, sex, marital status, familial status, parental status, religion, sexual orientation, genetic information, political beliefs, reprisal, or because all or a part of an individual's income is derived from any public assistance program. (Not all prohibited bases apply to all programs.) Persons with disabilities who require

alternative means for communication of program information (Braille, large print, audiotape, etc.) should contact USDA's TARGET Center at (202) 720-2600 (voice and TDD). To file a complaint of discrimination, write to USDA, Director, Office of Civil Rights, 1400 Independence Avenue, S.W., Washington, D.C. 20250-9410 or call (800) 795-3272 (voice) or (202) 720-6382 (TDD). USDA is an equal opportunity provider and employer.

Contents

Preface..... 2

How Soil Surveys Are Made.....5

Soil Map..... 8

 Soil Map.....9

 Legend.....10

 Map Unit Legend..... 11

 Map Unit Descriptions.....11

 Lea County, New Mexico..... 13

 PU—Pyote and Maljamar fine sands..... 13

 PY—Pyote soils and Dune land..... 14

References..... 17

How Soil Surveys Are Made

Soil surveys are made to provide information about the soils and miscellaneous areas in a specific area. They include a description of the soils and miscellaneous areas and their location on the landscape and tables that show soil properties and limitations affecting various uses. Soil scientists observed the steepness, length, and shape of the slopes; the general pattern of drainage; the kinds of crops and native plants; and the kinds of bedrock. They observed and described many soil profiles. A soil profile is the sequence of natural layers, or horizons, in a soil. The profile extends from the surface down into the unconsolidated material in which the soil formed or from the surface down to bedrock. The unconsolidated material is devoid of roots and other living organisms and has not been changed by other biological activity.

Currently, soils are mapped according to the boundaries of major land resource areas (MLRAs). MLRAs are geographically associated land resource units that share common characteristics related to physiography, geology, climate, water resources, soils, biological resources, and land uses (USDA, 2006). Soil survey areas typically consist of parts of one or more MLRA.

The soils and miscellaneous areas in a survey area occur in an orderly pattern that is related to the geology, landforms, relief, climate, and natural vegetation of the area. Each kind of soil and miscellaneous area is associated with a particular kind of landform or with a segment of the landform. By observing the soils and miscellaneous areas in the survey area and relating their position to specific segments of the landform, a soil scientist develops a concept, or model, of how they were formed. Thus, during mapping, this model enables the soil scientist to predict with a considerable degree of accuracy the kind of soil or miscellaneous area at a specific location on the landscape.

Commonly, individual soils on the landscape merge into one another as their characteristics gradually change. To construct an accurate soil map, however, soil scientists must determine the boundaries between the soils. They can observe only a limited number of soil profiles. Nevertheless, these observations, supplemented by an understanding of the soil-vegetation-landscape relationship, are sufficient to verify predictions of the kinds of soil in an area and to determine the boundaries.

Soil scientists recorded the characteristics of the soil profiles that they studied. They noted soil color, texture, size and shape of soil aggregates, kind and amount of rock fragments, distribution of plant roots, reaction, and other features that enable them to identify soils. After describing the soils in the survey area and determining their properties, the soil scientists assigned the soils to taxonomic classes (units). Taxonomic classes are concepts. Each taxonomic class has a set of soil characteristics with precisely defined limits. The classes are used as a basis for comparison to classify soils systematically. Soil taxonomy, the system of taxonomic classification used in the United States, is based mainly on the kind and character of soil properties and the arrangement of horizons within the profile. After the soil

Custom Soil Resource Report

scientists classified and named the soils in the survey area, they compared the individual soils with similar soils in the same taxonomic class in other areas so that they could confirm data and assemble additional data based on experience and research.

The objective of soil mapping is not to delineate pure map unit components; the objective is to separate the landscape into landforms or landform segments that have similar use and management requirements. Each map unit is defined by a unique combination of soil components and/or miscellaneous areas in predictable proportions. Some components may be highly contrasting to the other components of the map unit. The presence of minor components in a map unit in no way diminishes the usefulness or accuracy of the data. The delineation of such landforms and landform segments on the map provides sufficient information for the development of resource plans. If intensive use of small areas is planned, onsite investigation is needed to define and locate the soils and miscellaneous areas.

Soil scientists make many field observations in the process of producing a soil map. The frequency of observation is dependent upon several factors, including scale of mapping, intensity of mapping, design of map units, complexity of the landscape, and experience of the soil scientist. Observations are made to test and refine the soil-landscape model and predictions and to verify the classification of the soils at specific locations. Once the soil-landscape model is refined, a significantly smaller number of measurements of individual soil properties are made and recorded. These measurements may include field measurements, such as those for color, depth to bedrock, and texture, and laboratory measurements, such as those for content of sand, silt, clay, salt, and other components. Properties of each soil typically vary from one point to another across the landscape.

Observations for map unit components are aggregated to develop ranges of characteristics for the components. The aggregated values are presented. Direct measurements do not exist for every property presented for every map unit component. Values for some properties are estimated from combinations of other properties.

While a soil survey is in progress, samples of some of the soils in the area generally are collected for laboratory analyses and for engineering tests. Soil scientists interpret the data from these analyses and tests as well as the field-observed characteristics and the soil properties to determine the expected behavior of the soils under different uses. Interpretations for all of the soils are field tested through observation of the soils in different uses and under different levels of management. Some interpretations are modified to fit local conditions, and some new interpretations are developed to meet local needs. Data are assembled from other sources, such as research information, production records, and field experience of specialists. For example, data on crop yields under defined levels of management are assembled from farm records and from field or plot experiments on the same kinds of soil.

Predictions about soil behavior are based not only on soil properties but also on such variables as climate and biological activity. Soil conditions are predictable over long periods of time, but they are not predictable from year to year. For example, soil scientists can predict with a fairly high degree of accuracy that a given soil will have a high water table within certain depths in most years, but they cannot predict that a high water table will always be at a specific level in the soil on a specific date.


After soil scientists located and identified the significant natural bodies of soil in the survey area, they drew the boundaries of these bodies on aerial photographs and

Custom Soil Resource Report

identified each as a specific map unit. Aerial photographs show trees, buildings, fields, roads, and rivers, all of which help in locating boundaries accurately.

Soil Map


The soil map section includes the soil map for the defined area of interest, a list of soil map units on the map and extent of each map unit, and cartographic symbols displayed on the map. Also presented are various metadata about data used to produce the map, and a description of each soil map unit.

Custom Soil Resource Report
Soil Map

Custom Soil Resource Report

MAP LEGEND

Area of Interest (AOI)

 Area of Interest (AOI)

Soils

 Soil Map Unit Polygons

 Soil Map Unit Lines

 Soil Map Unit Points

Special Point Features

 Blowout

 Borrow Pit

 Clay Spot

 Closed Depression

 Gravel Pit

 Gravelly Spot

 Landfill

 Lava Flow

 Marsh or swamp

 Mine or Quarry

 Miscellaneous Water


 Perennial Water

 Rock Outcrop


 Saline Spot

 Sandy Spot

 Severely Eroded Spot


 Sinkhole

 Slide or Slip


 Sodic Spot

 Spoil Area

 Stony Spot


 Very Stony Spot

 Wet Spot

 Other

 Special Line Features

Water Features

 Streams and Canals

Transportation

 Rails


 Interstate Highways

 US Routes

 Major Roads

 Local Roads

Background

 Aerial Photography

MAP INFORMATION

The soil surveys that comprise your AOI were mapped at 1:20,000.

Warning: Soil Map may not be valid at this scale.

Enlargement of maps beyond the scale of mapping can cause misunderstanding of the detail of mapping and accuracy of soil line placement. The maps do not show the small areas of contrasting soils that could have been shown at a more detailed scale.

Please rely on the bar scale on each map sheet for map measurements.

Source of Map: Natural Resources Conservation Service
Web Soil Survey URL:
Coordinate System: Web Mercator (EPSG:3857)

Maps from the Web Soil Survey are based on the Web Mercator projection, which preserves direction and shape but distorts distance and area. A projection that preserves area, such as the Albers equal-area conic projection, should be used if more accurate calculations of distance or area are required.

This product is generated from the USDA-NRCS certified data as of the version date(s) listed below.

Soil Survey Area: Lea County, New Mexico
Survey Area Data: Version 18, Sep 10, 2021

Soil map units are labeled (as space allows) for map scales 1:50,000 or larger.

Date(s) aerial images were photographed: Feb 7, 2020—May 12, 2020

The orthophoto or other base map on which the soil lines were compiled and digitized probably differs from the background imagery displayed on these maps. As a result, some minor shifting of map unit boundaries may be evident.

Custom Soil Resource Report

Map Unit Legend

Map Unit Symbol	Map Unit Name	Acres in AOI	Percent of AOI
PU	Pyote and Maljamar fine sands	61.5	96.1%
PY	Pyote soils and Dune land	2.5	3.9%
Totals for Area of Interest		64.0	100.0%

Map Unit Descriptions

The map units delineated on the detailed soil maps in a soil survey represent the soils or miscellaneous areas in the survey area. The map unit descriptions, along with the maps, can be used to determine the composition and properties of a unit.

A map unit delineation on a soil map represents an area dominated by one or more major kinds of soil or miscellaneous areas. A map unit is identified and named according to the taxonomic classification of the dominant soils. Within a taxonomic class there are precisely defined limits for the properties of the soils. On the landscape, however, the soils are natural phenomena, and they have the characteristic variability of all natural phenomena. Thus, the range of some observed properties may extend beyond the limits defined for a taxonomic class. Areas of soils of a single taxonomic class rarely, if ever, can be mapped without including areas of other taxonomic classes. Consequently, every map unit is made up of the soils or miscellaneous areas for which it is named and some minor components that belong to taxonomic classes other than those of the major soils.

Most minor soils have properties similar to those of the dominant soil or soils in the map unit, and thus they do not affect use and management. These are called noncontrasting, or similar, components. They may or may not be mentioned in a particular map unit description. Other minor components, however, have properties and behavioral characteristics divergent enough to affect use or to require different management. These are called contrasting, or dissimilar, components. They generally are in small areas and could not be mapped separately because of the scale used. Some small areas of strongly contrasting soils or miscellaneous areas are identified by a special symbol on the maps. If included in the database for a given area, the contrasting minor components are identified in the map unit descriptions along with some characteristics of each. A few areas of minor components may not have been observed, and consequently they are not mentioned in the descriptions, especially where the pattern was so complex that it was impractical to make enough observations to identify all the soils and miscellaneous areas on the landscape.

The presence of minor components in a map unit in no way diminishes the usefulness or accuracy of the data. The objective of mapping is not to delineate pure taxonomic classes but rather to separate the landscape into landforms or landform segments that have similar use and management requirements. The delineation of such segments on the map provides sufficient information for the development of resource plans. If intensive use of small areas is planned, however,

Custom Soil Resource Report

onsite investigation is needed to define and locate the soils and miscellaneous areas.

An identifying symbol precedes the map unit name in the map unit descriptions. Each description includes general facts about the unit and gives important soil properties and qualities.

Soils that have profiles that are almost alike make up a *soil series*. Except for differences in texture of the surface layer, all the soils of a series have major horizons that are similar in composition, thickness, and arrangement.

Soils of one series can differ in texture of the surface layer, slope, stoniness, salinity, degree of erosion, and other characteristics that affect their use. On the basis of such differences, a soil series is divided into *soil phases*. Most of the areas shown on the detailed soil maps are phases of soil series. The name of a soil phase commonly indicates a feature that affects use or management. For example, Alpha silt loam, 0 to 2 percent slopes, is a phase of the Alpha series.

Some map units are made up of two or more major soils or miscellaneous areas. These map units are complexes, associations, or undifferentiated groups.

A *complex* consists of two or more soils or miscellaneous areas in such an intricate pattern or in such small areas that they cannot be shown separately on the maps. The pattern and proportion of the soils or miscellaneous areas are somewhat similar in all areas. Alpha-Beta complex, 0 to 6 percent slopes, is an example.

An *association* is made up of two or more geographically associated soils or miscellaneous areas that are shown as one unit on the maps. Because of present or anticipated uses of the map units in the survey area, it was not considered practical or necessary to map the soils or miscellaneous areas separately. The pattern and relative proportion of the soils or miscellaneous areas are somewhat similar. Alpha-Beta association, 0 to 2 percent slopes, is an example.

An *undifferentiated group* is made up of two or more soils or miscellaneous areas that could be mapped individually but are mapped as one unit because similar interpretations can be made for use and management. The pattern and proportion of the soils or miscellaneous areas in a mapped area are not uniform. An area can be made up of only one of the major soils or miscellaneous areas, or it can be made up of all of them. Alpha and Beta soils, 0 to 2 percent slopes, is an example.

Some surveys include *miscellaneous areas*. Such areas have little or no soil material and support little or no vegetation. Rock outcrop is an example.

Custom Soil Resource Report

Lea County, New Mexico

PU—Pyote and Maljamar fine sands

Map Unit Setting

National map unit symbol: dmqq
Elevation: 3,000 to 3,900 feet
Mean annual precipitation: 10 to 12 inches
Mean annual air temperature: 60 to 62 degrees F
Frost-free period: 190 to 205 days
Farmland classification: Not prime farmland

Map Unit Composition

Pyote and similar soils: 46 percent
Maljamar and similar soils: 44 percent
Minor components: 10 percent
Estimates are based on observations, descriptions, and transects of the mapunit.

Description of Pyote

Setting

Landform: Plains
Landform position (three-dimensional): Rise
Down-slope shape: Linear
Across-slope shape: Linear
Parent material: Sandy eolian deposits derived from sedimentary rock

Typical profile

A - 0 to 30 inches: fine sand
Bt - 30 to 60 inches: fine sandy loam

Properties and qualities

Slope: 0 to 3 percent
Depth to restrictive feature: More than 80 inches
Drainage class: Well drained
Runoff class: Negligible
Capacity of the most limiting layer to transmit water (Ksat): High (2.00 to 6.00 in/hr)
Depth to water table: More than 80 inches
Frequency of flooding: None
Frequency of ponding: None
Calcium carbonate, maximum content: 5 percent
Gypsum, maximum content: 1 percent
Maximum salinity: Nonsaline to very slightly saline (0.0 to 2.0 mmhos/cm)
Sodium adsorption ratio, maximum: 2.0
Available water supply, 0 to 60 inches: Low (about 5.1 inches)

Interpretive groups

Land capability classification (irrigated): 6e
Land capability classification (nonirrigated): 7s
Hydrologic Soil Group: A
Ecological site: R042XC003NM - Loamy Sand
Hydric soil rating: No

Custom Soil Resource Report

Description of Maljamar**Setting***Landform: Plains**Landform position (three-dimensional): Rise**Down-slope shape: Linear**Across-slope shape: Linear**Parent material: Sandy eolian deposits derived from sedimentary rock***Typical profile***A - 0 to 24 inches: fine sand**Bt - 24 to 50 inches: sandy clay loam**Bkm - 50 to 60 inches: cemented material***Properties and qualities***Slope: 0 to 3 percent**Depth to restrictive feature: 40 to 60 inches to petrocalcic**Drainage class: Well drained**Runoff class: Very low**Capacity of the most limiting layer to transmit water (Ksat): Very low to moderately low (0.00 to 0.06 in/hr)**Depth to water table: More than 80 inches**Frequency of flooding: None**Frequency of ponding: None**Calcium carbonate, maximum content: 5 percent**Gypsum, maximum content: 1 percent**Maximum salinity: Nonsaline to very slightly saline (0.0 to 2.0 mmhos/cm)**Sodium adsorption ratio, maximum: 2.0**Available water supply, 0 to 60 inches: Low (about 5.6 inches)***Interpretive groups***Land capability classification (irrigated): 6e**Land capability classification (nonirrigated): 7e**Hydrologic Soil Group: B**Ecological site: R042XC003NM - Loamy Sand**Hydric soil rating: No***Minor Components****Kermit***Percent of map unit: 10 percent**Ecological site: R042XC022NM - Sandhills**Hydric soil rating: No***PY—Pyote soils and Dune land****Map Unit Setting***National map unit symbol: dmqr**Elevation: 3,000 to 4,400 feet*

Custom Soil Resource Report

Mean annual precipitation: 10 to 15 inches
Mean annual air temperature: 60 to 64 degrees F
Frost-free period: 190 to 220 days
Farmland classification: Not prime farmland

Map Unit Composition

Pyote and similar soils: 46 percent
Dune land: 44 percent
Minor components: 10 percent
Estimates are based on observations, descriptions, and transects of the mapunit.

Description of Pyote**Setting**

Landform: Depressions
Landform position (two-dimensional): Footslope
Landform position (three-dimensional): Base slope
Down-slope shape: Concave
Across-slope shape: Concave
Parent material: Sandy eolian deposits derived from sedimentary rock

Typical profile

A - 0 to 30 inches: fine sand
Bt - 30 to 60 inches: fine sandy loam

Properties and qualities

Slope: 0 to 3 percent
Depth to restrictive feature: More than 80 inches
Drainage class: Well drained
Runoff class: Negligible
Capacity of the most limiting layer to transmit water (Ksat): High (2.00 to 6.00 in/hr)
Depth to water table: More than 80 inches
Frequency of flooding: None
Frequency of ponding: None
Calcium carbonate, maximum content: 5 percent
Gypsum, maximum content: 1 percent
Maximum salinity: Nonsaline to very slightly saline (0.0 to 2.0 mmhos/cm)
Sodium adsorption ratio, maximum: 2.0
Available water supply, 0 to 60 inches: Low (about 5.1 inches)

Interpretive groups

Land capability classification (irrigated): 6e
Land capability classification (nonirrigated): 7s
Hydrologic Soil Group: A
Ecological site: R042XC003NM - Loamy Sand
Hydric soil rating: No

Description of Dune Land**Setting**

Landform: Dunes
Landform position (two-dimensional): Backslope, shoulder
Landform position (three-dimensional): Side slope
Down-slope shape: Convex, linear
Across-slope shape: Convex
Parent material: Sandy eolian deposits derived from sedimentary rock

Custom Soil Resource Report

Typical profile

A - 0 to 6 inches: fine sand
C - 6 to 60 inches: fine sand

Interpretive groups

Land capability classification (irrigated): None specified
Land capability classification (nonirrigated): 8
Hydrologic Soil Group: A
Hydric soil rating: No

Minor Components

Kermit

Percent of map unit: 5 percent
Ecological site: R042XC022NM - Sandhills
Hydric soil rating: No

Maljamar, fine sand

Percent of map unit: 3 percent
Ecological site: R042XC003NM - Loamy Sand
Hydric soil rating: No

Wink

Percent of map unit: 2 percent
Ecological site: R042XC003NM - Loamy Sand
Hydric soil rating: No

References

- American Association of State Highway and Transportation Officials (AASHTO). 2004. Standard specifications for transportation materials and methods of sampling and testing. 24th edition.
- American Society for Testing and Materials (ASTM). 2005. Standard classification of soils for engineering purposes. ASTM Standard D2487-00.
- Cowardin, L.M., V. Carter, F.C. Golet, and E.T. LaRoe. 1979. Classification of wetlands and deep-water habitats of the United States. U.S. Fish and Wildlife Service FWS/OBS-79/31.
- Federal Register. July 13, 1994. Changes in hydric soils of the United States.
- Federal Register. September 18, 2002. Hydric soils of the United States.
- Hurt, G.W., and L.M. Vasilas, editors. Version 6.0, 2006. Field indicators of hydric soils in the United States.
- National Research Council. 1995. Wetlands: Characteristics and boundaries.
- Soil Survey Division Staff. 1993. Soil survey manual. Soil Conservation Service. U.S. Department of Agriculture Handbook 18. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2_054262
- Soil Survey Staff. 1999. Soil taxonomy: A basic system of soil classification for making and interpreting soil surveys. 2nd edition. Natural Resources Conservation Service, U.S. Department of Agriculture Handbook 436. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2_053577
- Soil Survey Staff. 2010. Keys to soil taxonomy. 11th edition. U.S. Department of Agriculture, Natural Resources Conservation Service. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2_053580
- Tiner, R.W., Jr. 1985. Wetlands of Delaware. U.S. Fish and Wildlife Service and Delaware Department of Natural Resources and Environmental Control, Wetlands Section.
- United States Army Corps of Engineers, Environmental Laboratory. 1987. Corps of Engineers wetlands delineation manual. Waterways Experiment Station Technical Report Y-87-1.
- United States Department of Agriculture, Natural Resources Conservation Service. National forestry manual. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/soils/home/?cid=nrcs142p2_053374
- United States Department of Agriculture, Natural Resources Conservation Service. National range and pasture handbook. <http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/landuse/rangepasture/?cid=stelpdb1043084>

Custom Soil Resource Report

United States Department of Agriculture, Natural Resources Conservation Service. National soil survey handbook, title 430-VI. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/soils/scientists/?cid=nrcs142p2_054242

United States Department of Agriculture, Natural Resources Conservation Service. 2006. Land resource regions and major land resource areas of the United States, the Caribbean, and the Pacific Basin. U.S. Department of Agriculture Handbook 296. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2_053624

United States Department of Agriculture, Soil Conservation Service. 1961. Land capability classification. U.S. Department of Agriculture Handbook 210. http://www.nrcs.usda.gov/Internet/FSE_DOCUMENTS/nrcs142p2_052290.pdf

Ecological site R042XC004NM Sandy

Accessed: 01/20/2022

General information




Figure 1. Mapped extent

Areas shown in blue indicate the maximum mapped extent of this ecological site. Other ecological sites likely occur within the highlighted areas. It is also possible for this ecological site to occur outside of highlighted areas if detailed soil survey has not been completed or recently updated.

Table 1. Dominant plant species

Tree	Not specified
Shrub	Not specified
Herbaceous	Not specified

Physiographic features

This site is on uplands, plains, dunes, fan piedmonts, terraces and in inter dunal areas. The parent material consists of mixed alluvium and or eolian sands or calcareous alluvium derived from sedimentary rock. Slope range on this site range from 0 to 9 percent with the average of 5 percent.

Low stabilized dunes may occur occasionally on this site. Elevations range from 2,800 to 5,000 feet.

Table 2. Representative physiographic features

Landforms	(1) Plain (2) Fan piedmont (3) Terrace
Flooding frequency	None
Ponding frequency	None
Elevation	2,842–4,500 ft

Slope	0–5%
Aspect	Aspect is not a significant factor

Climatic features

The average annual precipitation ranges from 8 to 13 inches. Variations of 5 inches, more or less, are common. Over 80 percent of the precipitation falls from April through October. Most of the summer precipitation comes in the form of high intensity short duration thunderstorms.

Temperatures are characterized by distinct seasonal changes and large annual and diurnal temperature changes. The average annual temperature is 61 degrees with extremes of 25 degrees below zero in the winter to 112 degrees in the summer.

The average frost-free season is 207 to 220 days. The last killing frost is in late March or early April, and the first killing frost is in late October or early November.

Temperature and rainfall both favor warm season perennial plant growth. In years of abundant spring moisture, annual forbs and cool season grasses can make up an important component of this site. Strong winds blow from the southwest in January through June which rapidly dries out the soil during a critical period for cool season plant growth.

Climate data was obtained from <http://www.wrcc.sage.dri.edu/summary/climsmnm.html> web site using 50% probability for freeze-free and frost-free seasons using 28.5 degrees F and 32.5 degrees F respectively.

Table 3. Representative climatic features

Frost-free period (average)	200 days
Freeze-free period (average)	219 days
Precipitation total (average)	12 in

Influencing water features

This site is not influenced from water from wetlands or streams.

Soil features

Soils are moderately deep or very deep. Surface textures are loamy fine sand, fine sandy loam, loamy very fine sand or gravelly sandy loam.

Subsurface is a sandy loam, loam, sandy clay loam, clay loam (contains more than 45 percent sand and 18 to 35 percent clay) and less than 15 percent carbonates.

Substratum is a sandy loam, fine sandy loam, sandy clay loam, clay loam, coarse sandy loam, or coarse sand and Calcium carbonate equivalent of 15 to 40 percent. Some layers high in lime or with caliche fragments may occur at depths of 20 to 30 inches.

These soils, if unprotected by plant cover and organic residue, become wind blown and low hummocks are formed. They contains more than 45 percent sand and 18 to 35 percent clay.

Minimum and maximum values listed below represent the characteristic soils for this site.

Characteristic Soils Are:

Anthony
Berino
Cacique
Harkey
Pajaritio

Reakor
 Mobeetie
 Wink
 Sotim
 Vinton
 Drake
 Onite
 Alma
 Poquita
 Dona Ana
 Monahans

Note: *Cacique soils is a shallow soil.

Table 4. Representative soil features

Surface texture	(1) Fine sandy loam (2) Sandy loam (3) Loamy fine sand
Family particle size	(1) Loamy
Drainage class	Well drained to moderately well drained
Permeability class	Moderately rapid to moderately slow
Soil depth	30–72 in
Surface fragment cover ≤3"	0–20%
Surface fragment cover >3"	0%
Available water capacity (0–40in)	3–11 in
Calcium carbonate equivalent (0–40in)	5–30%
Electrical conductivity (0–40in)	0–2 mmhos/cm
Sodium adsorption ratio (0–40in)	0–1
Soil reaction (1:1 water) (0–40in)	6.6–8.4
Subsurface fragment volume ≤3" (Depth not specified)	0–15%
Subsurface fragment volume >3" (Depth not specified)	0%

Ecological dynamics

Overview

The Sandy site often intergrades with the Loamy Sand and Deep Sand sites (SD-3). Sandy sites occur on plains, fans, or terraces between drainages. Slopes average less than five percent. Surface textures are usually sandy loams. The historic plant community of the Sandy site is dominated by black grama (*Bouteloua eriopoda*) and dropseeds (*Sporobolus flexuosus*, *S. contractus*, *S. cryptandrus*). Blue grama (*B. gracilis*) also occurs as a subdominant species. Perennial and annual forb abundance is distributed relative to precipitation occurrence. Litter and to a lesser extent, bare ground, compose a significant proportion of the ground cover while grasses compose the remainder. Decreases in black grama and other grass species' cover indicate a transition to states with an

increased shrub component. Shinnery oak (*Quercus havardii*), sand sage (*Artemisia filifolia*), and honey mesquite (*Prosopis glandulosa*) can all increase in composition. Lehmann lovegrass (*Eragrostis lehmanniana*) also may occur as a result of invasion and competition among grass species. Heavy grazing intensity and/or drought are influential in decreasing grass cover and subsequently increasing shrub cover. Fire suppression further supports shrub cover increase and an advantage over grass species. However, brush and grazing management may restore grass species and reverse shrub or grass/shrub dominated states back toward the historic plant community.

State and transition model

Plant Communities and Transitional Pathways (diagram)




Figure 6.

State 1**Historic Climax Plant Community****Community 1.1****Historic Climax Plant Community**

Grassland: The historic plant community is composed primarily of black grama, dropseeds, and a secondary component of blue grama. Black grama tends to dominate due to the predominance of sandy loam soils; however, dropseeds increase on more loamy soils. Perennial and annual forbs are common but their abundance and distribution are dependent on seasonal precipitation. Historical fire frequency is unknown but probably contributed to shrub reduction to the competitive advantage of grass species. Excessive grazing and drought are likely the dominant drivers that decrease black grama and increase dropseed and threeawn abundance within the historic plant community. Black grama has low seed viability, and therefore, reproduces vegetatively during the summer growing season. However, black grama growth is delayed one season after normal precipitation. Black grama is dormant for the remainder of the year; however, black grama retains nutritive value yearlong for grazing. In contrast, dropseeds have relatively abundant, viable seed production and can benefit from early spring as well as summer precipitation. Threeawns also respond to spring and summer moisture and tend to be the year's first palatable species. Threeawns and dropseeds, however, are not palatable during dormant periods, which extends grazing pressure to black grama. Moderate to heavy grazing reduces vegetative cover of black grama which increases its susceptibility to wind erosion and drought (Canfield 1939). Black grama is especially vulnerable to grazing during the summer growing season when stoloniferous growth and rooting occur. Black grama sustains short droughts through reduction of plant tufts which will subsequently emerge with sufficient moisture. Prolonged drought or grazing concurrently under drought conditions can delay or impede recovery of black grama (Nelson 1934) and increase abundance of dropseeds, threeawns, and blue grama. Historical fire events may have benefited black grama, especially, frequent, light intensity/severity fires in conjunction with sufficient moisture to increase stolon production (McPherson 1995). Fires which were hot and severe, however, probably contributed to black grama mortality, more so in drought conditions.

Diagnosis: This state is a grassland dominated by black grama, dropseeds, and threeawns, with subdominant blue grama. Shrubs, such as sand sage and mesquite, are sparsely dispersed throughout the grassland. Forb populations are present and fluctuate with precipitation variability.

Other grasses that could appear on this site include: fall withchgrass, slim tridens, Almejita signalgrass, Indian ricegrass and fluffgrass.

Other shrubs include: pale wolfberry, lotebush, tarbush, Apacheplume, and mesquite.

Other forbs include: plains tickseed, plains blackfoot, scorpionweed, nama, wooly guara, wooly dalea, spectaclepod mustard, bladderpod mustard, menodora, prickly lettuce, lambsquarter, wooly Indianwheat and wild buckwheat.

Table 5. Annual production by plant type

Plant Type	Low (Lb/Acre)	Representative Value (Lb/Acre)	High (Lb/Acre)
Grass/Grasslike	480	720	960
Forb	90	135	180
Shrub/Vine	30	45	60
Total	600	900	1200

Table 6. Ground cover

Tree foliar cover	0%
Shrub/vine/liana foliar cover	0%
Grass/grasslike foliar cover	35-40%
Forb foliar cover	0%
Non-vascular plants	0%

Biological crusts	0%
Litter	35-45%
Surface fragments >0.25" and <=3"	0%
Surface fragments >3"	0%
Bedrock	0%
Water	0%
Bare ground	15-20%

Figure 8. Plant community growth curve (percent production by month). NM2804, R042XC004NM-Sandy-HCPC. SD-3 Sandy - Warm season plant community .

Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec
0	1	3	4	10	10	25	30	12	5	0	0

State 2 Shinnery Oak Dominated

Community 2.1 Shinnery Oak Dominated

Shinnery Oak Dominated: This state is dominated by Shinnery oak with subdominant grass species from the historic plant community. Bare ground is a significant component in this state. Shinnery oak tends to be clumped in distribution in finer soil textures. Shinnery oak density increases (as well as dropseeds, threeawns, and blue grama) in coarse textured (e.g., Loamy Sand sites) and deeper, coarse textured (e.g., Deep Sand and Sandhills sites) soils. Shinnery oak predominates during periods of above average (i.e., 16 in.) precipitation during the months of July and August. Abundance and distribution also increases with disturbance, such as excessive grazing and fire, due to an aggressive rhizome system. Shinnery oak's extensive root system allows competitive exclusion of grasses and forbs. Brush control with herbicide treatments applied in the spring can reduce Shinnery oak (Herbel et al. 1979, Pettit 1986). In addition, repetitive seasons of goat browsing can also decrease Shinnery oak abundance. However, brush management should maintain shrub patches to prevent erosion and to provide wildlife cover and forage.

Diagnosis: This state represents a clumped distribution of Shinnery oak with patches of bare ground and subdominant grass species, such as black grama, dropseeds, threeawns, and blue grama. Shinnery oak density increases, as do dropseeds, threeawns, and blue grama, as Sandy site intergrades with Deep Sand and Sandhills sites.

Transition to Shinnery Oak-Dominated State (1a): Decrease in black grama with subsequent decrease in dropseeds and threeawns. Increase in Shinnery oak as a result of drought, above average precipitation (>16 inches), grazing, fire suppression, interspecific competition, and coarse textured soils.

Key indicators of approach to transition:

- Loss of black grama and other grass species cover
- Increase of dropseed/threeawn and shinnery oak
- Surface soil erosion and bare patch expansion

Transition to Historic Plant Community (1b): The Shinnery oak-dominated state begins to transition toward the historic plant community as drivers such as drought, but also above average precipitation (e.g., 16 inches) discontinue. Brush control can also drive the Shinnery oak state toward a grassland state.

State 3 Sand Sage Dominated

Community 3.1

Sand Sage Dominated

Sand Sage Dominated: This state is dominated by sand sage with subdominant grass species from the historic plant community. Sand sage occurs as a result of insufficient herbicide application in Shinnery oak dominated sites with subdominant sand sage. Sand sage either reestablishes dominance or colonizes from an off-site location and stabilizes soils. Sand sage stabilizes light sandy soils from wind erosion and provides a harbor for grass and forb species in heavily grazed conditions (Davis and Bonham 1979). Sand sage abundance increases with drought and/or heavy grazing, but decreases with light grazing due to herbaceous plant competition. Grass and forb species can reestablish as competition from sand sage is relatively light. Herbicide applied in the spring, especially when growth and photosynthesis rates are greatest, can reduce sand sage if there is subsequent rest from grazing (Herbel et al. 1979, Pettit 1986). Brush management should maintain patches of sand sage to prevent wind erosion and subsequent dune formation.

Diagnosis: This state is dominated by sand sage with subdominant grass species, such as black grama, dropseeds, threeawns, and blue grama. Sand sage tends to occur in sites with coarser textured soils.

Transition to Sand Sage Dominated (2): Sand sage appears from off-site locations and/or increases after insufficient herbicide applications aimed at removing Shinnery oak and sand sage.

Key indicators of approach to transition:

- Increase of sand sage seedlings and grasses
- Reduced soil erosion

Transition to Historic Plant Community (3): The sand sage dominated state transitions toward the historic plant community as sand sage decreases primarily through brush management but also with light intensity grazing management. Drought reduction will also support a transition to the historic plant community.

State 4

Lehmann Lovegrass + Natives

Community 4.1

Lehmann Lovegrass + Natives

Lehmann Lovegrass + Natives: This state is dominated by Lehmann lovegrass with subdominant grass species from the historic plant community. Lehmann lovegrass is a warm-season, perennial bunchgrass that was introduced from South Africa in the 1930's for rangeland restoration purposes (Humphrey 1970). Lehmann lovegrass invades from off-site locations with projects utilizing lovegrass for reseeding, soil stabilization, or highway projects. Lehmann lovegrass provides a winter and early spring forage for grazing. Lehmann lovegrass is vigorous in sandy to sandy loam soils which receive approximately 6-8 inches of summer precipitation (Cox et al. 1988). Lehmann lovegrass's aggressive competitive exclusion of native grass species has been attributed to lovegrass's low summer palatability, which reduces vigor of native species and allows lovegrass to increase vigor before grazing. Also, Lehmann lovegrass abundant seed production and establishment, especially after disturbances, allows for increased competition (Cable 1971, Cox et al. 1981). Lehmann lovegrass generally is tolerant to fire because of an aggressive seed-bank; however, severe fires can cause mature lovegrass mortality (Sumrall et al. 1991). Herbicide and reseeding is recommended for control of Lehmann lovegrass (Winn 1991).

Diagnosis: Lehmann lovegrass and grass species from the historic plant community, such as black grama, dropseeds, threeawns, and blue grama, dominate this state.

Transition to Lehmann lovegrass and native grass species (4a): Decrease in black grama with subsequent decrease in dropseeds and threeawns. Increase in Lehmann lovegrass as a result of drought, grazing, fire and interspecific competition from nearby sources of Lehmann lovegrass.

Key indicators of approach to transition:

- Loss of black grama and other grass species cover
- Disturbance and nearby source of Lehmann lovegrass
- Increase of Lehmann lovegrass seedlings

Transition to Historic Plant Community (4b): The Lehmann lovegrass/native grass state transitions toward the historic plant community after actions such as herbicide application and native reseeding have occurred. In addition, prevention of disturbances such as fire and livestock grazing also will encourage the transition to a native grass community

State 5

Grass/Mesquite

Community 5.1

Grass/Mesquite

Grass/Mesquite: This state is dominated by honey mesquite with dropseeds and/or threeawns. Black grama generally is rare as a result of heavy grazing intensity. Honey mesquite invades through seed dispersal from grazing livestock and/or wildlife. Dropseeds and threeawns cohabitate with mesquite due to sufficient precipitation. Mesquite tends to be arborescent due to less soil erosion relative to the Coppice Dunes state which reflects large soil loss. Mesquite obtains approximately half of its nitrogen from symbiotic bacteria housed in root nodules (Lajtha and Schlesinger 1986). Mesquite also provides nitrogen and soil organic matter to co-dominant grasses (Ansley and Jacoby 1998, Ansley et al. 1998). Historical fire occurrences reduced mesquite abundance by disrupting seed production cycles and suppressing seedlings; thus, grass species remained dominant. However, fire suppression has allowed mesquite to increase in density and abundance, increasing mesquite resistance to fires through aggressive resprouting. Herbicide application combined with subsequent prescribed fire may be effective in mesquite reduction (Britton and Wright 1971).

Diagnosis: This state is co-dominated by honey mesquite and dropseeds or threeawns.

Transition to Grass/Mesquite State (5a): This state occurs due to a decrease in black grama primarily from heavy grazing intensity and from an introduction of mesquite seeds from grazers. Dropseeds and threeawns increase and co-exist in the absence of black grama. Fire suppression also is responsible for an increase in mesquite.

Key indicators of approach to transition:

- Loss of black grama
- Increase of dropseeds and/or threeawns
- Increase of mesquite seedlings

Transition to Historic Plant Community (5b): Transition to the historic plant community requires brush management though herbicide application and possibly prescribed fire to reduce mesquite abundance. Once shrub species are removed, prescribed fire may be useful in maintaining a dominant grassland. Precipitation is also necessary in conjunction with management activities to support a dominant grassland.

State 6

Coppice Dunes

Community 6.1

Coppice Dunes

Coppice Dunes: This state is dominated by coppice mesquite dunes with minimal or no grass cover. Honey mesquite occurs in a multi-stemmed growth form which cultivates its dune formation by entrapping drifting sands. Mesquite utilizes its extensive tap and lateral roots to benefit from moisture deep in coarse textured soils. Grass species cannot compete for moisture, especially with compounding perturbations such as heavy grazing and drought. Soils succumb to wind erosion with the depletion of grass cover and eventually dunes form around mesquite plants (Gould 1982). Brush management is limited to herbicide application, biological control, or manual removal, as a lack of grass cover prevents prescribed burning. Seeding subsequent to brush control may transition this State toward the historic plant community.

Diagnosis: This state is characterized by low growing, multi-stemmed mesquite plants which form Coppice dunes by drifting soils from wind erosion. As grass cover decreases, windblown soils are removed from unprotected, inter-dune areas. Soils are then re-deposited on dunes which increases dune size.

Transition to Mesquite Coppice Dunes State (6): Decrease in black grama with subsequent decrease in dropseeds and threeawns due to competition with mesquite especially during drought, heavy grazing, and fire suppression. Competitive exclusion of grasses leads to wind erosion of sandy soils and dune formation of low growing mesquite plants.

Key indicators of approach to transition:

- Loss of black grama and other grass species cover
- Wind erosion as evidenced by pedestalled plants
- Bare patch expansion
- Increase of Coppice dune mesquites

Transition to Historic Plant Community (7): Transition toward the historic plant community requires mesquite removal though either herbicide application, biological control, or manual removal. In addition, seeding of native grass species with subsequent years of sufficient moisture is critical.

Additional community tables

Table 7. Community 1.1 plant community composition

Group	Common Name	Symbol	Scientific Name	Annual Production (Lb/Acre)	Foliar Cover (%)
Grass/Grasslike					
1	Warm Season			315–360	
	black grama	BOER4	<i>Bouteloua eriopoda</i>	315–360	–
2	Warm Season			45–90	
	blue grama	BOGR2	<i>Bouteloua gracilis</i>	45–90	–
3	Warm Season			27–45	
	bush muhly	MUPO2	<i>Muhlenbergia porteri</i>	27–45	–
4	Warm Season			90–135	
	spike dropseed	SPCO4	<i>Sporobolus contractus</i>	90–135	–
	sand dropseed	SPCR	<i>Sporobolus cryptandrus</i>	90–135	–
	mesa dropseed	SPFL2	<i>Sporobolus flexuosus</i>	90–135	–
5	Warm Season			27–45	
	threeawn	ARIST	<i>Aristida</i>	27–45	–
6	Warm Season			27–45	
	plains bristleglass	SEVU2	<i>Setaria vulpiseta</i>	27–45	–
7	Warm Season			27–45	
	Arizona cottontop	DICA8	<i>Digitaria californica</i>	27–45	–
8	Warm Season			45–72	
	silver bluestem	BOSA	<i>Bothriochloa saccharoides</i>	45–72	–
	little bluestem	SCSC	<i>Schizachyrium scoparium</i>	45–72	–
9	Warm Season			9–27	
	vine mesquite	PAOB	<i>Panicum obtusum</i>	9–27	–
10	Warm Season			9–27	
	tobosagrass	PLMU3	<i>Pleuraphis mutica</i>	9–27	–
11	Other Perennial Grasses			9–27	
	Grass, perennial	2GP	<i>Grass, perennial</i>	9–27	–
Shrub/Vine					
12	Shrub			9–45	

	yucca	YUCCA	<i>Yucca</i>	9–45	–
13	Shrub			9–27	
	catclaw mimosa	MIACB	<i>Mimosa aculeaticarpa</i> var. <i>biuncifera</i>	9–27	–
14	Shrub			9–27	
	fourwing saltbush	ATCA2	<i>Atriplex canescens</i>	9–27	–
15	Shrub			9–27	
	jointfir	EPHED	<i>Ephedra</i>	9–27	–
16	Shrub			9–27	
	javelina bush	COER5	<i>Condalia ericoides</i>	9–27	–
17	Shrub			9–27	
	sand sagebrush	ARFI2	<i>Artemisia filifolia</i>	9–27	–
	broom snakeweed	GUSA2	<i>Gutierrezia sarothrae</i>	9–27	–
18	Other Shrubs			9–27	
	Shrub (>.5m)	2SHRUB	<i>Shrub (>.5m)</i>	9–27	–
Forb					
19	Forb			27–63	
	croton	CROTO	<i>Croton</i>	27–63	–
	globemallow	SPHAE	<i>Sphaeralcea</i>	27–63	–
20	Forb			27–45	
	curlycup gumweed	GRSQ	<i>Grindelia squarrosa</i>	27–45	–
	woolly groundsel	PACA15	<i>Packera cana</i>	27–45	–
21	Forb			9–27	
	Adonis blazingstar	MEMU3	<i>Mentzelia multiflora</i>	9–27	–
22	Forb			27–45	
	redstem stork's bill	ERIC16	<i>Erodium cicutarium</i>	27–45	–
	Texas stork's bill	ERTE13	<i>Erodium texanum</i>	27–45	–
23	Other Forbs			9–27	
	Forb (herbaceous, not grass nor grass-like)	2FORB	<i>Forb (herbaceous, not grass nor grass-like)</i>	9–27	–

Animal community

This site provides habitat which support a resident animal community that is characterized by pronghorn antelope, black-tailed jackrabbit, spotted ground squirrel, black-tailed prairie dog, yellow-faced pocket gopher, Ord's kangaroo rat, Northern grasshopper mouse, southern plains woodrat, badger, meadowlark, roadrunner, burrowing owl, white-necked raven, cactus wren, pyrrhuloxia, lesser prairie chicken, mourning dove, scaled quail, Harris' hawk, side-blotched lizard, marbled whiptail, Texas horned lizard, prairie rattlesnake, plains spadefoot toad, and ornate box turtle.

Hydrological functions

The runoff curve numbers are determined by field investigations using hydraulic cover conditions and hydrologic soil groups.

Hydrologic Interpretations

Soil Series Hydrologic Group

Anthony B

Berino B

Cacique C *shallow soil
Harkey B
Pajaritio B
Reakor B
Mobeetie B
Wink B
Sotim B
Vinton B
Drake B
Onite B
Alma B
Poquita B
Dona Ana B
Monahans B

Recreational uses

This site offers recreation potential for hiking, horseback riding, nature observation, and photography, bird, antelope and predator hunting. During years of abundant spring moisture, this site displays a colorful array of wildflowers.

Wood products

This site has no potential for wood products.

Other products

This site is suitable for grazing by all classes and kinds of livestock during all seasons of the year. Under retrogression, plants such as black grama, blue grama, bush muhly, plains bristlegrass, Arizona cottontop, vine mesquite, little bluestem and fourwing saltbush will decrease while the dropseeds, threeawns, tobosa, yucca, catclaw mimosa, javelinabush, mesquite and broom snakeweed will increase. This site responds well to brush management and deferment. It is best suited to a system of management that rotates the season of use.

Other information

Guide to Suggested Initial Stocking Rate Acres per Animal Unit Month

Similarity Index Ac/AUM
100 - 76 2.7 – 3.8
75 – 51 3.5 – 5.0
50 – 26 5.0 – 8.0
25 – 0 8.1 +

Inventory data references

Other References:

Data collection for this site was done in conjunction with the progressive soil surveys within the Southern Desertic Basins, Plains and Mountains, Major Land Resource Areas of New Mexico. This site has been mapped and correlated with soils in the following soil surveys. Eddy County, Lea County, and Chaves County.

Other references

Other References:

Data collection for this site was done in conjunction with the progressive soil surveys within the Southern Desertic Basins, Plains and Mountains, Major Land Resource Areas of New Mexico. This site has been mapped and correlated with soils in the following soil surveys. Eddy County, Lea County, and Chaves County.

Literature Cited

Ansley, R. J.; Jacoby, P. W. 1998. Manipulation of fire intensity to achieve mesquite management goals in north Texas. In: Pruden, Teresa L.; Brennan, Leonard A., eds. Fire in ecosystem management: shifting the paradigm from suppression to prescription: Proceedings, Tall Timbers fire ecology conference; 1996 May 7-10; Boise, ID. No. 20. Tallahassee, FL: Tall Timbers Research Station:195-204.

Ansley, R. J.; Jones, D. L.; Tunnell, T. R.; [and others]. 1998. Honey mesquite canopy responses to single winter fires: relation to herbaceous fuel, weather and fire temperature. International Journal of Wildland Fire 8(4):241-252.

Britton, Carlton M.; Wright, Henry A. 1971. Correlation of weather and fuel variables to mesquite damage by fire. Journal of Range Management 24:136-141.

Cable, Dwight R. 1971. Lehmann lovegrass on the Santa Rita Experimental Range, 1937-1968. Journal of Range Management 24:17-21.

Canfield, R. H. 1939. The effect of intensity and frequency of clipping on density and yield of black grama and tobosa grass. Tech. Bull. 681. Washington, DC: U.S. Department of Agriculture. 32 p.

Cox, Jerry R.; Ruyle, G.B.; Fourle, Jan H.; Donaldson, Charlie. 1988. Lehmann lovegrass—central South Africa and Arizona, USA. Rangelands 10(2):53-55

Contributors

Don Sylvester
Quinn Hodgson

Rangeland health reference sheet

Interpreting Indicators of Rangeland Health is a qualitative assessment protocol used to determine ecosystem condition based on benchmark characteristics described in the Reference Sheet. A suite of 17 (or more) indicators are typically considered in an assessment. The ecological site(s) representative of an assessment location must be known prior to applying the protocol and must be verified based on soils and climate. Current plant community cannot be used to identify the ecological site.


Author(s)/participant(s)	
Contact for lead author	
Date	
Approved by	
Approval date	
Composition (Indicators 10 and 12) based on	Annual Production

Indicators

1. Number and extent of rills:

2. Presence of water flow patterns:

3. Number and height of erosional pedestals or terracettes:



USGS The National Map: National Boundaries Dataset, 3DEP Elevation Program, Geographic Names Information System, National Hydrography Dataset, National Land Cover Database, National Structures Dataset, and National Transportation Dataset; USGS Global Ecosystems; U.S. Census Bureau TIGER/Line data; USFS Road Data; Natural Earth Data; U.S. Department of State Humanitarian Information Unit; and NOAA National Centers for Environmental Information, U.S. Coastal Relief Model. Data refreshed August, 2021., Sources: Esri, Airbus DS, USGS, NOAA, NASA, CGIAR, INRIA, Robinson, NCEAS, NLS, OS, NMA, Geodatastyrelsen, Rijkswaterstaat, GSA, Geoland, FEMA, Intermap and the GIS user community, NMBGMR

ATTACHMENT 4



Dhugal Hanton <vertexresourcegroupusa@gmail.com>

48-HR Notification Billiken 6 CTB 1, Gaucho Unit 30 CTB 1, Green Wave 20 CTB 9 Liner Inspections

Dhugal Hanton <vertexresourcegroupusa@gmail.com>

Thu, Jan 13, 2022 at 1:52 PM

To: EMNRD-OCD-District1spills <emnrd-ocd-district1spills@state.nm.us>, "CFO_Spill, BLM_NM" <blm_nm_cfo_spill@blm.gov>, "Enviro, OCD, EMNRD" <OCD.Enviro@state.nm.us>

Cc: wesley.mathews@dvn.com, dale.woodall@dvn.com

Bcc: Jramirez@vertex.ca, bschafer@vertex.ca

All,

Please accept this email as 48-hr notification that Vertex Resource Services has scheduled 3 liner inspections to be conducted for the following releases:

nAPP2129845429 DOR: 10/24/2021 Site Name: Green Wave 20 CTB 9

nAPP2134155628 DOR: 12/3/2021 Site Name: Billiken 6 CTB 1

nAPP2131553617 DOR: 11/5/2021 Site Name: Gaucho Unit 30 CTB 1

This work will be completed on behalf of Devon Energy Production Company.

On Friday, January 21, 2022 at approximately 8:00 a.m., John Ramirez will be on the first site to conduct a liner inspection and continue them throughout the day. He can be reached at 575-725-1809. If you need directions to the sites, please do not hesitate to contact him. If you have any questions or concerns regarding this notification, please give me a call at 701-301-1564.

Thank you,

Brandon Schafer

Project Manager

Vertex Resource Services Inc.

P 701.645.3111 Ext. 706**C 701.301.1564****F 780.464.3731**www.vertex.ca

Confidentiality Notice: This message and any attachments are solely for the intended recipient and may contain confidential or privileged information. If you are not the intended recipient, any disclosure, copying, use, or distribution of the information included in this message and any attachment is prohibited. If you have received this communication in error, please notify us by reply email and immediately and permanently delete this message and any attachments. Thank you. '%!%{'

ATTACHMENT 5



Daily Site Visit Report

Client:	Devon Energy Corporation	Inspection Date:	1/21/2022
Site Location Name:	Billiken 6 CTB 1	Report Run Date:	1/21/2022 10:59 PM
Client Contact Name:	Wes Matthews	API #:	
Client Contact Phone #:	(575) 748-0176		
Unique Project ID		Project Owner:	
Project Reference #		Project Manager:	

Summary of Times

Arrived at Site	1/21/2022 9:55 AM
Departed Site	1/21/2022 10:20 AM

Field Notes

- 10:56** Arrived on site to perform liner inspection.
- 11:05** Inside and outside of the wall dike does not appear to have any significant damage.
- 11:09** The bottom of the containment does not appear to have any significant damage around and between the tanks.
- 11:09** There's is nothing that I see that brings up any environmental concern.

Next Steps & Recommendations

- 1 No recommendations at this time.

Daily Site Visit Report



Site Photos

Viewing Direction: South



Outside the wall dike east side.

Viewing Direction: Northwest



Inside the wall dike west side.

Viewing Direction: Northeast



Inside the wall dike north side.

Viewing Direction: South



West side of the containment.



Daily Site Visit Report

Viewing Direction: East



Bottom of containment between tanks 451 and 413

Viewing Direction: East



Bottom of containment between tanks 413 and 452

Viewing Direction: East



Bottom of containment between tanks 452 and 453

Viewing Direction: North



Bottom of containment between all tanks N-S



Daily Site Visit Report

Viewing Direction: East



Outside the wall dike north side.

Viewing Direction: North



Outside the wall dike west side.

Viewing Direction: East



Outside the wall dike south side.

Viewing Direction: North



Inside the wall dike east side.



Daily Site Visit Report

Viewing Direction: North



East side of the containment.

Viewing Direction: Southwest



South side of the containment.

Viewing Direction: Southeast



South side of the containment.

Viewing Direction: Southwest



Inside the wall dike south side.

Daily Site Visit Report



Daily Site Visit Signature

Inspector: Chance Dixon

Signature: 
Signature

ATTACHMENT 6

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nAPP2134155628
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party Devon Energy Production Company	OGRID 6137
Contact Name Dale Woodall	Contact Telephone
Contact email Dale.Woodall@dvn.com	Incident # (assigned by OCD)
Contact mailing address 6488 Seven Rivers Hwy Artesia, NM 88210	

Location of Release Source

Latitude 32.076535 Longitude -103.411171
(NAD 83 in decimal degrees to 5 decimal places)

Site Name Billiken 6 CTB 1	Site Type Oil
Date Release Discovered 12/03/2021	API# (if applicable)

Unit Letter	Section	Township	Range	County
D	6	23S	35E	Lea

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 236.28 BBLS	Volume Recovered (bbls) 236.28 BBLS
	Is the concentration of total dissolved solids (TDS) in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release Leak developed in flowline. Fluid remained in lined containment.

Incident ID	nAPP2134155628
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? The spill is over 25 BBLS.
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Notice given by Dale Woodall to OCD.	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped.	
<input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment.	
<input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.	
<input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why:	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Kendra DeHoyos</u>	Title: <u>EHS Associate</u>
Signature: <u>Kendra DeHoyos</u>	Date: <u>12/22/2021</u>
email: <u>Kendra.Ruiz@dvn.com</u>	Telephone: <u>575-748-0167</u>
<u>OCD Only</u>	
Received by: <u>Ramona Marcus</u>	Date: <u>12/27/2021</u>

NAPP2134155628

Spills In Lined Containment	
Measurements Of Standing Fluid	
Length(Ft)	100
Width(Ft)	53
Depth(in.)	4
Total Capacity without tank displacements (bbls)	314.66
No. of 500 bbl Tanks In Standing Fluid	7
No. of Other Tanks In Standing Fluid	1
OD Of Other Tanks In Standing Fluid(feet)	
Total Volume of standing fluid accounting for tank displacement.	236.28

District I
 1626 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-8101 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6176 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3482

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 88440

CONDITIONS

Operator: DEVON ENERGY PRODUCTION COMPANY, LP 333 West Sheridan Ave. Oklahoma City, OK 73102	OGRID: 8197
	Action Number: 88440
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
marcus	None	12/27/2021

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nAPP2134155628
District RP	
Facility ID	
Application ID	

Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	<u><50</u> (ft bgs)
Did this release impact groundwater or surface water?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within 300 feet of a wetland?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release overlying a subsurface mine?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release overlying an unstable area such as karst geology?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within a 100-year floodplain?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Did the release impact areas not on an exploration, development, production, or storage site?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No

Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.

Characterization Report Checklist: *Each of the following items must be included in the report.*

- ☒ Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells.
- ☒ Field data
- N/A Data table of soil contaminant concentration data
- ☒ Depth to water determination
- ☒ Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release
- N/A Boring or excavation logs
- ☒ Photographs including date and GIS information
- ☒ Topographic/Aerial maps
- N/A Laboratory data including chain of custody

State of New Mexico
Oil Conservation Division

Page 4

Incident ID	nAPP2134155628
District RP	
Facility ID	
Application ID	

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Dale Woodall Title: EHS Professional
Signature: Dale Woodall Date: Feb 3, 2022
email: Dale.Woodall@dvn.com Telephone: 575-748-1838

OCD Only

Received by: _____ Date: _____

Incident ID	nAPP2134155628
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: *Each of the following items must be included in the closure report.*

- ☒ A scaled site and sampling diagram as described in 19.15.29.11 NMAC
- ☒ Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- ☒ Laboratory analyses of final sampling (Note: appropriate OCD District office must be notified 2 days prior to final sampling)
- ☒ Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Dale Woodall

Title: EHS Professional

Signature: Dale Woodall
Dale Woodall (Feb 3, 2022 15:52 MST)

Date: Feb 3, 2022

email: Dale.Woodall@dvn.com

Telephone: 575-748-1838

OCD Only

Received by: Chad Hensley

Date: 02/23/2022

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by:

Chad Hensley

Date: 02/23/2022

Printed Name: Chad Hensley

Title: Environmental Specialist Advanced



February 2, 2022

Vertex Project #: 21E-00580-009

Spill Closure Report: Billiken 6 CTB 1
Unit D, Section 06, Township 26 South, Range 35 East
County: Lea
API: N/A
Tracking Number: nAPP2134155628

Prepared For: Devon Energy Production Company
6488 Seven Rivers Highway
Artesia, New Mexico 88210

New Mexico Oil Conservation Division – District 1 – Hobbs

1625 North French Drive
Hobbs, New Mexico 88240

Devon Energy Production Company (Devon) retained Vertex Resource Services Inc. (Vertex) to conduct a spill assessment and liner inspection for a produced water release that occurred at Billiken 6 CTB 1 (hereafter referred to as “Billiken CTB”). Devon provided immediate notification of the spill to New Mexico Oil Conservation Division (NMOCD) District 1 and the Bureau of Land Management (BLM), who own the property, on December 4, 2021, via phone call and email. The initial C-141 Release Notification was received by NMOCD on December 22, 2021 (Attachment 1). The NMOCD tracking number assigned to this incident is nAPP2134155628.

This letter provides a description of the liner inspection and demonstrates that closure criteria established in 19.15.29.12 *New Mexico Administrative Code* (NMAC; New Mexico Oil Conservation Division, 2022) have been met and all applicable regulations are being followed. This document is intended to serve as a final report to obtain approval from NMOCD for closure of this release.

Incident Description

On December 3, 2021, a release occurred at Devon’s Billiken CTB site when a leak developed in a flowline. The incident resulted in the release of approximately 236.28 barrels (bbl) of produced water into lined containment. A hydrovac arrived on-site to recover free fluids; approximately 236.28 bbls of produced water were recovered and removed for disposal off-site. The spill was fully contained within the bermed, lined containment on the facility pad. No produced water was released into undisturbed areas or waterways.

Site Characterization

The release at Billiken CTB occurred on federally-owned land, N 32.076535, W 103.411171, approximately 12.5 miles west of Jal, New Mexico. The legal description for the site is Unit D, Section 06, Township 26 South, Range 35 East, Lea County, New Mexico. This location is within the Permian Basin in southeast New Mexico and has historically been used for oil and gas exploration and production, and rangeland. An aerial map of the site is included in Attachment 2.

vertex.ca

3101 Boyd Drive, Carlsbad, New Mexico 88220, USA | P 575.725.5001

Billiken CTB is typical of oil and gas exploration and production sites in the western portion of the Permian Basin and is currently used for oil and gas production and storage. The following sections specifically describe the area in which the Billiken CTB facility is located.

The surrounding landscape is associated with sandy plains typical of elevations of 3,000 to 3,900 feet above sea level. The climate is semi-arid, with average annual precipitation ranging between 10 and 12 inches. Historically, the plant community was dominated by grasses, which stabilized the potentially erosive sandy soils; however, more recent conditions, resulting from fire suppression and extensive grazing, show increased woody plant abundance. The dominant grass species are black grama, dropseeds and bluestems, with scattered shinnery oak and sand sage. Litter and, to a lesser extent, bare ground are a significant proportion of ground cover while grasses compose the remainder (United States Department of Agriculture, Natural Resources Conservation Service, 2022). Limited to no vegetation is allowed to grow on the compacted facility pad.

The *Geological Map of New Mexico* indicates the surface geology at Billiken CTB is comprised of Qep – eolian and piedmont deposits that include eolian sands interlaid with piedmont-slope deposits (New Mexico Bureau of Geology and Mineral Resources, 2022). The Natural Resources Conservation Service *Web Soil Survey* characterizes the soil at the site as Pyote and Maljamar fine sands, characterized by deep, fine sandy and loamy fine sandy soil. It tends to be well-drained with very low to negligible runoff and low available moisture levels in the soil profile (United States Department of Agriculture, Natural Resources Conservation Service, 2022). There is low potential for karst geology to be present near Billiken CTB, though some erosional karst is possible (United States Department of the Interior, Bureau of Land Management, 2018).

There is no surface water located at Billiken CTB. The nearest significant watercourse, as defined in Subsection P of 19.15.17.7 NMAC, is an intermittent stream located approximately 1.19 miles east of the site. An emergent wetland is located approximately 0.64 miles west of the site. An intermittent lake is located approximately 14 miles south-southeast of the release site (United States Fish and Wildlife Service, 2022). At Billiken CTB, there are no continuously flowing watercourses, lakebeds, sinkholes, playa lakes, or other critical water or community features nearby as outlined in Paragraph (4) of Subsection C of 19.15.29.12 NMAC.

The nearest well to Billiken CTB is a United States Geological Survey-identified well located approximately 2.4 miles south of the site, with no groundwater data. New Mexico Office of the State Engineer-identified wells are located approximately 2.57 miles north and 3.57 miles west of the site with recorded depths to groundwater of 300 and 230 feet below ground surface, respectively (bgs; New Mexico Office of the State Engineer, New Mexico Water Rights Reporting System, 2022). Documentation pertaining to site characterization and depth to groundwater determination is included in Attachment 3.

Closure Criteria Determination

Using site characterization information, a closure criteria determination worksheet (Attachment 3) was completed to determine if the release was subject to any of the special case scenarios outlined in Paragraph (4) of Subsection C of 19.15.29.12 NMAC.

Based on data included in the closure criteria determination worksheet, the release at Billiken CTB is not subject to the requirements of Paragraph (4) of Subsection C of 19.15.29.12 NMAC. The nearest depth to groundwater reference is

vertex.ca

more than 0.5 miles from the site; therefore, the closure criteria for the incident assume the most stringent conditions (depth to groundwater <50 feet bgs) and are determined to be associated with the following constituent concentration limits.

Table 1. Closure Criteria for Soils Impacted by a Release		
Minimum depth below any point within the horizontal boundary of the release to ground water less than 10,000 mg/L TDS ¹	Constituent	Limit
< 50 feet	Chloride	600 mg/kg
	TPH ² (GRO + DRO + MRO)	100 mg/kg
	BTEX ³	50 mg/kg
	Benzene	10 mg/kg

¹Total Dissolved Solids (TDS)

²Total petroleum hydrocarbons (TPH) = gasoline range organics (GRO) + diesel range organics (DRO) + motor oil range organics (MRO)

³Benzene, toluene, ethylbenzene and xylenes (BTEX)

Liner Inspection

On January 13, 2022, Vertex provided 48-hour notification of the liner inspection to NMOCD and the BLM, as required by Subparagraph (a) of Paragraph (5) of Subsection A 19.15.29.11 NMAC (Attachment 4). On January 21, 2022, Vertex was on-site to conduct an inspection of the lined containment and verify that the liner was intact and had the ability to contain the release. The Daily Field Report and associated photographs of the liner inspection are included in Attachment 5. The inspection confirmed the liner remained intact and had the ability to contain the release. This was further evidenced by the amount of fluid released (~236.28 bbl) and recovered (~236.28 bbl).

Closure Request

Vertex recommends no additional remediation action to address the release at Billiken CTB. The secondary containment liner was intact and contained the release. There are no anticipated risks to human, ecological or hydrological receptors associated with the release site.

Vertex requests that this incident (nAPP2134155628) be closed as all closure requirements set forth in Subsection E of 19.15.29.12 NMAC have been met. Devon certifies that all information in this report and the attachments is correct, and that they have complied with all applicable closure requirements and conditions specified in Division rules and directives to meet NMOCD requirements to obtain closure on the December 3, 2021, release at Billiken CTB. A complete C-141 form is presented in Attachment 6.

Should you have any questions or concerns, please do not hesitate to contact the undersigned at 832.588.0674 or dhanton@vertex.ca

vertex.ca

3101 Boyd Drive, Carlsbad, New Mexico 88220, USA | P 575.725.5001

Devon Energy Production Company
Billiken 6 CTB 1

2022 Spill Assessment and Closure
February 2022



Lakin Pullman, B.Sc.
ENVIRONMENTAL TECHNICIAN, REPORT

February 2, 2022

Date

Dhugal Hanton, B.Sc., P.Ag, P.Biol., SR/WA.
VICE PRESIDENT- USA, REPORT REVIEW

February 2, 2022

Date

Attachments

- Attachment 1. NMOCD C-141 Initial Notification
- Attachment 2. Aerial Site Map
- Attachment 3. Closure Criteria for Soils Impacted by a Release Research Determination Documentation
- Attachment 4. 48-hr Notification of Confirmatory Sampling to Regulatory Agencies
- Attachment 5. Daily Field Report with Photographs
- Attachment 6. Complete C-141 Form

vertex.ca

3101 Boyd Drive, Carlsbad, New Mexico 88220, USA | P 575.725.5001

References

- New Mexico Bureau of Geology and Mineral Resources. (2022). *Interactive Geologic Map*. Retrieved from <http://geoinfo.nmt.edu>.
- New Mexico Office of the State Engineer, New Mexico Water Rights Reporting System. (2022). *Water Column/Average Depth to Water Report*. Retrieved from <http://nmwrrs.ose.state.nm.us/nmwrrs/waterColumn.html>.
- New Mexico Oil Conservation Division. (2022). *New Mexico Administrative Code – Natural Resources and Wildlife Oil and Gas Releases*. Santa Fe, New Mexico.
- United States Department of Agriculture, Natural Resources Conservation Service. (2022). *Web Soil Survey*. Retrieved from <https://websoilsurvey.nrcs.usda.gov/app/WebSoilSurvey.aspx>.
- United States Department of the Interior, Bureau of Land Management. (2018). *CFO Karst Public*. https://www.nm.blm.gov/shapeFiles/cfo/carlsbad_spatial_data.html
- United States Fish and Wildlife Service. (2022). *National Wetlands Inventory*. Retrieved from <https://www.fws.gov/wetlands/data/Mapper.html>.

Limitations

This report has been prepared for the sole benefit of Devon Energy Production Company (Devon). This document may not be used by any other person or entity, with the exception of the New Mexico Oil Conservation Division and Bureau of Land Management, without the express written consent of Vertex Resource Services Inc. (Vertex) and Devon. Any use of this report by a third party, or any reliance on decisions made based on it, or damages suffered as a result of the use of this report are the sole responsibility of the user.

The information and conclusions contained in this report are based upon work undertaken by trained professional and technical staff in accordance with generally accepted scientific practices current at the time the work was performed. The conclusions and recommendations presented represent the best judgement of Vertex based on the data collected during the assessment. Due to the nature of the assessment and the data available, Vertex cannot warrant against undiscovered environmental liabilities. Conclusions and recommendations presented in this report should not be considered legal advice.

ATTACHMENT 1

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nAPP2134155628
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party Devon Energy Production Company	OGRID 6137
Contact Name Dale Woodall	Contact Telephone
Contact email Dale.Woodall@dvn.com	Incident # (assigned by OCD)
Contact mailing address 6488 Seven Rivers Hwy Artesia, NM 88210	

Location of Release Source

Latitude 32.076535 Longitude -103.411171
(NAD 83 in decimal degrees to 5 decimal places)

Site Name Billiken 6 CTB 1	Site Type Oil
Date Release Discovered 12/03/2021	API# (if applicable)

Unit Letter	Section	Township	Range	County
D	6	23S	35E	Lea

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 236.28 BBLS	Volume Recovered (bbls) 236.28 BBLS
	Is the concentration of total dissolved solids (TDS) in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release Leak developed in flowline. Fluid remained in lined containment.

Incident ID	nAPP2134155628
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? The spill is over 25 BBLS.
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Notice given by Dale Woodall to OCD.	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why: 	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: Kendra DeHoyos	Title: EHS Associate
Signature: <u>Kendra DeHoyos</u>	Date: <u>12/22/2021</u>
email: Kendra.Ruiz@dvn.com	Telephone: 575-748-0167
<u>OCD Only</u>	
Received by: <u>Ramona Marcus</u>	Date: <u>12/27/2021</u>

NAPP2134155628

Spills In Lined Containment	
Measurements Of Standing Fluid	
Length(Ft)	100
Width(Ft)	53
Depth(in.)	4
Total Capacity without tank displacements (bbls)	314.66
No. of 500 bbl Tanks In Standing Fluid	7
No. of Other Tanks In Standing Fluid	1
OD Of Other Tanks In Standing Fluid(feet)	
Total Volume of standing fluid accounting for tank displacement.	236.28

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 68440

CONDITIONS


Operator: DEVON ENERGY PRODUCTION COMPANY, LP 333 West Sheridan Ave. Oklahoma City, OK 73102	OGRID: 6137
	Action Number: 68440
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
rmarcus	None	12/27/2021

ATTACHMENT 2



 Containment (~7,161 sq. ft.)



0 25 50 100 ft.

Map Center:
Lat: 32.076583,
NAD 1983 UTM Zone 13N Long:-103.411132
Date: Jan 24/22



Aerial Site Map
Billiken 6 CTB 1

FIGURE:
1



Geospatial data presented in this figure may be derived from external sources and Vertex does not assume any liability for inaccuracies. This figure is intended for reference use only and is not certified for legal, survey, or engineering purposes.

Note: Feature locations from aerial imagery, ESRI, 2021.

VERSATILITY. EXPERTISE.

ATTACHMENT 3

Closure Criteria Worksheet			
Site Name: Billiken 6 CTB 1			
Spill Coordinates:		X: 32.076535	Y: -103.411171
Site Specific Conditions		Value	Unit
1	Depth to Groundwater	<50	feet
2	Within 300 feet of any continuously flowing watercourse or any other significant watercourse	12,664	feet
3	Within 200 feet of any lakebed, sinkhole or playa lake (measured from the ordinary high-water mark)	74,079	feet
4	Within 300 feet from an occupied residence, school, hospital, institution or church	46,941	feet
5	i) Within 500 feet of a spring or a private, domestic fresh water well used by less than five households for domestic or stock watering purposes, or	13,556	feet
	ii) Within 1000 feet of any fresh water well or spring	13,556	feet
6	Within incorporated municipal boundaries or within a defined municipal fresh water field covered under a municipal ordinance adopted pursuant to Section 3-27-3 NMSA 1978 as amended, unless the municipality specifically approves	No	(Y/N)
7	Within 300 feet of a wetland	3,374	feet
8	Within the area overlying a subsurface mine	No	(Y/N)
9	Within an unstable area (Karst Map)	Low	Critical High Medium Low
10	Within a 100-year Floodplain	N/A	year
11	Soil Type	Fine Sand, Fine Sandy Loam, Sandy Clay Loam	
12	Ecological Classification	Loamy Sand	
13	Geology	Qep	
NMAC 19.15.29.12 E (Table 1) Closure Criteria		<50'	<50' 51-100' >100'

USGS Well Distance

2.40 miles

Legend

- 323010103244001
- 📌 Billiken 6 CTB 1 - liner inspection

Billiken 6 CTB 1 - liner inspection

323010103244001

Google Earth




1 mi

NMOSE Well Distance

2.57 Miles (13,556 Feet)

Legend


1





New Mexico Office of the State Engineer

Point of Diversion Summary

		(quarters are 1=NW 2=NE 3=SW 4=SE)				(quarters are smallest to largest)		(NAD83 UTM in meters)	
Well Tag	POD Number	Q64	Q16	Q4	Sec	Tw	Rng	X	Y
	C 02299	4	2	4	24	25S	34E	649517	3554125 
<hr/>									
Driller License: 122		Driller Company: UNKNOWN							
Driller Name: UNKNOWN									
Drill Start Date:		Drill Finish Date: 12/31/1949				Plug Date:			
Log File Date:		PCW Rev Date:				Source:			
Pump Type:		Pipe Discharge Size:				Estimated Yield: 3 GPM			
Casing Size: 8.00		Depth Well: 350 feet				Depth Water: 300 feet			

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

1/27/22 6:55 AM

POINT OF DIVERSION SUMMARY



New Mexico Office of the State Engineer

Water Right Summary



WR File Number: C 02299 **Subbasin:** CUB **Cross Reference:** -
Primary Purpose: PLS NON 72-12-1 LIVESTOCK WATERING
Primary Status: DCL DECLARATION
Total Acres: 0 **Subfile:** - **Header:** -
Total Diversion: 3 **Cause/Case:** -
Owner: INTREPID POTASH NEW MEXICO LLC
Contact: KATIE KELLER

Documents on File

Trn #	Doc	File/Act	Status		Transaction Desc.	From/		Acres	Diversion	Consumptive
			1	2		To				
get images	673682	UWL 2020-05-15	UWL	ACC	C 02299	T		0	0	
get images	652933	COWNF 2019-06-11	CHG	PRC	C 02299	T		0	0	
get images	648796	COWNF 2019-03-20	CHG	PRC	C 02299	T		0	0	
get images	198392	DCL 1993-02-02	DCL	PRC	C-02299	T		0	3	

Current Points of Diversion

POD Number	Well Tag	Source	Q		Tw	Rng	(NAD83 UTM in meters)		X	Y	Other Location Desc
			64	Q16			Q4	Sec			
C 02299			4	2	4	24	25S	34E	649517	3554125	

Priority Summary

Priority	Status	Acres	Diversion	Pod Number
12/31/1949	DCL	0	3	C 02299

Place of Use

Q Q		Acres	Diversion	CU	Use	Priority	Status	Other Location Desc
256	64							
Q16	Q4	0	3		PLS	12/31/1949	DCL	NO PLACE OF USE GIVEN

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.


1/27/22 6:55 AM

WATER RIGHT
SUMMARY

NMOSE Well Distance

3.57 miles

Legend



Google Earth

1 mi



New Mexico Office of the State Engineer

Point of Diversion Summary

(quarters are 1=NW 2=NE 3=SW 4=SE)

(quarters are smallest to largest)

(NAD83 UTM in meters)

Well Tag	POD Number	Q64 Q16 Q4 Sec TwS Rng	X	Y
	CP 01305 POD1	1 4 31 25S 37E	655628	3551065

x

Driller License: 1706 **Driller Company:** ELITE DRILLERS CORPORATION

Driller Name: WALLACE, BRYCE J.

Drill Start Date: 05/04/2017	Drill Finish Date: 05/06/2017	Plug Date:
Log File Date: 07/07/2017	PCW Rev Date:	Source: Artesian
Pump Type:	Pipe Discharge Size:	Estimated Yield: 60 GPM
Casing Size: 6.00	Depth Well: 420 feet	Depth Water: 230 feet

x

Water Bearing Stratifications:	Top	Bottom	Description
	280	320	Sandstone/Gravel/Conglomerate
	330	400	Sandstone/Gravel/Conglomerate
	400	420	Shale/Mudstone/Siltstone

x

Casing Perforations:	Top	Bottom
	320	420

x

Meter Number: 19203	Meter Make: TURBINES
Meter Serial Number: 7678015	Meter Multiplier: 1.0000
Number of Dials: 9	Meter Type: Diversion
Unit of Measure: Barrels 42 gal.	Return Flow Percent:
Usage Multiplier:	Reading Frequency: Monthly

x

Meter Readings (in Acre-Feet)

Read Date	Year	Mtr Reading	Flag	Rdr Comment	Mtr Amount Online
03/31/2021	2021	141799	A	RPT Initial reading submitted	0
05/31/2021	2021	1470544	A	ad	171.266
10/31/2021	2021	1610094	A	ad	17.987

x

**YTD Meter Amounts:	Year	Amount
	2021	189.253

x

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

1/27/22 6:55 AM

POINT OF DIVERSION SUMMARY



New Mexico Office of the State Engineer

Water Right Summary



[get image list](#)

WR File Number: CP 01305 **Subbasin:** CP **Cross Reference:** -
Primary Purpose: COM COMMERCIAL
Primary Status: PMT PERMIT
Total Acres: 0 **Subfile:** - **Header:** -
Total Diversion: 100 **Cause/Case:** -
Owner: FULFER OIL & CATTLE COMPANY
Contact: GREGG FULFER
Owner: ATKINS ENGR ASSOC INC
Contact: RICHARD CIBAK

Documents on File

Trn #	Doc	File/Act	Status		Transaction Desc.	From/		Acres	Diversion	Consumptive
			1	2		To				
get images	604490	APPRO 2016-01-21	PMT	MTR	CP 01305	T		0	100	100

Current Points of Diversion

(NAD83 UTM in meters)										
POD Number	Well Tag	Source	Q						Other Location Desc	
			64	Q16	Q4	Sec Tw	Rng	X		Y
CP 01305 POD1		Artesian	1	4	31	25S	37E	655628	3551065	

Priority Summary

Priority	Status	Acres	Diversion	Pod Number	
03/27/2014	PMT	0	100	CP 01305 POD1	Artesian

Place of Use

Q	Q			Acres	Diversion	CU	Use	Priority	Status	Other Location Desc
256	64	Q16	Q4							
				0	100	100	COM	03/27/2014	PMT	NO PLACE OF USE GIVEN


Source

Acres	Diversion	CU	Use	Priority	Source Description
0	100	100	COM	03/27/2014	GW

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

1/27/22 6:55 AM

 WATER RIGHT
SUMMARY



Nearest Continuously Flowing Watercourse



January 20, 2022


Wetlands

- Estuarine and Marine Deepwater
- Estuarine and Marine Wetland


- Freshwater Emergent Wetland
- Freshwater Forested/Shrub Wetland
- Freshwater Pond

- Lake
- Other
- Riverine

This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.



Lake 14 Miles (74,079 Feet)



January 20, 2022

Wetlands

- Estuarine and Marine Deepwater
- Estuarine and Marine Wetland

- Freshwater Emergent Wetland
- Freshwater Forested/Shrub Wetland
- Freshwater Pond

- Lake
- Other
- Riverine

This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.

Nearest Residence

8.89 Miles (46,941 Feet)

Legend



1

Billiken 6 CTB 1


Resident


3

Google Earth

TEXAS

7 km





Emergent Wetland 0.64 Miles (3,374 Feet)



January 20, 2022

Wetlands


- Estuarine and Marine Deepwater
- Estuarine and Marine Wetland

- Freshwater Emergent Wetland
- Freshwater Forested/Shrub Wetland
- Freshwater Pond

- Lake
- Other
- Riverine


This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.

Active Mines in New Mexico



1/20/2022, 10:48:08 AM



- | | | |
|---------------------------|-----------------------|-------------|
| Township / Range | Department of Defense | State Parks |
| Sections | Department of Energy | Tribal |
| Land Ownership | | |
| Bureau of Land Management | National Park Service | |
| Bureau of Reclamation | Private Land | |
| Department of Agriculture | State Game and Fish | |
| | State Land | |



U.S. Bureau of Land Management - New Mexico State Office, Sources:
Esri, USGS, NOAA, Sources: Esri, Garmin, USGS, NPS

EMNRD MMD GIS Coordinator

Document Path: G:\Projects\US PROJECTS\Devon Energy Corporation\21E-00580\009 - Billiken 6 CTB 1\Figure x Karst Potential Map Billiken 6 CTB 1 (21E-00580).mxd



Karst Potential

- Critical
- High
- Medium
- Low

- Site Location
- Site Buffer (1,000 ft.)

Overview Map

0 0.25 0.5 1 mi

Detail Map

0 150 300 600 ft.



Map Center:
Lat/Long: 32.077000, -103.411171

NAD 1983 UTM Zone 13N
Date: Jan 20/22



Karst Potential Map Billiken 6 CTB 1

FIGURE:

X



Geospatial data presented in this figure may be derived from external sources and Vertex does not assume any liability for inaccuracies. This figure is intended for reference use only and is not certified for legal, survey, or engineering purposes.

Note: Inset Map, ESRI 2021; Overview Map: ESRI World Topographic

VERSATILITY. EXPERTISE.

National Flood Hazard Layer FIRMMette



103°24'59"W 32°4'51"N



Legend

SEE FIS REPORT FOR DETAILED LEGEND AND INDEX MAP FOR FIRM PANEL LAYOUT

SPECIAL FLOOD HAZARD AREAS		Without Base Flood Elevation (BFE) <i>Zone A, V, A99</i>
		With BFE or Depth <i>Zone AE, AO, AH, VE, AR</i>
		Regulatory Floodway
OTHER AREAS OF FLOOD HAZARD		0.2% Annual Chance Flood Hazard, Areas of 1% annual chance flood with average depth less than one foot or with drainage areas of less than one square mile <i>Zone X</i>
		Future Conditions 1% Annual Chance Flood Hazard <i>Zone X</i>
		Area with Reduced Flood Risk due to Levee. See Notes. <i>Zone X</i>
		Area with Flood Risk due to Levee <i>Zone D</i>
		NO SCREEN Area of Minimal Flood Hazard <i>Zone X</i>
OTHER AREAS		Effective LOMRs
		Area of Undetermined Flood Hazard <i>Zone D</i>
GENERAL STRUCTURES		Channel, Culvert, or Storm Sewer
		Levee, Dike, or Floodwall
OTHER FEATURES		20.2 Cross Sections with 1% Annual Chance Water Surface Elevation
		17.5 Cross Sections with 1% Annual Chance Water Surface Elevation
		Coastal Transect
		Base Flood Elevation Line (BFE)
		Limit of Study
		Jurisdiction Boundary
		Coastal Transect Baseline
MAP PANELS		Digital Data Available
		No Digital Data Available
		Unmapped

The pin displayed on the map is an approximate point selected by the user and does not represent an authoritative property location.

This map complies with FEMA's standards for the use of digital flood maps if it is not void as described below. The basemap shown complies with FEMA's basemap accuracy standards

The flood hazard information is derived directly from the authoritative NFHL web services provided by FEMA. This map was exported on 1/20/2022 at 12:55 PM and does not reflect changes or amendments subsequent to this date and time. The NFHL and effective information may change or become superseded by new data over time.

This map image is void if the one or more of the following map elements do not appear: basemap imagery, flood zone labels, legend, scale bar, map creation date, community identifiers, FIRM panel number, and FIRM effective date. Map images for unmapped and unmodernized areas cannot be used for regulatory purposes.



United States
Department of
Agriculture

NRCS

Natural
Resources
Conservation
Service

A product of the National
Cooperative Soil Survey,
a joint effort of the United
States Department of
Agriculture and other
Federal agencies, State
agencies including the
Agricultural Experiment
Stations, and local
participants

Custom Soil Resource Report for **Lea County, New Mexico**



January 20, 2022

Preface

Soil surveys contain information that affects land use planning in survey areas. They highlight soil limitations that affect various land uses and provide information about the properties of the soils in the survey areas. Soil surveys are designed for many different users, including farmers, ranchers, foresters, agronomists, urban planners, community officials, engineers, developers, builders, and home buyers. Also, conservationists, teachers, students, and specialists in recreation, waste disposal, and pollution control can use the surveys to help them understand, protect, or enhance the environment.

Various land use regulations of Federal, State, and local governments may impose special restrictions on land use or land treatment. Soil surveys identify soil properties that are used in making various land use or land treatment decisions. The information is intended to help the land users identify and reduce the effects of soil limitations on various land uses. The landowner or user is responsible for identifying and complying with existing laws and regulations.

Although soil survey information can be used for general farm, local, and wider area planning, onsite investigation is needed to supplement this information in some cases. Examples include soil quality assessments (<http://www.nrcs.usda.gov/wps/portal/nrcs/main/soils/health/>) and certain conservation and engineering applications. For more detailed information, contact your local USDA Service Center (<https://offices.sc.egov.usda.gov/locator/app?agency=nrcs>) or your NRCS State Soil Scientist (http://www.nrcs.usda.gov/wps/portal/nrcs/detail/soils/contactus/?cid=nrcs142p2_053951).

Great differences in soil properties can occur within short distances. Some soils are seasonally wet or subject to flooding. Some are too unstable to be used as a foundation for buildings or roads. Clayey or wet soils are poorly suited to use as septic tank absorption fields. A high water table makes a soil poorly suited to basements or underground installations.

The National Cooperative Soil Survey is a joint effort of the United States Department of Agriculture and other Federal agencies, State agencies including the Agricultural Experiment Stations, and local agencies. The Natural Resources Conservation Service (NRCS) has leadership for the Federal part of the National Cooperative Soil Survey.

Information about soils is updated periodically. Updated information is available through the NRCS Web Soil Survey, the site for official soil survey information.

The U.S. Department of Agriculture (USDA) prohibits discrimination in all its programs and activities on the basis of race, color, national origin, age, disability, and where applicable, sex, marital status, familial status, parental status, religion, sexual orientation, genetic information, political beliefs, reprisal, or because all or a part of an individual's income is derived from any public assistance program. (Not all prohibited bases apply to all programs.) Persons with disabilities who require

alternative means for communication of program information (Braille, large print, audiotape, etc.) should contact USDA's TARGET Center at (202) 720-2600 (voice and TDD). To file a complaint of discrimination, write to USDA, Director, Office of Civil Rights, 1400 Independence Avenue, S.W., Washington, D.C. 20250-9410 or call (800) 795-3272 (voice) or (202) 720-6382 (TDD). USDA is an equal opportunity provider and employer.

Contents

Preface..... 2

How Soil Surveys Are Made.....5

Soil Map..... 8

 Soil Map.....9

 Legend.....10

 Map Unit Legend..... 11

 Map Unit Descriptions.....11

 Lea County, New Mexico..... 13

 PU—Pyote and Maljamar fine sands..... 13

 PY—Pyote soils and Dune land..... 14

References..... 17

How Soil Surveys Are Made

Soil surveys are made to provide information about the soils and miscellaneous areas in a specific area. They include a description of the soils and miscellaneous areas and their location on the landscape and tables that show soil properties and limitations affecting various uses. Soil scientists observed the steepness, length, and shape of the slopes; the general pattern of drainage; the kinds of crops and native plants; and the kinds of bedrock. They observed and described many soil profiles. A soil profile is the sequence of natural layers, or horizons, in a soil. The profile extends from the surface down into the unconsolidated material in which the soil formed or from the surface down to bedrock. The unconsolidated material is devoid of roots and other living organisms and has not been changed by other biological activity.

Currently, soils are mapped according to the boundaries of major land resource areas (MLRAs). MLRAs are geographically associated land resource units that share common characteristics related to physiography, geology, climate, water resources, soils, biological resources, and land uses (USDA, 2006). Soil survey areas typically consist of parts of one or more MLRA.

The soils and miscellaneous areas in a survey area occur in an orderly pattern that is related to the geology, landforms, relief, climate, and natural vegetation of the area. Each kind of soil and miscellaneous area is associated with a particular kind of landform or with a segment of the landform. By observing the soils and miscellaneous areas in the survey area and relating their position to specific segments of the landform, a soil scientist develops a concept, or model, of how they were formed. Thus, during mapping, this model enables the soil scientist to predict with a considerable degree of accuracy the kind of soil or miscellaneous area at a specific location on the landscape.

Commonly, individual soils on the landscape merge into one another as their characteristics gradually change. To construct an accurate soil map, however, soil scientists must determine the boundaries between the soils. They can observe only a limited number of soil profiles. Nevertheless, these observations, supplemented by an understanding of the soil-vegetation-landscape relationship, are sufficient to verify predictions of the kinds of soil in an area and to determine the boundaries.

Soil scientists recorded the characteristics of the soil profiles that they studied. They noted soil color, texture, size and shape of soil aggregates, kind and amount of rock fragments, distribution of plant roots, reaction, and other features that enable them to identify soils. After describing the soils in the survey area and determining their properties, the soil scientists assigned the soils to taxonomic classes (units). Taxonomic classes are concepts. Each taxonomic class has a set of soil characteristics with precisely defined limits. The classes are used as a basis for comparison to classify soils systematically. Soil taxonomy, the system of taxonomic classification used in the United States, is based mainly on the kind and character of soil properties and the arrangement of horizons within the profile. After the soil

Custom Soil Resource Report

scientists classified and named the soils in the survey area, they compared the individual soils with similar soils in the same taxonomic class in other areas so that they could confirm data and assemble additional data based on experience and research.

The objective of soil mapping is not to delineate pure map unit components; the objective is to separate the landscape into landforms or landform segments that have similar use and management requirements. Each map unit is defined by a unique combination of soil components and/or miscellaneous areas in predictable proportions. Some components may be highly contrasting to the other components of the map unit. The presence of minor components in a map unit in no way diminishes the usefulness or accuracy of the data. The delineation of such landforms and landform segments on the map provides sufficient information for the development of resource plans. If intensive use of small areas is planned, onsite investigation is needed to define and locate the soils and miscellaneous areas.

Soil scientists make many field observations in the process of producing a soil map. The frequency of observation is dependent upon several factors, including scale of mapping, intensity of mapping, design of map units, complexity of the landscape, and experience of the soil scientist. Observations are made to test and refine the soil-landscape model and predictions and to verify the classification of the soils at specific locations. Once the soil-landscape model is refined, a significantly smaller number of measurements of individual soil properties are made and recorded. These measurements may include field measurements, such as those for color, depth to bedrock, and texture, and laboratory measurements, such as those for content of sand, silt, clay, salt, and other components. Properties of each soil typically vary from one point to another across the landscape.

Observations for map unit components are aggregated to develop ranges of characteristics for the components. The aggregated values are presented. Direct measurements do not exist for every property presented for every map unit component. Values for some properties are estimated from combinations of other properties.

While a soil survey is in progress, samples of some of the soils in the area generally are collected for laboratory analyses and for engineering tests. Soil scientists interpret the data from these analyses and tests as well as the field-observed characteristics and the soil properties to determine the expected behavior of the soils under different uses. Interpretations for all of the soils are field tested through observation of the soils in different uses and under different levels of management. Some interpretations are modified to fit local conditions, and some new interpretations are developed to meet local needs. Data are assembled from other sources, such as research information, production records, and field experience of specialists. For example, data on crop yields under defined levels of management are assembled from farm records and from field or plot experiments on the same kinds of soil.

Predictions about soil behavior are based not only on soil properties but also on such variables as climate and biological activity. Soil conditions are predictable over long periods of time, but they are not predictable from year to year. For example, soil scientists can predict with a fairly high degree of accuracy that a given soil will have a high water table within certain depths in most years, but they cannot predict that a high water table will always be at a specific level in the soil on a specific date.


After soil scientists located and identified the significant natural bodies of soil in the survey area, they drew the boundaries of these bodies on aerial photographs and

Custom Soil Resource Report

identified each as a specific map unit. Aerial photographs show trees, buildings, fields, roads, and rivers, all of which help in locating boundaries accurately.

Soil Map


The soil map section includes the soil map for the defined area of interest, a list of soil map units on the map and extent of each map unit, and cartographic symbols displayed on the map. Also presented are various metadata about data used to produce the map, and a description of each soil map unit.

Custom Soil Resource Report
Soil Map

Custom Soil Resource Report

MAP LEGEND

Area of Interest (AOI)

 Area of Interest (AOI)

Soils

 Soil Map Unit Polygons

 Soil Map Unit Lines

 Soil Map Unit Points

Special Point Features

 Blowout

 Borrow Pit

 Clay Spot

 Closed Depression

 Gravel Pit

 Gravelly Spot

 Landfill

 Lava Flow

 Marsh or swamp

 Mine or Quarry

 Miscellaneous Water

 Perennial Water

 Rock Outcrop

 Saline Spot

 Sandy Spot

 Severely Eroded Spot


 Sinkhole

 Slide or Slip


 Sodic Spot

 Spoil Area

 Stony Spot


 Very Stony Spot

 Wet Spot

 Other

 Special Line Features

Water Features

 Streams and Canals

Transportation

 Rails


 Interstate Highways

 US Routes

 Major Roads

 Local Roads

Background

 Aerial Photography

MAP INFORMATION

The soil surveys that comprise your AOI were mapped at 1:20,000.

Warning: Soil Map may not be valid at this scale.

Enlargement of maps beyond the scale of mapping can cause misunderstanding of the detail of mapping and accuracy of soil line placement. The maps do not show the small areas of contrasting soils that could have been shown at a more detailed scale.

Please rely on the bar scale on each map sheet for map measurements.

Source of Map: Natural Resources Conservation Service
Web Soil Survey URL:
Coordinate System: Web Mercator (EPSG:3857)

Maps from the Web Soil Survey are based on the Web Mercator projection, which preserves direction and shape but distorts distance and area. A projection that preserves area, such as the Albers equal-area conic projection, should be used if more accurate calculations of distance or area are required.

This product is generated from the USDA-NRCS certified data as of the version date(s) listed below.

Soil Survey Area: Lea County, New Mexico
Survey Area Data: Version 18, Sep 10, 2021

Soil map units are labeled (as space allows) for map scales 1:50,000 or larger.

Date(s) aerial images were photographed: Feb 7, 2020—May 12, 2020

The orthophoto or other base map on which the soil lines were compiled and digitized probably differs from the background imagery displayed on these maps. As a result, some minor shifting of map unit boundaries may be evident.

Custom Soil Resource Report

Map Unit Legend

Map Unit Symbol	Map Unit Name	Acres in AOI	Percent of AOI
PU	Pyote and Maljamar fine sands	61.5	96.1%
PY	Pyote soils and Dune land	2.5	3.9%
Totals for Area of Interest		64.0	100.0%

Map Unit Descriptions

The map units delineated on the detailed soil maps in a soil survey represent the soils or miscellaneous areas in the survey area. The map unit descriptions, along with the maps, can be used to determine the composition and properties of a unit.

A map unit delineation on a soil map represents an area dominated by one or more major kinds of soil or miscellaneous areas. A map unit is identified and named according to the taxonomic classification of the dominant soils. Within a taxonomic class there are precisely defined limits for the properties of the soils. On the landscape, however, the soils are natural phenomena, and they have the characteristic variability of all natural phenomena. Thus, the range of some observed properties may extend beyond the limits defined for a taxonomic class. Areas of soils of a single taxonomic class rarely, if ever, can be mapped without including areas of other taxonomic classes. Consequently, every map unit is made up of the soils or miscellaneous areas for which it is named and some minor components that belong to taxonomic classes other than those of the major soils.

Most minor soils have properties similar to those of the dominant soil or soils in the map unit, and thus they do not affect use and management. These are called noncontrasting, or similar, components. They may or may not be mentioned in a particular map unit description. Other minor components, however, have properties and behavioral characteristics divergent enough to affect use or to require different management. These are called contrasting, or dissimilar, components. They generally are in small areas and could not be mapped separately because of the scale used. Some small areas of strongly contrasting soils or miscellaneous areas are identified by a special symbol on the maps. If included in the database for a given area, the contrasting minor components are identified in the map unit descriptions along with some characteristics of each. A few areas of minor components may not have been observed, and consequently they are not mentioned in the descriptions, especially where the pattern was so complex that it was impractical to make enough observations to identify all the soils and miscellaneous areas on the landscape.

The presence of minor components in a map unit in no way diminishes the usefulness or accuracy of the data. The objective of mapping is not to delineate pure taxonomic classes but rather to separate the landscape into landforms or landform segments that have similar use and management requirements. The delineation of such segments on the map provides sufficient information for the development of resource plans. If intensive use of small areas is planned, however,

Custom Soil Resource Report

onsite investigation is needed to define and locate the soils and miscellaneous areas.

An identifying symbol precedes the map unit name in the map unit descriptions. Each description includes general facts about the unit and gives important soil properties and qualities.

Soils that have profiles that are almost alike make up a *soil series*. Except for differences in texture of the surface layer, all the soils of a series have major horizons that are similar in composition, thickness, and arrangement.

Soils of one series can differ in texture of the surface layer, slope, stoniness, salinity, degree of erosion, and other characteristics that affect their use. On the basis of such differences, a soil series is divided into *soil phases*. Most of the areas shown on the detailed soil maps are phases of soil series. The name of a soil phase commonly indicates a feature that affects use or management. For example, Alpha silt loam, 0 to 2 percent slopes, is a phase of the Alpha series.

Some map units are made up of two or more major soils or miscellaneous areas. These map units are complexes, associations, or undifferentiated groups.

A *complex* consists of two or more soils or miscellaneous areas in such an intricate pattern or in such small areas that they cannot be shown separately on the maps. The pattern and proportion of the soils or miscellaneous areas are somewhat similar in all areas. Alpha-Beta complex, 0 to 6 percent slopes, is an example.

An *association* is made up of two or more geographically associated soils or miscellaneous areas that are shown as one unit on the maps. Because of present or anticipated uses of the map units in the survey area, it was not considered practical or necessary to map the soils or miscellaneous areas separately. The pattern and relative proportion of the soils or miscellaneous areas are somewhat similar. Alpha-Beta association, 0 to 2 percent slopes, is an example.

An *undifferentiated group* is made up of two or more soils or miscellaneous areas that could be mapped individually but are mapped as one unit because similar interpretations can be made for use and management. The pattern and proportion of the soils or miscellaneous areas in a mapped area are not uniform. An area can be made up of only one of the major soils or miscellaneous areas, or it can be made up of all of them. Alpha and Beta soils, 0 to 2 percent slopes, is an example.

Some surveys include *miscellaneous areas*. Such areas have little or no soil material and support little or no vegetation. Rock outcrop is an example.

Custom Soil Resource Report

Lea County, New Mexico**PU—Pyote and Maljamar fine sands****Map Unit Setting**

National map unit symbol: dmqq
Elevation: 3,000 to 3,900 feet
Mean annual precipitation: 10 to 12 inches
Mean annual air temperature: 60 to 62 degrees F
Frost-free period: 190 to 205 days
Farmland classification: Not prime farmland

Map Unit Composition

Pyote and similar soils: 46 percent
Maljamar and similar soils: 44 percent
Minor components: 10 percent
Estimates are based on observations, descriptions, and transects of the mapunit.

Description of Pyote**Setting**

Landform: Plains
Landform position (three-dimensional): Rise
Down-slope shape: Linear
Across-slope shape: Linear
Parent material: Sandy eolian deposits derived from sedimentary rock

Typical profile

A - 0 to 30 inches: fine sand
Bt - 30 to 60 inches: fine sandy loam

Properties and qualities

Slope: 0 to 3 percent
Depth to restrictive feature: More than 80 inches
Drainage class: Well drained
Runoff class: Negligible
Capacity of the most limiting layer to transmit water (Ksat): High (2.00 to 6.00 in/hr)
Depth to water table: More than 80 inches
Frequency of flooding: None
Frequency of ponding: None
Calcium carbonate, maximum content: 5 percent
Gypsum, maximum content: 1 percent
Maximum salinity: Nonsaline to very slightly saline (0.0 to 2.0 mmhos/cm)
Sodium adsorption ratio, maximum: 2.0
Available water supply, 0 to 60 inches: Low (about 5.1 inches)

Interpretive groups

Land capability classification (irrigated): 6e
Land capability classification (nonirrigated): 7s
Hydrologic Soil Group: A
Ecological site: R042XC003NM - Loamy Sand
Hydric soil rating: No

Custom Soil Resource Report

Description of Maljamar**Setting***Landform:* Plains*Landform position (three-dimensional):* Rise*Down-slope shape:* Linear*Across-slope shape:* Linear*Parent material:* Sandy eolian deposits derived from sedimentary rock**Typical profile***A - 0 to 24 inches:* fine sand*Bt - 24 to 50 inches:* sandy clay loam*Bkm - 50 to 60 inches:* cemented material**Properties and qualities***Slope:* 0 to 3 percent*Depth to restrictive feature:* 40 to 60 inches to petrocalcic*Drainage class:* Well drained*Runoff class:* Very low*Capacity of the most limiting layer to transmit water (Ksat):* Very low to moderately low (0.00 to 0.06 in/hr)*Depth to water table:* More than 80 inches*Frequency of flooding:* None*Frequency of ponding:* None*Calcium carbonate, maximum content:* 5 percent*Gypsum, maximum content:* 1 percent*Maximum salinity:* Nonsaline to very slightly saline (0.0 to 2.0 mmhos/cm)*Sodium adsorption ratio, maximum:* 2.0*Available water supply, 0 to 60 inches:* Low (about 5.6 inches)**Interpretive groups***Land capability classification (irrigated):* 6e*Land capability classification (nonirrigated):* 7e*Hydrologic Soil Group:* B*Ecological site:* R042XC003NM - Loamy Sand*Hydric soil rating:* No**Minor Components****Kermit***Percent of map unit:* 10 percent*Ecological site:* R042XC022NM - Sandhills*Hydric soil rating:* No**PY—Pyote soils and Dune land****Map Unit Setting***National map unit symbol:* dmqr*Elevation:* 3,000 to 4,400 feet

Custom Soil Resource Report

Mean annual precipitation: 10 to 15 inches
Mean annual air temperature: 60 to 64 degrees F
Frost-free period: 190 to 220 days
Farmland classification: Not prime farmland

Map Unit Composition

Pyote and similar soils: 46 percent
Dune land: 44 percent
Minor components: 10 percent
Estimates are based on observations, descriptions, and transects of the mapunit.

Description of Pyote**Setting**

Landform: Depressions
Landform position (two-dimensional): Footslope
Landform position (three-dimensional): Base slope
Down-slope shape: Concave
Across-slope shape: Concave
Parent material: Sandy eolian deposits derived from sedimentary rock

Typical profile

A - 0 to 30 inches: fine sand
Bt - 30 to 60 inches: fine sandy loam

Properties and qualities

Slope: 0 to 3 percent
Depth to restrictive feature: More than 80 inches
Drainage class: Well drained
Runoff class: Negligible
Capacity of the most limiting layer to transmit water (Ksat): High (2.00 to 6.00 in/hr)
Depth to water table: More than 80 inches
Frequency of flooding: None
Frequency of ponding: None
Calcium carbonate, maximum content: 5 percent
Gypsum, maximum content: 1 percent
Maximum salinity: Nonsaline to very slightly saline (0.0 to 2.0 mmhos/cm)
Sodium adsorption ratio, maximum: 2.0
Available water supply, 0 to 60 inches: Low (about 5.1 inches)

Interpretive groups

Land capability classification (irrigated): 6e
Land capability classification (nonirrigated): 7s
Hydrologic Soil Group: A
Ecological site: R042XC003NM - Loamy Sand
Hydric soil rating: No

Description of Dune Land**Setting**

Landform: Dunes
Landform position (two-dimensional): Backslope, shoulder
Landform position (three-dimensional): Side slope
Down-slope shape: Convex, linear
Across-slope shape: Convex
Parent material: Sandy eolian deposits derived from sedimentary rock

Custom Soil Resource Report

Typical profile

A - 0 to 6 inches: fine sand
C - 6 to 60 inches: fine sand

Interpretive groups

Land capability classification (irrigated): None specified
Land capability classification (nonirrigated): 8
Hydrologic Soil Group: A
Hydric soil rating: No

Minor Components

Kermit

Percent of map unit: 5 percent
Ecological site: R042XC022NM - Sandhills
Hydric soil rating: No

Maljamar, fine sand

Percent of map unit: 3 percent
Ecological site: R042XC003NM - Loamy Sand
Hydric soil rating: No

Wink

Percent of map unit: 2 percent
Ecological site: R042XC003NM - Loamy Sand
Hydric soil rating: No

References

- American Association of State Highway and Transportation Officials (AASHTO). 2004. Standard specifications for transportation materials and methods of sampling and testing. 24th edition.
- American Society for Testing and Materials (ASTM). 2005. Standard classification of soils for engineering purposes. ASTM Standard D2487-00.
- Cowardin, L.M., V. Carter, F.C. Golet, and E.T. LaRoe. 1979. Classification of wetlands and deep-water habitats of the United States. U.S. Fish and Wildlife Service FWS/OBS-79/31.
- Federal Register. July 13, 1994. Changes in hydric soils of the United States.
- Federal Register. September 18, 2002. Hydric soils of the United States.
- Hurt, G.W., and L.M. Vasilas, editors. Version 6.0, 2006. Field indicators of hydric soils in the United States.
- National Research Council. 1995. Wetlands: Characteristics and boundaries.
- Soil Survey Division Staff. 1993. Soil survey manual. Soil Conservation Service. U.S. Department of Agriculture Handbook 18. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2_054262
- Soil Survey Staff. 1999. Soil taxonomy: A basic system of soil classification for making and interpreting soil surveys. 2nd edition. Natural Resources Conservation Service, U.S. Department of Agriculture Handbook 436. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2_053577
- Soil Survey Staff. 2010. Keys to soil taxonomy. 11th edition. U.S. Department of Agriculture, Natural Resources Conservation Service. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2_053580
- Tiner, R.W., Jr. 1985. Wetlands of Delaware. U.S. Fish and Wildlife Service and Delaware Department of Natural Resources and Environmental Control, Wetlands Section.
- United States Army Corps of Engineers, Environmental Laboratory. 1987. Corps of Engineers wetlands delineation manual. Waterways Experiment Station Technical Report Y-87-1.
- United States Department of Agriculture, Natural Resources Conservation Service. National forestry manual. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/soils/home/?cid=nrcs142p2_053374
- United States Department of Agriculture, Natural Resources Conservation Service. National range and pasture handbook. <http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/landuse/rangepasture/?cid=stelprdb1043084>

Custom Soil Resource Report

United States Department of Agriculture, Natural Resources Conservation Service. National soil survey handbook, title 430-VI. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/soils/scientists/?cid=nrcs142p2_054242

United States Department of Agriculture, Natural Resources Conservation Service. 2006. Land resource regions and major land resource areas of the United States, the Caribbean, and the Pacific Basin. U.S. Department of Agriculture Handbook 296. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2_053624

United States Department of Agriculture, Soil Conservation Service. 1961. Land capability classification. U.S. Department of Agriculture Handbook 210. http://www.nrcs.usda.gov/Internet/FSE_DOCUMENTS/nrcs142p2_052290.pdf

Ecological site R042XC004NM Sandy

Accessed: 01/20/2022

General information




Figure 1. Mapped extent

Areas shown in blue indicate the maximum mapped extent of this ecological site. Other ecological sites likely occur within the highlighted areas. It is also possible for this ecological site to occur outside of highlighted areas if detailed soil survey has not been completed or recently updated.

Table 1. Dominant plant species

Tree	Not specified
Shrub	Not specified
Herbaceous	Not specified

Physiographic features

This site is on uplands, plains, dunes, fan piedmonts, terraces and in inter dunal areas. The parent material consists of mixed alluvium and or eolian sands or calcareous alluvium derived from sedimentary rock. Slope range on this site range from 0 to 9 percent with the average of 5 percent.

Low stabilized dunes may occur occasionally on this site. Elevations range from 2,800 to 5,000 feet.

Table 2. Representative physiographic features

Landforms	(1) Plain (2) Fan piedmont (3) Terrace
Flooding frequency	None
Ponding frequency	None
Elevation	2,842–4,500 ft

Slope	0–5%
Aspect	Aspect is not a significant factor

Climatic features

The average annual precipitation ranges from 8 to 13 inches. Variations of 5 inches, more or less, are common. Over 80 percent of the precipitation falls from April through October. Most of the summer precipitation comes in the form of high intensity short duration thunderstorms.

Temperatures are characterized by distinct seasonal changes and large annual and diurnal temperature changes. The average annual temperature is 61 degrees with extremes of 25 degrees below zero in the winter to 112 degrees in the summer.

The average frost-free season is 207 to 220 days. The last killing frost is in late March or early April, and the first killing frost is in late October or early November.

Temperature and rainfall both favor warm season perennial plant growth. In years of abundant spring moisture, annual forbs and cool season grasses can make up an important component of this site. Strong winds blow from the southwest in January through June which rapidly dries out the soil during a critical period for cool season plant growth.

Climate data was obtained from <http://www.wrcc.sage.dri.edu/summary/climsmnm.html> web site using 50% probability for freeze-free and frost-free seasons using 28.5 degrees F and 32.5 degrees F respectively.

Table 3. Representative climatic features

Frost-free period (average)	200 days
Freeze-free period (average)	219 days
Precipitation total (average)	12 in

Influencing water features

This site is not influenced from water from wetlands or streams.

Soil features

Soils are moderately deep or very deep. Surface textures are loamy fine sand, fine sandy loam, loamy very fine sand or gravelly sandy loam.

Subsurface is a sandy loam, loam, sandy clay loam, clay loam (contains more than 45 percent sand and 18 to 35 percent clay) and less than 15 percent carbonates.

Substratum is a sandy loam, fine sandy loam, sandy clay loam, clay loam, coarse sandy loam, or coarse sand and Calcium carbonate equivalent of 15 to 40 percent. Some layers high in lime or with caliche fragments may occur at depths of 20 to 30 inches.

These soils, if unprotected by plant cover and organic residue, become wind blown and low hummocks are formed. They contains more than 45 percent sand and 18 to 35 percent clay.

Minimum and maximum values listed below represent the characteristic soils for this site.

Characteristic Soils Are:

Anthony
Berino
Cacique
Harkey
Pajaritio

Reakor
 Mobeetie
 Wink
 Sotim
 Vinton
 Drake
 Onite
 Alma
 Poquita
 Dona Ana
 Monahans

Note: *Cacique soils is a shallow soil.

Table 4. Representative soil features

Surface texture	(1) Fine sandy loam (2) Sandy loam (3) Loamy fine sand
Family particle size	(1) Loamy
Drainage class	Well drained to moderately well drained
Permeability class	Moderately rapid to moderately slow
Soil depth	30–72 in
Surface fragment cover ≤3"	0–20%
Surface fragment cover >3"	0%
Available water capacity (0–40in)	3–11 in
Calcium carbonate equivalent (0–40in)	5–30%
Electrical conductivity (0–40in)	0–2 mmhos/cm
Sodium adsorption ratio (0–40in)	0–1
Soil reaction (1:1 water) (0–40in)	6.6–8.4
Subsurface fragment volume ≤3" (Depth not specified)	0–15%
Subsurface fragment volume >3" (Depth not specified)	0%

Ecological dynamics

Overview

The Sandy site often intergrades with the Loamy Sand and Deep Sand sites (SD-3). Sandy sites occur on plains, fans, or terraces between drainages. Slopes average less than five percent. Surface textures are usually sandy loams. The historic plant community of the Sandy site is dominated by black grama (*Bouteloua eriopoda*) and dropseeds (*Sporobolus flexuosus*, *S. contractus*, *S. cryptandrus*). Blue grama (*B. gracilis*) also occurs as a subdominant species. Perennial and annual forb abundance is distributed relative to precipitation occurrence. Litter and to a lesser extent, bare ground, compose a significant proportion of the ground cover while grasses compose the remainder. Decreases in black grama and other grass species' cover indicate a transition to states with an

increased shrub component. Shinnery oak (*Quercus havardii*), sand sage (*Artemisia filifolia*), and honey mesquite (*Prosopis glandulosa*) can all increase in composition. Lehmann lovegrass (*Eragrostis lehmanniana*) also may occur as a result of invasion and competition among grass species. Heavy grazing intensity and/or drought are influential in decreasing grass cover and subsequently increasing shrub cover. Fire suppression further supports shrub cover increase and an advantage over grass species. However, brush and grazing management may restore grass species and reverse shrub or grass/shrub dominated states back toward the historic plant community.

State and transition model

Plant Communities and Transitional Pathways (diagram)




Figure 6.

State 1**Historic Climax Plant Community****Community 1.1****Historic Climax Plant Community**

Grassland: The historic plant community is composed primarily of black grama, dropseeds, and a secondary component of blue grama. Black grama tends to dominate due to the predominance of sandy loam soils; however, dropseeds increase on more loamy soils. Perennial and annual forbs are common but their abundance and distribution are dependent on seasonal precipitation. Historical fire frequency is unknown but probably contributed to shrub reduction to the competitive advantage of grass species. Excessive grazing and drought are likely the dominant drivers that decrease black grama and increase dropseed and threeawn abundance within the historic plant community. Black grama has low seed viability, and therefore, reproduces vegetatively during the summer growing season. However, black grama growth is delayed one season after normal precipitation. Black grama is dormant for the remainder of the year; however, black grama retains nutritive value yearlong for grazing. In contrast, dropseeds have relatively abundant, viable seed production and can benefit from early spring as well as summer precipitation. Threeawns also respond to spring and summer moisture and tend to be the year's first palatable species. Threeawns and dropseeds, however, are not palatable during dormant periods, which extends grazing pressure to black grama. Moderate to heavy grazing reduces vegetative cover of black grama which increases its susceptibility to wind erosion and drought (Canfield 1939). Black grama is especially vulnerable to grazing during the summer growing season when stoloniferous growth and rooting occur. Black grama sustains short droughts through reduction of plant tufts which will subsequently emerge with sufficient moisture. Prolonged drought or grazing concurrently under drought conditions can delay or impede recovery of black grama (Nelson 1934) and increase abundance of dropseeds, threeawns, and blue grama. Historical fire events may have benefited black grama, especially, frequent, light intensity/severity fires in conjunction with sufficient moisture to increase stolon production (McPherson 1995). Fires which were hot and severe, however, probably contributed to black grama mortality, more so in drought conditions.

Diagnosis: This state is a grassland dominated by black grama, dropseeds, and threeawns, with subdominant blue grama. Shrubs, such as sand sage and mesquite, are sparsely dispersed throughout the grassland. Forb populations are present and fluctuate with precipitation variability.

Other grasses that could appear on this site include: fall withchgrass, slim tridens, Almejita signalgrass, Indian ricegrass and fluffgrass.

Other shrubs include: pale wolfberry, lotebush, tarbush, Apacheplume, and mesquite.

Other forbs include: plains tickseed, plains blackfoot, scorpionweed, nama, wooly guara, wooly dalea, spectaclepod mustard, bladderpod mustard, menodora, prickly lettuce, lambsquarter, wooly Indianwheat and wild buckwheat.

Table 5. Annual production by plant type

Plant Type	Low (Lb/Acre)	Representative Value (Lb/Acre)	High (Lb/Acre)
Grass/Grasslike	480	720	960
Forb	90	135	180
Shrub/Vine	30	45	60
Total	600	900	1200

Table 6. Ground cover

Tree foliar cover	0%
Shrub/vine/liana foliar cover	0%
Grass/grasslike foliar cover	35-40%
Forb foliar cover	0%
Non-vascular plants	0%

Biological crusts	0%
Litter	35-45%
Surface fragments >0.25" and <=3"	0%
Surface fragments >3"	0%
Bedrock	0%
Water	0%
Bare ground	15-20%

Figure 8. Plant community growth curve (percent production by month). NM2804, R042XC004NM-Sandy-HCPC. SD-3 Sandy - Warm season plant community .

Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec
0	1	3	4	10	10	25	30	12	5	0	0

State 2 Shinnery Oak Dominated

Community 2.1 Shinnery Oak Dominated

Shinnery Oak Dominated: This state is dominated by Shinnery oak with subdominant grass species from the historic plant community. Bare ground is a significant component in this state. Shinnery oak tends to be clumped in distribution in finer soil textures. Shinnery oak density increases (as well as dropseeds, threeawns, and blue grama) in coarse textured (e.g., Loamy Sand sites) and deeper, coarse textured (e.g., Deep Sand and Sandhills sites) soils. Shinnery oak predominates during periods of above average (i.e., 16 in.) precipitation during the months of July and August. Abundance and distribution also increases with disturbance, such as excessive grazing and fire, due to an aggressive rhizome system. Shinnery oak's extensive root system allows competitive exclusion of grasses and forbs. Brush control with herbicide treatments applied in the spring can reduce Shinnery oak (Herbel et al. 1979, Pettit 1986). In addition, repetitive seasons of goat browsing can also decrease Shinnery oak abundance. However, brush management should maintain shrub patches to prevent erosion and to provide wildlife cover and forage.

Diagnosis: This state represents a clumped distribution of Shinnery oak with patches of bare ground and subdominant grass species, such as black grama, dropseeds, threeawns, and blue grama. Shinnery oak density increases, as do dropseeds, threeawns, and blue grama, as Sandy site intergrades with Deep Sand and Sandhills sites.

Transition to Shinnery Oak-Dominated State (1a): Decrease in black grama with subsequent decrease in dropseeds and threeawns. Increase in Shinnery oak as a result of drought, above average precipitation (>16 inches), grazing, fire suppression, interspecific competition, and coarse textured soils.

Key indicators of approach to transition:

- Loss of black grama and other grass species cover
- Increase of dropseed/threeawn and shinnery oak
- Surface soil erosion and bare patch expansion

Transition to Historic Plant Community (1b): The Shinnery oak-dominated state begins to transition toward the historic plant community as drivers such as drought, but also above average precipitation (e.g., 16 inches) discontinue. Brush control can also drive the Shinnery oak state toward a grassland state.

State 3 Sand Sage Dominated

Community 3.1

Sand Sage Dominated

Sand Sage Dominated: This state is dominated by sand sage with subdominant grass species from the historic plant community. Sand sage occurs as a result of insufficient herbicide application in Shinnery oak dominated sites with subdominant sand sage. Sand sage either reestablishes dominance or colonizes from an off-site location and stabilizes soils. Sand sage stabilizes light sandy soils from wind erosion and provides a harbor for grass and forb species in heavily grazed conditions (Davis and Bonham 1979). Sand sage abundance increases with drought and/or heavy grazing, but decreases with light grazing due to herbaceous plant competition. Grass and forb species can reestablish as competition from sand sage is relatively light. Herbicide applied in the spring, especially when growth and photosynthesis rates are greatest, can reduce sand sage if there is subsequent rest from grazing (Herbel et al. 1979, Pettit 1986). Brush management should maintain patches of sand sage to prevent wind erosion and subsequent dune formation.

Diagnosis: This state is dominated by sand sage with subdominant grass species, such as black grama, dropseeds, threeawns, and blue grama. Sand sage tends to occur in sites with coarser textured soils.

Transition to Sand Sage Dominated (2): Sand sage appears from off-site locations and/or increases after insufficient herbicide applications aimed at removing Shinnery oak and sand sage.

Key indicators of approach to transition:

- Increase of sand sage seedlings and grasses
- Reduced soil erosion

Transition to Historic Plant Community (3): The sand sage dominated state transitions toward the historic plant community as sand sage decreases primarily through brush management but also with light intensity grazing management. Drought reduction will also support a transition to the historic plant community.

State 4

Lehmann Lovegrass + Natives

Community 4.1

Lehmann Lovegrass + Natives

Lehmann Lovegrass + Natives: This state is dominated by Lehmann lovegrass with subdominant grass species from the historic plant community. Lehmann lovegrass is a warm-season, perennial bunchgrass that was introduced from South Africa in the 1930's for rangeland restoration purposes (Humphrey 1970). Lehmann lovegrass invades from off-site locations with projects utilizing lovegrass for reseeding, soil stabilization, or highway projects. Lehmann lovegrass provides a winter and early spring forage for grazing. Lehmann lovegrass is vigorous in sandy to sandy loam soils which receive approximately 6-8 inches of summer precipitation (Cox et al. 1988). Lehmann lovegrass's aggressive competitive exclusion of native grass species has been attributed to lovegrass's low summer palatability, which reduces vigor of native species and allows lovegrass to increase vigor before grazing. Also, Lehmann lovegrass abundant seed production and establishment, especially after disturbances, allows for increased competition (Cable 1971, Cox et al. 1981). Lehmann lovegrass generally is tolerant to fire because of an aggressive seed-bank; however, severe fires can cause mature lovegrass mortality (Sumrall et al. 1991). Herbicide and reseeding is recommended for control of Lehmann lovegrass (Winn 1991).

Diagnosis: Lehmann lovegrass and grass species from the historic plant community, such as black grama, dropseeds, threeawns, and blue grama, dominate this state.

Transition to Lehmann lovegrass and native grass species (4a): Decrease in black grama with subsequent decrease in dropseeds and threeawns. Increase in Lehmann lovegrass as a result of drought, grazing, fire and interspecific competition from nearby sources of Lehmann lovegrass.

Key indicators of approach to transition:

- Loss of black grama and other grass species cover
- Disturbance and nearby source of Lehmann lovegrass
- Increase of Lehmann lovegrass seedlings

Transition to Historic Plant Community (4b): The Lehmann lovegrass/native grass state transitions toward the historic plant community after actions such as herbicide application and native reseeding have occurred. In addition, prevention of disturbances such as fire and livestock grazing also will encourage the transition to a native grass community

State 5 Grass/Mesquite

Community 5.1 Grass/Mesquite

Grass/Mesquite: This state is dominated by honey mesquite with dropseeds and/or threeawns. Black grama generally is rare as a result of heavy grazing intensity. Honey mesquite invades through seed dispersal from grazing livestock and/or wildlife. Dropseeds and threeawns cohabitate with mesquite due to sufficient precipitation. Mesquite tends to be arborescent due to less soil erosion relative to the Coppice Dunes state which reflects large soil loss. Mesquite obtains approximately half of its nitrogen from symbiotic bacteria housed in root nodules (Lajtha and Schlesinger 1986). Mesquite also provides nitrogen and soil organic matter to co-dominant grasses (Ansley and Jacoby 1998, Ansley et al. 1998). Historical fire occurrences reduced mesquite abundance by disrupting seed production cycles and suppressing seedlings; thus, grass species remained dominant. However, fire suppression has allowed mesquite to increase in density and abundance, increasing mesquite resistance to fires through aggressive resprouting. Herbicide application combined with subsequent prescribed fire may be effective in mesquite reduction (Britton and Wright 1971).

Diagnosis: This state is co-dominated by honey mesquite and dropseeds or threeawns.

Transition to Grass/Mesquite State (5a): This state occurs due to a decrease in black grama primarily from heavy grazing intensity and from an introduction of mesquite seeds from grazers. Dropseeds and threeawns increase and co-exist in the absence of black grama. Fire suppression also is responsible for an increase in mesquite.

Key indicators of approach to transition:

- Loss of black grama
- Increase of dropseeds and/or threeawns
- Increase of mesquite seedlings

Transition to Historic Plant Community (5b): Transition to the historic plant community requires brush management though herbicide application and possibly prescribed fire to reduce mesquite abundance. Once shrub species are removed, prescribed fire may be useful in maintaining a dominant grassland. Precipitation is also necessary in conjunction with management activities to support a dominant grassland.

State 6 Coppice Dunes

Community 6.1 Coppice Dunes

Coppice Dunes: This state is dominated by coppice mesquite dunes with minimal or no grass cover. Honey mesquite occurs in a multi-stemmed growth form which cultivates its dune formation by entrapping drifting sands. Mesquite utilizes its extensive tap and lateral roots to benefit from moisture deep in coarse textured soils. Grass species cannot compete for moisture, especially with compounding perturbations such as heavy grazing and drought. Soils succumb to wind erosion with the depletion of grass cover and eventually dunes form around mesquite plants (Gould 1982). Brush management is limited to herbicide application, biological control, or manual removal, as a lack of grass cover prevents prescribed burning. Seeding subsequent to brush control may transition this State toward the historic plant community.

Diagnosis: This state is characterized by low growing, multi-stemmed mesquite plants which form Coppice dunes by drifting soils from wind erosion. As grass cover decreases, windblown soils are removed from unprotected, inter-dune areas. Soils are then re-deposited on dunes which increases dune size.

Transition to Mesquite Coppice Dunes State (6): Decrease in black grama with subsequent decrease in dropseeds and threeawns due to competition with mesquite especially during drought, heavy grazing, and fire suppression. Competitive exclusion of grasses leads to wind erosion of sandy soils and dune formation of low growing mesquite plants.

Key indicators of approach to transition:

- Loss of black grama and other grass species cover
- Wind erosion as evidenced by pedestalled plants
- Bare patch expansion
- Increase of Coppice dune mesquites

Transition to Historic Plant Community (7): Transition toward the historic plant community requires mesquite removal though either herbicide application, biological control, or manual removal. In addition, seeding of native grass species with subsequent years of sufficient moisture is critical.

Additional community tables

Table 7. Community 1.1 plant community composition

Group	Common Name	Symbol	Scientific Name	Annual Production (Lb/Acre)	Foliar Cover (%)
Grass/Grasslike					
1	Warm Season			315–360	
	black grama	BOER4	<i>Bouteloua eriopoda</i>	315–360	–
2	Warm Season			45–90	
	blue grama	BOGR2	<i>Bouteloua gracilis</i>	45–90	–
3	Warm Season			27–45	
	bush muhly	MUPO2	<i>Muhlenbergia porteri</i>	27–45	–
4	Warm Season			90–135	
	spike dropseed	SPCO4	<i>Sporobolus contractus</i>	90–135	–
	sand dropseed	SPCR	<i>Sporobolus cryptandrus</i>	90–135	–
	mesa dropseed	SPFL2	<i>Sporobolus flexuosus</i>	90–135	–
5	Warm Season			27–45	
	threeawn	ARIST	<i>Aristida</i>	27–45	–
6	Warm Season			27–45	
	plains bristleglass	SEVU2	<i>Setaria vulpiseta</i>	27–45	–
7	Warm Season			27–45	
	Arizona cottontop	DICA8	<i>Digitaria californica</i>	27–45	–
8	Warm Season			45–72	
	silver bluestem	BOSA	<i>Bothriochloa saccharoides</i>	45–72	–
	little bluestem	SCSC	<i>Schizachyrium scoparium</i>	45–72	–
9	Warm Season			9–27	
	vine mesquite	PAOB	<i>Panicum obtusum</i>	9–27	–
10	Warm Season			9–27	
	tobosagrass	PLMU3	<i>Pleuraphis mutica</i>	9–27	–
11	Other Perennial Grasses			9–27	
	Grass, perennial	2GP	<i>Grass, perennial</i>	9–27	–
Shrub/Vine					
12	Shrub			9–45	

	yucca	YUCCA	<i>Yucca</i>	9–45	–
13	Shrub			9–27	
	catclaw mimosa	MIACB	<i>Mimosa aculeaticarpa</i> var. <i>biuncifera</i>	9–27	–
14	Shrub			9–27	
	fourwing saltbush	ATCA2	<i>Atriplex canescens</i>	9–27	–
15	Shrub			9–27	
	jointfir	EPHED	<i>Ephedra</i>	9–27	–
16	Shrub			9–27	
	javelina bush	COER5	<i>Condalia ericoides</i>	9–27	–
17	Shrub			9–27	
	sand sagebrush	ARFI2	<i>Artemisia filifolia</i>	9–27	–
	broom snakeweed	GUSA2	<i>Gutierrezia sarothrae</i>	9–27	–
18	Other Shrubs			9–27	
	Shrub (>.5m)	2SHRUB	<i>Shrub (>.5m)</i>	9–27	–
Forb					
19	Forb			27–63	
	croton	CROTO	<i>Croton</i>	27–63	–
	globemallow	SPHAE	<i>Sphaeralcea</i>	27–63	–
20	Forb			27–45	
	curlycup gumweed	GRSQ	<i>Grindelia squarrosa</i>	27–45	–
	woolly groundsel	PACA15	<i>Packera cana</i>	27–45	–
21	Forb			9–27	
	Adonis blazingstar	MEMU3	<i>Mentzelia multiflora</i>	9–27	–
22	Forb			27–45	
	redstem stork's bill	ERIC16	<i>Erodium cicutarium</i>	27–45	–
	Texas stork's bill	ERTE13	<i>Erodium texanum</i>	27–45	–
23	Other Forbs			9–27	
	Forb (herbaceous, not grass nor grass-like)	2FORB	<i>Forb (herbaceous, not grass nor grass-like)</i>	9–27	–

Animal community

This site provides habitat which support a resident animal community that is characterized by pronghorn antelope, black-tailed jackrabbit, spotted ground squirrel, black-tailed prairie dog, yellow-faced pocket gopher, Ord's kangaroo rat, Northern grasshopper mouse, southern plains woodrat, badger, meadowlark, roadrunner, burrowing owl, white-necked raven, cactus wren, pyrrhuloxia, lesser prairie chicken, mourning dove, scaled quail, Harris' hawk, side-blotched lizard, marbled whiptail, Texas horned lizard, prairie rattlesnake, plains spadefoot toad, and ornate box turtle.

Hydrological functions

The runoff curve numbers are determined by field investigations using hydraulic cover conditions and hydrologic soil groups.

Hydrologic Interpretations

Soil Series Hydrologic Group

Anthony B

Berino B

Cacique C *shallow soil
Harkey B
Pajaritio B
Reakor B
Mobeetie B
Wink B
Sotim B
Vinton B
Drake B
Onite B
Alma B
Poquita B
Dona Ana B
Monahans B

Recreational uses

This site offers recreation potential for hiking, horseback riding, nature observation, and photography, bird, antelope and predator hunting. During years of abundant spring moisture, this site displays a colorful array of wildflowers.

Wood products

This site has no potential for wood products.

Other products

This site is suitable for grazing by all classes and kinds of livestock during all seasons of the year. Under retrogression, plants such as black grama, blue grama, bush muhly, plains bristlegrass, Arizona cottontop, vine mesquite, little bluestem and fourwing saltbush will decrease while the dropseeds, threeawns, tobosa, yucca, catclaw mimosa, javelinabush, mesquite and broom snakeweed will increase. This site responds well to brush management and deferment. It is best suited to a system of management that rotates the season of use.

Other information

Guide to Suggested Initial Stocking Rate Acres per Animal Unit Month

Similarity Index Ac/AUM
100 - 76 2.7 – 3.8
75 – 51 3.5 – 5.0
50 – 26 5.0 – 8.0
25 – 0 8.1 +

Inventory data references

Other References:

Data collection for this site was done in conjunction with the progressive soil surveys within the Southern Desertic Basins, Plains and Mountains, Major Land Resource Areas of New Mexico. This site has been mapped and correlated with soils in the following soil surveys. Eddy County, Lea County, and Chaves County.

Other references

Other References:

Data collection for this site was done in conjunction with the progressive soil surveys within the Southern Desertic Basins, Plains and Mountains, Major Land Resource Areas of New Mexico. This site has been mapped and correlated with soils in the following soil surveys. Eddy County, Lea County, and Chaves County.

Literature Cited

Ansley, R. J.; Jacoby, P. W. 1998. Manipulation of fire intensity to achieve mesquite management goals in north Texas. In: Pruden, Teresa L.; Brennan, Leonard A., eds. Fire in ecosystem management: shifting the paradigm from suppression to prescription: Proceedings, Tall Timbers fire ecology conference; 1996 May 7-10; Boise, ID. No. 20. Tallahassee, FL: Tall Timbers Research Station:195-204.

Ansley, R. J.; Jones, D. L.; Tunnell, T. R.; [and others]. 1998. Honey mesquite canopy responses to single winter fires: relation to herbaceous fuel, weather and fire temperature. International Journal of Wildland Fire 8(4):241-252.

Britton, Carlton M.; Wright, Henry A. 1971. Correlation of weather and fuel variables to mesquite damage by fire. Journal of Range Management 24:136-141.

Cable, Dwight R. 1971. Lehmann lovegrass on the Santa Rita Experimental Range, 1937-1968. Journal of Range Management 24:17-21.

Canfield, R. H. 1939. The effect of intensity and frequency of clipping on density and yield of black grama and tobosa grass. Tech. Bull. 681. Washington, DC: U.S. Department of Agriculture. 32 p.

Cox, Jerry R.; Ruyle, G.B.; Fourle, Jan H.; Donaldson, Charlie. 1988. Lehmann lovegrass—central South Africa and Arizona, USA. Rangelands 10(2):53-55

Contributors

Don Sylvester
Quinn Hodgson

Rangeland health reference sheet

Interpreting Indicators of Rangeland Health is a qualitative assessment protocol used to determine ecosystem condition based on benchmark characteristics described in the Reference Sheet. A suite of 17 (or more) indicators are typically considered in an assessment. The ecological site(s) representative of an assessment location must be known prior to applying the protocol and must be verified based on soils and climate. Current plant community cannot be used to identify the ecological site.


Author(s)/participant(s)	
Contact for lead author	
Date	
Approved by	
Approval date	
Composition (Indicators 10 and 12) based on	Annual Production

Indicators

1. Number and extent of rills:

2. Presence of water flow patterns:

3. Number and height of erosional pedestals or terracettes:



USGS The National Map: National Boundaries Dataset, 3DEP Elevation Program, Geographic Names Information System, National Hydrography Dataset, National Land Cover Database, National Structures Dataset, and National Transportation Dataset; USGS Global Ecosystems; U.S. Census Bureau TIGER/Line data; USFS Road Data; Natural Earth Data; U.S. Department of State Humanitarian Information Unit; and NOAA National Centers for Environmental Information, U.S. Coastal Relief Model. Data refreshed August, 2021., Sources: Esri, Airbus DS, USGS, NOAA, NASA, CGIAR, INR, Robinson, NCEAS, NLS, OS, NMA, Geodatastyrelsen, Rijkswaterstaat, GSA, Geoland, FEMA, Intermap and the GIS user community, NMBGMR

ATTACHMENT 4



Dhugal Hanton <vertexresourcegroupusa@gmail.com>

48-HR Notification Billiken 6 CTB 1, Gaucho Unit 30 CTB 1, Green Wave 20 CTB 9 Liner Inspections

Dhugal Hanton <vertexresourcegroupusa@gmail.com>

Thu, Jan 13, 2022 at 1:52 PM

To: EMNRD-OCD-District1spills <emnrd-ocd-district1spills@state.nm.us>, "CFO_Spill, BLM_NM" <blm_nm_cfo_spill@blm.gov>, "Enviro, OCD, EMNRD" <OCD.Enviro@state.nm.us>

Cc: wesley.mathews@dvn.com, dale.woodall@dvn.com

Bcc: Jramirez@vertex.ca, bschafer@vertex.ca

All,

Please accept this email as 48-hr notification that Vertex Resource Services has scheduled 3 liner inspections to be conducted for the following releases:

nAPP2129845429 DOR: 10/24/2021 Site Name: Green Wave 20 CTB 9

nAPP2134155628 DOR: 12/3/2021 Site Name: Billiken 6 CTB 1

nAPP2131553617 DOR: 11/5/2021 Site Name: Gaucho Unit 30 CTB 1

This work will be completed on behalf of Devon Energy Production Company.

On Friday, January 21, 2022 at approximately 8:00 a.m., John Ramirez will be on the first site to conduct a liner inspection and continue them throughout the day. He can be reached at 575-725-1809. If you need directions to the sites, please do not hesitate to contact him. If you have any questions or concerns regarding this notification, please give me a call at 701-301-1564.

Thank you,

Brandon Schafer

Project Manager

Vertex Resource Services Inc.

P 701.645.3111 Ext. 706**C 701.301.1564****F 780.464.3731**www.vertex.ca

Confidentiality Notice: This message and any attachments are solely for the intended recipient and may contain confidential or privileged information. If you are not the intended recipient, any disclosure, copying, use, or distribution of the information included in this message and any attachment is prohibited. If you have received this communication in error, please notify us by reply email and immediately and permanently delete this message and any attachments. Thank you. '%!%{

ATTACHMENT 5



Daily Site Visit Report

Client:	Devon Energy Corporation	Inspection Date:	1/21/2022
Site Location Name:	Billiken 6 CTB 1	Report Run Date:	1/21/2022 10:59 PM
Client Contact Name:	Wes Matthews	API #:	
Client Contact Phone #:	(575) 748-0176		
Unique Project ID		Project Owner:	
Project Reference #		Project Manager:	

Summary of Times

Arrived at Site	1/21/2022 9:55 AM
Departed Site	1/21/2022 10:20 AM

Field Notes

- 10:56** Arrived on site to perform liner inspection.
- 11:05** Inside and outside of the wall dike does not appear to have any significant damage.
- 11:09** The bottom of the containment does not appear to have any significant damage around and between the tanks.
- 11:09** There's is nothing that I see that brings up any environmental concern.

Next Steps & Recommendations

- 1 No recommendations at this time.

Daily Site Visit Report



Site Photos

Viewing Direction: South



Outside the wall dike east side.

Viewing Direction: Northwest



Inside the wall dike west side.

Viewing Direction: Northeast



Inside the wall dike north side.

Viewing Direction: South



West side of the containment.



Daily Site Visit Report

Viewing Direction: East



Bottom of containment between tanks 451 and 413

Viewing Direction: East



Bottom of containment between tanks 413 and 452

Viewing Direction: East



Bottom of containment between tanks 452 and 453

Viewing Direction: North



Bottom of containment between all tanks N-S



Daily Site Visit Report

Viewing Direction: East



Outside the wall dike north side.

Viewing Direction: North



Outside the wall dike west side.

Viewing Direction: East



Outside the wall dike south side.

Viewing Direction: North



Inside the wall dike east side.



Daily Site Visit Report

Viewing Direction: North



East side of the containment.

Viewing Direction: Southwest



South side of the containment.

Viewing Direction: Southeast



South side of the containment.

Viewing Direction: Southwest



Inside the wall dike south side.

Daily Site Visit Report



Daily Site Visit Signature

Inspector: Chance Dixon

Signature:

A handwritten signature in black ink, appearing to be 'CD'.

Signature

ATTACHMENT 6

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nAPP2134155628
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party Devon Energy Production Company	OGRID 6137
Contact Name Dale Woodall	Contact Telephone
Contact email Dale.Woodall@dvn.com	Incident # (assigned by OCD)
Contact mailing address 6488 Seven Rivers Hwy Artesia, NM 88210	

Location of Release Source

Latitude 32.076535 Longitude -103.411171
(NAD 83 in decimal degrees to 5 decimal places)

Site Name Billiken 6 CTB 1	Site Type Oil
Date Release Discovered 12/03/2021	API# (if applicable)

Unit Letter	Section	Township	Range	County
D	6	23S	35E	Lea

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 236.28 BBLS	Volume Recovered (bbls) 236.28 BBLS
	Is the concentration of total dissolved solids (TDS) in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release Leak developed in flowline. Fluid remained in lined containment.

Incident ID	nAPP2134155628
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? The spill is over 25 BBLs.
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Notice given by Dale Woodall to OCD.	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why: 	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Kendra DeHoyos</u>	Title: <u>EHS Associate</u>
Signature: <u>Kendra DeHoyos</u>	Date: <u>12/22/2021</u>
email: <u>Kendra.Ruiz@dvn.com</u>	Telephone: <u>575-748-0167</u>
<u>OCD Only</u>	
Received by: <u>Ramona Marcus</u>	Date: <u>12/27/2021</u>

NAPP2134155628

Spills In Lined Containment	
Measurements Of Standing Fluid	
Length(Ft)	100
Width(Ft)	53
Depth(in.)	4
Total Capacity without tank displacements (bbls)	314.66
No. of 500 bbl Tanks In Standing Fluid	7
No. of Other Tanks In Standing Fluid	1
OD Of Other Tanks In Standing Fluid(feet)	
Total Volume of standing fluid accounting for tank displacement.	236.28

District I
 1626 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-8101 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-8720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6176 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3482

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 88440

CONDITIONS

Operator: DEVON ENERGY PRODUCTION COMPANY, LP 333 West Sheridan Ave. Oklahoma City, OK 73102	OGRID:
	8197
	Action Number: 88440
Action Type: [C-141] Release Corrective Action (C-141)	

CONDITIONS

Created By	Condition	Condition Date
marcus	None	12/27/2021

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nAPP2134155628
District RP	
Facility ID	
Application ID	

Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	<u><50</u> (ft bgs)
Did this release impact groundwater or surface water?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within 300 feet of a wetland?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release overlying a subsurface mine?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release overlying an unstable area such as karst geology?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within a 100-year floodplain?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Did the release impact areas not on an exploration, development, production, or storage site?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No

Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.

Characterization Report Checklist: *Each of the following items must be included in the report.*

- ☒ Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells.
- ☒ Field data
- N/A Data table of soil contaminant concentration data
- ☒ Depth to water determination
- ☒ Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release
- N/A Boring or excavation logs
- ☒ Photographs including date and GIS information
- ☒ Topographic/Aerial maps
- N/A Laboratory data including chain of custody

State of New Mexico
Oil Conservation Division

Incident ID	nAPP2134155628
District RP	
Facility ID	
Application ID	

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Dale Woodall

Title: EHS Professional

Signature: Dale Woodall
Dale Woodall (Feb 3, 2022 15:52 MST)

Date: Feb 3, 2022

email: Dale.Woodall@dm.com

Telephone: 575-748-1838

OCD Only

Received by: _____

Date: _____

Incident ID	nAPP2134155628
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: *Each of the following items must be included in the closure report.*

- ☒ A scaled site and sampling diagram as described in 19.15.29.11 NMAC
- ☒ Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- ☒ Laboratory analyses of final sampling (Note: appropriate OCD District office must be notified 2 days prior to final sampling)
- ☒ Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Dale Woodall

Title: EHS Professional

Signature: Dale Woodall
Dale Woodall (Feb 3, 2022 15:52 MST)

Date: Feb 3, 2022

email: Dale.Woodall@dvn.com

Telephone: 575-748-1838

OCD Only

Received by: _____

Date: _____

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by: _____ Date: _____

Printed Name: _____

Title: _____

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 79957

CONDITIONS

Operator: DEVON ENERGY PRODUCTION COMPANY, LP 333 West Sheridan Ave. Oklahoma City, OK 73102	OGRID: 6137
	Action Number: 79957
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
chensley	Closure report approved.	2/23/2022
chensley	NOTE: The OCD requires a copy of all correspondence relative to remedial projects be included in all proposal and/or final closure reports. Correspondence required to be included in reports may include, but not necessarily limited to, extension requests, liner inspection notifications, sample event notifications, spill/release/fire notifications, and variance requests. This will allow for notifications and requests to become a documented part of the incident file.	2/23/2022