

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

OCT 20 2014

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1429431024

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC # 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Honey Graham State Com #1H	Facility Type: Battery

Surface Owner: State	Mineral Owner: State	API No. 30-015-37465
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	29	26S	28E	330	North	660	West	Eddy

Latitude 32.018610330935 Longitude -104.11702930695

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 353 bbls Oil ; 60 bbls PW	Volume Recovered: 0 bbls Oil ; 0 bbls PW
Source of Release: Flood damaged battery	Date and Hour of Occurrence: 9/19/2014	Date and Hour of Discovery: 10-6-2014 12:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - OCD	
By Whom? Robert McNeill	Date and Hour: 9/22/2014 8:00 am (phone call)	
Was a Watercourse Reached? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse. Unknown	



If a Watercourse was Impacted, Describe Fully.*
Torrential rains caused flood waters to rise. Waters over ran the location, broke tank drain lines. This location was inaccessible for several weeks.

Describe Cause of Problem and Remedial Action Taken.*

Describe Area Affected and Cleanup Action Taken.*

The impacted area shows no signs of hydrocarbon or brine impact. Once the area dries out and is accessible to heavy equipment we will conduct a more thorough search of the area for hydrocarbon impact. Equipment will be removed from the draw and disposed of at an NMOCD approved facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 10/21/14	Expiration Date: NA
E-mail Address: atrujillo@concho.com	Conditions of Approval:	
Date: October 20, 2014 Phone: 575-748-6940	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 11/21/14

2RP-2559

Bratcher, Mike, EMNRD

From: Amanda Trujillo <ATrujillo@concho.com>
Sent: Monday, October 20, 2014 5:00 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Subject: (Initial C-141) Honey Graham State Com #1H (30-015-37465)
Attachments: 10-6-2014 Honey Graham State Com #1H (TB) Initial.pdf

Mr. Bratcher,

COG Operating LLC is reported the release at the **Honey Graham State Com #1H (30-015-37465)** on 9/22/2014 by phone.

Unit D Section 29 Township 26S Range 28E

The release occurred on 09/19/2014.

Released: 353 bbls Oil; 60 bbls Produced Water

Recovered: 0 bbls Recovered

This release was caused by torrential rains. Waters over ran the location, braking the tank drain lines. This location was in accessible for several weeks. Attached is a C-141 Initial for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

Amanda Trujillo

Senior Environmental Coordinator

COG Operating LLC

Cell: 505.350.1336

Office: 575.748.6930

atrujillo@concho.com

2208 W. Main St.

Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Incident ID	NAB1429431024
District RP	2RP-2559
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: *Each of the following items must be included in the closure report.*

- ☐ A scaled site and sampling diagram as described in 19.15.29.11 NMAC
- ☐ Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- ☐ Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)
- ☐ Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Ike Tavaréz Title: Staff Program Manager
Signature: *Ike Tavaréz* Date: 1/12/2022
email: Ike. Tavaréz@ConocoPhillips.com Telephone: (432) 701-8630

OCD Only

Received by: _____ Date: _____

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by: *Bradford Billings* Date: 03/04/2022
Printed Name: Bradford Billings Title: Envi.Spec.A

From: [Tavarez, Ike](#)
To: [Abbott, Sam](#)
Cc: [Gonzales, Clair](#)
Subject: FW: [EXTERNAL] RE: [EXTERNAL]NAB14294331624 Honey Graham
Date: Thursday, January 13, 2022 2:37:35 PM

CAUTION: This email originated from an external sender. Verify the source before opening links or attachments.

Sam,

Here is Brad's response on the Honey Graham project. I have attached the initial and final C-141 for submittal. After submittal, send Brad an email to notify him the submittal is complete so he can pull C-141 and sign to close out the project. Call me if we need to discuss, Thanks

Ike Tavarez, P. G. | Risk Management & Remediation | ConocoPhillips
O:432-685-2573 | C:432-701-8630 | [600 W. Illinois Avenue, Midland, Texas 79701](#)

From: Billings, Bradford, EMNRD <Bradford.Billings@state.nm.us>
Sent: Thursday, January 13, 2022 12:57 PM
To: Tavarez, Ike <Ike.Tavarez@conocophillips.com>
Subject: RE: [EXTERNAL] RE: [EXTERNAL]NAB14294331624 Honey Graham

You bet

From: Tavarez, Ike <Ike.Tavarez@conocophillips.com>
Sent: Thursday, January 13, 2022 11:56 AM
To: Billings, Bradford, EMNRD <Bradford.Billings@state.nm.us>
Subject: [EXTERNAL] RE: [EXTERNAL]NAB14294331624 Honey Graham

CAUTION: This email originated outside of our organization. Exercise caution prior to clicking on links or opening attachments.

Perfect. I had sent Mike the initial C-141 and attached the final closure C-141 (new format) with it. I will submit it into the portal and let you know when completed. Thanks for the quick response.

Ike Tavarez, P. G. | Risk Management & Remediation | ConocoPhillips
O:432-685-2573 | C:432-701-8630 | [600 W. Illinois Avenue, Midland, Texas 79701](#)

From: Billings, Bradford, EMNRD <Bradford.Billings@state.nm.us>
Sent: Thursday, January 13, 2022 12:49 PM
To: Tavarez, Ike <Ike.Tavarez@conocophillips.com>
Subject: [EXTERNAL]NAB14294331624 Honey Graham

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Hi Ike,

Mike asked me to deal with this, the following:

You need to copy the C-141 and make sure to mark it Final (can use the old form) and submit it to the portal. It can be closed from there. Make sure you let me know this has happened (the submittal) so I can pull it out for my response. Thanks.

Bradford

Bradford Billings • Enviro. Spec. A
Environmental Bureau
EMNRD - Oil Conservation Division
5200 Oakland Ave. NE Suite 100 | Albuquerque, NM 87113
505.670.6549. jbradford.billings@state.nm.us
<http://www.emnrd.state.nm.us/OCD/>

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 72504

CONDITIONS

Operator: COG OPERATING LLC 600 W Illinois Ave Midland, TX 79701	OGRID: 229137
	Action Number: 72504
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
bbillings	None	3/4/2022