District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

| Incident ID | nAPP2218939473 |
|----------------|----------------|
| District RP | |
| Facility ID | |
| Application ID | |

Release Notification

Responsible Party

| Responsible Party | OXY USA INC. | OGRID | 16696 |
|-------------------------|--------------------------|------------------------------|----------------|
| Contact Name | WADE DITTRICH | Contact Telephone | (575) 390-2828 |
| Contact email | WADE_DITTRICH@OXY.COM | Incident # (assigned by OCD) | |
| Contact mailing address | PO BOX 4294; HOUSTON, TX | 77210 | |
| | | | |

Location of Release Source

| Latitude | N 32.1 | 132 | (NAD 83 in d | Longitud ecimal degrees to 5 de | W 103.940292 cimal places) | | |
|---|------------|---------------------------|------------------|------------------------------------|--|--|--|
| Site Name | | BRADLY 13 F | EDERAL #1 | Site Typ | 3 | | |
| Date Release | Discovered | | | API# (if a | pplicable) 3001533384 | | |
| Unit Letter Section Township Range | | | | | unty | | |
| F | 13 | 25S | 2 9E | | UNTY , NM | | |
| Surface Owner | : State | Federal 🔳 Tr | | Name:d Volume of | Release | | |
| | Materia | l(s) Released (Select all | | | ic justification for the volumes provided below) | | |
| Crude Oil | | Volume Release | d (bbls) 187 bbl | S | Volume Recovered (bbls) 96 bbls | | |
| Produced | Water | Volume Release | d (bbls) | | Volume Recovered (bbls) | | |
| Is the concentration of dissolved chloride produced water >10,000 mg/l? | | | | chloride in the | ☐ Yes ☐ No | | |
| Condensar | te | Volume Released | | | Volume Recovered (bbls) | | |
| ☐ Natural G | as | Volume Released | l (Mcf) | | Volume Recovered (Mcf) | | |
| Other (describe) Volume/Weight Released (provide units) | | | | e units) | Volume/Weight Recovered (provide units) | | |
| Cause of Rele | ase | | | | | | |
| 4" load line | valve fa | ilure | | | | | |
| | | | | | | | |
| | | | | | | | |

Form C-141 Page 2

State of New Mexico Oil Conservation Division

| Incident ID | nAPP2218939473 |
|----------------|----------------|
| District RP | |
| Facility ID | |
| Application ID | |

| Was this a major release as defined by 19.15.29.7(A) NMAC? ■ Yes □ No | If YES, for what reason(s) does the respon | |
|--|--|--|
| If YES, was immediate no | otice given to the OCD? By whom? To who | om? When and by what means (phone, email, etc)? |
| The responsible i | Initial Re | sponse unless they could create a safety hazard that would result in injury |
| | | amess they could create a sujety hazara that would result in injury |
| ■ The source of the rele | ease has been stopped. | |
| ■ The impacted area has | s been secured to protect human health and t | he environment. |
| Released materials ha | we been contained via the use of berms or di | kes, absorbent pads, or other containment devices. |
| All free liquids and re | ecoverable materials have been removed and | managed appropriately. |
| Per 19.15.29.8 B. (4) NM. | AC the responsible party may commence re | mediation immediately after discovery of a release. If remediation |
| within a lined containmen | nt area (see 19.15.29.11(A)(5)(a) NMAC), pl | fforts have been successfully completed or if the release occurred ease attach all information needed for closure evaluation. |
| regulations all operators are a public health or the environm failed to adequately investigated. | required to report and/or file certain release notifi nent. The acceptance of a C-141 report by the OC ate and remediate contamination that pose a threa | est of my knowledge and understand that pursuant to OCD rules and cations and perform corrective actions for releases which may endanger CD does not relieve the operator of liability should their operations have to groundwater, surface water, human health or the environment. In esponsibility for compliance with any other federal, state, or local laws |
| Printed Name: Wade | Dittrich | Title: Environmental Coordinator |
| Signature: /// | | Date: 7-13-27 |
| email: wade_dittric | ch@oxy.com | Telephone: (575) 390-2828 |
| OCD Only | | |
| Received by:Jocelyn I | Harimon | Date: |

***** LIQUID SPILLS - VOLUME CALCULATIONS ******

| 73 | | - 4 | |
|----|-----|-----|-----|
| U | aaa | - 2 | 0 |
| | age | .,7 | · O |
| | 0 | | ~ |

Location of spill: Bradly 13 Federal #1 Date of Spill: 7/6/2022

Site Soil Type: Fine Sand

Average Daily Production: BBL Oil BBL Water

| Total Area Calculations | | | | | | | | |
|-------------------------|-------|---|--------|---|----------------|---------|--|--|
| Total Surface Area | width | | length | | wet soil depth | oil (%) | | |
| Rectangle Area #1 | 40 ft | Х | 110 ft | Х | 9 in | 100% | | |
| Rectangle Area #2 | 0 ft | X | 0 ft | Χ | 0 in | 100% | | |
| Rectangle Area #3 | 0 ft | X | 0 ft | X | 0 in | 0% | | |
| Rectangle Area #4 | 0 ft | X | 0 ft | X | 0 in | 0% | | |
| Rectangle Area #5 | 0 ft | X | 0 ft | X | 0 in | 0% | | |
| Rectangle Area #6 | 0 ft | X | 0 ft | X | 0 in | 0% | | |
| Rectangle Area #7 | 0 ft | X | 0 ft | X | 0 in | 0% | | |
| Rectangle Area #8 | 0 ft | X | 0 ft | Х | 0 in | 0% | | |
| 3 | | | | | | | | |

Porosity 0.16 gal per gal

96.0 BBL

0.0 BBL

| Saturated | Soil Volume Calculations: | | | | |
|----------------------------|---------------------------|------------|-------------|---------|-------------------|
| | | <u>H2O</u> | OIL | : | Soil Type |
| Area #1 | 4400 sq. ft. | cu. ft. | 3,190 | cu. ft. | Clay |
| Area #2 | 0 sq. ft. | cu. ft. | | cu. ft. | Peat |
| Area #3 | 0 sq. ft. | cu. ft. | | cu. ft. | Glacial Sediments |
| Area #4 | 0 sq. ft. | cu. ft. | | cu. ft. | Sandy Clay |
| Area #5 | 0 sq. ft. | cu. ft. | | cu. ft. | Silt |
| Area #6 | 0 sq. ft. | cu. ft. | | cu. ft. | Loess |
| Area #7 | 0 sq. ft. | cu. ft. | | cu. ft. | Fine Sand |
| Area #8 | 0 sq. ft. | cu. ft. | | cu. ft. | Medium Sand |
| Total Solid/Liquid Volume: | 4,400 sq. ft. | cu. ft. | 3,190 | cu. ft. | Coarse Sand |
| | | | | | Gravely Sand |
| Estimated | d Volumes Spilled | | | | Fine Gravel |
| | | <u>H2O</u> | <u>OIL</u> | | Medium Gravel |
| Liqu | id in Soil: | 0.0 BBL | 90.9 | BBL | Coarse Gravel |
| Liquid Re | covered : | 0.0 BBL | <u>96.0</u> | BBL | Sandstone |
| | | | | | Siltstone |
| Si | pill Liquid | 0.0 BBL | 186.9 | BBL | Shale |
| Total Sp | oill Liquid: | 18 | 6.9 | | Limestone |
| | | | | | Basalt |
| Recov | vered Volumes | | | | Volcanic Tuff |
| | | | | | |

| Soil Type | Porosity |
|-------------------|----------|
| Clay | 0.15 |
| Peat | 0.40 |
| Glacial Sediments | 0.13 |
| Sandy Clay | 0.12 |
| Silt | 0.16 |
| Loess | 0.25 |
| Fine Sand | 0.16 |
| Medium Sand | 0.25 |
| Coarse Sand | 0.26 |
| Gravely Sand | 0.26 |
| Fine Gravel | 0.26 |
| Medium Gravel | 0.25 |
| Coarse Gravel | 0.18 |
| Sandstone | 0.25 |
| Siltstone | 0.18 |
| Shale | 0.05 |
| Limestone | 0.13 |
| Basalt | 0.19 |
| Volcanic Tuff | 0.20 |
| Standing Liquids | |

Estimated oil recovered:

Estimated water recovered:

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 127925

CONDITIONS

| Operator: | OGRID: |
|-----------------------|---|
| OXY USA INC | 16696 |
| P.O. Box 4294 | Action Number: |
| Houston, TX 772104294 | 127925 |
| | Action Type: |
| | [C-141] Release Corrective Action (C-141) |

CONDITIONS

| Created By | Condition | Condition Date |
|------------|-----------|-------------------|
| jharimor | None | 7/21/2022 |