Received by O	CD: 12/3/2021	11:58:05 AM	of New Mexico
Page 2		Oil Con	servation Division

	Page I of
Incident ID	T uge T of
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the responsible party consider this a major release? Oil spill larger than 25 Bbls			
	If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Initial C-141 submitted within 24 hours of spill discovery by Aaron Hickert to NMOCD through online Portal			
	Initial Response			
The responsible	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury			
The source of the rele	ease has been stopped.			
The impacted area ha	s been secured to protect human health and the environment.			
Released materials ha	ave been contained via the use of berms or dikes, absorbent pads, or other containment devices.			
All free liquids and re	ecoverable materials have been removed and managed appropriately.			
Per 19,15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.				
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.				
Printed Name:Aaroı	Hickert Title: Sr EHS Coordinator			
Signature:	Date: <u>11/25/2021</u>			
email: _ahickert@scout	ep.com Telephone: 620-353-4960			
OCD Only				
Received by:	Date:			

Received by OCD: 12/3/2021 11:58:05 AM
Form C-141
State of New Mexico
Page 3
Oil Conservation Division

	Page 2
Incident ID	
District RP	
Facility ID	
Application ID	

Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	(ft bgs)		
Did this release impact groundwater or surface water?	☐ Yes ⊠ No		
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	☐ Yes 🛭 No		
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	☐ Yes ☒ No		
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	☐ Yes ⊠ No		
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	☐ Yes ⊠ No		
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	☐ Yes ⊠ No		
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	☐ Yes ⊠ No		
Are the lateral extents of the release within 300 feet of a wetland?	☐ Yes ⊠ No		
Are the lateral extents of the release overlying a subsurface mine?	☐ Yes ⊠ No		
Are the lateral extents of the release overlying an unstable area such as karst geology?	☐ Yes 🛛 No		
Are the lateral extents of the release within a 100-year floodplain?	☐ Yes ⊠ No		
Did the release impact areas not on an exploration, development, production, or storage site?	⊠ Yes □ No		
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.			
Characterization Report Checklist: Each of the following items must be included in the report.			
Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps Laboratory data including chain of custody			

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Received by OCD: 12/3/2021 11:58:05 AM of New Mexico
Page 4 Oil Conservation Division

	Page 3 0
Incident ID	1 ugc 3 o
District RP	
Facility ID	
Application ID	

I hereby certify that the information given above is true and complete to the regulations all operators are required to report and/or file certain release not public health or the environment. The acceptance of a C-141 report by the failed to adequately investigate and remediate contamination that pose a threaddition, OCD acceptance of a C-141 report does not relieve the operator of and/or regulations.	offications and perform corrective actions for releases which may endanger of looks not relieve the operator of liability should their operations have eat to groundwater, surface water, human health or the environment. In
Printed Name:	Title:
Signature:	Date:
email:	Telephone:
OCD Only	
Received by:	Date:

Received by OCD: 12/3/2021 11:58:05 AM State of New Mexico
Page 5 Oil Conservation Division

Incident ID	Page 4
Incident ID	
District RP	
Facility ID	
Application ID	

Remediation Plan

e included in the plan.
ts
12(C)(4) NMAC
neline is more than 90 days OCD approval is required)
nfirmed as part of any request for deferral of remediation.
roduction equipment where remediation could cause a major facility
h, the environment, or groundwater.
ance of a C-141 report by the OCD does not relieve the operator of the and remediate contamination that pose a threat to groundwater, acceptance of a C-141 report does not relieve the operator of laws and/or regulations.
Title:
Date:
Telephone:
Date:
Date: of Approval

Received by OCD: 12/3/2021 11:58:05 AM State of New Mexico
Page 6 Oil Conservation Division

Incident ID
District RP
Facility ID
Application ID

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of	of the following items must be included in the closure report.	
A scaled site and sampling diagram as descri	bed in 19.15.29.11 NMAC	
Photographs of the remediated site prior to b must be notified 2 days prior to liner inspection)	packfill or photos of the liner integrity if applicable (Note: appropriate OCD District office	
☐ Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)		
Description of remediation activities		
and regulations all operators are required to report may endanger public health or the environment. It should their operations have failed to adequately in human health or the environment. In addition, OC compliance with any other federal, state, or local frestore, reclaim, and re-vegetate the impacted surfaccordance with 19.15.29.13 NMAC including no	is true and complete to the best of my knowledge and understand that pursuant to OCD rules that and/or file certain release notifications and perform corrective actions for releases which The acceptance of a C-141 report by the OCD does not relieve the operator of liability investigate and remediate contamination that pose a threat to groundwater, surface water. CD acceptance of a C-141 report does not relieve the operator of responsibility for laws and/or regulations. The responsible party acknowledges they must substantially face area to the conditions that existed prior to the release or their final land use in obtification to the OCD when reclamation and re-vegetation are complete.	
	Title:	
Signature:	Date:	
email:	Telephone:	
OCD Only		
Received by:	Date:	
Closure approval by the OCD does not relieve the remediate contamination that poses a threat to groparty of compliance with any other federal, state,	e responsible party of liability should their operations have failed to adequately investigate an oundwater, surface water, human health, or the environment nor does not relieve the responsibl , or local laws and/or regulations.	
Closure Approved by:	Date:	
	Title:	

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 64944

CONDITIONS

Operator:	OGRID:
SCOUT ENERGY MANAGEMENT LLC	330949
13800 Montfort Road	Action Number:
Dallas, TX 75240	64944
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By		Condition Date
jharimon	None	8/3/2022