District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	nAPP2226327719
District RP	
Facility ID	
Application ID	

# **Release Notification**

## **Responsible Party**

Responsible Party Spur Energy Partners, LLC		OGRID	328947			
Contact Name Chad Hensley		Contact Te	Геlephone (346) 339-1494			
Contact email chensley@spurenergy.com		Incident #	# (assigned by OCD) nAPP2226327719			
Contact mail	ing address	9655 Katy Free	eway, Suite 500,	Houston, TX 77	7024	
			Location	of Release So	Source	
Latitude 32	2.633419			Longitude _		
			(NAD 83 in dec	imal degrees to 5 decin	imal places)	
Site Name	Lakewood	d AQE state Sw	 d	Site Type	SWD	
Date Release	Discovered	9/15/2022		API# (if app	oplicable) 30-015-22233	
Unit Letter	Section	Township	Range	Coun	inty	
F	30	19 S	26E	Eddy		
				•		
Surface Owner	r: X State	☐ Federal ☐ Tr	ribal	lame:	)	
			Nature and	Volume of 1	Release	
	Materia	l(s) Released (Select al	I that apply and attach	calculations or specific	ic justification for the volumes provided below)	
Crude Oil	·	Volume Release		carculations of specific	Volume Recovered (bbls)	
Produced	Water	Volume Release	d (bbls) 55		Volume Recovered (bbls) 40	
			tion of dissolved cl	nloride in the	☐ Yes ☐ No	
Condensa	te	Volume Release			Volume Recovered (bbls)	
Natural G	as	Volume Release	d (Mcf)		Volume Recovered (Mcf)	
Other (des	scribe)	Volume/Weight	Released (provide	units)	Volume/Weight Recovered (provide units)	
Cause of Release Pressure						
		i icssuic				

Th	-		-
Page	٠,	a	•
1 420	-	v	

Incident ID	nAPP2226327719
District RP	
Facility ID	
Application ID	_

Was this a major release as defined by	If YES, for what reason(s) does the respon	sible party consider this a major release?
19.15.29.7(A) NMAC?	Release was over 25	hhls
☐ Yes ☐ No	Trelease was over 20	DDIO.
If YES, was immediate no	Lotice given to the OCD? By whom? To what is a second of the OCD?	nom? When and by what means (phone, email, etc)?
11 1 22, 111111041410	given to the case by whether to wi	(mining the many of the many o
	Initial Ro	esponse
The responsible	party must undertake the following actions immediatel	y unless they could create a safety hazard that would result in injury
<u> </u>	ease has been stopped.	
The impacted area ha	as been secured to protect human health and	the environment.
Released materials ha	ave been contained via the use of berms or d	likes, absorbent pads, or other containment devices.
All free liquids and re	ecoverable materials have been removed and	d managed appropriately.
If all the actions described	d above have <u>not</u> been undertaken, explain	why:
Per 19.15.29.8 B. (4) NM	IAC the responsible party may commence r	emediation immediately after discovery of a release. If remediation
has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred		
within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.		
		best of my knowledge and understand that pursuant to OCD rules and
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have		
failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws		
and/or regulations.	Ta C-141 report does not reneve the operator or	responsionity for comphance with any other rederar, state, or local laws
Printed Name: Chad I	Hensley	Title: EHS Coordinator
Signature:	Hend	Date:09/20/2022_
email: chensley@spu	•	Telephone: (346) 339-1494
OCD Only		
Received by: Jocelyn	n Harimon	Date: 09/20/2022
1		

	Puge 3
Incident ID	nAPP2226327719
District RP	
Facility ID	

**Application ID** 

### **Site Assessment/Characterization**

 $This information \ must \ be \ provided \ to \ the \ appropriate \ district \ of fice \ no \ later \ than \ 90 \ days \ after \ the \ release \ discovery \ date.$ 

What is the shallowest depth to groundwater beneath the area affected by the release?	(ft bgs)	
Did this release impact groundwater or surface water?	☐ Yes ☐ No	
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	☐ Yes ☐ No	
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	☐ Yes ☐ No	
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	☐ Yes ☐ No	
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	☐ Yes ☐ No	
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	☐ Yes ☐ No	
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	☐ Yes ☐ No	
Are the lateral extents of the release within 300 feet of a wetland?	☐ Yes ☐ No	
Are the lateral extents of the release overlying a subsurface mine?	☐ Yes ☐ No	
Are the lateral extents of the release overlying an unstable area such as karst geology?	☐ Yes ☐ No	
Are the lateral extents of the release within a 100-year floodplain?		
Did the release impact areas <b>not</b> on an exploration, development, production, or storage site?	☐ Yes ☐ No	
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.		
Characterization Report Checklist: Each of the following items must be included in the report.		
Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells.  Field data  Data table of soil contaminant concentration data  Depth to water determination  Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release  Boring or excavation logs  Photographs including date and GIS information  Topographic/Aerial maps  Laboratory data including chain of custody		

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Received by OCD: 9/20/2022 7:52:51 AM Form C-141 State of New Mexico Page 4 Oil Conservation Division

Page 4 of 7
Incident ID nAPP2226327719
District RP
Facility ID
Application ID

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Printed Name:		
Signature:	Date:	
email:	Telephone:	
OCD Only		
Received by:	Date:	

ceived by OCD: 9/20/2022 7:52:51 AM
State of New Mexico

Incident ID	nAPP2226327719
District RP	
Facility ID	
Application ID	

# **Remediation Plan**

Remediation Plan Checklist: Each of the following items must b	e included in the plan.	
<ul> <li>□ Detailed description of proposed remediation technique</li> <li>□ Scaled sitemap with GPS coordinates showing delineation points</li> <li>□ Estimated volume of material to be remediated</li> <li>□ Closure criteria is to Table 1 specifications subject to 19.15.29.12(C)(4) NMAC</li> <li>□ Proposed schedule for remediation (note if remediation plan timeline is more than 90 days OCD approval is required)</li> </ul>		
<u>Deferral Requests Only</u> : Each of the following items must be con	nfirmed as part of any request for deferral of remediation.	
Contamination must be in areas immediately under or around predeconstruction.	roduction equipment where remediation could cause a major facility	
Extents of contamination must be fully delineated.		
Contamination does not cause an imminent risk to human health	n, the environment, or groundwater.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Printed Name:	Title:	
Signature:	Date:	
email:	Telephone:	
OCD Only		
Received by:	Date:	
☐ Approved ☐ Approved with Attached Conditions of	Approval	
Signature:	<u>Date:</u>	

eived by OCD: 9/20/2022 7:52:51 AM
State of New Mexico

Incident ID	nAPP2226327719
District RP	
Facility ID	
Application ID	

# Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

A scaled site and sampling diagram as described in 19.15.29.11 NMAC		
Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)		
☐ Laboratory analyses of final sampling (Note: appropriate ODC	C District office must be notified 2 days prior to final sampling)	
☐ Description of remediation activities		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.  Printed Name:  Title:  Title:		
Signature:	Date:	
email:	Telephone:	
OCD Only		
Received by:	Date:	
Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.		
Closure Approved by:	Date:	
Printed Name:	Title:	

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 144773

### **CONDITIONS**

Operator:	OGRID:
Spur Energy Partners LLC	328947
9655 Katy Freeway	Action Number:
Houston, TX 77024	144773
	Action Type:
	[C-141] Release Corrective Action (C-141)

#### CONDITIONS

Created By	Condition	Condition Date
jharimon	When submitting future reports regarding this release, please submit the calculations used or specific justification for the volumes reported on the initial C-141	9/20/2022