District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party				OGRID					
Contact Name				Contact To	Contact Telephone				
Contact email				Incident #	Incident # (assigned by OCD)				
Contact mail	ing address			1					
			Location	of Release So	ource				
Latitude				Longitude					
			(NAD 83 in de	cimal degrees to 5 decir	nal places)				
Site Name				Site Type					
Date Release	Discovered			API# (if app	plicable)				
Unit Letter	Section	Township	Range	Cour	County				
Crude Oi		l(s) Released (Select al Volume Release	ll that apply and attach	d Volume of l		e volumes provided below) overed (bbls)			
Produced	Water	Volume Release	ed (bbls)		Volume Recovered (bbls)				
Is the concentration of dissolved chloric produced water >10,000 mg/l?			chloride in the	☐ Yes ☐ No					
Condensate Volume Released (bbls)				Volume Recovered (bbls)					
Natural Gas Volume Released (Mcf)				Volume Recovered (Mcf)					
Other (describe) Volume/Weight Released (provide units			e units)	Volume/Weight Recovered (provide units)					
Cause of Rel	ease								

Received by OCD: 11/11/2022 3:19:32 PM Form C-141 State of New Mexico Page 2 Oil Conservation Division

	ruge 2 0j
Incident ID	
District RP	
Facility ID	
Application ID	

Was this a major release as defined by	If YES, for what reason(s) does the respon	sible party consider this a major release?
19.15.29.7(A) NMAC?		
☐ Yes ☐ No		
If YES, was immediate no	tice given to the OCD? By whom? To wh	om? When and by what means (phone, email, etc)?
	Initial Re	esponse
The responsible p	arty must undertake the following actions immediatel	unless they could create a safety hazard that would result in injury
☐ The source of the relea	ase has been stopped.	
☐ The impacted area has	s been secured to protect human health and	the environment.
Released materials have	ve been contained via the use of berms or d	ikes, absorbent pads, or other containment devices.
☐ All free liquids and red	coverable materials have been removed and	l managed appropriately.
If all the actions described	above have <u>not</u> been undertaken, explain v	vhy:
has begun, please attach a	a narrative of actions to date. If remedial	emediation immediately after discovery of a release. If remediation efforts have been successfully completed or if the release occurred lease attach all information needed for closure evaluation.
		pest of my knowledge and understand that pursuant to OCD rules and
public health or the environm failed to adequately investiga	nent. The acceptance of a C-141 report by the O ate and remediate contamination that pose a threa	ications and perform corrective actions for releases which may endanger CD does not relieve the operator of liability should their operations have at to groundwater, surface water, human health or the environment. In responsibility for compliance with any other federal, state, or local laws
Printed Name		Title:
Signature: _	tan Esparage	Date:
email:		Telephone:
OCD Only		
Received by:Jocely	yn Harimon	Date:11/14/2022

L48 Spill Volume Estimate Form - Fill In Gray Cells											
Facility Name & Well Number(s):				CR1 PW Transfer Line Release			Release Discovery Date & Time: 10/29/2022 Foun			d 08:00 AM	
		Provide any known de	etails about the event:	Water transfer line was cut by 3rd party resulting in release. Unknown when line was cut and how much fluid was pumped in the line Ops data provided indicates lines produces between 200 to 500 bbls per day. Cam to Plan Mapping.							
			Recovered Volume (bbl.) (if available, not included in volume calculations) Recovered Volume (bbl.) (if Method of Determination (dropdown)		Release Type (dropdown):		> 1/2" of Rain in Last 24 Hours (dropdown):		% Rainwater Recovered (not included in volume calculations, informational):		
BU:	Permian ~	Asset Area:	DBE - Asset Avg.	20	Field Measurement		Produced Water ~		No ~		0%
		Known	Volume (dropdown):	No ~							
	Known Area (dropdown)			Yes	Mapped Area (sq. ft.)	Average Depth (in.)	On/Off Pad		Soil Spilled-Fluid Saturation	Total Estimated Volume of Spill (bbl.)	
			~	21000	7	On-Pad ✓		10.50%	228.95		

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 158250

CONDITIONS

Operator:	OGRID:
CONOCOPHILLIPS COMPANY	217817
600 W. Illinois Avenue	Action Number:
Midland, TX 79701	158250
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
jharimon	None	11/14/2022