

Page 1 of 2
Received by OCD: 11/30/2022 10:35:14 AM
Released to Imaging: 11/30/2022 10:36:55 AM

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company:	COG Operating LLC	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	GOOSE STATE #001H	Facility Type:	Flare
Surface Owner:	State	Mineral Owner:	API No. 30-025-41106

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	32	20S	34E	190'	North	1980'	West	Lea

Latitude 32.5363159 Longitude 103.5845566

NATURE OF RELEASE

Type of Release:	Oil (Fire)	Volume of Release:	.25bbls	Volume Recovered:	0bbls
Source of Release:	Flare	Date and Hour of Occurrence:	02/14/2017 06:00 am	Date and Hour of Discovery:	02/14/2017 06:00 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Ms. Yu - NMOCS / Ms. Groves - SLO		
By Whom?	Robert Grubbs Jr.	Date and Hour:	Time of this email.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a sales BPV malfunctioned intermittently causing the separator to hit high level sending the fluid to the flare.

Describe Area Affected and Cleanup Action Taken.*

This release was located in the pasture. No fluid to recover due to the fire burning off any standing fluids.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:			
Printed Name:	Robert Grubbs Jr.	Approved by Environmental Specialist: 	
Title:	Senior HSE Coordinator	Approval Date:	11/30/2022
E-mail Address:	rgrubbs@concho.com	Expiration Date:	
Date:	February 14, 2017	Phone:	432-683-7443
Attach Additional Sheets If Necessary		Conditions of Approval:	Attached <input type="checkbox"/>

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 162519

CONDITIONS

Operator: COG OPERATING LLC 600 W Illinois Ave Midland, TX 79701	OGRID: 229137
	Action Number: 162519
	Action Type: [IM-SD] Incident File Support Doc (ENV) (IM-BNF)

CONDITIONS

Created By	Condition	Condition Date
amaxwell	None	11/30/2022