

CARMONA RESOURCES



## SITE INFORMATION

---

### **Closure Report**

**Ridge Nose Federal Com #1H (07.08.22)**

**Incident #: NAPP2221537537**

**Eddy County, New Mexico**

**Unit G Sec 31 T26S R29E**

**32.000605°, -104.022330°**

### **Produced Water Release**

**Point of Release: Tank overflow**

**Release Date: 07/08/2022**

**Volume Released: 20 barrels of Produced Water**

**Volume Recovered: 20 barrels of Produced Water**

CARMONA RESOURCES



### **Prepared for:**

**Concho Operating, LLC**

**15 West London Road**

**Loving, New Mexico 88256**

### **Prepared by:**

**Carmona Resources, LLC**

**310 West Wall Street**

**Suite 415**

**Midland, Texas 79701**

310 West Wall Street, Suite 415  
Midland TX, 79701  
432.813.1992

## **TABLE OF CONTENTS**

### **1.0 SITE INFORMATION AND BACKGROUND**

### **2.0 SITE CHARACTERIZATION AND GROUNDWATER**

### **3.0 NMAC REGULATORY CRITERIA**

### **4.0 LINER INSPECTION ACTIVITIES**

### **5.0 CONCLUSIONS**

## **FIGURES**

**FIGURE 1                      OVERVIEW                      FIGURE 2                      TOPOGRAPHIC**

**FIGURE 3                      SECONDARY CONTAINMENT MAP**

## **APPENDICES**

**APPENDIX A                      PHOTOS**

**APPENDIX B                      INITIAL C-141 AND FINAL/NMOCD CORRESPONDENCE**

**APPENDIX C                      SITE CHARACTERIZATION AND GROUNDWATER**

October 11, 2022

Mike Bratcher  
District Supervisor  
Oil Conservation Division, District 2  
811 S. First Street  
Artesia, New Mexico 88210

**Re: Closure Report  
Ridge Nose Federal Com #1H (07.08.22)  
Concho Operating, LLC  
Incident ID NAPP2221537537  
Site Location: Unit G, S31, T26S, R29E  
(Lat 32.000605°, Long -104.022330°)  
Eddy County, New Mexico**

Mr. Bratcher:

On behalf of Concho Operating, LLC (COG), Carmona Resources, LLC has prepared this letter to document site activities for Ridge Nose Federal Com #1H (07.08.22). The site is located at 32.000605°, -104.022330° within Unit G, S31, T26S, R29E, in Eddy County, New Mexico (Figures 1 and 2).

### **1.0 Site information and Background**

Based on the initial C-141 obtained from the New Mexico Oil Conservation Division (NMOCD), the release was discovered on June 8, 2022, due to tanks overflowing inside the secondary containment. It resulted in the release of approximately twenty (20) barrels of produced water and twenty (20) barrels of produced water recovered. See figure 3. The initial C-141 form is attached in Appendix B

### **2.0 Site Characterization and Groundwater**

The site is located within a medium karst area. Based on a review of the New Mexico Office of State Engineers and USGS databases, no known water source. The closest well is located approximately 2.96 miles Northwest of the site in S27, T26S, R28E and was drilled in 2017. The well has a reported depth to groundwater of 145' feet below ground surface (ft bgs). A copy of the associated point of diversion is attached in Appendix C.

### **3.0 Site Characterization and Groundwater**

Per the NMOCD regulatory criteria established in 19.15.29.12 NMAC, the following criteria were utilized in assessing the site.

- Benzene: 10 milligrams per kilogram (mg/kg).
- Benzene, toluene, ethylbenzene, and total xylenes (BTEX): 50 mg/kg.
- TPH: 100 mg/kg (GRO + DRO + MRO).
- Chloride: 600 mg/kg.



#### **4.0 Liner Inspection Activities**

Carmona Resources, LLC conducted liner inspection activities to assess the liner's integrity within the facility and determined the liner was intact with no integrity issues. Refer to the Photolog.

#### **5.0 Conclusions**

Based on the liner inspection throughout the facility, no further actions are required at the site. The final C-141 is attached, and COG formally requests closure of the spill. If you have any questions regarding this report or need additional information, don't hesitate to contact us at 432-813-1992.

Sincerely,

**Carmona Resources, LLC**

Conner Moehring  
Sr. Project Manager


Ashton Thielke  
Sr. Project Manager



## FIGURES

CARMONA RESOURCES





0 2 4 8  
Miles

**Legend**  
★ Site Location

**OVERVIEW MAP**  
**COG OPERATING**  
RIDGE NOSE FEDERAL COM 1H (07.08.22)  
EDDY COUNTY, NEW MEXICO  
32.000605, -104.022330

SCALE: As Shown

Date: 7/31/2022



**Carmona Resources**  
310 West Wall Street, Suite 415  
Midland, Texas 79701

**NOTES:**


1. Base Image: ESRI Maps & Data 2013
2. Map Projection: NAD 1983 UTM Zone 13N

DRAWING NUMBER:

**FIGURE 1**

SHEET NUMBER:

**1 of 1**



## Legend

★ Site Location

Copyright:© 2013

### TOPOGRAPHIC MAP COG OPERATING

RIDGE NOSE FEDERAL COM 1H (07.08.22)  
EDDY COUNTY, NEW MEXICO  
32.000605, -104.022330

SCALE: As Shown

Date: 7/31/2022

CARMONA RESOURCES



**Carmona Resources**  
310 West Wall Street, Suite 415  
Midland, Texas 79701

### NOTES:

1. Base Image: ESRI Maps & Data 2013
2. Map Projection: NAD 1983 UTM Zone 13N

DRAWING NUMBER:

**FIGURE 2**

SHEET NUMBER:

**1 of 1**





**SECONDARY CONTAINMENT MAP**  
**COG OPERATING**  
 RIDGE NOSE FEDERAL COM 1H (07.08.22)  
 EDDY COUNTY, NEW MEXICO  
 32.000605, -104.022330

SCALE: As Shown

Date: 7/31/2022



**Carmona Resources**  
 310 West Wall Street, Suite 415  
 Midland, Texas 79701

**NOTES:**

1. Base Image: ESRI Maps & Data 2013
2. Map Projection: NAD 1983 UTM Zone 13N

DRAWING NUMBER:

**FIGURE 3**

SHEET NUMBER:

**1 of 1**

## APPENDIX A

CARMONA RESOURCES





# PHOTOGRAPHIC LOG

Concho Operating, LLC

## Photograph No. 1

**Facility:** Ridge Nose Federal Com #1H  
(07.08.22)

**County:** Eddy County, New Mexico

**Description:**

View Southwest of lined facility.



## Photograph No. 2

**Facility:** Ridge Nose Federal Com #1H  
(07.08.22)

**County:** Eddy County, New Mexico

**Description:**

View North of lined facility.




## Photograph No. 3

**Facility:** Ridge Nose Federal Com #1H  
(07.08.22)

**County:** Eddy County, New Mexico

**Description:**

View North of lined facility.





# PHOTOGRAPHIC LOG

Concho Operating, LLC

## Photograph No. 4

**Facility:** Ridge Nose Federal Com #1H  
(07.08.22)

**County:** Eddy County, New Mexico

**Description:**

View North of lined facility.



## Photograph No. 5

**Facility:** Ridge Nose Federal Com #1H  
(07.08.22)

**County:** Eddy County, New Mexico

**Description:**

View South of lined facility.



## Photograph No. 6

**Facility:** Ridge Nose Federal Com #1H  
(07.08.22)

**County:** Eddy County, New Mexico

**Description:**

View Southeast of lined facility.





**PHOTOGRAPHIC LOG****Concho Operating, LLC****Photograph No. 7****Facility:** Ridge Nose Federal Com #1H  
(07.08.22)**County:** Eddy County, New Mexico**Description:**

View North of lined facility with new gravel.

**Photograph No. 8****Facility:** Ridge Nose Federal Com #1H  
(07.08.22)**County:** Eddy County, New Mexico**Description:**

View West of lined facility with new gravel.

**Photograph No. 9****Facility:** Ridge Nose Federal Com #1H  
(07.08.22)**County:** Eddy County, New Mexico**Description:**

View Northeast of lined facility with new gravel.





## PHOTOGRAPHIC LOG

Concho Operating, LLC

### Photograph No. 10

**Facility:** Ridge Nose Federal Com #1H  
(07.08.22)

**County:** Eddy County, New Mexico

**Description:**

View East of lined facility with new gravel.



### Photograph No. 11

**Facility:** Ridge Nose Federal Com #1H  
(07.08.22)

**County:** Eddy County, New Mexico

**Description:**

View Southwest of lined facility with new gravel.



## APPENDIX B

CARMONA RESOURCES



District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural  
Resources Department  
  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 24, 2018  
Submit to appropriate OCD District office

Incident ID	
District RP	
Facility ID	
Application ID	

## Release Notification

### Responsible Party

Responsible Party	OGRID
Contact Name	Contact Telephone
Contact email	Incident # (assigned by OCD)
Contact mailing address	

### Location of Release Source

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_  
(NAD 83 in decimal degrees to 5 decimal places)

Site Name	Site Type
Date Release Discovered	API# (if applicable)

Unit Letter	Section	Township	Range	County

Surface Owner: ☐ State ☐ Federal ☐ Tribal ☐ Private (Name: \_\_\_\_\_)

### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)
Cause of Release		

## Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?  <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release?
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?	

**Initial Response**

*The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury*

<input type="checkbox"/> The source of the release has been stopped.	
<input type="checkbox"/> The impacted area has been secured to protect human health and the environment.	
<input type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.	
<input type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why:	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: _____	Title: _____
Signature: <u>Battani Espinoza</u>	Date: _____
email: _____	Telephone: _____
<b><u>OCD Only</u></b>	
Received by: _____	Date: _____

Incident ID	
District RP	
Facility ID	
Application ID	

## Site Assessment/Characterization

*This information must be provided to the appropriate district office no later than 90 days after the release discovery date.*

What is the shallowest depth to groundwater beneath the area affected by the release?	_____ (ft bgs)
Did this release impact groundwater or surface water?	<input type="checkbox"/> Yes <input type="checkbox"/> No
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	<input type="checkbox"/> Yes <input type="checkbox"/> No
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	<input type="checkbox"/> Yes <input type="checkbox"/> No
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	<input type="checkbox"/> Yes <input type="checkbox"/> No
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	<input type="checkbox"/> Yes <input type="checkbox"/> No
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	<input type="checkbox"/> Yes <input type="checkbox"/> No
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	<input type="checkbox"/> Yes <input type="checkbox"/> No
Are the lateral extents of the release within 300 feet of a wetland?	<input type="checkbox"/> Yes <input type="checkbox"/> No
Are the lateral extents of the release overlying a subsurface mine?	<input type="checkbox"/> Yes <input type="checkbox"/> No
Are the lateral extents of the release overlying an unstable area such as karst geology?	<input type="checkbox"/> Yes <input type="checkbox"/> No
Are the lateral extents of the release within a 100-year floodplain?	<input type="checkbox"/> Yes <input type="checkbox"/> No
Did the release impact areas <b>not</b> on an exploration, development, production, or storage site?	<input type="checkbox"/> Yes <input type="checkbox"/> No

Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.

### **Characterization Report Checklist:** *Each of the following items must be included in the report.*

- ☐ Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells.
- ☐ Field data
- ☐ Data table of soil contaminant concentration data
- ☐ Depth to water determination
- ☐ Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release
- ☐ Boring or excavation logs
- ☐ Photographs including date and GIS information
- ☐ Topographic/Aerial maps
- ☐ Laboratory data including chain of custody

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

State of New Mexico  
Oil Conservation Division

Page 4

Incident ID	
District RP	
Facility ID	
Application ID	

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: \_\_\_\_\_ Title: \_\_\_\_\_

Signature: *Jacqueline Harimon* Date: \_\_\_\_\_

email: \_\_\_\_\_ Telephone: \_\_\_\_\_

**OCD Only**

Received by: Jocelyn Harimon Date: 10/17/2022

Incident ID	
District RP	
Facility ID	
Application ID	

## Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

**Closure Report Attachment Checklist:** *Each of the following items must be included in the closure report.*

- ☐ A scaled site and sampling diagram as described in 19.15.29.11 NMAC
- ☐ Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- ☐ Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)
- ☐ Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: \_\_\_\_\_ Title: \_\_\_\_\_

Signature: Jacqueline Harimon Date: \_\_\_\_\_

email: \_\_\_\_\_ Telephone: \_\_\_\_\_

### OCD Only

Received by: Jocelyn Harimon Date: 10/17/2022

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by: Jennifer Nobui Date: \_\_\_\_\_

Printed Name: \_\_\_\_\_ Title: \_\_\_\_\_

---

**From:** Mike Carmona  
**Sent:** Tuesday, July 19, 2022 9:58 AM  
**To:** OCD.Enviro@state.nm.us  
**Cc:** Conner Moehring; Harris, Jacqui  
**Subject:** COG Ridge Nose Fed Com #1H (7.08.22) Notification

Good Morning,

On behalf of COG, Carmona Resources will conduct a liner inspection at the below-referenced site on 07/21/2022. Please let me know if you have any questions.

Ridge Nose Fed Com #1H (7.08.22)  
32.0006°, -104.0224°  
Eddy County, New Mexico

Mike J. Carmona  
310 West Wall Street, Suite 415  
Midland TX, 79701  
M: 432-813-1992  
[Mcarmona@carmonaresources.com](mailto:Mcarmona@carmonaresources.com)

CARMONA RESOURCES





## APPENDIX C

CARMONA RESOURCES








# NEAREST WATER WELL


COG OPERATING


Legend


 0.50 Mile Radius

 2.96 Miles

 2.97 Miles

 NMSEO Water Well

 Ridge Nose Federal Com #1H (07.08.22)





# MEDIUM KARST


COG OPERATING

Legend

High

Medium

Ridge Nose Federal Com #1H (07.08.22)





# New Mexico Office of the State Engineer

## Water Column/Average Depth to Water

(A CLW##### in the POD suffix indicates the POD has been replaced & no longer serves a water right file.)

(R=POD has been replaced, O=orphaned, C=the file is closed)

(quarters are 1=NW 2=NE 3=SW 4=SE)

(quarters are smallest to largest)

(NAD83 UTM in meters)

(In feet)

POD Number	POD Sub-Code	basin	County	Q 64	Q 16	Q 4	Sec	Tws	Rng	X	Y	Distance	Depth Well	Depth Water	Water Column
<a href="#">C 04022 POD2</a>	CUB	ED		2	2	2	27	26S	28E	588106	3543082	4772	250	145	105
<a href="#">C 03605 POD1</a>	CUB	ED		4	2	3	27	26S	29E	596990	3541983	4775	45	0	45
<a href="#">C 04630 POD1</a>	CUB	ED		3	4	3	22	26S	29E	596792	3543275	5051			

Average Depth to Water: **72 feet**

Minimum Depth: **0 feet**

Maximum Depth: **145 feet**

Record Count: 3

### UTMNAD83 Radius Search (in meters):

**Easting (X):** 592342.85

**Northing (Y):** 3540884.12

**Radius:** 6000

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

7/25/22 1:23 PM

Page 1 of 1


WATER COLUMN/ AVERAGE  
DEPTH TO WATER





# New Mexico Office of the State Engineer

## Point of Diversion Summary

		(quarters are 1=NW 2=NE 3=SW 4=SE)				(NAD83 UTM in meters)	
		(quarters are smallest to largest)				X	Y
Well Tag	POD Number	Q64	Q16	Q4	Sec	Tw	Rng
C	03605 POD1	4	2	3	27	26S	29E
						596990	3541983 
Driller License:		1249		Driller Company:		ATKINS ENGINEERING ASSOC. INC.	
Driller Name:		ATKINS, JACKIE D. (LD)					
Drill Start Date:		01/23/2013		Drill Finish Date:		01/23/2013	
Log File Date:		02/26/2013		PCW Rcv Date:		Plug Date:	
Pump Type:				Pipe Discharge Size:		01/28/2013	
Casing Size:				Depth Well:		Source:	
				45 feet		Estimated Yield:	
						Depth Water:	
						0 feet	

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

7/25/22 1:25 PM POINT OF DIVERSION SUMMARY



# New Mexico Office of the State Engineer

## Point of Diversion Summary

(quarters are 1=NW 2=NE 3=SW 4=SE)

(quarters are smallest to largest)

(NAD83 UTM in meters)

Well Tag	POD Number	Q64	Q16	Q4	Sec	Tw	Rng	X	Y
C	04022 POD2	2	2	2	27	26S	28E	588106	3543082

Driller License: 1184

Driller Company: WEST TEXAS WATER WELL SERVICE

Driller Name: KEITH, RONNY

Drill Start Date: 05/08/2017

Drill Finish Date: 05/12/2017

Plug Date:

Log File Date: 06/05/2017

PCW Rev Date:

Source: Shallow

Pump Type:

Pipe Discharge Size:

Estimated Yield: 60 GPM

Casing Size: 12.25

Depth Well: 250 feet

Depth Water: 145 feet

Water Bearing Stratifications:

Top Bottom Description

150 160 Sandstone/Gravel/Conglomerate

160 180 Sandstone/Gravel/Conglomerate

180 190 Sandstone/Gravel/Conglomerate


Casing Perforations:

Top Bottom


130 250

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

# New Mexico NFHL Data



July 25, 2022



FEMA, Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey,

nmflood.org is made possible through a collaboration with NMDHSEM,

This is a non-regulatory product for informational use only. Please consult your local floodplain administrator for further information.

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS  
  
Action 151128

CONDITIONS

Operator: COG OPERATING LLC 600 W Illinois Ave Midland, TX 79701	OGRID: 229137
	Action Number: 151128
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
jnobui	Closure Report Approved.	12/15/2022