

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nAPP2308346645
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party <i>Targa Resources</i>	OGRID 24650
Contact Name <i>Amber Groves</i>	Contact Telephone 575-635-9096
Contact email <i>agroves@targaresources.com</i>	Incident # (assigned by OCD) nAPP2308346645
Contact mailing address <i>PO Box 67, Monument, NM 88265</i>	

Location of Release Source

Latitude 32.5866 Longitude -103.2091
(NAD 83 in decimal degrees to 5 decimal places)

Site Name <i>Leak #17</i>	Site Type <i>Gathering Pipeline</i>
Date Release Discovered <i>03/23/2023</i>	API# (if applicable)

Unit Letter	Section	Township	Range	County
<i>K</i>	<i>12</i>	<i>20S</i>	<i>37E</i>	<i>Lea</i>

Surface Owner: ☐ State ☐ Federal ☐ Tribal ☒ Private (Name: *S-W Cattle Company*)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

☐ Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
☐ Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	☐ Yes ☐ No
☒ Condensate	Volume Released (bbls) <i>7.5 bbls</i>	Volume Recovered (bbls)
☒ Natural Gas	Volume Released (Mcf) <i>19.32 MCF</i>	Volume Recovered (Mcf) <i>0 MCF</i>
☐ Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

7.5 bbls of condensate and 19.32 MCF of natural gas were released from Targa's 12" Steel line due to corrosion. Upon discovery, the section of pipeline was isolated and depressurized to prevent further release and to protect personnel and equipment. The heavily saturated surface soil was removed.

Form C-141

Page 2

State of New Mexico
Oil Conservation Division

Incident ID	nAPP2308346645
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? ☐ Yes ☒ No	If YES, for what reason(s) does the responsible party consider this a major release? <i>This release was larger than 25 barrels of condensate.</i>
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

☒ The source of the release has been stopped. ☒ The impacted area has been secured to protect human health and the environment. ☒ Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. ☒ All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why:	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Chris Price</u>	Title: <u>Area Manager</u>
Signature: <u></u>	Date: <u>3-24-23</u>
Email: <u>cprice@targaresources.com</u>	Telephone: <u>(575) 602-6005</u>
<u>OCD Only</u>	
Received by: <u>Jocelyn Harimon</u>	Date: <u>03/29/2023</u>

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 201733

CONDITIONS

Operator: TARGA MIDSTREAM SERVICES LLC 811 Louisiana Street Houston, TX 77002	OGRID: 24650
	Action Number: 201733
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
jharimon	None	3/29/2023