

1RP-1090

Cabot Q SWD

Spill date – 10/16/2006.

Spill & Volume: 70 bbl produced water, 20 bbl recovered

Spill notes: Injection line failure. Spill mostly contained in firewall. Small volume escaped onto well pad affecting area 10' x 100' near well head. No pasture affected.

Delineation or remediation: According to C-141: added chat to pad area affected and blended.

Photos: none

Additional notes: It appears that the addition of chat was under the approval of the OCD; Fasken only has the C-141, which discusses adding chat.

Documents Attached:

New Mexico Form C-141

Final New Mexico Form C-141

FASKEN STATUS: DEFERRED

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company <u>Fasken Oil and Ranch, Ltd.</u>	Contact <u>Jimmy D. Carlile</u>
Address <u>303 W. Wall, Ste 1800 Midland, TX</u>	Telephone No. <u>432 687-1777</u>
Facility Name <u>Cabot Q SWD</u>	Facility Type <u>Battery</u>
Surface Owner <u>State</u>	Mineral Owner <u>State</u>
Lease No. _____	

LOCATION OF RELEASE


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	7	15S	35E	1980	South	560	West	Lea

Latitude _____ Longitude _____

WR-501

NATURE OF RELEASE

Type of Release <u>produced water</u>	Volume of Release <u>70</u>	Volume Recovered <u>20</u>
Source of Release <u>battery - tank overflow</u>	Date and Hour of Occurrence _____	Date and Hour of Discovery _____
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <u>Larry Johnson's voice mail</u>	<u>4 pm 10/16/06</u>
By Whom? <u>Jimmy D. Carlile</u>	Date and Hour <u>10/17/06 9 am</u>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.*

NA

Describe Cause of Problem and Remedial Action Taken.*

Check valve on pump plugged causing system to back up and tank to overflow. Check valve was cleaned out and put back in service. Plans are to re-plumb piping to solve this problem from occurring again.

Describe Area Affected and Cleanup Action Taken.*

Firewall area 75' x 25' area filled and overflowed. Approximately 10 bbls ran on caliche 10' x 100' on pad site. Plans are to mix in 2 loads of chat into the pad to dilute any residual chlorides.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Jimmy D. Carlile</u>	OIL CONSERVATION DIVISION	
Printed Name: <u>Jimmy D. Carlile</u>	Approved by District Supervisor: <u>[Signature]</u>	
Title: <u>Regulatory Affairs Coord.</u>	Approval Date: <u>6.5.07</u>	Expiration Date: <u>8.5.07</u>
E-mail Address: <u>jimmyc@forl.com</u>	Conditions of Approval: <input checked="" type="checkbox"/> Attached <input type="checkbox"/>	
Date: <u>10/17/06</u> Phone: <u>432 687-1777</u>	<u>SUBMIT FINAL REPORT BY</u>	

* Attach Additional Sheets If Necessary

RPH
1090

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company : Fasken Oil And Ranch, Ltd	Contact: Aaron Pachlhofer
Address: 6101 Holiday Hill Road, Midland, TX 79707	Telephone No.: 432-687-1777
Facility Name: Cabot 'Q' SWD	Facility Type: SWD Battery

Surface Owner: State	Mineral Owner: State	API No.
----------------------	----------------------	---------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	7	15S	35E	1980	South	560	West	Lea

Latitude 33.029916° Longitude -103.453821°

NATURE OF RELEASE


Type of Release: Produced Water	Volume of Release: 70	Volume Recovered: 20
Source of Release: Tank Overflow	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? 10/16/06	10/16/06 4:00 pm
By Whom? Jimmy D. Carlike	Date and Hour: 10/17/06 9:00 am Larry Johnson's Voicemail	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
Not Applicable

Describe Cause of Problem and Remedial Action Taken.*
Check valve on pump plugged causing system to back up and tank to overflow. Check valve was cleaned out and put back into service. Plans are to re-plumb piping to solve this problem from occurring again.

Describe Area Affected and Cleanup Action Taken.*
Initial – Firewall area 75' x 25' area filled and overflowed. Approximately 10 bbls ran on caliche 10' x 100' on pad site. Plans are to mix in 2 loads of chat into the pad to dilute any residual chlorides.
Final – Chat blended into affected pad area. Complete until abandonment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Aaron Pachlhofer	Approved by Environmental Specialist:	
Title: Environmental Coordinator	Approval Date:	Expiration Date:
E-mail Address: aaronp@forl.com	Conditions of Approval:	
Date: 5/15/18 Phone: 432-687-1777	Attached <input type="checkbox"/> 1RP-1090	

* Attach Additional Sheets If Necessary



6101 Holiday Hill Road
Midland, TX 79707
(432) 687-1777
(432) 687-1570 (FAX)

February 28, 2019

Mr. Bradford Billings
New Mexico Energy, Mineral, and Natural Resources Department
Oil Conservation Division
1220 South St. Francis Street
Santa Fe, NM 87505

RE: 1RP-1090

Mr. Billings,

Thank you for meeting with me on February 21st to discuss spills that have been reported to the OCD and remain in an "open" status.

As we discussed this spill which was originally reported to the OCD by Fasken on October 16, 2006.

Fasken Oil and Ranch, Ltd. respectfully requests to **DEFER** this spill until the SWD battery is decommissioned.

Thank you very much,

Aaron Pachlhofer
Environmental Coordinator
Fasken Oil and Ranch, Ltd.

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720
District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720
District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 204042

CONDITIONS

Operator: FASKEN OIL & RANCH LTD 6101 Holiday Hill Rd Midland, TX 79707	OGRID: 151416
	Action Number: 204042
	Action Type: [IM-SD] Incident File Support Doc (ENV) (IM-BNF)

CONDITIONS

Created By	Condition	Condition Date
amaxwell	Upload of historical documents.	4/11/2023
amaxwell	Deferral request approved. The deferral request and C-141 will be accepted for record and marked accordingly. The release will remain open in OCD database files and reflect an open environmental issue.	4/11/2023
amaxwell	Upon P&A activities, submit a report verifying that 19.15.29.13 NMAC stipulations have been met for the site.	4/11/2023