District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	nAPP2310150208
District RP	-
Facility ID	
Application ID	

# **Release Notification**

### **Responsible Party**

Responsible Party Maverick Permian, LLC			OGRID	331199		
Contact Name Bryce Wagoner			Contact Telephone	(928) 241-1862		
Contact ema	il Bry	ce.Wagoner@ma	vresources.com		Incident # (assigned by OC	D) nAPP2310150208
Contact mail	ing address	1410 NW Count Hobbs, New Me				
			Location	n of R	elease Source	
Latitude 32.	.7825				Longitude <u>-103.4777</u>	
			(NAD 83 in a	decimal deg	rees to 5 decimal places)	
Site Name		EVGSAU 054	6-038		Site Type Flowline Lea	ak
Date Release	Discovered	02/24/2023			API# (if applicable)	
Unit Letter	Section	Township	Range		County	
L2	05	18S	35E	Lea	•	
		Federal T	Nature an	nd Vol	ume of Release	the volumes provided below)
Crude Oi		Volume Releas				covered (bbls) 1
Produced	Water	Volume Releas	ed (bbls) 10		Volume Rec	covered (bbls) 1
Is the concentration of dissolved chloride in the produced water >10,000 mg/l?		in the Yes 🖂	No			
Condensa	ite	Volume Releas	ed (bbls)		Volume Re	covered (bbls)
Natural C	ias	Volume Releas	ed (Mcf)		Volume Rec	covered (Mcf)
Other (de	scribe)	Volume/Weigh	t Released (provi	ide units)	Volume/We	eight Recovered (provide units)
Cause of Rel Internal corre		ow line.				

- 73				0
···	an	0 )		• )
1	ag		$-\boldsymbol{v}$	, ,

Incident ID	nAPP2310150208
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the respon	sible party consider this a major release?
☐ Yes ⊠ No		
If YES, was immediate no Not Applicable	otice given to the OCD? By whom? To wh	om? When and by what means (phone, email, etc)?
	Initial Re	esponse
The responsible	party must undertake the following actions immediatel	unless they could create a safety hazard that would result in injury
The source of the rele	ease has been stopped.	
The impacted area ha	s been secured to protect human health and	the environment.
Released materials ha	we been contained via the use of berms or d	ikes, absorbent pads, or other containment devices.
All free liquids and re	ecoverable materials have been removed and	I managed appropriately.
P. 10 15 20 0 P. (4) NP.		
has begun, please attach	a narrative of actions to date. If remedial	emediation immediately after discovery of a release. If remediation efforts have been successfully completed or if the release occurred lease attach all information needed for closure evaluation.
regulations all operators are public health or the environr failed to adequately investig	required to report and/or file certain release notified. The acceptance of a C-141 report by the Cate and remediate contamination that pose a three	pest of my knowledge and understand that pursuant to OCD rules and fications and perform corrective actions for releases which may endanger CD does not relieve the operator of liability should their operations have at to groundwater, surface water, human health or the environment. In responsibility for compliance with any other federal, state, or local laws
Printed Name: Bryce W	agoner	Title: Permian HSE Specialist
Signature: Kyrwyr	<del></del>	Date: 4/21/2023
email: <u>Bryce.Wagoner@</u>	mavresources.com_	Telephone: (928) 241-1862
OCD Only		
Received by:	elyn Harimon	Date: 04/21/2023

	Page 3 of	8
Incident ID	nAPP2310150208	
District RP		
Facility ID		
Application ID		

### **Site Assessment/Characterization**

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	(ft bgs)	
Did this release impact groundwater or surface water?	☐ Yes ☐ No	
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	Yes No	
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	☐ Yes ☐ No	
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	☐ Yes ☐ No	
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	☐ Yes ☐ No	
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	☐ Yes ☐ No	
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	☐ Yes ☐ No	
Are the lateral extents of the release within 300 feet of a wetland?	☐ Yes ☐ No	
Are the lateral extents of the release overlying a subsurface mine?	☐ Yes ☐ No	
Are the lateral extents of the release overlying an unstable area such as karst geology?	☐ Yes ☐ No	
Are the lateral extents of the release within a 100-year floodplain?	☐ Yes ☐ No	
Did the release impact areas <b>not</b> on an exploration, development, production, or storage site?	☐ Yes ☐ No	
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and ver contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.	tical extents of soil	
Characterization Report Checklist: Each of the following items must be included in the report.		
Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells.  Field data  Data table of soil contaminant concentration data  Depth to water determination  Determination of water sources and significant watercourses within ⅓2-mile of the lateral extents of the release  Boring or excavation logs  Photographs including date and GIS information  Topographic/Aerial maps  Laboratory data including chain of custody		

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Received by OCD: 4/21/2023 2:40:38 PM Form C-141 State of New Mexico Page 4 Oil Conservation Division

	Page 4 o	f 8
Incident ID	nAPP2310150208	
District RP		
Facility ID		
Application ID		

regulations all operators are required to report and/or file certain release not public health or the environment. The acceptance of a C-141 report by the failed to adequately investigate and remediate contamination that pose a thru addition, OCD acceptance of a C-141 report does not relieve the operator of and/or regulations.	ifications and perform corrective actions for releases which may endanger OCD does not relieve the operator of liability should their operations have eat to groundwater, surface water, human health or the environment. In
Printed Name:	_ Title:
Signature:	Date:
email:	Telephone:
OCD Only	
Received by:	Date:

	Page 5 of	f 8
Incident ID	nAPP2310150208	
District RP		
Facility ID		
Application ID		

# **Remediation Plan**

Remediation Plan Checklist: Each of the following items must b	e included in the plan.
<ul> <li>□ Detailed description of proposed remediation technique</li> <li>□ Scaled sitemap with GPS coordinates showing delineation poin</li> <li>□ Estimated volume of material to be remediated</li> <li>□ Closure criteria is to Table 1 specifications subject to 19.15.29.</li> <li>□ Proposed schedule for remediation (note if remediation plan times)</li> </ul>	12(C)(4) NMAC
<u>Deferral Requests Only</u> : Each of the following items must be con	nfirmed as part of any request for deferral of remediation.
Contamination must be in areas immediately under or around predeconstruction.	roduction equipment where remediation could cause a major facility
☐ Extents of contamination must be fully delineated.	
Contamination does not cause an imminent risk to human health	n, the environment, or groundwater.
	e and remediate contamination that pose a threat to groundwater, acceptance of a C-141 report does not relieve the operator of
Printed Name:	Title:
Signature:	Date:
email:	Telephone:
OCD Only	
Received by:	Date:
☐ Approved ☐ Approved with Attached Conditions of	Approval
Signature:	<u>Date:</u>

tate of New Mexico

Incident ID	nAPP2310150208
District RP	
Facility ID	
Application ID	

# Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

☐ A scaled site and sampling diagram as described in 19.15.29.1	1 NMAC
Photographs of the remediated site prior to backfill or photos must be notified 2 days prior to liner inspection)	of the liner integrity if applicable (Note: appropriate OCD District office
☐ Laboratory analyses of final sampling (Note: appropriate ODC	District office must be notified 2 days prior to final sampling)
☐ Description of remediation activities	
and regulations all operators are required to report and/or file certain may endanger public health or the environment. The acceptance of a	nediate contamination that pose a threat to groundwater, surface water, a C-141 report does not relieve the operator of responsibility for tions. The responsible party acknowledges they must substantially additions that existed prior to the release or their final land use in CD when reclamation and re-vegetation are complete.
Signature:	Date:
email:	Telephone:
OCD Only	
Received by:	Date:
	of liability should their operations have failed to adequately investigate and water, human health, or the environment nor does not relieve the responsible or regulations.
Closure Approved by:	Date:
Printed Name:	Title:

#### \*\*\*\*\*\* LIQUID SPILLS - VOLUME CALCULATIONS \*\*\*\*\*\*

Location of Spill:	EVGSAU 0546-038	Date of Spill:	2/24/2023				
If the leak/spill is associated with production equipment, i.e wellhead, stuffing box, flowline, tank battery, production vessel, transfer pump, or storage tank place an "X" here:							
		Input Data:					

·					own enter the volumes here:  a Calculations" is optional.	0.0000 BBI		0.0000 BBL le the calculated volu	ımes.	
	Total Area Cal	culations				Standing L	iquid (	Calculations		
Total Confess Aves	:	la marth	wet soil	-:1 (0/)	Otan diam Limited Assa	!		la marth	liannial alamata	-:1 (0/)
Total Surface Area	width	length	depth	oil (%)	Standing Liquid Area	width		length	liquid depth	oil (%)
Rectangle Area #1	95.00 ft X	70.00 ft X	0.50 in	25.00%	Rectangle Area #1	65.00 ft	Х	20.00 ft X	0.25 in	15.00%
Rectangle Area #2	0.00 ft X	0.00 ft X	0.00 in	0.00%	Rectangle Area #2	0.00 ft	X	0.00 ft X	0.00 in	0.00%
Rectangle Area #3	0.00 ft X	0.00 ft X	0.00 in	0.00%	Rectangle Area #3	0.00 ft	X	0.00 ft X	0.00 in	0.00%
Rectangle Area #4	0.00 ft X	0.00 ft X	0.00 in	0.00%	Rectangle Area #4	0.00 ft	X	0.00 ft X	0.00 in	0.00%
Rectangle Area #5	0.00 ft X	0.00 ft X	0.00 in	0.00%	Rectangle Area #5	0.00 ft	X	0.00 ft X	0.00 in	0.00%
Rectangle Area #6	0.00 ft X	0.00 ft X	0.00 in	0.00%	Rectangle Area #6	0.00 ft	Χ	0.00 ft X	0.00 in	0.00%
Rectangle Area #7	0.00 ft X	0.00 ft X	0.00 in	0.00%	Rectangle Area #7	0.00 ft	X	0.00 ft X	0.00 in	0.00%
Rectangle Area #8	0.00 ft X	0.00 ft X	0.00 in	0.00%	Rectangle Area #8	0.00 ft	Χ	0.00 ft X	0.00 in	0.00%

Average Daily Production:  Oil Water  BBL BBL  BBL  BBL								
Did leak occur before the sepa Amount of Free Liquid Recovered:	z BBL	N/A (place an "X")	Percentage of Oi	il in Free Liquid Recovered:	50.00% (percentage)			
Liquid holding factor *:	0.14 gal per gal	Use the following when the spill w * sand = .08 gallon liquid per gall * gravelly (caliche) loam = .14 gall * sandy clay loam soil = .14 gallor * clay loam = .16 gallon liquid per	on volume of soil. Ion liquid per gallon volume of soil. I liquid per gallon volume of soil.	Occures when the spi	en the liquid completely fills the pore space of the soil: ill soaked soil is contained by barriers, natural (or not). am = .25 gallon liquid per gallon volume of soil. lon liquid per gallon volume of soil.			

Saturated Soil Volume Calculations:			Free Liquid Vo	lume Calculations:		
Total Solid/Liquid Volume: 6,650 sq. ft.	<u>H2O</u> 208 cu. ft.	OIL 69 cu. ft.	Total Free Liquid Volume:	1,300 sq. ft.	<u>H2O</u> 23 cu. ft.	OIL 4 cu. ft.
Estimated Volumes Spilled			Estimated Production	Volumes Lost		
Liquid in Soil: Free Liquid:	<u>H2O</u> 5.2 BBL 4.1 BBL	OIL 1.7 BBL 0.7 BBL	Estimated Production		<u>H2O</u> 0.0 BBL	OIL 0.0 BBL
Totals:	9.3 BBL	2.5 BBL	Estimated Surfac Surface Area:	e Damage 6,650 sq. ft.		
Total Spill Liquid:	9.3 BBL	2.5 BBL	Surface Area:	.1527 acre		
Recovered Volumes			Estimated Weights,	and Volumes		
Estimated oil recovered: 1.0 BBL Estimated water recovered: 1.0 BBL	check - oka check - oka	•	Saturated Soil = Total Liquid =	31,033 lbs 12 BBL	277 cu.ft. 493 gallon	10 cu.yds. 4,100 lbs

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 208336

#### **CONDITIONS**

Operator:	OGRID:
Maverick Permian LLC	331199
1111 Bagby Street Suite 1600	Action Number:
Houston, TX 77002	208336
	Action Type:
	[C-141] Release Corrective Action (C-141)

#### CONDITIONS

Created By		Condition Date
jharimon	None	4/21/2023