District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

)

Incident ID	
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party	OGRID
Contact Name	Contact Telephone
Contact email	Incident # (assigned by OCD)
Contact mailing address	

Location of Release Source

Latitude	Longitude			
	(NAD 83 in decimal degrees to 5 decimal places)			
Site Name	Site Type			

Site Name	Site Type
Date Release Discovered	API# (if applicable)

Unit Letter	Section	Township	Range	County

Surface Owner: State Federal Tribal Private (Name: _

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No
Condensate	Volume Released (bbls)	Volume Recovered (bbls)
Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)
Cause of Release		

Incident ID	
District RP	
Facility ID	
Application ID	

Page 2 of 4

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the responsible party consider this a major release?
Yes No	
If YES, was immediate n	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

The impacted area has been secured to protect human health and the environment.

Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

The source of the release has been stopped.

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name	Title:
Signature:	Date:
email:	Telephone:
OCD Only	
Received by: Jocelyn Harimon	Date:06/15/2023

L48 Spill Volume Estimate Form - Fill In Gray Cells												
			Facility Nam	e & Well Number(s):				Release Discov Time:	very Date &	6.8.23	-	
		Provide a	any known del	ails about the event:	check valve leaked				Primary Cause (dropdown):		Secondary Cause (dropdown):	~
					Recovered Volume (bbl.) (if available, not included in volume calculations)	available, not included in Determination Release Type (dropdown):			> 1/2" of Rain	in Last 24 Hours (dropdown):		covered (not included in ations, informational):
BU: P	ermian ~		Asset Area:	DBW - Fine Sands		Field Measurement \checkmark	Produce	d Water \checkmark		No		
			Known	Volume (dropdown):	No							
		Known Area (dropdown): No										
				Spi	ill Calculation - Subsurface	Spill - Cylinder					Remediation	Recommendation
Convert Irregular shape into a series of rectangles	Diameter (ft.)	Average Depth (in.)	On/Off Pad (dropdown)	Soil Spilled-Fluid Saturation (%.)	Estimated volume of each area (bbl.)	Total Estimated Volume of Spill (bbl.)					Total Estimated Contaminated Soil, uncompacted, 25% (yd ³ .)	Current Rule of Thumb - RMR Handover Volume, (yd ³ .)
Rectangle A	10.0	1.0	Off-Pad∕	13.69%	1.17	0.16					0.30	
Rectangle B			~		0.00						0.00	
Rectangle C			* *		0.00						0.00	
			~		0.00						0.00	
Rectangle D			×		0.00						0.00	750
Rectangle E		Rectangle F									0.00	
Rectangle E Rectangle F			~									
Rectangle E			*		0.00							
Rectangle E Rectangle F Rectangle G					0.00 0.00						0.00	
Rectangle E Rectangle F Rectangle G Rectangle H			~		0.00	0.1595					0.00	BU

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:			
COG OPERATING LLC	229137			
600 W Illinois Ave	Action Number:			
Midland, TX 79701	228752			
	Action Type:			
	[C-141] Release Corrective Action (C-141)			
CONDITIONS				

Created By Condition Condition Date 6/15/2023 jharimon None

CONDITIONS

Page 4 of 4

Action 228752