District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Page 1 of 7

Incident ID	nAPP2320576371
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party: Cimarex Energy Co. of Colorado	OGRID: 162683	
Contact Name: Laci Luig	Contact Telephone: (432) 571-7800	
Contact email: laci.luig@coterra.com	Incident # (assigned by OCD) nAPP2320576371	
Contact mailing address: 6001 Deauville Blvd., Suite 300N Midland, TX 79706		

Location of Release Source

Latitude 32.079316_

Longitude -103.591916_ (NAD 83 in decimal degrees to 5 decimal places)

Site Name: Cascade 29 Federal Com 75H Drill Cuttings	Site Type: Lease Road
Date Release Discovered: 7/22/2023	API# (if applicable)

Unit Letter	Section	Township	Range	County
В	5	26S	33E	Lea

Surface Owner: State Federal Tribal Private (Name: Basin Properties______

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No
Condensate	Volume Released (bbls)	Volume Recovered (bbls)
Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
Other (describe)	Volume/Weight Released (provide units) 1 yard oil based mud/cuttings	Volume/Weight Recovered (provide units) 0

Cause of Release: Equipment Failure

Around 7:00 pm CST on 7/22/2023, an oil base cuttings spill on a lease road in Lea County, NM was reported to our EHS department. A Waste Management truck was hauling cuttings from the Cactus 148 drilling rig, currently drilling Cimarex Energy's Cascade 29 Federal Com 75H, to Waste Management's landfill in Orla, TX. A mount on the end dump trailer sheared off, allowing slack in the gate of the trailer. Cuttings were found, sporadically, along 3 miles of the caliche lease road going towards Battle Axe Road, and sporadically along ~11 miles of Battle Axe road to the stop sign at C-1. The driver realized his trailer was releasing cuttings after pulling onto C-1 and immediately pulled off the road. Repairs were made to the trailer to prevent additional impact. Waste Management was immediately notified and dispatched a 3rd party contractor to remove all impact found along Battle Axe Road. The impacted lease roads were surface scraped and the impact hauled to the landfill for disposal. A total of 1 cubic yard of oil based mud was released from the trailer.

	Page 2 of
Incident ID	nAPP2320576371
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the responsible party consider this a major release?	
🗌 Yes 🖾 No		
If YES, was immediate n	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?	
By: Laci Luig		
To: OCD Enviro, BLM, SLO		
By: Email		

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

 \square The source of the release has been stopped.

The impacted area has been secured to protect human health and the environment.

Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Laci Luig	Title: ESH Specialist
Signature: <u>AC</u>	_ Date: 7/24/2023
email: laci.luig@coterra.com	Telephone: (432) 208-3035
OCD Only	
Received by: <u>Shelly Wells</u>	Date: <u>7/27/2023</u>

Cascade 29 Fed Com 75H

Oil Based Mud Drill Cuttings Release

Start Point: 32.077698, -103.591803 B-5-26S-33E

Lease road = 3.1 miles Battle Axe road = 11 miles



Legend

Second 29 FC 75H cutting - Battle Axe

Page 3 of

NEW N


N


4 mi

- Second 29 FC 75H cuttings lease road
- **OBM** Start

Google Earth

Released to Phile ing 19/29/92023 4:36:16 P.







District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
CIMAREX ENERGY CO. OF COLORADO	162683
6001 Deauville Blvd, Ste 300N	Action Number:
Midland, TX 79706	245149
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By Condition

scwells None CONDITIONS

Action 245149

Condition Date

7/27/2023