Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 471527

QUESTIONS

ı	Operator:	OGRID:
ı	XTO ENERGY, INC	5380
ı	6401 Holiday Hill Road	Action Number:
ı	Midland, TX 79707	471527
ı		Action Type:
ı		[NOTIFY] Notification Of Liner Inspection (C-141L)

QUESTIONS

Prerequisites	
Incident ID (n#)	nAPP2510447031
Incident Name	NAPP2510447031 PLU 30 BIG SINKS BATTERY @ 0
Incident Type	Produced Water Release
Incident Status	Initial C-141 Approved

Location of Release Source		
Site Name	PLU 30 Big Sinks Battery	
Date Release Discovered	04/13/2025	
Surface Owner	Federal	

Liner Inspection Event Information				
ase answer all the questions in this group.				
What is the liner inspection surface area in square feet	826			
Have all the impacted materials been removed from the liner	Yes			
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	06/11/2025			
Time liner inspection will commence	08:00 AM			
Please provide any information necessary for observers to liner inspection	Tracy Hillard - thillard@ensolum.com			
Please provide any information necessary for navigation to liner inspection site	GPS at 32.104174, -103.821509. Open Access, potential H2S and livestock.			

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 471527

CONDITIONS

Operator:	OGRID:
XTO ENERGY, INC	5380
6401 Holiday Hill Road	Action Number:
Midland, TX 79707	471527
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

CONDITIONS

Created By		Condition Date
kthomason01	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	6/6/2025