Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 488714

## **QUESTIONS**

Operator:	OGRID:
XTO ENERGY, INC	5380
6401 Holiday Hill Road	Action Number:
Midland, TX 79707	488714
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

## QUESTIONS

Prerequisites		
Incident ID (n#)	nAPP2517251958	
Incident Name	NAPP2517251958 HAT MESA 31/32 STATE BATTERY @ 0	
Incident Type	Produced Water Release	
Incident Status	Initial C-141 Approved	
Incident Facility	[fAPP2126349697] HAT MESA '31' STATE BATT 1,2	

Location of Release Source		
Site Name	HAT MESA 31/32 STATE BATTERY	
Date Release Discovered	06/20/2025	
Surface Owner	State	

Liner Inspection Event Information		
Please answer all the questions in this group.		
What is the liner inspection surface area in square feet	3,900	
Have all the impacted materials been removed from the liner	Yes	
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	07/30/2025	
Time liner inspection will commence	10:00 AM	
Please provide any information necessary for observers to liner inspection	Riley Arnold 575-552-2953	
Please provide any information necessary for navigation to liner inspection site	From the intersection of Goathead Rd and NM 176 turn right E on Nm 176. Continue E on Nm 176 for 0.9 Miles. Turn right S on unnamed lease road. Continue on unnamed lease road for 0.9 Mi to dead end, then turn left E for 400 feet into location Hat Mesa 31 State 002 GPS 32.535052, -103.700383	

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory <a href="https://www.emnrd.nm.gov/ocd/contact-us">https://www.emnrd.nm.gov/ocd/contact-us</a>

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 488714

## **CONDITIONS**

Operator:	OGRID:
XTO ENERGY, INC	5380
6401 Holiday Hill Road	Action Number:
Midland, TX 79707	488714
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

## CONDITIONS

Created By		Condition Date
chensley02	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	7/25/2025