Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 507847

QUESTIONS

ı	Operator:	OGRID:
ı	OXY USA INC	16696
ı	P.O. Box 4294	Action Number:
ı	Houston, TX 772104294	507847
ı		Action Type:
ı		[NOTIFY] Notification Of Liner Inspection (C-141L)

QUESTIONS

uisites	
Incident ID (n#)	nAPP2523232222
Incident Name	NAPP2523232222 CORRAL WTR TREATMENT FAC @ M-01-25S-29E
Incident Type	Produced Water Release
Incident Status	Initial C-141 Approved

Location of Release Source		
Site Name	CORRAL WTR TREATMENT FAC	
Date Release Discovered	08/19/2025	
Surface Owner	State	

Liner Inspection Event Information				
Please answer all the questions in this group.				
What is the liner inspection surface area in square feet	23,000			
Have all the impacted materials been removed from the liner	Yes			
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	09/25/2025			
Time liner inspection will commence	09:00 AM			
Please provide any information necessary for observers to liner inspection	512-496-4197			
Please provide any information necessary for navigation to liner inspection site	32.15403, -103.94595			

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 507847

CONDITIONS

Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	507847
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

CONDITIONS

Created By	Condition	Condition Date
dsparks	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	9/22/2025