

From: [Smith, Clarence, EMNRD](#)
To: [Hall, Brittany, EMNRD](#)
Subject: Fw: Pre Enforcement Notification for iCZS2526542933
Date: Thursday, September 25, 2025 3:40:36 PM

From: Engineer, OCD, EMNRD <OCD.Engineer@emnrd.nm.gov>
Sent: Tuesday, September 23, 2025 10:45 AM
To: dhanosh426@gmail.com <dhanosh426@gmail.com>
Cc: DHANOSH426@GMAIL.COM <DHANOSH426@GMAIL.COM>; Smith, Clarence, EMNRD <Clarence.Smith@emnrd.nm.gov>
Subject: Pre Enforcement Notification for iCZS2526542933

State Of New Mexico

Energy, Minerals and Natural Resources Department

23-Sep-25

ENERDYNE, LLC

12812 PIRU S.E.

Albuquerque, NM 87123

Pre Enforcement Notification

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the Compliance Officer copied on this letter, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

[30-031-20647] STATE #024

OGRID: 185239

B-28-20N-09W 660 FNL
2310 FEL

Inspection Date	Type Inspection	Inspector	Inspection No.
9/22/2025	Complaintant Response	[CZS] Clarence Smith	iCZS2526542933
Violation	Title		Corrective Action Due
cCZS2526638698	19.15.29 Releases Unauthorized Release		12/21/2025
(Inspection performed and remediation excavation still open remediation closure report was due December 16, 2024. No report received.)			

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 509526

CONDITIONS

Operator: ENERDYNE, LLC 12812 PIRU S.E. Albuquerque, NM 87123	OGRID: 185239
	Action Number: 509526
	Action Type: [IM-SD] Incident File Support Doc (ENV) (IM-BNF)

CONDITIONS

Created By	Condition	Condition Date
bhall	Upload of Pre Enforcement Notification sent to operator after an OCD inspector performed inspection of the site.	9/25/2025