Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory <a href="https://www.emnrd.nm.gov/ocd/contact-us">https://www.emnrd.nm.gov/ocd/contact-us</a>

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 515487

## **QUESTIONS**

ı	Operator:	OGRID:
ı	XTO ENERGY, INC	5380
ı	6401 Holiday Hill Road	Action Number:
ı	Midland, TX 79707	515487
ı		Action Type:
ı		[NOTIFY] Notification Of Liner Inspection (C-141L)

## QUESTIONS

Prerequisites			
Incident ID (n#)	nAPP2527942053		
Incident Name	NAPP2527942053 ROSS DRAW 25 NORTH BATTERY @ FAPP2126040305		
Incident Type	Produced Water Release		
Incident Status	Initial C-141 Approved		
Incident Facility	[fAPP2126040305] Ross Draw 25 North Battery		

Location of Release Source		
Site Name	ROSS DRAW 25 NORTH BATTERY	
Date Release Discovered	10/05/2025	
Surface Owner	Federal	

Liner Inspection Event Information			
lease answer all the questions in this group.			
What is the liner inspection surface area in square feet	253		
Have all the impacted materials been removed from the liner	Yes		
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	10/21/2025		
Time liner inspection will commence	09:00 AM		
Please provide any information necessary for observers to liner inspection	Tacoma Morrissey 337-257-8307		
Please provide any information necessary for navigation to liner inspection site	GPS at 32.018848, -103.936031. Open access, potential H2S and livestock.		

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory <a href="https://www.emnrd.nm.gov/ocd/contact-us">https://www.emnrd.nm.gov/ocd/contact-us</a>

## State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 515487

## **CONDITIONS**

Operator:	OGRID:
XTO ENERGY, INC	5380
6401 Holiday Hill Road	Action Number:
Midland, TX 79707	515487
	Action Type:
	[NOTIFY] Notification Of Liner Inspection (C-141L)

## CONDITIONS

Created By	Condition	Condition Date
thillard	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	10/15/2025