

C9+ AnalysisGPA 2172/API 14.5 Report with GPA 2145 Physical Properties

Sample Information

		Sample Information
Sample Name		BODACIOUS 5H CHECK 6-19-25
Operator		Permian Resources
Lease		BODACIOUS 5H CHECK
Sample Date/Time:	Effective Date:	6-19-25 7:18 AM
Sample End Date		
Laboratory		Premier Measurement and Laboratory Services
Technician		AN
Analyzer Type		Gas Chromatograph - TCD
Analyzer Make & Model		Agilent Micro GC 3000
Last Calibration/Validation Date		6-16-2025
Sample Temperature		87 F
Sample Pressure		167 PSI
Sample Flow Rate		1438 MCF
Ambient Temperature		78 F
Heat Tracing		No
Sample Type		Spot
Sampling Method		Fill and Purge
Company Collecting Sample		LSM
Sampled By		TH
Cylinder #		4187
Mole, Weight, or Percent (For F	lowcal DON'T EDIT)	M
Sample Calculation Method(For	Flowcal DON'T EDIT)	GPA 2172/API 14.5 Report with GPA 2145 Physical Properties
Analysis Date		2025-06-20 11:08:36

Component Results

Component Name	Un-Normalized Mole%	Norm Mole%
Nitrogen	1.0400	1.0296
Carbon Dioxide	2.8340	2.8057
Methane	80.1150	79.3164
Ethane	9.6930	9.5964
Propane	4.2540	4.2116
isobutane	0.5940	0.5881

Component Name	Un-Normalized Mole%	Norm Mole%
n-Butane	1.2900	1.2771
isopentane	0.3170	0.3138
n-Pentane	0.3200	0.3168
hexanes	0.3270	0.3237
heptanes	0.1310	0.1297
octanes	0.0310	0.0307
nonanes+	0.0110	0.0109
hydrogen sulfide	0.0500	0.0495
Total:	101.0070	100.0000

Results Summary

Result	Dry	Wet/Sat
Total Un-Normalized Mole%	101.0070	
Pressure Base (psia)	14.730	
Temperature Base (Deg. F)	60.00	
Gross Heating Value (BTU / Ideal cu.ft.)	1191.2	1170.5
Gross Heating Value (BTU / Real cu.ft.)	1195.3	1174.9
Relative Density (G), Ideal	0.7252	0.7234
Relative Density (G), Real	0.7274	0.7259
Compressibility (Z) Factor	0.9966	0.9962
Total GPM	18.871	18.650



Permian Resources meters all flared volumes, and volumes reported on C-129's in connection with flaring events are based on the available meter readings. While Permian Resources reports metered volumes on C-129 submissions, PR reviews the metered data for accuracy, reconciles any discovered discrepancies, and, where appropriate, submits amended C-129 reported volumes post-reconciliation to ensure accurate reporting.

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

DEFINITIONS

Action 525576

DEFINITIONS

Operator:	OGRID:
Earthstone Operating, LLC	331165
300 N. Marienfeld St Ste 1000	Action Number:
Midland, TX 79701	525576
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- this application's operator, hereinafter "this operator";
- venting and/or flaring, hereinafter "vent or flare";
- any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms";
- the statements in (and/or attached to) this, hereinafter "the statements in this";
- and the past tense will be used in lieu of mixed past/present tense questions and statements.

Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116 Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 525576

QI	JESTIONS	
Operator:		OGRID:
Earthstone Operating, LLC 300 N. Marienfeld St Ste 1000	,	331165 Action Number:
Midland, TX 79701		525576
	,	Action Type: [C-129] Venting and/or Flaring (C-129)
QUESTIONS		
Prerequisites		
Any messages presented in this section, will prevent submission of this application. Please resolve t	hese issues before continuing with t	the rest of the questions.
Incident Well	Unavailable.	
Incident Facility	[fAPP2123755583] BODACIOUS 5-32 FED COM BATTERY	
Determination of Reporting Requirements		
Answer all questions that apply. The Reason(s) statements are calculated based on your answers an	d may provide addional quidance	
Was this vent or flare caused by an emergency or malfunction	No	
Did this vent or flare last eight hours or more cumulatively within any 24-hour		
period from a single event	Yes	
Is this considered a submission for a vent or flare event	Yes, minor venting and/or fla	aring of natural gas.
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during ve	enting and/or flaring that is or may b	e a major or minor release under 19.15.29.7 NMAC.
Was there at least 50 MCF of natural gas vented and/or flared during this event	Yes	
Did this vent or flare result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No	
Was the vent or flare within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No	
Province and law of the		
Equipment Involved		_
Primary Equipment Involved	Not answered.	
Additional details for Equipment Involved. Please specify	Not answered.	
Representative Compositional Analysis of Vented or Flared Natural Gas		
Please provide the mole percent for the percentage questions in this group.		
Methane (CH4) percentage	79	
Nitrogen (N2) percentage, if greater than one percent	1	
Hydrogen Sulfide (H2S) PPM, rounded up	0	
Carbon Dioxide (C02) percentage, if greater than one percent	3	
Oxygen (02) percentage, if greater than one percent	0	
If you are venting and/or flaring because of Pipeline Specification, please provide the required specification (CH4) percentage quality requirement	fications for each gas. Not answered.	
Nitrogen (N2) percentage quality requirement	Not answered.	
Hydrogen Sufide (H2S) PPM quality requirement	Not answered.	
Carbon Dioxide (C02) percentage quality requirement Oxygen (02) percentage quality requirement	Not answered. Not answered.	
Oxygon (02) percentage quanty requirement	ivol allowered.	

Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS, Page 2

Action 525576

OUESTI	ONS (continued)	
Operator:	OGRID:	
Earthstone Operating, LLC	331165	
300 N. Marienfeld St Ste 1000 Midland, TX 79701	Action Number: 525576	
	Action Type: [C-129] Venting and/or Flaring (C-129)	
QUESTIONS	1 12 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	
Date(s) and Time(s)		
Date vent or flare was discovered or commenced	11/01/2025	
Time vent or flare was discovered or commenced	11/01/2025	
Time vent or flare was discovered or commenced Time vent or flare was terminated	12:00 AM	
Cumulative hours during this event	11:59 PM 24	
Cumulative flours during this event		
Measured or Estimated Volume of Vented or Flared Natural Gas		
Natural Gas Vented (Mcf) Details	Not answered.	
Natural Gas Flared (Mcf) Details	Cause: Equipment Failure Pipeline (Any) Natural Gas Flared Released: 96 Mcf Recovered: 0 Mcf Lost: 96 Mcf.	
Other Released Details	Not answered.	
Additional details for Measured or Estimated Volume(s). Please specify	Not answered.	
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.	
Venting or Flaring Resulting from Downstream Activity		
	[
Was this vent or flare a result of downstream activity	No	
Was notification of downstream activity received by this operator Downstream OGRID that should have notified this operator	Not answered.	
`	Not answered.	
Date notified of downstream activity requiring this vent or flare Time notified of downstream activity requiring this vent or flare	Not answered.	
Time notified of downstream activity requiring this vent of flare	Not answered.	
Steps and Actions to Prevent Waste		
For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control.	True	
Please explain reason for why this event was beyond this operator's control	Compressor down - 5H unloading	
Steps taken to limit the duration and magnitude of vent or flare	Open valves to divert gas to a second midstream company to relieve pressure off the line	
Corrective actions taken to eliminate the cause and reoccurrence of vent or flare	Clear consistent communication with midstream provider	

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 525576

ACKNOWLEDGMENTS

Operator:	OGRID:
Earthstone Operating, LLC	331165
300 N. Marienfeld St Ste 1000	Action Number:
Midland, TX 79701	525576
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

ACKNOWLEDGMENTS

V	I acknowledge that I am authorized to submit a Venting and/or Flaring (C-129) report on behalf of this operator and understand that this report can be a complete C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC.
V	I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively.
V	I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
V	I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
<u>~</u>	I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 525576

CONDITIONS

Operator:	OGRID:
Earthstone Operating, LLC	331165
300 N. Marienfeld St Ste 1000	Action Number:
Midland, TX 79701	525576
	Action Type:
	[C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
jdoolingpr	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	11/11/2025